

SALE SUMMARY LIST

PLEASE NOTE: Every effort has been made to accurately describe items and their condition; however, additional problems may exist, items may not be complete or exactly as described. Bidders are deemed to have reviewed the Terms and Conditions on bid forms and relied entirely on their own inspection and evaluation prior to bidding. Vehicles and equipment are sold "AS IS, WHERE IS", there is no implied or express warranty.

Visit www.SaskSurplus.ca for pictures and link to download Bid Form.

- Items identified with * have been on a previous sale and will be listed first on www.SaskSurplus.ca web site.
- SaskBuilds and Procurement, SaskSurplus, reserves right to have unadvertised minimum selling prices on items.

It is the Bidder's responsibility to review the terms and conditions of sale on the Offer to Purchase, Bid Form.

Bid Forms are available from www.SaskSurplus.ca or from the SaskSurplus Sales Lot, 500 McLeod Street, Regina, SK.

Bid Forms can be submitted in the following ways:

- by deposit in the bid box at the SaskSurplus Sales Lot,
- by fax to 306-767-2092; by phone 306-767-2062 or 306-767-2236,
- by email to sasksurplus@gov.sk.ca, or
- by mail, addressed to: Ministry of SaskBuilds and Procurement, SaskSurplus, 500 McLeod Street, Regina, SK S6N 6Y1.

(If mailing your bid, please allow sufficient time for bid to be received.)

- Bids received after close date and time cannot be accepted.

MT = (Ministry Transfer) This means that the item has been claimed by another ministry and automatically transferred to the ministry.

WD = (Withdrawn) This can happen if the item was requested to be removed by the seller.

No Bid = Items that did not receive any bids are normally carried forward to the next sale or may be withdrawn.

Item #	Description	Kms	Min Price	Serial Number
REGINA, SaskBuilds and Procurement, SaskSurplus Sales Lot, 500 McLeod Street - Vehicles				
Contact SaskSurplus 306-787-2062 or 306-798-3306.				
3,888.88	7-035	Car 2013 CHEVROLET Impala LS FWD 3.6L V6 gas auto A/C, tilt, cruise, AM/FM/CD player, power mirrors/locks/windows/ left front seat, keyless entry-2 keys 2 fobs , Grey, TOW ONLY, NO SGI Inspection. It is unknown if any repairs or safety concerns exist (if any). Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs if required. , 250,295 km, PROBLEMS: Powertrain rack leaking, wheel alignment, grille broke, bumper chips scratches, rocker panel loose near front, left front door rust inside, roof rust spots scratched, no first aid kit, no fire extinguisher, windshield chips, minor exterior damage.> , As is, Where is	250,295 km	\$2,888 2G1WA5E30D1249571
750.00	7-012	Car 2007 CHEVROLET Impala LS FWD 3.5L V6 gas auto A/C, tilt, cruise, AM/FM/CD player, power mirrors/locks/windows/left front seat/trunk release, keyless entry 1 keys 1 fobs , blue , FOR PARTS ONLY, NO SGI INSPECTION.**THIS VEHICLE IS FOR RECYCLING PURPOSES ONLY AND NOT FOR RESALE. THIS VEHICLE CANNOT BE REGISTERED WITHIN ANY JURISDICTION. **, 199,580 km, PROBLEMS: Front struts mounts, rear struts, front pads and rotors, all four tires, alignment, hole in floor, grille chrome poor, hood scratches/road rash/dents, front bumper chips, rear bumper scratches/chips, front left fender chips, right side fenders scratches/road rash, rocker panels rusted, left side doors road rash/paint peeling, right side doors road rash, roof scratches, trunk lid rust/scratches, windshield crack/chips, poor battery, minor exterior damage.> , As is, Where is	199,580 km	\$270 2G1WB58K779343002
850.00	7-017	Car 2009 CHEVROLET Impala LS FWD 3.5L V6 gas auto Dual Zone A/C, tilt, cruise, AM/FM/CD player, power mirrors/locks/windows/left front seat/trunk release, keyless entry-1 fobs, 2 keys , grey, FOR PARTS ONLY, NO SGI INSPECTION.**THIS VEHICLE IS FOR RECYCLING PURPOSES ONLY AND NOT FOR RESALE. THIS VEHICLE CANNOT BE REGISTERED WITHIN ANY JURISDICTION. **, 178,783 km, PROBLEMS: Power steering pump, four wheel alignment, head lamps foggy, driver door pins, frame ripped left rear, hood scratches/chips/dents, rear bumper scratches/dent, rocker panels rusted, all doors paint peeling/rust at bottom, roof rust/scratches, left roof rail scratches, no first aid kit/fire extinguisher, windshield chips, poor battery, minor exterior damage.> , As is, Where is	178,783 km	\$274 2G1WB57K891325434

Item #	Description	Kms	Min Price	Serial Number
800.00 7-020	Car 2009 CHEVROLET Impala LS FWD 3.5L V6 gas auto Dual zone A/C, tilt, cruise, AM/FM/CD player, power mirrors/locks/windows/ left front seat/trunk release, keyless entry-1 keys 1 fobs , grey, FOR PARTS ONLY, NO SGI INSPECTION.**THIS VEHICLE IS FOR RECYCLING PURPOSES ONLY AND NOT FOR RESALE. THIS VEHICLE CANNOT BE REGISTERED WITHIN ANY JURISDICTION. **, 227,889 km, PROBLEMS: Rear rotors, headlights foggy, hood chips/scratches/dents, front and rear bumper scratches/chips, left front fender scratches, right side fenders rust, rocker panels rusted, all doors rust at bottom inside and out, roof rusted, trunk lid rusted/scratches, no first aid kit/fire extinguisher, windshield chips, poor battery, minor exterior damage.>, As is, Where is	227,889 km	\$255	2G1WB57KX91325080
720.72 7-016	Car 2009 CHEVROLET Impala LS FWD 3.5L V6 gas auto Dual Zone A/C, tilt, cruise, AM/FM/CD player, power mirrors/locks/windows/left front seat/trunk release, keyless entry-2 fobs, 3 keys , grey, FOR PARTS ONLY, NO SGI INSPECTION.**THIS VEHICLE IS FOR RECYCLING PURPOSES ONLY AND NOT FOR RESALE. THIS VEHICLE CANNOT BE REGISTERED WITHIN ANY JURISDICTION. **, 239,254 km, PROBLEMS: Left head light fogged, hood chips/scratches/dents, both bumper's scrape/scratches, left side fenders scratches, left side rocker panel rusted hole, all doors rust inside and out at bottom, rear right door dented, roof rust spots, trunk lid rust/scratches, no first aid kit/fire extinguisher, windshield chips, poor battery, minor exterior damage.>, As is, Where is	239,254 km	\$255	2G1WB57KX91327167
900.00 7-018	Car 2009 CHRYSLER Sebring LX FWD 2.4L Inline 4 gas auto A/C, tilt, cruise, AM/FM/CD player, power heated mirrors/locks/windows/trunk release, keyless entry-2 fobs , red, FOR PARTS ONLY, NO SGI INSPECTION.**THIS VEHICLE IS FOR RECYCLING PURPOSES ONLY AND NOT FOR RESALE. THIS VEHICLE CANNOT BE REGISTERED WITHIN ANY JURISDICTION. **, 234,518 km, PROBLEMS: Washer, wiper blades, head lamps foggy, hood scratches/paint bubbling, front bumper broke, both bumpers clear coat peeling, left front fender scratches, right rear fender rusted, left side doors rust inside bottom/road rash, right side doors rusted/dents/chips, trunk lid rusted-hole/scratches, trunk rusted through, no first aid kit/fire extinguisher, windshield chips, poor battery, minor exterior damage.>, As is, Where is	234,518 km	\$253	1C3LC46B39N573435

Item #	Description	Kms	Min Price	Serial Number
700.00 7-019	Car 2006 CHRYSLER Sebring Touring FWD 2.7L V6 gas auto A/C, tilt, cruise, AM/FM/CD player, fog/driving lights, power mirrors/locks/windows/trunk release, keyless entry-2 keys 2 fobs , silver, FOR PARTS ONLY, NO SGI INSPECTION.**THIS VEHICLE IS FOR RECYCLING PURPOSES ONLY AND NOT FOR RESALE. THIS VEHICLE CANNOT BE REGISTERED WITHIN ANY JURISDICTION. **, 192,904 km, PROBLEMS: Rear struts, front and rear pads and rotors, hood chips/scratches, front and rear bumper chips/scratches/cracks, left rear fender scratches, right front fender dents/scrape, rear right fender rust, rocker panels rusted, left rear door scratches, roof small dent, trunk lid chips/scratches/dents, no first aid kit/fire extinguisher, windshield chips, poor battery, minor exterior damage.>, As is, Where is	192,904 km	\$253	1C3EL56R56N223666
700.00 7-011	Car 2009 FORD Focus SE FWD 2.0L Inline 4 gas auto A/C, tilt, cruise, AM/FM/CD player/Bluetooth, power heated mirrors, power locks/windows/trunk release, keyless entry 2 keys 2 fobs , grey, FOR PARTS ONLY, NO SGI INSPECTION.**THIS VEHICLE IS FOR RECYCLING PURPOSES ONLY AND NOT FOR RESALE. THIS VEHICLE CANNOT BE REGISTERED WITHIN ANY JURISDICTION. **, 229,718 km, PROBLEMS: Both rear upper lateral arms, right marker light, headlight assembly foggy, hood dents/scratches/chips, both bumpers scratches/chips/scrape, left front fender scratches, rocker panels rusted threw/paint flaking, left rear door chips/road rash, no first aid kit/fire extinguisher, windshield chips/scratches, both mirrors pitted, poor battery, minor exterior damage.>, As is, Where is	229,718 km	\$255	1FAHP35N89W104370
1,250.00 7-014	SUV 2016 CHEVROLET Equinox LS AWD 2.4L Inline 4 gas auto A/C, tilt, cruise, AM/FM/Bluetooth, power mirrors/windows/locks/left front seat, keyless entry-2 key fobs , white, FOR PARTS ONLY, NO SGI INSPECTION.**THIS VEHICLE IS FOR RECYCLING PURPOSES ONLY AND NOT FOR RESALE. THIS VEHICLE CANNOT BE REGISTERED WITHIN ANY JURISDICTION. **, 242,236 km, PROBLEMS: Misfire, check engine light codes P0014 exhaust camshaft position/P0011 intake camshaft position, front and rear pads and rotors, all four tires, grille hole, hood chips, left side fender chips/road rash/rust, both rocker panels rusted, left front door chips/rust inside bottom, left rear door chips, right side doors rust inside bottom, tailgate paint poor/rust, no first aid kit/fire extinguisher, windshield chips, poor battery, minor exterior damage.>, As is, Where is	242,236 km	\$277	2GNFLEEK7F6318004

Item #	Description	Kms	Min Price	Serial Number
800.00 7-015	SUV 2008 FORD Escape Hybrid 4WD 2.3L Inline 4 gas auto A/C, tilt, cruise, AM/FM/CD player, dual zone A/C, power mirrors/locks/windows/left front seat, 2 keys , white, FOR PARTS ONLY, NO SGI INSPECTION. **THIS VEHICLE IS FOR RECYCLING PURPOSES ONLY AND NOT FOR RESALE. THIS VEHICLE CANNOT BE REGISTERED WITHIN ANY JURISDICTION. **, 255,637 km, PROBLEMS: Hood stone chips, both bumpers scratched, front bumper cracked, left front fender paint flaking, left rear fender rust, right front fender dent, right rear and front fender road rash, rocker panels rusted, left side doors rust along bottom and inside, right side doors rust inside bottom, left front and right front and rear windows glass scratched, roof small rust/chips, hole in roof 1 sealed, tailgate rust along bottom/glass scratched, wheel wrench missing, no first aid kit/fire extinguisher, windshield chips/scratches, poor battery, minor exterior damage.>, As is, Where is	255,637 km	\$325	1FMCU59H98KE17927
3,907.00 7-023	SUV 2008 JEEP Liberty Sport 4WD 3.7L V6 gas auto A/C, tilt, cruise, AM/FM/CD player, driving lights, power mirrors/locks/windows, keyless entry 1 key fob , red, TOW ONLY, FAILED SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. **Please note: the SGI Inspection currently provided is only valid for 30 days after the date of the inspection.** , 251,079 km, PROBLEMS: Tire pressure monitoring system (TPMS) light on, right rear tire sensor, lower rad support, park brake doesn't hold, right rear door weather stripping ripped, left license light, headlights fogged, left front seat stained, missing trim, no stops on glove box, hood hail dents, chips, scratches, front bumper chips, scratches, left front and rear fenders road rash right font dents, left front door rust at bottom, roof hail dents, rust, tailgate rust, glass scratched, wipers, no first aid kit/fire extinguisher, windshield chips, poor battery, minor exterior damage.>, As is, Where is	251,079 km	\$1,889	1J8GN28K48W251770
7,989.00 7-036	Truck 2009 CHEVEROLET Silverado 2500 HD 4WD, 8' Box, Extended Cab 6.0L V8 gas auto A/C, tilt, cruise, AM/FM, 2 keys Grille inserts, front recovery hooks, mud flaps, side steps, hitch, trailer wiring, electric trailer brake, Knaack ladder rack, has a back seat, black, TOW ONLY, FAILED SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. **Please note: the SGI Inspection currently provided is only valid for 30 days after the date of the inspection.** , 261,942 km, PROBLEMS: Windshield cracked, left rear taillight assembly cracked, hood chips/scratches, front bumper extension broke/chrome poor, front valance cracked, left rear fender chips/scratches/dents, left front door chips, left rear door chips/scrape/dents, right side doors dents/scratches, roof scratches, tailgate dents/scratches/missing decal, wheel wrench loose under rear, no first aid kit/fire extinguisher, poor battery, minor exterior damage.>, As is, Where is	261,942 km	\$5,768	1GCHK49K49E150329

Item #	Description	Kms	Min Price	Serial Number
6,612.00 7-025	Truck 2009 CHEVROLET Silverado 1500 4WD, 6'8" box, Ext Cab 5.3L V8 gas auto A/C, tilt, cruise, AM/FM/CD player, power mirrors/locks/windows, keyless entry, 2 keys, 2 fobs Grille inserts, front tow hooks, side steps, mud flaps, headache rack with beacon, box liner, hitch, trailer wiring, electric trailer brake, blue , TOW ONLY, FAILED SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. **Please note: the SGI Inspection currently provided is only valid for 30 days after the date of the inspection.** , 122,052 km, Recent Repairs: Replaced battery PROBLEMS: Leaking transmission fluid, tread low on tires, front and rear wheel alignment needed, left front seat starting to tare, hood chips, scratches, dents, front left bumper extension dent, both rear fenders rusted, both box rails dented, roof small rust spots, scratches, tailgate small dents, scratches, Windshield has rock chips starting to spider, wipers do not clear windshield, poor battery, minor exterior damage.>, As is, Where is	122,052 km	\$4,119	1GCEK19069Z257004
7,555.99 7-026	Truck 2015 CHEVROLET Silverado 1500 4WD, 6'6" box, Crew Cab 4.3L V6 gas auto A/C, tilt, cruise, AM/FM/CD player, power mirrors/locks/windows, keyless entry, 2 fobs, 2 keys, 1 key for tonneau cover Front tow hooks, hitch, trailer wiring, OEM electric trailer brake, Roll-N-Lock tonneau (condition unknown), has a back seat, white, TOW ONLY, FAILED SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. **Please note: the SGI Inspection currently provided is only valid for 30 days after the date of the inspection.** , 191,193 km, Recent Repairs: sealed 3 holes in front hump PROBLEMS: Check engine light C00050, right rear wheel speed circuit malfunction, Stabilitrak light comes on over bumps, poor engine, 8 holes in rear hump 3 sealed in front, front brake pads rotor dishes inside edge, front and rear rotors, hood hail dents, left rear fender small dent, front scratched, both rear door paint peeling, 5 holes in roof sealed, no first aid kit/fire extinguisher, windshield chips, poor battery, minor exterior damage, As is, Where is	191,193 km	\$5,705	3GCUKPEH5FG267643
4,999.99 7-033	Truck 2008 CHEVROLET Silverado 2500HD RWD, 6'8" box, Extended Cab 6.0L V8 gas auto A/C tilt, cruise, after market AM/FM, power locks, 2 keys Grille inserts, front tow hooks, side steps, mud flaps, hitch, trailer wiring, electric trailer brake, Black, TOW ONLY, FAILED SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. **Please note: the SGI Inspection currently provided is only valid for 30 days after the date of the inspection.** , 259,176 km, PROBLEMS: Front brake pads and rotors, front tires, crown wheel, wheel well covers rust, headlamps foggy, hood hail chips scratches, left bumper dented, rear pad loose, both right fenders scratches, front chrome peeling, fenders rusty scratches dents, doors chips rust scratches, roof hail and rust spots, tailgate rust scratches dents bent, left front mirror housing cracked, left front seat worn,, padding visible, no first aid kit, no fire extinguisher, windshield chips minor exterior damage.>, As is, Where is	259,176 km	\$3,331	1GCHC29K08E209411

Item #	Description	Kms	Min Price	Serial Number
No Bid * 5-005	Truck 2002 CHEVROLET Silverado 3500 RWD, Crew Cab, 9' x 7' Dump Body 8.1L V8 gas auto A/C, tilt, cruise, AM/FM, power locks, keyless entry-1 fob 1 key Grille inserts, hitch, trailer wiring, electric trailer brake dump body condition good, 7731 hours on box meter, front wheel covers loose in cab, has a back seat, dual rear wheels, yellow, TOW ONLY, FAILED SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. **Please note: the SGI Inspection currently provided is only valid for 30 days after the date of the inspection.**, 278,416 km, Recent Repairs: new battery July 19/23 PROBLEMS: Left front lower ball joint loose, unable to test drive, transmission kicks out of gear, left rear tire inner bald, right front tire leaking, oil cooler line leak, grille chrome peeling/missing logo, hood chips/dents/scratches, front bumper bent, front left fender clear coat peeling, left rocker panel paint worn, left side doors clear coat peeling/road rash, front right door dent, right cab corner road rash, dash peeling, seats soiled/sagging, left right seat hole, head liner loose, no first aid kit/fire extinguisher, right mirror missing trim, right washer does not spray top of windshield, right front driving light bulb burnt out, minor exterior damage.>, As is, Where is	278,416 km	\$6,921	1GBJC33GX2F212057
3,111.00 7-030	Truck 2014 DODGE Ram 2500 4WD, 6'5" box, Crew Cab 5.7 V8 gas auto A/C, tilt, cruise, AM/FM, power mirrors/locks/windows, keyless entry, 1 key fob, 1 key Grille inserts, front tow hooks, hitch, trailer wiring, OEM trailer brakes, headache rack with beacon, has a backseat, white, TOW ONLY, FAILED SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. **Please note: the SGI Inspection currently provided is only valid for 30 days after the date of the inspection.**, 256,350 km, PROBLEMS: Check engine light, P0300 random misfire, P0441, EVAP purge performance, runs rough, no power, left headlight assembly moisture, both front wheel bearings lose, motor noise, hood chips rust spot, front and rear bumpers rusted, rear bumper pushed in, both fenders badly rusted right fender dented, rocker panel road rash, chips, both front doors glass scratched, tailgate missing trim dented, scratched, spare tire loose in box may not be compatible, jack missing, no first aid kit, no fire extinguisher, windshield large stone crack, left mirror housing cracked, left front seat worn, padding sagging, windshield chips, poor battery, minor exterior damage.>, As is, Where is	256,350 km	\$2,463	3C6TR5CT9EG193037

Item #	Description	Kms	Min Price	Serial Number
No Bid 7-037	Truck 2015 DODGE Ram 2500 4WD, 54" Box, Crew Cab 5.7L V8 gas auto A/C, tilt, cruise, after market CD player/radio, power heated mirrors/locks/windows, 1 key fob Tow hooks, grille inserts, hitch, trailer wiring, OEM trailer brakes, has back seat, white, TOW ONLY, FAILED SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. **Please note: the SGI Inspection currently provided is only valid for 30 days after the date of the inspection.**, 154,234 km, PROBLEMS: Check engine light, noise's (diagnosed as internal engine failure), misfiring, both front wheel bearings have play, both ball joints have play upper and lower, missing jump seat, B pillar inside molding holes cut, A pillar inside molding loose, Right A pillar trim loose, right side step loose, holes drilled in front hump, hole on head liner, holes in dash and trim, mud flap loose, hood chips, front bumper rust spots, rear bumper dents/rust spots, left front fender rusted, left rear fender dents, rocker panels road rash, left rear door missing trim/holes drilled, roof multiple dents, hole in roof 2 sealed, tailgate dented/rust/missing molding, rear left signal light out, wheel wrench/jack loose in back seat, no first aid kit /fire extinguisher, windshield chips, poor battery, minor exterior damage.>, As is, Where is	154,234 km	\$7,703	3C6TR5CT1FG544766
5,519.00 7-031	Truck 2015 DODGE Ram 2500 4WD, 6'4" box, Crew Cab 5.7L V8 gas auto A/C, tilt, cruise, AM/FM, power mirrors/locks/windows, keyless entry, 1 key Grille inserts, front tow hooks, hitch, trailer wiring, OEM trailer brake, side steps, mudflaps, grey, TOW ONLY, FAILED SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. **Please note: the SGI Inspection currently provided is only valid for 30 days after the date of the inspection.**, 156,731 km, PROBLEMS: Right cylinder head cracked, key stuck in ignition, differential poor, possible transmission issues, motor poor, check engine light on, all 4 ball joints, battery is dead, no brake lights, back up lights, left or right rear signals, headlights have moisture, rear seatbelts, front centre console missing, right rear window switch, right rear inside door handle, will not open from the inside, dirty oil, missing jump seat, holes drilled in rear hump, hole in headliner, moldings on A pillars modified, missing lower front valance, no horn, wheel wrench is loose under, right rear seat, grille scratched, hood chips and dents, both bumpers dented, left front door dents, roof small rust spots, 12 holes in roof sealed, tailgate molding broke scratches, windshield cracked, poor battery, minor exterior damage.>, As is, Where is	156,731 km	\$5,203	3C6TR5CT3FG569426

Item #	Description	Kms	Min Price	Serial Number
9,145.45 * 6-018	Truck 2015 DODGE Ram 2500 4WD, Crew Cab, 6'4" Box 5.7L V8 gas auto A/C, tilt, cruise, AM/FM, power windows/locks/mirrors, keyless entry-3 key fobs Grille inserts, front tow hooks, side steps, mud flaps, hitch, trailer wiring, OEM trailer brakes, box liner, has back seat, brown, TOW ONLY, FAILED SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. **Please note: the SGI Inspection currently provided is only valid for 30 days after the date of the inspection.**, 252,486 km, PROBLEMS: Left upper ball joint, left back up light, electrical engine tick/hesitation, front bumper pitted/rust, rear bumper bent/dented, left front fender rust hole, left rear fender dents, right side fenders rusted/scratched/road rash, rocker panels road rash/rust, one hole in roof sealed, tailgate will not open/dents/scratches, right cab corner rust, rear of cab dented, holes drilled in both box rails, no first aid kit/fire extinguisher, windshield chips, poor battery, minor exterior damage.>, As is, Where is	252,486 km	\$5,711	3C6TR5CT6FG674848
2,999.99 7-024	Truck 2007 DODGE Ram 2500 4WD, 6'5" box, Quad Cab 5.7L V8 gas auto A/C, tilt, cruise, AM/FM/CD player, 5 keys total Side steps, mud flaps, hitch, trailer wiring, electric trailer brake, has a back seat, plate for gooseneck attachments in box, white, TOW ONLY, FAILED SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. **Please note: the SGI Inspection currently provided is only valid for 30 days after the date of the inspection.**, 250,136 km, PROBLEMS: Rear rotors, rear shocks, front struts, park brake doesn't hold, floor rusted through where parking brake cable goes through, both cab corners, inside of box in all corners rusted, front of box dented, rear bumper dents, left rear fender dents, both fenders rust, right front rust, right rear scratches, both rocker panels rusted, left front door rust, dents, rear rust, both right doors rusted inside bottom, roof rust spots, small dents, antenna hole sealed, tailgate dented, bent, rust and scratches, left front vinyl cracked, tools for jack under left rear seat, wheel wrench missing, windshield chips, poor battery, minor exterior damage.>, As is, Where is	250,136 km	\$2,000	3D7KS28D17G817897

Item #	Description	Kms	Min Price	Serial Number
4,201.99 7-021	Truck 2012 DODGE Ram 2500 4WD, 70"w x 82"d, Crew Cab 5.7L V8 gas auto A/C, tilt, cruise, AM/FM/CD player, power mirrors/locks/windows, 1 key Grille inserts, front tow hooks, mud flaps, hitch, trailer wiring, has a back seat, white, TOW ONLY, FAILED SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. **Please note: the SGI Inspection currently provided is only valid for 30 days after the date of the inspection.**, 220,201 km, PROBLEMS: Engine tick, steering box worn, (sector shaft bushing worn, moves side to side), speedometer out approx. 5%, battery is dead, needs to be replaced - not secure, will not start, front tires worn, rear tires cupped, holes drilled in roof and door frame above front doors, dent below back window of cab, front mud flap lose due to fender rusting, fender wells need to be attached, driver's seat torn, frame visible, missing jump seat, center console missing, front bumper chips, scratches, rear bumper dents, rust, left front fender creased, left rear fender road rash, roof scratched, rust, 3 holes sealed, tailgate chips, dents, no first aid kit/ fire extinguisher all side glass scratched, windshield chips, poor battery, minor exterior damage.>, As is, Where is	220,201 km	\$3,519	3C6TD5CT4CG189313
No Bid 7-029	Truck 2009 DODGE Ram 5500 RWD, 7'6" x 10' box, Quad Cab 6.7L Inline 6 diesel Auto A/C, tilt, cruise, AM/FM/CD player, power mirrors/trailer tow, 1 key fob, dual rear wheels Grille inserts, front tow hooks, side steps, mud flaps, hitch, trailer wiring, electric trailer brake, Aero board with beacon, unknown condition, controls in cab, has a back seat, white, TOW ONLY, FAILED SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. **Please note: the SGI Inspection currently provided is only valid for 30 days after the date of the inspection.**, 291,439 km, PROBLEMS: Engine light is on, will not stay running, small leak rear pinion, right front rotor below spec, park brake does not hold, cables falling off from rust, left front seat bottom cushion hole exposing metal, plate bulb, middle rear marker bulbs, right rear lower marker light, cab corners road rash, hood chips clear coat peeling and dents, front bumper rust and dented, left front fender rust spot, dented and out of alignment, right front fender chip, left front door chip rust, roof antenna, spare tire loose in box, no first aid kit, no fire extinguisher, windshield chipped, poor battery, minor exterior damage.>, As is, Where is	291,439 km	\$18,060	3D6WC78L79G554342

Item #	Description	Kms	Min Price	Serial Number
No Bid 7-008	Truck 2009 DODGE Ram 5500 RWD, Quad Cab, 10'3"w x 7'4"d dump body 6.7L Inline 6 diesel auto A/C, tilt, cruise, AM/FM/CD player, power heated trailer mirrors/windows/locks, keyless entry-2 key fobs, 1 other key Dump body stainless steel, fold down sides, integrated headache rack with beacon condition unknown, power lift gate badly rust mechanically condition unknown, side steps, front tow hooks, hitch, trailer wiring, electric trailer brakes, has a back seat, white, TOW ONLY, FAILED SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. **Please note: the SGI Inspection currently provided is only valid for 30 days after the date of the inspection.**, 298,206 km, PROBLEMS: Small oil leak in rear, park brake not holding, power steering cap missing, engine oil over full, hood shocks not holding, 2 rear markers bulbs are missing lenses, large object in right rear outer tread, right front mud flap gone, both head lights partially fogged, hood chips/dent/scratches, front bumper rust/bent, left front fender chips/rusted, left front door dents, roof small rust spots, hole in roof 1 sealed/rusted around antenna, no spare tire/wheel wrench/jack/first aid kit/fire extinguisher, windshield chips, right front seat wore to frame, left front seat hole/worn to frame, interior soiled, poor battery, minor exterior damage.>, As is, Where is	298,206 km	\$19,987	3D6WC78L19G554126
No Bid 7-028	Truck 2014 DODGE Ram 5500 ST RWD, 7'7" X 10' Dump Body, Crew Cab 6.7L Inline 6 diesel auto A/C, tilt, cruise, AM/FM power trailer tow mirrors/windows/locks, key less entry, 2 key fobs, Grille inserts, front tow hooks, side steps, hitch, trailer wiring, OEM trailer brakes, mud flaps and computer stand, has a back seat, stainless steel dump body, sides bent, unknown if operational, right rear corner badly bent, WALTCO liftgate model DT16 liftgate right rear bent, seriously deteriorated, WANCO control board with controls, unknown if operational, slip tank straps, no slip tank, beacons, condition unknown, 3 new fuel filters in back seat, unknown if compatible with unit, white, TOW ONLY, FAILED SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. **Please note: the SGI Inspection currently provided is only valid for 30 days after the date of the inspection.**, 347,976 km, PROBLEMS: No power steering, poor brakes hard to stop, oil leaks, power steering pressure hose leaking, power steering line leaking at reservoir, power steering non operational, 2 marker lamps out, headlamps have water intrusion, hydroboost non operational, rear shocks leaking, service engine light on, A/C non operational, spare tire lose in box, hood chips, front bumper chips and rust spots, left front fender chips, rocker panel road rash, liftgate rusted, left front seat worn frame visible, rear seat small hole, right front seat worn/ripped no jump seat hour meter 4176 hours, no first aid kit, no fire extinguisher, windshield cracked, poor battery, minor exterior damage.>, As is, Where is	347,976 km	\$21,250	3C7WRMEL0EG225941

Item #	Description	Kms	Min Price	Serial Number
5,999.99 7-006	Truck 2013 FORD F150, RWD, Super Cab, 8' box 5.0L V8 gas auto A/C, tilt, cruise, Bluetooth, AM/FM/CD player, power windows/mirrors/locks, keyless entry-2 key fobs Wig-wags on grille, side steps, mudflaps, box liner, headache rack with beacon, hitch, trailer wiring, has a back seat, white, TOW ONLY, FAILED SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. **Please note: the SGI Inspection currently provided is only valid for 30 days after the date of the inspection.**, 217,389 km, PROBLEMS: Right front outer tie rod, rear brake pads and rotors, front tires scalloped, tire need rotation, oil change due, hood slight hail, rear bumper minor rust, left rear door rust inside bottom, hole in roof 1 antenna, tailgate dent/bent/scratches, no first aid kit/fire extinguisher, windshield chips, left front mirror housing cracked missing reflector, left front seat hole/worn sagged to frame, missing OEM jump seat, holes in front hump, poor battery, minor exterior damage.>. As is, Where is	217,389 km	\$4,980	1FTVX1CF7DKE84587
No Bid 7-002	Truck 2016 FORD F350 Super Duty, 4WD, 8' box, Crew Cab 6.7L Turbo diesel auto A/C, tilt, cruise, AM/FM, power heated trailer tow mirrors, power windows/locks, keyless entry-2 key fobs Hitch, trailer wiring, OEM Trailer brakes, grille insert, tow hooks, has a back seat, white, TOW ONLY, FAILED SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. **Please note: the SGI Inspection currently provided is only valid for 30 days after the date of the inspection.**, 322,603 km, PROBLEMS: Engine light on, TPMS light on, left front lower ball joint, park brake not working, all tires are miss match, both side mirror marker bulbs, both light side marker bulbs, no rear tail lights, signal lights, brake lights and reverse lights, grille broke, hood dents/right washer nozzle not working, left front fender road rash, left rear fender cracked/road rash/dents, front right fender road rash, right rear fender road rash/rust, holes in front hump, roof scratches, hole in roof 1 sealed, headache rack bent, missing right side wheel covers, missing mudflaps, side steps bent, tailgate badly damaged/missing parts/may not open, spare tire loose in box (may not be compatible with vehicle), no first aid kit/fire extinguisher, windshield cracked, left and right mirror housing broke, poor battery, minor exterior damage.>. As is, Where is	322,603 km	\$20,384	1FT8W3BT5GEB81085

Item #	Description	Kms	Min Price	Serial Number
No Bid 7-001	Truck 2016 FORD F350 Super Duty, 4WD, Crew Cab, 8' box 6.7 V8 diesel auto A/C, tilt, cruise, AM/FM, power heated trailer tow mirrors, power windows/locks, keyless entry-1 key fob Grille inserts front wigwags and beacon condition unknown, front tow hooks, side steps, box liner, headache rack, hitch, trailer wiring, OEM trailer brake, has a back seat, deep pan attached inside box 49" x 30" x 1 3/4", white, TOW ONLY, FAILED SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. **Please note: the SGI Inspection currently provided is only valid for 30 days after the date of the inspection.**, 306,482 km, PROBLEMS: Engine/ABS/Trac light on, oil change required, T-case/front Differential dirty, rear brakes at 1mm/rear pads/rotors failed, park brake not holding, front tires miss matched, side mirror mark bulbs, head light side marker bulbs, no plate bulb, spare missing, spare hoist seized, front bumper scratched/pitted, rear bumper dented/bent/pad loose, left rear fender dented, right rear door missing weather strip, roof small rust spots, tailgate badly damaged missing parts/may not open, wheel wrench/jack loose in back seat, no first aid kit/fire extinguisher, windshield cracked, left front mirror housing broke, left front seat ripped/worn/sagging, mudflaps loose, holes in front hump, hole in floor behind left rear seat, poor battery, minor exterior damage.>, As is, Where is	306,482 km	\$21,384	1FT8W3BT5GEB65372
No Bid 7-007	Truck 2008 GMC Sierra 2500 HD, 4WD, Extended Cab, 8' box 6.0L V8 gas auto A/C, tilt, cruise, AM/FM, 2 keys Mudflaps, front tow hooks, wheel flares, side steps, hitch, trailer wiring, electric trailer brakes, has a back seat, white, TOW ONLY, FAILED SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. **Please note: the SGI Inspection currently provided is only valid for 30 days after the date of the inspection.**, 330,392 km, PROBLEMS: Left front axle, TPMS light is on, oil change due, front lower valance loose, both rails paint worn/dented, box floor has holes drilled/rusted, antenna mast missing-replaced with wire, left head light fogged, hood chips/missing air deflector, both bumpers dent/bent, left rear fenders dents/rust, right rear fenders road rash, left side doors dent/road rash/rust, right side doors road rash/dents, hole in roof 3 sealed, tailgate dented/right lower corner bent, spare tire missing, no first aid kit/fire extinguisher, windshield chips, left front seat worn/foam visible, holes drilled in front hump, rear seat stained/ripped, poor battery, minor exterior damage.>, As is, Where is	330,392 km	\$4,165	1GTHK29K58E210766

Item #	Description	Kms	Min Price	Serial Number
6,145.45 7-010	Van 2009 DODGE Grand Caravan Cargo FWD 3.3L V6 gas auto A/C, tilt, cruise, AM/FM/CD player, power mirrors/locks/front windows, keyless entry-2 key fobs-3 other keys Stainless steel floor loose in back, white, TOW ONLY, FAILED SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. **Please note: the SGI Inspection currently provided is only valid for 30 days after the date of the inspection.**, 97,738 km, PROBLEMS: Front brakes and rotors, rear tires are close to worn, front tire worn out, tire light on, right rear quarter panel has rust hole, hood hail, front bumper scratches/dents, left front fender rust/missing molding, right side fenders rusted/dents, right rear door paint cracked/rust, roof hail/small rust spots, hole in roof 2 sealed, tailgate dent, no first aid kit/fire extinguisher, windshield chips, left front seat worn/ripped, poor battery, minor exterior damage.>, As is, Where is	97,738 km	\$1,213	2D4HN11E29R617636
715.99 7-013	Van 2009 DODGE Grand Caravan SE FWD 3.3L V6 gas auto A/C, tilt, cruise, rear HVAC, AM/FM, power front windows/mirrors/locks, remote start-functions 1 fob, keyless entry 2 key fobs Stow-N-Go, missing 2nd row and 3rd row seats, brown, FOR PARTS ONLY, NO SGI INSPECTION.**THIS VEHICLE IS FOR RECYCLING PURPOSES ONLY AND NOT FOR RESALE. THIS VEHICLE CANNOT BE REGISTERED WITHIN ANY JURISDICTION. **, 227,009 km, PROBLEMS: Front struts/links, cross over pipe, alignment, oil dip stick, hood paint bubbling/dents, both bumpers broken/chips/scratches, left front fender rusted missing molding, left rear fender rusted, right side fenders rusted/missing molding, rocker panels rusted, right side doors holes drilled interior trim/rear right door dent, roof small rust spot, no first aid kit/fire extinguisher, left front cushion ripped/worn, hole in left front carpet, missing 2nd row and third row seating, poor battery, minor exterior damage.>, As is, Where is	227,009 km	\$253	2D8HN44E59R683433
5,556.78 7-022	Van 2013 DODGE Grand Caravan SE FWD 3.6L V6 gas auto A/C, tilt, cruise, AM/FM/CD player, power mirrors/locks/windows, rear HVAC, keyless entry 2 key fobs Stow N' Go third row seat only, red, TOW ONLY, FAILED SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. **Please note: the SGI Inspection currently provided is only valid for 30 days after the date of the inspection.**, 263,541 km, PROBLEMS: Tire pressure monitoring system(TPMS) light on, rear rotors, right front side marker, hood paint bubbling, hail dents, chips and scratches, front bumper chips, rear bumper cracked dents, both rear fenders rust and scratches, left rear door paint poor, roof, hail dents, small rust spots, tailgate glass scratched, no first aid kit/fire extinguisher, windshield cracked, poor battery, minor exterior damage.>, As is, Where is	263,541 km	\$2,881	2C4RDGBG8DR634151

Item #	Description	Kms	Min Price	Serial Number
5,325.01 7-005	Van 2009 DODGE/RAM Grand Caravan Cargo FWD 3.3L V6 gas auto A/C, tilt, cruise, AM/FM/CD player, power front windows/locks/mirrors, keyless entry-2 key fobs Roof rack brackets-no cross members, handle on tailgate, hitch, stainless steel floor-not attached, white, TOW ONLY, FAILED SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. **Please note: the SGI Inspection currently provided is only valid for 30 days after the date of the inspection.** , 112,222 km, PROBLEMS: Steering rack leaking, front and rear motor mounts, TPMS light on, rear right tire needs sensor, head lights foggy, gas cap will not close, hood paint bubbling, front bumper cracked, left side fenders rusted, right front door rusted, right rear door trim cracked, left and right front doors rust inside bottom, roof rust spots, hole in roof 2 sealed, no first aid kit/fire extinguisher, windshield chips and cracked passengers corner, holes in head liner, inside trim on both B-pillars damaged, left mirror housing cracked, left front seat worn/ripped, poor battery, minor exterior damage.>, As is, Where is	112,222 km	\$972	2D4HN11E99R617634
8,145.45 7-009	Van 2008 GMC Savana 3500 RWD 6.0L V8 gas auto A/C, tilt, cruise, AM/FM/CD player, rear HVAC, power mirrors/locks/front windows, 2 keys Gurni anchors in rear, 5 passenger, green, TOW ONLY, FAILED SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. **Please note: the SGI Inspection currently provided is only valid for 30 days after the date of the inspection.** , 242,676 km, Recent Repairs: Right rear tire repaired PROBLEMS: Right lower ball joint, driver side door pins worn, hood chips/small dents, front bumper pitted, rear bumper scuffed/rust spots, left rear fender scratches/scrapes/dents, right rear fender large dents/scrapes, rocker panels rust/road rash/scrape, right rear door dents/scrape, tailgate dent/scratches, no first aid kit/fire extinguisher, windshield chips, poor battery, minor exterior.>, As is, Where is	242,676 km	\$5,263	1GJHG39K581218986

Item #	Description	Kms	Min Price	Serial Number
REGINA, SaskBuilds and Procurement, SaskSurplus Sales Lot, 500 McLeod Street - Miscellaneous Items and Equipment.				
Contact SaskSurplus 306-787-2062 or 306-798-3306.				
No Bid * 4-101	Box, metal 20"w x 8"d x 16"h, grey, bolted to a removable metal base, hinged lid with a lock but no key. Fair		\$15	171,975
No Bid * 5-102	Box, Metal 20"w x 8"d x 16"h, grey, hinged lid, hole in lid, no lock. Fair		\$15	
No Bid 7-101	Box, Metal Grey, hinged lid with a hole, lock, no key, 20"w x 8"d x 16"h. Fair		\$15	
No Bid 7-102	Box, Metal Grey, hinged lid, no lock, 20"w x 8"d x 16"h. Fair		\$15	
No Bid 7-103	Seat Covers, Fia TR40 Series Wrangler, fabric Grey/Black, complete set for front 40/20/40 seat, removed from a 2007 Ram Quad Cab 430204, Includes head rest covers. Good		\$40	
No Bid 7-104	Shelf, Stainless steel 2 shelves with particle board backing, 48 inches long, 48"w x 18"d x 36.5"h, 12 hooks attached to back. Good		\$25	
1.06 * 12-121	Tire , 225/65R/17, Sumitomo HTR Enhance C/X. M+S. Manufacture date, week 13, year 2018. Good		\$1	
152.10 * 4-104	Tires, Set of 4 Sumitomo Ice Edge. Snow Flake, M+S. 215/60R/16 Manufacture date. Week 17, year 2019. Fair		\$120	
44.44 * 4-108	Tires, Set of 4 225/60R/17 Sumitomo HTR Enhance L/X. M+S. Manufacture date. Week 50, year 2016. Poor		\$40	
176.00 * 4-112	Tires, Set of 4 225/55R/17 Goodyear Assurance Max Life. M+S. Manufacture date. Week 07, year 2018. Good		\$160	
176.00 * 4-114	Tires, Set of 4 225/60R/16 Sumitomo HTR Enhance LX2. M+S. Manufacture date. Week 33, year 2019. Good		\$160	
126.00 * 5-103	Tires, Set of 4 215/60R/16, Sumitomo HTR Enhance L/X. M+S. Manufacture date. Week 12, year 2019. Fair		\$120	
151.00 * 5-105	Tires, Set of 4 225/60R/16, Sumitomo HTR Enhance L/X. M+S. Manufacture date. Week 44, year 2016. Fair		\$120	
171.00 * 5-124	Tires, Set of 4 225/60R/16, Sumitomo HTR Enhance LX. M+S. Manufacture date. Week 07, year 2019. Good		\$160	
176.00 * 6-105	Tires, Set of 4 225/60R/16, Firestone All Season, M+S Manufacture date. Week 43, year 2021. Good		\$160	
*WD * 6-106	Tires, Set of 3 225/65R/16, Sumitomo Ice Edge. Snow Flake, M+S Manufacture date. Week 17, year 2017 Good		\$120	
186.00 * 6-109	Tires, Set of 4 225/55R/17, Firestone All Season, M+S Manufacture date. Week 38, year 2020. Good		\$160	

Item #	Description	Kms	Min Price	Serial Number
165.00 * 6-110	Tires, Set of 4 225/60R/16, Firestone All Season, M+S Manufacture date. Week 37, year 2021. Good		\$160	
186.00 * 6-112	Tires, Set of 4 225/65R/17, Michelin Latitude Tour, M+S Manufacture date. Week 51, year 2013. Fair		\$100	
186.00 * 6-115	Tires, Set of 4 215/60R/16, Firestone All season, M+S Manufacture date. Week 26, year 2021. Good		\$160	
No Bid * 6-116	Tires, Set of 4 225/60R/16, Sumitomo Ice Edge, Snow Flake, M+S Manufacture date. Week 19, Year 2018. Good		\$160	
155.01 * 6-117	Tires, Set of 4 225/65R/17, Sumitomo HTR Enhance, M+S Manufacture date. Week 48, year 2017. Fair		\$120	
176.00 * 6-177	Tires, 225/65R/17, Bridgestone Alenza AS/02. M+S Manufacture date. Week 16, Year 2021. Good		\$30	
No Bid * 6-178	Tires, Set of 4 225/65R/17, Goodyear Assurance Fuel Max. M+S Manufacture date. Week 22, Year 2018. Poor		\$40	
181.00 7-106	Tires, Set of 4 225/60R/16, Sumitomo HTR Enhance, M+S Manufacture date. Week 30, year 2017. Good		\$160	
220.00 7-107	Tires, Set of 4 225/65R/16, Firestone Winterforce 2. Snow flake, M+S Manufacture date. Week 03, year 2020. Good		\$160	
No Bid 7-108	Tires, Set of 4 225/65R/16, Sumitomo Ice Edge, Snow flake, M+S Manufacture date. Week 18, year 2017. Fair		\$120	
190.00 7-109	Tires, Set of 2 LT245/70R/17, BF Goodrich All-Terrain T/A KO2. Snow flake, M+S, Load range E Manufacture date. Week 33, year 2020. Excellent		\$150	
No Bid 7-111	Tire, 225/60R/16, Matrix Tour Multi Mile, M+S Manufacture date. Week 50, year 2013. Good		\$10	
No Bid 7-112	Tires, Set of 4 225/60R/16, Sailum Inspire. M+S Manufacture date. Week 39, year 2019. Fair		\$90	
186.00 7-113	Tires, Set of 4 225/60R/16, Sumitomo HTR Enhance. M+S Manufacture date. Week 33, year 2018. Good		\$160	
145.01 7-114	Tires, Set of 4 225/65R/17, Yokohama Avid 833, M+S Manufacture date. Week 33, year 2016. Fair		\$120	
No Bid * 5-106	Topper, ARE, Fiberglass 68.5"w x 83.5"d x 20.5"h, color is Ford Stone Grey with slider side windows, removed from a 2019 Ford F150 XLT Crew Cab, has key unknown if lock works, has 4 hold down clamps. Good		\$1,100	801,410

Item #	Description	Kms	Min Price	Serial Number
No Bid 7-115	Topper, Fiberglass, Range Rider White, side windows open in up direction, locks and 1 key, 61"w x 64"d, beacon on top, mounting bolts included, removed from a 2012 Chev Colorado #437001. Good		\$250	
12.00 7-105	Utility Hooks, Metal Grey, holes for mounting, 2 units in the set. 12"w each. 4 hooks per unit- 8 hooks in total. Fair		\$2	
55.00 * 2-700	Water Cooler, Crystal Mountain, ALP A2WTW1 12"w x 12"d x 38"h, cold and room temperature, operational, white. Fair		\$45	1,101,067,020,458
3.50 * 6-119	Printer, Desktop, Hewlett-Packard LaserJet 4050N Operational (powers on, no noises, no further testing), some scratches, wiped/reset, power cord. Fair		\$1	USBD024545
11.00 * 5-180	Printer, Desktop, Hewlett-Packard LaserJet 4350DTN Operational (powers on, no noises, no further testing), some scratches, wiped/reset, power cord included. Fair		\$1	CNRXB98130
5.75 * 5-181	Printer, Desktop, Hewlett-Packard LaserJet P1505 Operational (powers on, no noises, no further testing), some scratches, wiped/reset, power cord included. Fair		\$1	VND3B34283
11.00 * 5-193	Printer, Floor-model, Hewlett-Packard LaserJet 5500DTN With wheels, operational (powers on, no noises, no further testing), some scratches, wiped/reset, power cord included. Fair		\$1	JPJR006455
11.00 * 5-132	Printer, Desktop, Hewlett-Packard LaserJet 1020 Operational (powers on, no noises, no further testing), some scratches, wiped/reset, no power cord included. Fair		\$1	CNBK786720
2.57 * 5-134	Printer, Desktop, Hewlett-Packard LaserJet 2300 Operational (powers on, no noises, no further testing), some scratches, wiped/reset, no power cord included. Fair		\$1	CNBGG78723
25.00 * 6-130	Printer, Desktop, Hewlett-Packard LaserJet M1319F MFP Operational (powers on, no noises, no further testing), some scratches, wiped/reset, power cord. Fair		\$1	CNFZ87S1BD
2.24 * 6-131	Printer, Desktop, Hewlett-Packard LaserJet P1505 Operational (powers on, no noises, no further testing), some scratches, wiped/reset, power cord. Fair		\$1	VND3C20037
16.25 * 6-139	Printer, Desktop, Hewlett-Packard LaserJet P2055X Operational (powers on, no noises, no further testing), some scratches, wiped/reset, power cord. Fair		\$1	CNB9M25506
36.50 * 5-158	Printer, Desktop, Hewlett-Packard OfficeJet Pro 8210 Colour Operational (powers on, no noises, no further testing), some scratches, wiped/reset, no power cord included. Fair		\$1	CN14FJT07S
3.30 * 6-155	Printer, Desktop, HP LaserJet 4250DTN Operational (powers on, no noises, no further testing), some scratches, wiped/reset, power cord. Fair		\$1	CNBXC38773
3.35 * 6-156	Printer, Desktop, HP LaserJet 4250DTN Operational (powers on, no noises, no further testing), some scratches, wiped/reset, power cord. Fair		\$1	CNGXC26756
3.40 * 6-157	Printer, Desktop, HP LaserJet 4250DTN Operational (powers on, no noises, no further testing), some scratches, wiped/reset, power cord. Fair		\$1	CNGXF40805

Item #	Description	Kms	Min Price	Serial Number
10.05 * 6-166	Printer , Floor-model, Hewlett-Packard LaserJet 9050N With wheels, operational (powers on, no noises, no further testing), some scratches, wiped/reset, power cord included. Fair		\$1	JPRL86K006
26.00 * 6-167	Printer , Floor-model, HP Color LaserJet 5550DTN With wheels, operational (powers on, no noises, no further testing), some scratches, wiped/reset, power cord included. Fair		\$1	SJPEC54L002
2.24 * 6-170	Printer , Hewlett-Packard LaserJet 4250DTN With wheels, operational (powers on, no noises, no further testing), some scratches, wiped/reset, power cord included. Fair		\$1	CNRXR08403
2.86 * 5-163	Printer , Large Desktop, Hewlett-Packard LaserJet 8150DN Operational (powers on, no noises, no further testing), some scratches, wiped/reset, no power cord included. Fair		\$1	JPBLM61045
11.50 * 5-164	Printer , Large Desktop, Hewlett-Packard LaserJet 8150N Operational (powers on, no noises, no further testing), some scratches, wiped/reset, no power cord included. Fair		\$1	JPBLL38398
11.50 * 6-174	Printer , Large Desktop, HP Color LaserJet CP4025DN With wheels, operational (powers on, no noises, no further testing), some scratches, wiped/reset, power cord included. Fair		\$1	JPBCD2Q0TT
7.01 * 6-175	Printer , Large Desktop. Hewlett-Packard LaserJet 9050DN With wheels, operational (powers on, no noises, no further testing), some scratches, wiped/reset, power cord included. Fair		\$1	JPRL7D900Z

Item #	Description	Kms	Min Price	Serial Number
CANDLE LAKE PROVINCIAL PARK, Parks Culture and Sport, Call for Directions				
Contact Janelle Franc 306-929-8401, janelle.franc@gov.sk.ca				
No Bid 7-548	Car, 2008CHEVEROLET Impala LS2WD3.5L, V6 gas autoAC, cruise, AM/FM3 speed, GVW 2057kg, single tire, tire size, 225 60/R15 4 plywhiteTOW ONLY, NO SGI Inspection. It is unknown if any repairs or safety concerns exist (if any). Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs if required. 232,161 kmRecent Repairs:PROBLEMS: Motor, brakes, battery, body, frame, paint, windshield, windshield wipers and horn are all in poor condition, may need batteries to start, minor exterior damage.> As is, Where is	232,161 km	\$500	2G1WB58K481352045
No Bid 7-540	Car, 2002CHEVEROLET Malibu2WD3.1L, V6 gas autoA/C, AM/FM, heated mirrors, power locks3 speed, GVW 1385 kg, tire size 215/60R15greenTOW ONLY, NO SGI Inspection. It is unknown if any repairs or safety concerns exist (if any). Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs if required. 203,535 kmRecent Repairs:PROBLEMS: Motor, brakes, battery, body, frame, paint, windshield, windshield wipers and horn are all in poor condition, may need batteries to start, minor exterior damage.> As is, Where is	203,535 km	\$500	1G1ND52J32M632377
No Bid 7-566	Car, 2006CHRYSLER Sebring, Touring2WD, 4 door2.7L, V6, gas manualAC, AM/FM, CD player3 speed, GVW 1917 kg, single tire, tire size, 205 60/R16, 4 plywhiteTOW ONLY, NO SGI Inspection. It is unknown if any repairs or safety concerns exist (if any). Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs if required. 179,098 kmPROBLEMS: Motor, brakes, battery, body, frame, paint, windshield, windshield wipers and horn are all in poor condition, may need batteries to start, minor exterior damage.> As is, Where is	179,098 km	\$500	1C3EL56R06N261127
3,434.34 7-549	Truck, 2009CHEVEROLET Colorado, LT Extended Cab2WD, 6' box3.7L, V6 gas autoA/C, tilt, cruise, power locks3 speed GVW 2268 kg, single axlewhiteTOW ONLY, NO SGI Inspection. It is unknown if any repairs or safety concerns exist (if any). Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs if required. 120,826 kmRecent Repairs:PROBLEMS: Motor, brakes, battery, body, frame, paint, windshield, windshield wipers and horn are all in poor condition, may need batteries to start, minor exterior damage.> As is, Where is	120,826 km	\$500	1GCCS13E798155986

Item #	Description	Kms	Min Price	Serial Number
1,678.90 7-541	Truck, 2003CHEVEROLET S102WD4.3L, V6 gas autoA/C, tilt, cruise, AM/FM, power locks, mirrors, heated mirrors,3 speed, GVW 2087 kg, tire size 215/70R15, ply 5whiteTOW ONLY, NO SGI Inspection. It is unknown if any repairs or safety concerns exist (if any). Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs if required. 172,526 kmRecent Repairs:PROBLEMS: Motor, brakes, battery, body, frame, paint, windshield, windshield wipers and horn are all in poor condition, may need batteries to start, minor exterior damage.> As is, Where is	172,526 km	\$500	1GCCS19X238246468
519.99 7-539	Truck, 2001DODGE Ram 25004WD, no box 5.2L V8 gas auto* FOR PARTS ONLY*GVW 3992 kg, single tire, tire size 245/75R/16whiteTOW ONLY, NO SGI Inspection. It is unknown if any repairs or safety concerns exist (if any). Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs if required. 226,299 kmRecent Repairs:PROBLEMS: Motor, brakes, battery, body, frame, paint, windshield, windshield wipers and horn are all in poor condition, may need batteries to start, minor exterior damage, needs front tires.> As is, Where is	226,299 km	\$500	1B7KF23Z61J594246
No Bid 7-567	Van, 1994PLYMOUTH Voyager2WD2.5L, inline 4, gas auto3 speed, single tire, tire size, 195 75/R14, 3 plywhiteTOW ONLY, NO SGI Inspection. It is unknown if any repairs or safety concerns exist (if any). Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs if required. 208,592 kmPROBLEMS: Motor, brakes, battery, body, frame, paint, windshield, windshield wipers and horn are all in poor condition, may need batteries to start, minor exterior damage.> As is, Where is	208,592 km	\$100	2P4GH25K2RR666028
DUCK MOUNTAIN PROVINCIAL PARK, Parks, Culture and Sport, Call for location				
Contact Ryan Bielecki 306-590-7792, ryan.bielecki@gov.sk.ca				
611.00 7-502	Truck, 2005FORD F150, 2WD, extended cab4.6L, V8, gas autoA/C, cruiseStandard differential, 4 speed, GVW 3039kg, single tire, tire size, P265/70/R17, 5 ply, 145m wheel basewhiteTOW ONLY, NO SGI Inspection. It is unknown if any repairs or safety concerns exist (if any). Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs if required. 199, 937 kmPROBLEMS: Motor, transmission, tires, brakes, battery, windshield, wipers, interior and lights all in poor condition, drivers seat is torn, rims rusting, body rust As is, Where is	199, 937 km	\$400	1FTRX12W05NB26251
2,656.56 7-501	Truck, 2005FORD F150, 4x4, Supercrew4.6L, V8, gas autoA/C, tilt, cruise, AM/FM, CD player, power mirrors, windows, locks Posi-traction, 4 speed, GVW 3265 kg, single tire, tire size, LT 265170 R17 silverTOW ONLY, NO SGI Inspection. It is unknown if any repairs or safety concerns exist (if any). Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs if required. 114,542 kmPROBLEMS: transmission oil leak, battery is poor, windshield cracked, interior is poor, torn drivers seat As is, Where is	114,542 km	\$400	1FTPW14555KE64776

Item #	Description	Kms	Min Price	Serial Number
327.56 7-503	Van, 2006CHEVROLET UplanderFWD3.5L, V6, gas autoA/C, tilt, cruiseStandard differential, 4 speed, GVW 2550 lg, single tire, tire size 2251/60R17, 4 plyblueTOW ONLY, NO SGI Inspection. It is unknown if any repairs or safety concerns exist (if any). Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs if required. 149, 237 kmRecent Repairs: Replaced rear shocksPROBLEMS: Motor, tires and interior all in poor condition, front struts are bad, rear springs weak and suspension bad, brake pads are poor, windshield glass cracked, side door mouldings off, right rear reverse light out, radio stays on wont turn off unless it is turned off manually, horn does not work As is, Where is	149, 237 km	\$200	1GNDU23LX6D158541
GREENWATER LAKE Provincial Park, Parks Culture and Sport, Call for directions.				
Contact Jolene Mansuy 306-278-3520, jolene.mansuy@gov.sk.ca or Jeff Hingtgen 306-278-3519, jeff.hingtgen@gov.sk.ca				
3.16 7-507	Pumps and Motors, Lot of approx. 7 For water and sewer systems, non operational. Beyond Repair		\$1	
GREENWATER LAKE Provincial Park, Parks Culture and Sport. Maintenance Compound				
Contact Easton Kapeller 306-278-7073, easton.kapeller@gov.sk.ca or Jolene Mansuy 306-278-8248, jolene.mansuy@gov.sk.ca (Office 306-278-3515)				
1,680.00 7-532	Truck, 2003DODGE Dakota4WD extended cab4.7L, V8, gas autoA/C tilt, cruiseStandard differential, 4 speed, GVW 2726 kg, single tire, tire size LT245/75R16, ply 8whiteTOW ONLY, NO SGI Inspection. It is unknown if any repairs or safety concerns exist (if any). Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs if required. 246,253 kmRecent Repairs: Recent upper rad hose, all stabilizer bushingsPROBLEMS: Loud howling noise coming from front end, all ball joints poor, engine light on, blower fan not functioning, left front signal lens broken, right front signal burnt out, missing right wiper, right window crank fallen off, park brake light stays on, park brake handle broken, front sway bar worn, rear fender wells rusted through, battery is poor.> As is, Where is	246,253 km	\$500	1D7HG32N23S278955
1,629.00 7-533	Truck, 2008GMC Sierra 25004WD, extended cab6.0L, V8, gas AutoA/C tilt, cruise, power locksStandard differential, 6 speed, GVW 4173 kg, single tire, tire size LT265/75/R16, ply 10whiteTOW ONLY, NO SGI Inspection. It is unknown if any repairs or safety concerns exist (if any). Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs if required. 345,400 kmRecent Repairs: New Ign. Lock Cylinder, New Ign. SwitchPROBLEMS: #4 cylinder has poor compression, has parasitic drain in electrical system, rear RH quarter panel damaged from collision, no tailgate, no back seat.> As is, Where is	345,400 km	\$1,200	1GTHK29KX8E210360

Item #	Description	Kms	Min Price	Serial Number
529.00 7-531	Van, 2002FORD WindstarFWD3.8L, V6, gas autoA/C tilt, cruise, power windows/locks Standard differential, 4 speed, GVW 2521 kg, tire size 215 70R15, ply 4whiteTOW ONLY, NO SGI Inspection. It is unknown if any repairs or safety concerns exist (if any). Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs if required. 158,200 kmRecent Repairs:PROBLEMS: Transmission makes a clunk when shifting to forward or reverse, windshield has crack in driver's line of sight As is, Where is	158,200 km	\$500	2FMZA55402BB18253
KENOSEE LAKE, Parks Culture & Sport, Box 277 Kenosee Lake				
Contact Leigh Potter 306-577-7810, leigh.potter@gov.sk.ca				
3,799.00 7-569	Truck, 2001DODGE Dakota 4WD, Club Cab4.7L V8 gas autoA/C, tilt, cruise2 differentials, GVW 4700 lbs, tire size 225/65R16, ply 4whiteTOW ONLY, NO SGI Inspection. It is unknown if any repairs or safety concerns exist (if any). Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs if required. 233,279 km leaky power steering. Dead battery despite a new battery being installed in May.> As is, Where is	233,279 km	\$500	1B7GG22N71S260044
LA RONGE, Saskatchewan Public Safety Agency, Land Operations, 800 Poirier St				
Contact Amelick Halkett 306-425-6651, amelick.halkett@gov.sk.ca				
*WD 7-528	Truck, 1998DODGE Ram 1500, Crew Cab2WD, 8' Box5.2L, V8, gas autoA/C, tilt, cruise, manual windowsStandard differential, 6 speed, GVW 3334kg, single tire, tire size LT245/75R16blueTOW ONLY, NO SGI Inspection. It is unknown if any repairs or safety concerns exist (if any). Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs if required. 238,135 kmRecent Repairs: Replaced drivers side window 2018Needs battery, wiper blader need replacing, paint chipped and scratched, body exterior minor rust paint chips, minor exterior damage.>. As is, Where is	238,135 km	\$3,000	3B7HC12Y5WG189414
MELVILLE, Saskatchewan Crop Insurance Corporation (SCIC) 484 Prince William Dr				
Contact Lindsey D. Pringle 639-398-2289, lindsey.pringle@scic.ca				
No Bid 7-561	Fall Protection Lanyards, Lot of 3 Yellow. New- Unused		\$50	
No Bid 7-560	Fall Protection Harnesses, Lot of 6 3 XXL, 3 small. New- Unused		\$50	

Item #	Description	Kms	Min Price	Serial Number
MOOSE JAW, Highways & Infrastructure, Fleet Services, 1 km south of Moose Jaw on Highway #2.				
Contact Al Froehlich 306-694-3775, allan.froehlich@gov.sk.ca or Tara Watson 306-694-3773, tara.watson@gov.sk.ca				
867.00	7-542	Dump Truck, 1998FORD LT9513side dump box, 10 yard10.3L inline 6, diesel Eaton auto selectCat C-10-305PARTS ONLY 10 speed, standard differential, tire size front 425/65R22.5 rear 11R22.5yellowTOW ONLY, NO SGI Inspection. It is unknown if any repairs or safety concerns exist (if any). Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs if required. unknown kmRecent Repairs:PROBLEMS: unit was taken out of service in 2018 and parts have been removed over the years. Unit is not running and condition of any components unknown.> As is, Where is	unknown km	\$1 1FDZS96K3WVA14660
866.00	7-563	Dump Truck, 1998FORD LT9513side dump box, 10 yard10.3L inline 6, diesel Eaton Auto Select*FOR PARTS ONLY* 10 speed, standard differential, tandem axle, tire size front 425/65R22.5 rear 11R22.5yellowTOW ONLY, NO SGI Inspection. It is unknown if any repairs or safety concerns exist (if any). Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs if required. unknown kmPROBLEMS: Condition of motor and transmission unknown, tires, brakes, exhaust, windshield glass, washer, wipers, paint, exterior, interior, mirrors and horn all in poor condition, lights do not work, does not have a battery, parts have been removed over the years. Unit is not running and condition of any components unknown. As is, Where is	unknown km	\$1 1FDZS96K3WVA09135
561.13	7-562	Dump Truck, 1996VOLVO WG64D12-310, inline 6, diesel Super 10"FOR PARTS ONLY" 10 speed, standard differential, tandem axle, dual tire, tire size front 425/65R22.5 rear 11R22.5yellowTOW ONLY, NO SGI Inspection. It is unknown if any repairs or safety concerns exist (if any). Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs if required. unknown kmPROBLEMS: Condition of motor and transmission unknown, tires, brakes, body exterior, exhaust, windshield glass, washer, wipers, paint, interior, mirrors and horn all in poor condition, unit is not running and condition of any components unknown, lights do not work, does not have a battery.> As is, Where is	unknown km	\$1 4V5JCBGE7TR844996
516.13	7-564	Gravel Truck, 1993FORD LTS900010L inline 6, diesel manual*FOR PARTS ONLY* 9 speed, standard differential, tandem, dual tire, tire size front 315/80R22.5 rear 11R22.5yellowTOW ONLY, NO SGI Inspection. It is unknown if any repairs or safety concerns exist (if any). Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs if required. unknown kmPROBLEMS: No box, hood falling off, lights do not work, does not have a battery, motor and transmission condition unknown, tires, brakes, body exterior, exhaust, windshield glass, washer, wipers, paint, interior, mirrors and horn all in poor condition. As is, Where is	unknown km	\$1 1FDZY90LXPVA09375

Item #	Description	Kms	Min Price	Serial Number
789.00 7-565	Gravel Truck, 1996VOLVO WG6410 yard dump boxD12, inline 6, diesel Super 10*FOR PARTS ONLY* 10 speed, tandem axle, standard differential, tire size front 425/65R22.5 rear 11R22.5yellowTOW ONLY, NO SGI Inspection. It is unknown if any repairs or safety concerns exist (if any). Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs if required. unknown kmPROBLEMS: "FOR PARTS ONLY" Unit was taken out of service and parts have been removed over the years. Unit is not running and condition of any components unknown, bent main frame tires, brakes, exhaust, windshield glass, wipers, interior, mirrors and horn all in poor condition, lights do not work. As is, Where is	unknown km	\$1	4V5JCBGE0TR844998
No Bid * 5-551	Packer/Roller, 1979Massey SP912Self propelled rollerFord 300GF, 118hp, inline 6, gas HydrostaticTire size 7.50/15, 12 plyyellow4454 hrsPROBLEMS: 2 flat tires, valve cover leak, leak at distributor, water holding tank rusty with holes, steering pump leak. As is, Where is	4454 hrs	\$1,500	335
1,102.00 7-568	Tractor, 1995FORD 8240SLFS6 PVR, inline 6, diesel manualsingle tire, tire size rear 18.4x38, front 11Lx16yellowTOW ONLY, NO SGI Inspection. It is unknown if any repairs or safety concerns exist (if any). Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs if required. unknown kmPROBLEMS: Tires, brakes, exhaust, windshield glass, wipers, interior and marrows all in poor condition, lights do not work, cab burnt out, engine and transmission condition unknown.> As is, Where is	unknown km	\$1	BD96650

Item #	Description	Kms	Min Price	Serial Number
NORTH BATTLEFORD, SaskBuilds and Procurement, Accommodations, 1 Jersey Street (Sask Hosp).				
Contact Dan Nahirney 306-440-4144, dan.nahirney@gov.sk.ca.				
No Bid * 1-849	Water Meter, Neptune Tru/Flo 6 inch Compound Meter 5 years old with 5 years warranty left, comes with strainer and TRICONE 420, TRICON E (4-20MA) XMITTERS, operational. Good		\$500	
No Bid * 1-850	Water Meter, Neptune Tru/Flo 6 inch Compound Meter 5 years old with 5 years warranty left, comes with strainer and TRICONE 420, TRICON E (4-20MA) XMITTERS, operational. Good		\$500	
PRINCE ALBERT, Highways, Northern Operations, 81 N. Industrial Dr.				
Contact Cory Palko 306-960-5152, cory.palko@gov.sk.ca.				
*WD 7-555	Trailer, 1996, JC, JC40, Flat Deck, , , , Tandem axle, dual tire, tire size 255/70R22.5, GVW 40000 Lbs, yellow, , , PROBLEMS: Tires poor. As is, Where is		\$5,000	2J9C3X4B7SK001029
5,404.97 7-557	Trailer, 2000JC Flat Deck Tandem axle, dual tire, tire size 225/70R22.5, GVW 20 tonyellow87,570 kmPROBLEMS: Tires poor. As is, Where is	87,570 km	\$5,000	2J9B7A4C5YK001173
4,001.00 7-556	Trailer, 1980Trailing TTK20Tilt Flat Deck Tandem axle, GVW 40000 LbsyellowPROBLEMS: Tires poor. As is, Where is		\$3,500	TK198068
5,088.77 7-558	Trailer, 1999Trailtech TD220Flat Deck Tandem axle, dual tire, tire size 255/70R22.5, GVW 46000 Lbs32,632 kmPROBLEMS: Tires poor. As is, Where is	32,632 km	\$5,000	2CUDCE3N4Y2005888
*WD 7-554	Trailer , 1995 JC40Flat Deck Tandem axle, dual tire, tire size 255/70R22.5, GVW 40000 LbsyellowPROBLEMS: Tires poor. As is, Where is		\$5,000	2J9C3X4B3SK001030
No Bid 7-508	Grader Fenders, Set of 2 John Deere, 2023, Plastic Rear, left and right, black Good		\$750	
No Bid 7-509	Grader Fenders, Set of 2 John Deere, 2023, Plastic Rear, left and right, black Good		\$750	
251.11 * 6-592	Scarifier, Front mount From John Deere 2010 770D, yellow. Good		\$1	
17,678.91 7-538	Motor Grader, 1994Champion 740ARWDLT10, inline 6, diesel PowershiftLocking differential, single tireyellowTOW ONLY, NO SGI Inspection. It is unknown if any repairs or safety concerns exist (if any). Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs if required. 3742 hrsRecent Repairs:PROBLEMS: Tires are poor, unit will need batteries to start.> As is. Where is	3742 hrs	\$12,500	24,258

Item #	Description	Kms	Min Price	Serial Number
PRINCE ALBERT, SaskPolytech, Room-H126 - Technical, call for directions.				
Contact Chris Perry 306-659-4043 perrychr@saskpolytech.ca				
480.00	7-504	Concrete Mixer, Monarch, C3-SE electric, operational when taken out of service. Note: not towable in current condition because the tires are flat and not sure if it is road worthy. Fair	\$1	C31861371-B
111.50	7-505	Concrete Vibrator, Stow, 130E operational, has concrete residue on the housing surface. Fair	\$1	
1,111.00	7-506	Dust Collector, Canwood, CWD12-575 operational, 5hp, dual bag. Good	\$1	039816
PRINCE ALBERT, Saskatchewan Public Safety Agency, 2120 Central Ave N				
Contact Bob Northey 306-930-8719 bob.northey@gov.sk.ca or Brent Zbaraschuk 306-940-7075 brent.zbaraschuk@gov.sk.ca				
100.00	7-543	Cargo Box, Thule 80"w x 32"d x 14"h, opens from either side. Fair	\$1	
298.33	7-544	Hitch and Skid Plate, Holland, Metal 5th wheel hitch mounted on 4" lift frame comes with air slide 5 th wheel adjustment, came off a 1997 Western Star HD picker/tractor unit. Poor	\$1	
1,695.25	7-545	Lift Picker, Palfinger, PK32000C 33000 lb, hydraulic hose or seal leaking, last inspected Aug 13, 2018. Fair	\$1	49,675,001
356.78	7-546	Loader, John Deere, Front-End 1.5 yard bucket. Fair	\$1	
657.00	7-547	Skid Steer Tracks, Kubota SVL 90 2 complete sets, some typical wear, operational. Fair	\$1	
PRINCE ALBERT, Saskatchewan Public Safety Agency, 2120 Central Ave (Nisbet Warehouse)				
Contact Brent Zbaraschuk 306-953-2428 (off) 306-940-7075 (cell), brent.zbaraschuk@gov.sk.ca				
8,389.89	7-559	Loader, 1983-1985MICHIGAN CLARK 55C - G1 Loader4WD453 Detroit, 4 cylinder, diesel autoindustrial bucketstandard differential, single axle, 3 speed, single tire size type 45/17.5R22yellowTOW ONLY, NO SGI Inspection. It is unknown if any repairs or safety concerns exist (if any). Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs if required. 1798 hrsPROBLEMS: Rear differential Problem , planetaries, has a sound, 1 tire is flat, does not have a battery, windshield washer and horn are non operational, interior and mirrors are poor, unknown if lights are operational. - TOW ONLY > As is Where is	1798 hrs	\$1 480B108CB

Item #	Description	Kms	Min Price	Serial Number
REGINA, Agriculture Crops and Irrigation, 226 - 3085 Albert St				
Contact Denise Konieczny 306-787-5854 denise.konieczny@gov.sk.ca (until Oct 25) or Shelby Bakun 306-787-9457, shelby.bakun@gov.sk.ca				
21.00	7-550	Desk Shield, Lot of 2 Plexiglass Clear, 84"w x 24"h, shield for top of desk. Excellent	\$1	
123.45	7-553	Safe, Sentry, metal Operational, with key and combination - both options, 17"w x 18"d x 23"h. Good	\$20	
REGINA, Agriculture Crops and Irrigation, 329 - 3085 Albert St				
Contact Yvonne Bachelu 306-787-4325 , yvonne.bachelu@gov.sk.ca				
5.00	7-551	Desk Shield, Lot of 2 Plexiglass Clear, 39"w x 31.5"h, shield for top of desk. Excellent	\$1	
5.00	7-552	Desk Shield, Lot of 2 Plexiglass Clear, 90"w x 24"h, shield for top of desk. Excellent	\$1	
REGINA, Corrections Policing and Public Safety 217 College W - 3737 Wascana Parkway				
Contact Cheryl McLean Keil , 306-787-4200, cheryl.mcleankeil@gov.sk.ca or Melanie Hart 306-787-8871, melanie.hart@gov.sk.ca				
11.10 *	6-502	Acrylic Protection Screens, Lot of 5 Plastic Comes with the mounting stands to hold the screens; two have slot in the front (for customer service area), 22.5"w x 7.25"d x 31.5"h; three are solid, 26.5"w x 7.5"d x 40"h. Good	\$1	
156.78 *	6-503	Conference Camera, HuddleCam HD, HCD20X - Simpltrack2 Lecturer tracking or conference recorder (zoom, teams), automatically tracks up to 50 feet away, 20x optical zoom lens, comes with a remote control and in original box, software can be downloaded from the manufacturer's website, operational. Excellent	\$100	HS2-80002049
51.51 *	6-504	Fax Machine, Brother Intellifax 2820 Comes with the instruction manual, no memory/hard drive, operational. Good	\$1	U61325E9N893090
15.50 *	6-506	Printer, Desktop, HP Laser Jet 1020 Includes power cord, unused HP 12A toner cartridge (unknown if useable), no hard drive/memory, operational. Good	\$1	CNBK473795
No Bid *	6-509	Teleprompter, Tripod/phone/camera mounted Includes cloth hood for protection. New- Unused	\$20	
REGINA, Energy and Resources 201 Dewdney Ave E				
Contact Kelly Laverdiere 306-787-2622, kelly.laverdiere@gov.sk.ca or Shelby Lamontagne 306-787-1178, shelby.lamontagne@gov.sk.ca.				
3.00 *	5-570	Wood Posts, Lot of approx. 20 Assorted Brown/white, approx. 1"w x 1"d x 60"h, some with hardware, used. Fair	\$1	

Item #	Description	Kms	Min Price	Serial Number
REGINA, Energy and Resources, 1945 Hamilton St				
Contact Shelby Lamontagne 306-787-1178, shelby.lamontagne@gov.sk.ca or Davio Robinson 306-787-8716, davio.robinson@gov.sk.ca				
45.00	7-529			
	File Cabinets, Lot of 2 Metal, lateral 36"w x 24"d 27"h, beige, locks with key. Fair		\$2	
25.00	7-530			
	Microscope, with Accessories Black in a brown case 14"w x 12"d x 12"h, unknown if operational, locks with key. Fair		\$1	
REGINA, Immigration and Career Training, 10th Fl., 2103 - 11th Ave				
Contact Verna Ziegler 306-787-2580, verna.ziegler@gov.sk.ca or Kayla Swicheniuk 306-787-5014, kayla.swicheniuk@gov.sk.ca				
5.25	7-516			
	Cabinet, for AV Equipment 28"w x 19"d x 32"h, black with wood top. Good		\$1	
36.70	7-518			
	File Cabinet, 3 drawer, 2 door 36"w x 18"d x 40.5", beige, no key. Good		\$1	
*MT	7-519			
	File Cabinet, 3 drawer, lateral 36"w x 18"d x 40"h x beige, locks with key. Good		\$1	
*MT	7-520			
	File Cabinet, 3 drawer, lateral 36"w x 18"d x 40"h x beige, locks with key. Good		\$1	
1.34	7-521			
	File Cabinet, 3 drawer, lateral 36"w x 18"d x 40"h x beige, no key. Good		\$1	
*MT	7-522			
	File Cabinet, 3 drawer, lateral 36"w x 18"d x 40.5"h, black, locks with key. Good		\$1	
*WD	7-523			
	File Cabinet, 3 drawer, lateral 36"w x 18"d x 41"h, beige, no key Good		\$1	
*MT	7-524			
	File Cabinet, 4 drawer, lateral 36"w x 18"d x 51.5"h, beige, no key. Good		\$1	
*MT	7-525			
	File Cabinet, 4 drawer, lateral 36"w x 18"d x 51.5"h, beige, no key. Good		\$1	
206.00	7-526			
	File Cabinet, 73"w x 18"d x 73"h, with lockable shutter with key, grey. Excellent		\$1	
206.00	7-527			
	File Cabinet, 73"w x 18"d x 73"h, with lockable shutter with key, grey. Excellent		\$1	
11.00	7-517			
	Shelf, Printer Cart, on wheels. 27.5"w x 23.75"d x 30"h, beige. Good		\$1	

Item #	Description	Kms	Min Price	Serial Number
REGINA, SaskBuilds and Procurement, 1920 Rose St				
Contact Kathy Bergen 306-787-9649, kathy.bergen@gov.sk.ca or Joseph Garcia 306-787-6911, joseph.garcia@gov.sk.ca				
3.10 * 6-530	Chair, Swivel, fabric White/black, adjustable level, no rips, 5 casters. Good		\$1	
SASKATOON, Corrections, Policing and Public Safety, SCC, 910 60th St. E				
Contact Renee Pound 306-956-8817, renee.pound@gov.sk.ca or Danielle Corriveau 306-956-8869 danielle.corriveau@gov.sk.ca.				
118.01 7-510	Flat Bar, Lot of 4 Steel 2"d x 1/4" thick, three pieces 20' length and one piece 19' length, total 79'. Good		\$90	
154.00 7-511	Flat Bar, Lot of 7 Steel 20'w x 1 1/2"d x 1/4"thick, total 140'. Good		\$138	
24.00 * 6-559	Flatbar, Steel Each 20' length, 1/2" x 1/8", 40' total. Good		\$4	
No Bid * 4-634	Floor Cleaner, Extract-Away, metal yellow, unknown if operational, 13.5 amps, 60 cycles, 712 hours. Poor		\$1	E1151-032
No Bid * 6-561	Grating, Steel, oxide primer Some used, 1" w x 1/8" thick, assorted sizes, 24" x 36", 48" x 36", 12" x 36", 12" x 120". Good		\$605	
No Bid * 5-521	Sheet Metal, Lot of 3 Steel 48"w x 120"d x 11ga, perforated, 1/4" holes. Good		\$1,348	
No Bid * 5-522	Sheet Metal, Lot of 4 Steel 48"w x 120"d x 11ga, perforated, 3/16" holes. Good		\$1,797	
No Bid * 5-523	Sheet Metal, Lot of 2 Steel 48"w x 120"d x 11ga, perforated, 3/8" holes. Good		\$814	
25.55 7-512	Threaded Rod, Lot of 2 Steel One piece 10' length and one piece 9' length of 5/8", total 19'. Good		\$4	
105.55 7-513	Tubing, Lot of 3 Steel 1" x 2" x 16 gauge, one piece 20'l, one piece 16' l and one piece 15' l, rectangular, total 51', two pieces (16' and 15') length have been used and have paint on them. Good		\$21	
255.55 7-514	Tubing, Lot of 7 Steel 1"x2" x .125 thick, each 24' length, rectangular, total 168'. Good		\$205	
63.00 7-515	Tubing, Steel 2"x 3"x .188 thick, 12' length, rectangular. Good		\$51	
SOUTHEND Corrections Policing and Public Safety 15 College Dr				
Contact Nolan Hoggarth 306-758-6254, nolan.hoggarth@gov.sk.ca				
No Bid * 6-515	Sonar Head Unit, Eagle, SupraPro ID Unknown if operational. Poor		\$1	7,239,602
No Bid * 6-516	Sonar Head Unit, Hummingbird, LCR400 ID Unknown if operational. Poor		\$1	3,197,452
No Bid * 6-517	Sonar Kit, Eagle, SupraPro ID Unknown if operational, includes head unit, case, and transducer. Poor		\$1	7,373,821

Item #	Description	Kms	Min Price	Serial Number
WEYBURN, Highways, 18 Souris Ave. Hwy 1 West Entrance				
Contact Kurt Whitford 306-861-9971, kurt.whitford@gov.sk.ca or Gord Haines 306-861-5004, gord.haines@gov.sk.ca (Gord will be on leave in October)				
300.00	7-534	Chain Link Fence , Lot of 5 Metal Various length from 8m to 40m, 6'h. Fair	\$1	
1,273.00	7-535	Snow Blower , Schulte 9600, 3 Point Hitch Attachment Operational. Poor	\$1	
102.00	7-536	Tripod and GPS, Cansel, Trimble Juno 3B TNJ31 Unknown if operational. Fair	\$1	31,000,160,800,901
37.40	7-537	Tripod and GPS, Cansel, Trimble Juno 3B TNJ32 Unknown if operational. Fair	\$1	31,000,153,000,734