

SALE SUMMARY LIST

PLEASE NOTE: Every effort has been made to accurately describe items and their condition; however, additional problems may exist, items may not be complete or exactly as described. Bidders are deemed to have reviewed the Terms and Conditions on bid forms and relied entirely on their own inspection and evaluation prior to bidding. Vehicles and equipment are sold "AS IS, WHERE IS", there is no implied or express warranty.

Visit www.SaskSurplus.ca for pictures and link to download Bid Form.

- Items identified with * have been on a previous sale and will be listed first on www.SaskSurplus.ca web site.
- SaskBuilds and Procurement, SaskSurplus, reserves right to have unadvertised minimum selling prices on items.

It is the Bidder's responsibility to review the terms and conditions of sale on the Offer to Purchase, Bid Form.

Bid Forms are available from www.SaskSurplus.ca or from the SaskSurplus Sales Lot, 500 McLeod Street, Regina, SK.

Bid Forms can be submitted in the following ways:

- by deposit in the bid box at the SaskSurplus Sales Lot,
- by fax to 306-787-2092; by phone 306-787-2062 or 306-787-2238,
- by email to sasksurplus@gov.sk.ca, or
- by mail, addressed to: Ministry of SaskBuilds and Procurement, SaskSurplus, 500 McLeod Street, Regina, SK S4N 4Y1.

(If mailing your bid, please allow sufficient time for bid to be received.)

- Bids received after close date and time cannot be accepted.

MT = (Ministry Transfer) This means that the item has been claimed by another ministry and automatically transferred to the ministry.

WD = (Withdrawn) This can happen if the item was requested to be removed by the seller.

No Bid = Items that did not receive any bids are normally carried forward to the next sale or may be withdrawn.

Item #	Description	Kms	Min Price	Serial Number
REGINA, SaskBuilds and Procurement, SaskSurplus Sales Lot, 500 McLeod Street - Vehicles				
Contact SaskSurplus 306-787-2062 or 306-798-3306.				
750.00	8-016	Car 2006 CHEVROLET Cobalt 2WD 2.2L, Inline 4, gas auto A/C, tilt, cruise, AM/FM/CD player, power locks, keyless entry, 1 fob, 2 keys , white, FOR PARTS ONLY, NO SGI INSPECTION. **THIS VEHICLE IS FOR RECYCLING PURPOSES ONLY AND NOT FOR RESALE. THIS VEHICLE CANNOT BE REGISTERED WITHIN ANY JURISDICTION. **, 153,261 km, PROBLEMS: Right head light foggy, hood scratches/hail, both bumpers' chips/scratches, both dog legs rust, rocker panels rusted through, all doors rust bottom inside and out, roof hail, trunk lid hail, no first aid kit/fire extinguisher, windshield chips, poor battery, minor exterior damage.>, As is, Where is	153,261 km	\$183 1G1AJ55F467841193
800.00	8-013	Car 2008 CHEVROLET Impala LS 2WD 3.5L, V6, gas auto A/C, tilt, cruise, AM/FM/CD player, power locks/ windows/ mirrors/ trunk release/ left front seat, keyless entry, 2 keys, 2 fobs , gold, FOR PARTS ONLY, NO SGI INSPECTION. **THIS VEHICLE IS FOR RECYCLING PURPOSES ONLY AND NOT FOR RESALE. THIS VEHICLE CANNOT BE REGISTERED WITHIN ANY JURISDICTION. **, 207,730 km, PROBLEMS: Front pads and rotors, right wheel bearing, alignment, hood shocks, floor rusted through, wiper blades, missing left side wheel cover, hood chips, front bumper flaking, rear bumper chips/scratches, left side fenders scratched, rocker panels rusted, left side doors rust along inside bottom, right side doors rust inside bottom, roof rust front edge, trunk lid rust/scratched/dents, no first aid kit/fire extinguisher, windshield chips, poor battery, minor exterior damage.>, As is, Where is	207,730 km	\$262 2G1WB58K481352482
800.00	8-011	Car 2008 CHEVROLET Impala LS 2WD 3.5L, V6, gas auto A/C, tilt, cruise, AM/FM/CD player, power mirrors/ locks/ windows/ left front seat/ trunk release, keyless entry, 1 fob, 3 keys , grey, FOR PARTS ONLY, NO SGI INSPECTION. **THIS VEHICLE IS FOR RECYCLING PURPOSES ONLY AND NOT FOR RESALE. THIS VEHICLE CANNOT BE REGISTERED WITHIN ANY JURISDICTION. **, 301,933 km, PROBLEMS: Right lower ball joint, alignment, frame ripped, washer nozzle, missing left rear wheel cover, hood chips/scratches/dents/rust, front bumper broken, rear bumper scratches, left side fenders scratches/chips, right side fenders road rash/rust, rocker panels rusted, all doors rusted inside and out, roof dent, trunk lid scratches/rust/dents, no fire aid kit/fire extinguisher, windshield chips, poor battery, minor exterior damage.>, As is, Where is	301,933 km	\$263 2G1WB58K381358824

Item #	Description	Kms	Min Price	Serial Number
800.00 8-012	Car 2009 CHEVROLET Impala LS 2WD 3.5L, V6, gas auto A/C dual zone, tilt, cruise, AM/FM/CD player, power mirrors/locks/ windows/ left front seat, keyless entry, 1 fob, 1 key , gold, FOR PARTS ONLY, NO SGI INSPECTION.**THIS VEHICLE IS FOR RECYCLING PURPOSES ONLY AND NOT FOR RESALE. THIS VEHICLE CANNOT BE REGISTERED WITHIN ANY JURISDICTION. **, 192,142 km, PROBLEMS: Power steering rack leaking, front sway bar links, front links, front wheel alignment needs rack, hood chips/scratches, front bumper chips, rear bumper scratches/scrapes, left front fender small rust, left rear fender dent, rocker panels rusted through, all doors rusted, tail gate chips, back window scratched, no first aid kit/fire extinguisher, windshield chips/scratches, poor battery, minor exterior damage.>, As is, Where is	192,142 km	\$264	2G1WB57K491325348
850.00 8-017	Car 2013 CHEVROLET Impala LS 2WD 3.6L, V6, gas auto A/C, tilt, cruise, AM/FM/CD player, power locks/ windows/ mirrors/ trunk release/ left front seat, keyless entry, 2 keys, 2 fobs , grey, FOR PARTS ONLY, NO SGI INSPECTION.**THIS VEHICLE IS FOR RECYCLING PURPOSES ONLY AND NOT FOR RESALE. THIS VEHICLE CANNOT BE REGISTERED WITHIN ANY JURISDICTION. **, 165,916 km, PROBLEMS: All pads and rotors, rear right taillight back up not working, hood scratches/chips/dents, both bumper's chips/scratches, left front fender scratches, left rear fender rust, rocker panels rust, left rear door rust inside bottom, trunk lid scratches, no first aid kit/fire extinguisher, windshield chips, poor battery, minor exterior damage.>, As is, Where is	165,916 km	\$342	2G1WA5E36D1186623
1,727.27 8-036	Car 2013 CHEVROLET Impala LS 2WD 3.6L, V6, gas auto A/C, tilt, cruise, AM/FM/CD- player, power mirrors/ locks/ windows/ left front seat, keyless entry, 1 key, 2 key fobs , black, TOW ONLY, FAILED SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. **Please note: the SGI Inspection currently provided is only valid for 30 days after the date of the inspection.**, 240,595 km, PROBLEMS: Left rear strut leaking, suspension/ attachments, undercarriage damage, transmission poor, left front carpet hole, right front seat trim loose, hood chips, scratches and dents, front bumper scratches and road rash, rear bumper road rash, left front/ rear fender scratches and chips, right front fender dent, both left doors rusted inside bottom, right rear door rusted inside bottom, roof rusted, trunk lid, dented and scratches, no first aid kit/ fire extinguisher windshield chips, poor battery, minor exterior damage.> , As is, Where is	240,595 km	\$1,508	2G1WA5E38D1187479

Item #	Description	Kms	Min Price	Serial Number
4,623.66 8-031	Car 2013 CHEVROLET Impala LS 2WD 3.6L, V6, gas auto A/C, tilt, cruise, AM/ FM/ CD player, power mirrors/ locks/ windows/ left front seat, keyless entry, 1 fob, 1 key , black, TOW ONLY, FAILED SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. **Please note: the SGI Inspection currently provided is only valid for 30 days after the date of the inspection.**, 228,277 km, PROBLEMS: Rear brake pads/ rotors, license plate lights, hood poor paint chips scratches dents, front/ rear bumpers road rash scratches chips, left front fender scratches chips, left rear fender rust clear coat peeling, right front / rear fenders scratches, left front/ rear doors road rash rust inside bottom chips scratches, right front and rear doors road rash chips scratches, roof rust scratches, trunk lid scratches dents missing letter 'p', right mirror housing broke, no first aid kit/ fire extinguisher, windshield chipped, cracked on right upper corner, poor battery, minor exterior damage.> , As is, Where is	228,277 km	\$2,536	2G1WA5E30D1186150
800.00 8-014	Car 2013 CHEVROLET Impala LS 2WD 3.6L, V6, gas auto A/C, tilt, cruise, AM/FM/CD player, power mirrors/ locks/ windows/ trunk release/ left front seat, keyless entry, 2 fobs, 2 keys , grey, FOR PARTS ONLY, NO SGI INSPECTION.**THIS VEHICLE IS FOR RECYCLING PURPOSES ONLY AND NOT FOR RESALE. THIS VEHICLE CANNOT BE REGISTERED WITHIN ANY JURISDICTION. **, 237,144 km, PROBLEMS: Alignment, right low beam, wiper blades, hood chips/dents/scratches, both bumper scratches/chips/dents, left side fender scratches, right rear fender dents/scrapes, rocker panels rust, left side front door rust inside bottom, right side door rust inside bottom, roof rust at front/scratches, truck lid scratched, windshield chips, poor battery minor exterior damage.> , As is, Where is	237,144 km	\$308	2G1WA5E32D1249278
700.00 8-010	Car 2008 CHRYSLER Sebring 2WD 2.7L, V6, gas auto A/C, tilt, cruise, AM/FM/CD player, power heated mirrors/ locks/ windows/ trunk release, driving lights, keyless entry, 2 key fobs , beige, FOR PARTS ONLY, NO SGI INSPECTION.**THIS VEHICLE IS FOR RECYCLING PURPOSES ONLY AND NOT FOR RESALE. THIS VEHICLE CANNOT BE REGISTERED WITHIN ANY JURISDICTION. **, 202,886 km, PROBLEMS: Power steering rack leaking, rear struts leaking, rear brakes noise, park brake shoes and hardware, rear brake light, head lamps foggy, hood 2 tone paint, paint bubbling, front bumper chips/cracked, front left fender scratches, right front fender dent, rear fenders rusted, rocker panels rusted/through, left side doors scratches/road rash, right rear door rust inside bottom, tailgate scratches, right front mirror paint peeling, no first aid/fire extinguisher, windshield chips/scratches, poor battery, minor exterior damage.> , As is, Where is	202,886 km	\$253	1C3LC56R58N230532

Item #	Description	Kms	Min Price	Serial Number
4,889.89 8-020	Car 2010 CHRYSLER Sebring LX 2WD 2.4L, Inline 4, gas auto A/C, tilt, cruise, AM/FM/CD player, power heated mirrors/ locks/ windows, keyless entry, 2 key fobs, 1 key , white, TOW ONLY, FAILED SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. **Please note: the SGI Inspection currently provided is only valid for 30 days after the date of the inspection.**, 159,825 km, PROBLEMS: left front axle, wheel alignment, parking brake warning light/ sticks, front bumper loose on right side, rear bumper scratches, left front fender dents, left rear fender rusted, right rear fender scratches / rust, left dog leg rust, all four doors rust inside bottom, roof paint chips, trunk lid rust spot, wheel wrench/ jack loose in trunk, no first aid kit/ fire extinguisher, windshield chips, wiper blades, poor battery, minor exterior damage.>, As is, Where is	159,825 km	\$2,549	1C3CC4FB8AN108539
4,789.89 8-021	Car 2008 CHRYSLER Sebring Touring 2WD 2.7L, V6, gas auto A/C, tilt, cruise, AM/FM, power heated mirrors/ locks/ windows, keyless entry 2 key fobs , red, TOW ONLY, FAILED SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. **Please note: the SGI Inspection currently provided is only valid for 30 days after the date of the inspection.**, 181,519 km, PROBLEMS: headlights foggy, hood paint bubbling, left rear bumper scratches, left rear fender scratches, right front fender rust, left doors scratches/ chips, right rear door rust, roof hail, tailgate hail/ scratches, no first aid kit/ fire extinguisher, poor battery and minor exterior damage.> , As is, Where is	181,519 km	\$2,943	1C3LC56R48N230487
3,955.55 8-033	Car 2011 DODGE Avenger SE 2WD 2.4L, Inline 4, gas auto A/C, tilt, cruise, AM/FM/CDplayer, power mirrors/locks/windows, keyless entry, 2 key fobs , black, TOW ONLY, FAILED SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. **Please note: the SGI Inspection currently provided is only valid for 30 days after the date of the inspection.**, 242,119 km, PROBLEMS: Rear struts, brakes, rotors, parking break light on, park brake stays on, headlamps foggy, windshield, grille lower hole, hood scratches/ paint bubbling/ chips and hail, front bumper road rash and scratches, rear bumper scratches, left front/ rear fenders scratches, right front fender and chips, left/ right rocker panels road rash, left front door rusted, left rear door rusted and road rash, right front door rusted, right rear door rusted and road rash, roof hail, trunk lid hail and scratches, no first aid kit/ fire extinguisher, trunk liner loose, hail left roof rail, windshield chip, poor battery, minor exterior damage.> , As is, Where is	242,119 km	\$2,751	1B3BD4FB7BN501228

Item #	Description	Kms	Min Price	Serial Number
4,189.89 8-022	Car 2013 DODGE Avenger SE 2WD 2.4L, Inline 4, gas auto A/C, tilt, cruise, AM/FM/CD player, power mirrors/ locks/ windows, keyless entry, 2 key fobs , silver, TOW ONLY, FAILED SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. **Please note: the SGI Inspection currently provided is only valid for 30 days after the date of the inspection.**, 243,836 km, PROBLEMS: Steering rack leaking, headlights foggy, hood paint bubbling, scratches, front/rear bumper chips scratches, left front/rear fenders scratches, right front fender dent, left rear door road rash, both right doors rust inside bottom, right rear door road rash, tailgate scratches, no first aid kit/ fire extinguisher, windshield cracks chips, poor battery, minor exterior damage.> , As is, Where is	243,836 km	\$1,000	1C3CDZAB1DN604515
850.00 8-007	Car 2009 FORD Crown Victoria LX 2WD 4.6L, V8, gas auto A/C, tilt, cruise, AM/FM, power adjustable brake pedal/ left front seat/ mirrors/ locks/ windows/ trunk release, 3 keys interior car warmer, white, FOR PARTS ONLY, NO SGI INSPECTION.**THIS VEHICLE IS FOR RECYCLING PURPOSES ONLY AND NOT FOR RESALE. THIS VEHICLE CANNOT BE REGISTERED WITHIN ANY JURISDICTION. **, 131,474 km, PROBLEMS: PARTS ONLY VEHICLE, both rocker panels rusted through, rear floor pans rusted through, fuel tank seep, front centre console loose/missing parts, plastic rear seat (OEM rear seat missing), floor pan loose, left front door switch panel loose, driver's seat belt buckle damaged, wipers deteriorated, hood large paintless spot, front bumper scratches, right rear fender rusted, both dog legs rusted, left doors rusted inside and out at bottom, right rear door rusted inside and out at bottom, roof rust spots, trunk lid dents, spare tire/ wheel wrench/ jack loose in truck, no first aid kit/extinguisher, windshield chipped, poor battery and minor exterior damage.>, As is, Where is	131,474 km	\$281	2FAHP71V09X144489
7,089.89 8-023	Car 2011 TOYOTA Camry, LE 2WD 3.5L, V6, gas auto A/C, tilt, cruise, AM/FM/CD player, Bluetooth, power mirrors/ locks/ windows/ left front seat, keyless entry, 2 key fobs 4 fabric mats in trunk, grey, TOW ONLY, FAILED SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. **Please note: the SGI Inspection currently provided is only valid for 30 days after the date of the inspection.**, 264,454 km, PROBLEMS: Left lower ball joint, brakes have bad pulse, front rotor, driver door pins, hood chips, front bumper pitted chips, roof rust, left mirror housing scrape, headlights fogged, no fist aid kit/ fire extinguisher, windshield chipped, poor battery, minor exterior damage.>, As is, Where is	264,454 km	\$4,837	4T1BK3EK8BU130002

Item #	Description	Kms	Min Price	Serial Number
8,190.00 8-032	Car 2011 TOYOTA Camry, LE 2WD 3.5L, V6, gas auto A/C, tilt, cruise, AM/ FM/ CD player/ Bluetooth, power mirrors/ locks/ windows/ left front seat, keyless entry, 2 key fobs , grey, PASSED SGI Inspection. **Please note: the SGI Inspection currently provided is only valid for 30 days after the date of the inspection.**, 258,643 km, PROBLEMS: Left headlight fogged, grille paint chips, hood chips scratches hail, front/rear bumpers chips scratches, roof hail scratches, trunk lid chips scratches, hail no first id kit/ fire extinguisher, windshield chips, poor battery, minor exterior damage.> , As is, Where is	258,643 km	\$5,995	4T1BK3EK1BU129354
1,350.00 8-015	SUV 2015 CHEVROLET Equinox LS 4WD 2.4L, Inline 4, gas auto A/C, tilt, cruise, AM/FM, Bluetooth, power windows/ mirrors/ locks/ left front seat, keyless entry, 2 key fobs , white, FOR PARTS ONLY, NO SGI INSPECTION.**THIS VEHICLE IS FOR RECYCLING PURPOSES ONLY AND NOT FOR RESALE. THIS VEHICLE CANNOT BE REGISTERED WITHIN ANY JURISDICTION. **, 241,921 km, PROBLEMS: Rear rotors, mud flaps, left front door weather stripping, grille missing lower grill, hood chips/scratches, front bumper chips, rear bumper chips/trim broken, left front fender rusted, left rear fender road rash/poor paint, right front fender rust, right side fenders paint poor/road rash, both rocker panels rusted, all four doors rust along inside bottom/road rash, left rear door weather strip loose, tailgate rusted/pain poor, interior soiled, no first aid kit/fire extinguisher windshield cracked, wiper blades, poor battery, minor exterior damage.> , As is, Where is	241,921 km	\$342	2GNFLEEK0F6314229
1,500.00 8-006	SUV 2015 CHEVROLET Equinox LS AWD 2.4L, Inline 4, gas auto A/C, tilt, cruise, AM/FM, power locks/ mirrors/ windows/ left front seat, keyless entry, 2 key fobs , white, FOR PARTS ONLY, NO SGI INSPECTION.**THIS VEHICLE IS FOR RECYCLING PURPOSES ONLY AND NOT FOR RESALE. THIS VEHICLE CANNOT BE REGISTERED WITHIN ANY JURISDICTION. **, 160,013 km, PROBLEMS: PARTS ONLY VEHICLE, both rocker panels rusted, park brake not holding, hood chips, front bumper chips, left fenders rust, right front fender rust, left and right dog legs rust, left and right rocker panels rusted, left rear door rusted on inside bottom, no first aid kit, no fire extinguisher, windshield chips, poor battery minor exterior damage.> , As is, Where is	160,013 km	\$385	2GNFLEEK4F6204378

Item #	Description	Kms	Min Price	Serial Number
5,572.89 8-035	SUV 2008 JEEP Commander Sport 4WD 3.7L, V6, gas auto A/C, tilt, cruise, AM/FM/CD player, power heated mirrors/ locks/ windows/ left front seat, keyless entry, 2 key fobs Roof rack, driving lights, hitch, trailer wiring, grey, TOW ONLY, FAILED SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. **Please note: the SGI Inspection currently provided is only valid for 30 days after the date of the inspection.** , 297,488 km, PROBLEMS: Front rotors, hood paint bubbling, front bumper scuffs and chips, left/ right dog legs road rash, both left doors rust at bottom, right front door rust at bottom, right front wheel flare loose at bottom, tailgate missing inside trim, right mirror housing cracked, no first aid kit/ fire extinguisher, windshield chips, poor battery, minor exterior damage.> , As is, Where is	297,488 km	\$2,993	1J8HG48K58C225156
1,500.00 8-005	Truck 2012 CHEVROLET Colorado 4WD, Ext Cab, Box 6' 3.7L, inline 5, gas auto A/C, tilt, cruise, AM/FM, 1 key front tow hooks, driving lights, box liner, UWS Gull Wing tool box - condition fair, hitch, trailer wiring, mudflaps, 1 key, no key for toolbox, white, FOR PARTS ONLY, NO SGI INSPECTION.**THIS VEHICLE IS FOR RECYCLING PURPOSES ONLY AND NOT FOR RESALE. THIS VEHICLE CANNOT BE REGISTERED WITHIN ANY JURISDICTION. **, 202,097 km, PROBLEMS: PARTS ONLY VEHICLE, left rocker rusted, front drive shaft missing bolt, rack pinion seal, rack leaks, TPMS warning light, no back seat, hood chips, front bumper chips rust, rear bumper bent rusted, right rear door road rash chips, tailgate rust chips and scratches, wheel wrench loose in backseat, left front seat worn and ripped, both box rails paint worn from tool box, no first aid kit, no fire extinguisher, windshield chipped, poor battery, minor exterior damage.> , As is, Where is	202,097 km	\$261	1GJTCFE3C8126438
7,250.00 8-028	Truck 2014 CHEVROLET Silverado 1500 4WD, Double Cab, Box 6'6" 4.3L, V6, gas auto A/C, tilt, cruise, AM/FM, Power mirrors/ locks/ windows/ left front seat, keyless entry, 2 fobs, 3 keys(1 key for Tonneau) grille inserts with wigwags, tow hooks, headache rack with beacon/ wigwags, hitch trailer wiring, OEM trailer brakes, 500 Watt Eliminator power converter (condition unknown), has a back seat, tuxedo roll up Tonneau cover fair condition, white, TOW ONLY, FAILED SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. **Please note: the SGI Inspection currently provided is only valid for 30 days after the date of the inspection.** , 327,316 km, PROBLEMS: Left outer tie rod, rear pads, rear rotors, alignment, hood chips dents, front bumper chips valance loose scratches, rear bumper scratches, left rear fender clear coat peeling road rash, right rear fender clear coat peeling road rash, all 4 doors chips clear coat peeling, tailgate dents scratches, left front seat worn small holes, Velcro on dashboard, no first aid kit/ fire extinguisher, windshield chipped, poor battery, minor exterior damage.> , As is, Where is	327,316 km	\$6,001	1GCVKPEH7EZ265346

Item #	Description	Kms	Min Price	Serial Number
12,567.00 8-038	Truck 2015 CHEVROLET Silverado 1500 4WD, Crew Cab, Box 6'5" 4.3L, V6, gas auto A/C, tilt, cruise, AM/FM, power mirrors/ locks/ windows, keyless entry, 2 key fobs, 2 keys Grille inserts, tow hooks, side steps, mud flaps, box liner, headache rack, hitch, trailer wiring, OEM trailer brakes, has a back seat, white, TOW ONLY, FAILED SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. **Please note: the SGI Inspection currently provided is only valid for 30 days after the date of the inspection.**, 294,414 km, PROBLEMS: Left headlight assembly, front bumper road rash, chips and scratches, rear left fender dents and scratches, rear right fender scratches, chips, rust and bent near tailgate, left rear door paint peeling, tailgate scratches and chips, left front seat worn and ripped, tar on exterior, interior soiled, no first aid kit/ fire extinguisher, windshield chips, cracked, poor battery, minor exterior damage.> , As is, Where is	294,414 km	\$8,341	3GCUKPEH0FG265590
4,656.50 * 5-005	Truck 2002 CHEVROLET Silverado 3500 RWD, Crew Cab, 9' x 7' Dump Body 8.1L V8 gas auto A/C, tilt, cruise, AM/FM, power locks, keyless entry-1 fob 1 key Grille inserts, hitch, trailer wiring, electric trailer brake dump body condition good, 7731 hours on box meter, front wheel covers loose in cab, has a back seat, dual rear wheels, yellow, TOW ONLY, FAILED SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. **Please note: the SGI Inspection currently provided is only valid for 30 days after the date of the inspection.**, 278,416 km, Recent Repairs: new battery July 19/23 PROBLEMS: Left front lower ball joint loose, unable to test drive, transmission kicks out of gear, left rear tire inner bald, right front tire leaking, oil cooler line leak, grille chrome peeling/missing logo, hood chips/dents/scratches, front bumper bent, front left fender clear coat peeling, left rocker panel paint worn, left side doors clear coat peeling/road rash, front right door dent, right cab corner road rash, dash peeling, seats soiled/sagging, left right seat hole, head liner loose, no first aid kit/fire extinguisher, right mirror missing trim, right washer does not spray top of windshield, right front driving light bulb burnt out, minor exterior damage.> , As is, Where is	278,416 km	\$3,460	1GBJC33GX2F212057

Item #	Description	Kms	Min Price	Serial Number
6,205.00 8-037	Truck 2012 DODGE 2500 4WD, Crew Cab, Box 6'3" 5.7L, V8, gas auto A/C, tilt, cruise, AM/FM/CD player, power locks/ windows/ heated mirrors, keyless entry, 2 key fobs, 1 key Grille inserts, tow hooks, side steps, hitch with reciever mudflaps, has a back seat, silver, TOW ONLY, FAILED SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. **Please note: the SGI Inspection currently provided is only valid for 30 days after the date of the inspection.**, 184,934 km, PROBLEMS: Exhaust leaks, manifold leaks, brake pads and rotors, tires, no lights in back, wiper blades, fender dented, grille chips, holes drilled, hood, chips and dents, front bumper rusted, rear bumper dents, left front fender scratches, rear left fender scratches, right front and rear fenders scratches, both rocker panels road rash, left front door dent, right front door scratches, right rear door scratches and dent, roof scratches, hole in roof 13 sealed, tailgate rust, dents, bent and molding broke, left mirror housing cracked, left front seat worn, frame visible, left front seta back worn, frame visible, the paint is poor under the left front headlight, holes drilled in dash, holes drilled in rear cupholder, hole in right front floor, missing jump seat, no first aid kit/ fire extinguisher, windshield chips, poor battery, minor exterior damage.> , As is, Where is	184,934 km	\$5,744	3C6TD5CTXCG195035
2,505.00 8-029	Truck 2013 DODGE Ram 1500 4WD, Quad Cab, Box 6'4" 4.7L, V8, gas auto A/C, tilt, cruise, AM/FM, power heated mirrors/locks/windows, keyless entry, 1 key fob tow hooks, side steps, mudflaps, hitch, trailer wiring, has a back seat, silver, TOW ONLY, FAILED SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. **Please note: the SGI Inspection currently provided is only valid for 30 days after the date of the inspection.**, 288,131 km, PROBLEMS: Check engine light (P0456 EVAP, P0733 gear ratio 3rd, P0734 gear ratio 4th), transmission problems – shifting issues, right cab corner rusted, hood has paint bubbling and dents, front bumper scratched, rear bumper rusted and dented, both rear fenders rust and dents, left front door dents, roof rust on front edge, tailgate dents, left front seat worn with small rip, no first aid kit, no fire extinguisher, windshield chips, , minor exterior damage.> , As is, Where is	288,131 km	\$2,121	1C6RR7FP9DS515980

Item #	Description	Kms	Min Price	Serial Number
2,599.00 8-001	Truck 2014 DODGE Ram 2500 4WD, 8' Box, Crew Cab 5.7L, V8, gas auto A/C, tilt, cruise, AM/FM, power locks/windows, heated mirrors, keyless entry-2 key fobs, 2 keys tow hooks, side steps, hitch, trailer wiring, OEM trailer brakes, box liner, white, TOW ONLY, FAILED SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. **Please note: the SGI Inspection currently provided is only valid for 30 days after the date of the inspection.**, 282,268 km, PROBLEMS: Engine has a knock, check engine light (U110E lost ambient temperature) 4WD shift (V0403), both right ball joints, washer hose, power steering leak, both front shocks, needs alignment, TPMS light on, left rear door latch missing bolts, right mirror housing broken, surface rust on rockers, tailgate damage, spare tire, grille broke inserts loose, hood road rash, front bumper bent/rusted, rear bumper rusted/missing sensors, left side fenders road rash/rust, right side fender rust/dent, rocker panels road rash, left side doors chips/dents, right doors chips, no wheel wrench, jack loose under back seat, holes drilled in box rails, both rear storage compartments broken, no first aid kit/fire extinguisher, no horn, left front seat worn, poor battery, minor exterior damage.>, As is, Where is	282,268 km	\$2,500	3C6TR5HT1EG212107
4,345.67 * 7-037	Truck 2015 DODGE Ram 2500 4WD, 54" Box, Crew Cab 5.7L V8 gas auto A/C, tilt, cruise, after market CD player/radio, power heated mirrors/locks/windows, 1 key fob Tow hooks, grille inserts, hitch, trailer wiring, OEM trailer brakes, has back seat, white, TOW ONLY, FAILED SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. **Please note: the SGI Inspection currently provided is only valid for 30 days after the date of the inspection.**, 154,234 km, PROBLEMS: Check engine light, noise's (diagnosed as internal engine failure), misfiring, both front wheel bearings have play, both ball joints have play upper and lower, missing jump seat, B pillar inside molding holes cut, A pillar inside molding loose, Right A pillar trim loose, right side step loose, holes drilled in front hump, hole on head liner, holes in dash and trim, mud flap loose, hood chips, front bumper rust spots, rear bumper dents/rust spots, left front fender rusted, left rear fender dents, rocker panels road rash, left rear door missing trim/holes drilled, roof multiple dents, hole in roof 2 sealed, tailgate dented/rust/missing molding, rear left signal light out, wheel wrench/jack loose in back seat, no first aid kit /fire extinguisher, windshield chips, poor battery, minor exterior damage.>, As is, Where is	154,234 km	\$3,853	3C6TR5CT1FG544766

Item #	Description	Kms	Min Price	Serial Number
No Bid 8-030	Truck 2015 DODGE RAM 3500 4WD, Crew cab, Box 8' 6.4L, V8, gas auto A/C, tilt, cruise, AM/FM, power heated trailer tow mirrors/ windows/ locks, keyless entry, 1 key fob tow hooks, side step, mudflaps, hitch, trailer wiring, OEM trailer brake, box liner, winter front in back seat, white, TOW ONLY, FAILED SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. **Please note: the SGI Inspection currently provided is only valid for 30 days after the date of the inspection.**, 342,992 km, PROBLEMS: ABS/traction warning lights, u-joint squeak in reverse, right front brake pads, park brake not holding, locks not working, both front upper ball joints loose, left rear tire, exhaust leak at manifold, right rear taillight assembly cracked, rear seat not secure, rear middle seat belt not secure, left front seat bottom badly worn exposing frame, hood chips dents, front bumper dents rust, left rear fender road rash dents, right front fender rust, right rear fender road rash dents, left/right rocker panel rusted road rash, right front door rust at bottom, right mirror housing broke, no tailgate/ first aid kit/ fire extinguisher, windshield chipped, poor battery and minor exterior damage.> , As is, Where is	342,992 km	\$8,982	3C63R3GJ6FG678623
No Bid * 7-029	Truck 2009 DODGE Ram 5500 RWD, 7'6" x 10' box, Quad Cab 6.7L Inline 6 diesel Auto A/C, tilt, cruise, AM/FM/CD player, power mirrors/trailer tow, 1 key fob, dual rear wheels Grille inserts, front tow hooks, side steps, mud flaps, hitch, trailer wiring, electric trailer brake, Aero board with beacon, unknown condition, controls in cab, has a back seat, white, TOW ONLY, FAILED SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. **Please note: the SGI Inspection currently provided is only valid for 30 days after the date of the inspection.**, 291,439 km, PROBLEMS: Engine light is on, will not stay running, small leak rear pinion, right front rotor below spec, park brake does not hold, cables falling off from rust, left front seat bottom cushion hole exposing metal, plate bulb, middle rear marker bulbs, right rear lower marker light, cab corners road rash, hood chips clear coat peeling and dents, front bumper rust and dented, left front fender rust spot, dented and out of alignment, right front fender chip, left front door chip rust, roof antenna, spare tire loose in box, no first aid kit, no fire extinguisher, windshield chipped, poor battery, minor exterior damage.> , As is, Where is	291,439 km	\$12,642	3D6WC78L79G554342

Item #	Description	Kms	Min Price	Serial Number
18,325.00 * 7-008	Truck 2009 DODGE Ram 5500 RWD, Quad Cab, 10'3"w x 7'4"d dump body 6.7L Inline 6 diesel auto A/C, tilt, cruise, AM/FM/CD player, power heated trailer mirrors/windows/locks, keyless entry-2 key fobs, 1 other key Dump body stainless steel, fold down sides, integrated headache rack with beacon condition unknown, power lift gate badly rust mechanically condition unknown, side steps, front tow hooks, hitch, trailer wiring, electric trailer brakes, has a back seat, white, TOW ONLY, FAILED SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. **Please note: the SGI Inspection currently provided is only valid for 30 days after the date of the inspection.**, 298,206 km, PROBLEMS: Small oil leak in rear, park brake not holding, power steering cap missing, engine oil over full, hood shocks not holding, 2 rear markers bulbs are missing lenses, large object in right rear outer tread, right front mud flap gone, both head lights partially fogged, hood chips/dent/scratches, front bumper rust/bent, left front fender chips/rusted, left front door dents, roof small rust spots, hole in roof 1 sealed/rusted around antenna, no spare tire/wheel wrench/jack/first aid kit/fire extinguisher, windshield chips, right front seat wore to frame, left front seat hole/worn to frame, interior soiled, poor battery, minor exterior damage.>, As is, Where is	298,206 km	\$13,990	3D6WC78L19G554126
*WD 8-018	Truck 2014 DODGE Ram 5500 ST 2WD, Crew Cab, dump body 7'5"x10' stainless steel 6.7L, Inline 6, diesel auto A/C, tilt, cruise, AM/FM, power heated trailer tow mirrors/ locks/ windows, keyless entry, 2 key fobs tow hooks, grille inserts, sign board WVMBM-3LP, Waltco liftgate, beacons, wigwags, hitch, trailer wiring, OEM trailer brakes, has a back seat , white, TOW ONLY, FAILED SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. **Please note: the SGI Inspection currently provided is only valid for 30 days after the date of the inspection.**, 285,653 km, PROBLEMS: water in fuel warning light, left rear signal/brake light out, font middle seat loose, missing buckle and belt, hood road rash, dent, front bumper pitted, rust, left front fender rust, no wheel wrench/ jack/ first aid kit/ fire extinguisher, left front seat worn/ padding visible, holes in front hump, holes in headliner, mechanical condition of sign board, liftgate, dump body unknown, dump body dents/ fair condition, spare tire mounted in box, windshield chips, poor battery minor exterior damage.> , As is, Where is	285,653 km	\$22,911	3C7WRMEL9EG219460

Item #	Description	Kms	Min Price	Serial Number
No Bid * 7-028	Truck 2014 DODGE Ram 5500 ST RWD, 7'7" X 10' Dump Body, Crew Cab 6.7L Inline 6 diesel auto A/C, tilt, cruise, AM/FM power trailer tow mirrors/windows/locks, key less entry, 2 key fobs, Grille inserts, front tow hooks, side steps, hitch, trailer wiring, OEM trailer brakes, mud flaps and computer stand, has a back seat, stainless steel dump body, sides bent, unknown if operational, right rear corner badly bent, WALTCO liftgate model DT16 liftgate right rear bent, seriously deteriorated, WANCO control board with controls, unknown if operational, slip tank straps, no slip tank, beacons, condition unknown, 3 new fuel filters in back seat, unknown if compatible with unit, white, TOW ONLY, FAILED SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. **Please note: the SGI Inspection currently provided is only valid for 30 days after the date of the inspection.**, 347,976 km, PROBLEMS: No power steering, poor brakes hard to stop, oil leaks, power steering pressure hose leaking, power steering line leaking at reservoir, power steering non operational, 2 marker lamps out, headlamps have water intrusion, hydroboost non operational, rear shocks leaking, service engine light on, A/C non operational, spare tire lose in box, hood chips, front bumper chips and rust spots, left front fender chips, rocker panel road rash, liftgate rusted, left front seat worn frame visible, rear seat small hole, right front seat worn/ripped no jump seat hour meter 4176 hours, no first aid kit, no fire extinguisher, windshield cracked, poor battery, minor exterior damage.>, As is, Where is	347,976 km	\$10,625	3C7WRMEL0EG225941
9,005.00 8-003	Truck 2016 FORD F250 SD 4WD, 8' Box, Crew Cab 6.2L, V8, gas auto A/C, tilt, cruise, AM/FM, power windows/locks, keyless entry 2 key fobs grille inserts, tow hooks, side steps, mud flaps, hitch, trailer wiring, OEM trailer brakes, headache rack with a beacon and wigwags, power trailer tow mirrors, white, TOW ONLY, FAILED SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. **Please note: the SGI Inspection currently provided is only valid for 30 days after the date of the inspection.**, 212,525 km, PROBLEMS: Engine light on, sluggish acceleration, vibration in rear at highway speeds, left rear lower gasket loose, transfer case plug too tight, front wheel alignment out of spec, brake pedal pad worn out, both front headlight side marker bulbs, left front side mirror marker bulb, right rear plate light bulb/housing, left rear tail light assembly broken, bad windshield, left front washer nozzle, front bumper pitted, rear bumper rust spots/dent, left right fender road rash/dents, right rear fender road rash/chips, left doors chips/rust spots, right rear door rust spots, tailgate rusted/dents, no first aid kit/fire extinguisher, mirror left housing cracked, lower part of jump seal missing, holes in dash, poor battery, minor exterior damage.>, As is, Where is	212,525 km	\$8,973	1FT7W2B67GED05454

Item #	Description	Kms	Min Price	Serial Number
15,111.99 * 7-002	Truck 2016 FORD F350 Super Duty, 4WD, 8' box, Crew Cab 6.7L Turbo diesel auto A/C, tilt, cruise, AM/FM, power heated trailer tow mirrors, power windows/locks, keyless entry-2 key fobs Hitch, trailer wiring, OEM Trailer brakes, grille insert, tow hooks, has a back seat, white, TOW ONLY, FAILED SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. **Please note: the SGI Inspection currently provided is only valid for 30 days after the date of the inspection.**, 322,603 km, PROBLEMS: Engine light on, TPMS light on, left front lower ball joint, park brake not working, all tires are miss match, both side mirror marker bulbs, both light side marker bulbs, no rear tail lights, signal lights, brake lights and reverse lights, grille broke, hood dents/right washer nozzle not working, left front fender road rash, left rear fender cracked/road rash/dents, front right fender road rash, right rear fender road rash/rust, holes in front hump, roof scratches, hole in roof 1 sealed, headache rack bent, missing right side wheel covers, missing mudflaps, side steps bent, tailgate badly damaged/missing parts/may not open, spare tire loose in box (may not be compatible with vehicle), no first aid kit/fire extinguisher, windshield cracked, left and right mirror housing broke, poor battery, minor exterior damage.>, As is, Where is	322,603 km	\$9,784	1FT8W3BT5GEB81085
15,111.99 * 7-001	Truck 2016 FORD F350 Super Duty, 4WD, Crew Cab, 8' box 6.7 V8 diesel auto A/C, tilt, cruise, AM/FM, power heated trailer tow mirrors, power windows/locks, keyless entry-1 key fob Grille inserts front wigwags and beacon condition unknown, front tow hooks, side steps, box liner, headache rack, hitch, trailer wiring, OEM trailer brake, has a back seat, deep pan attached inside box 49" x 30" x 1 3/4", white, TOW ONLY, FAILED SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. **Please note: the SGI Inspection currently provided is only valid for 30 days after the date of the inspection.**, 306,482 km, PROBLEMS: Engine/ABS/Trac light on, oil change required, T-case/front Differential dirty, rear brakes at 1mm/rear pads/rotors failed, park brake not holding, front tires miss matched, side mirror mark bulbs, head light side marker bulbs, no plate bulb, spare missing, spare hoist seized, front bumper scratched/pitted, rear bumper dented/bent/pad loose, left rear fender dented, right rear door missing weather strip, roof small rust spots, tailgate badly damaged missing parts/may not open, wheel wrench/jack loose in back seat, no first aid kit/fire extinguisher, windshield cracked, left front mirror housing broke, left front seat ripped/worn/sagging, mudflaps loose, holes in front hump, hole in floor behind left rear seat, poor battery, minor exterior damage.>, As is, Where is	306,482 km	\$9,984	1FT8W3BT5GEB65372

Item #	Description	Kms	Min Price	Serial Number
5,111.11 * 7-007	Truck 2008 GMC Sierra 2500 HD, 4WD, Extended Cab, 8' box 6.0L V8 gas auto A/C, tilt, cruise, AM/FM, 2 keys Mudflaps, front tow hooks, wheel flares, side steps, hitch, trailer wiring, electric trailer brakes, has a back seat, white, TOW ONLY, FAILED SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. **Please note: the SGI Inspection currently provided is only valid for 30 days after the date of the inspection.**, 330,392 km, PROBLEMS: Left front axle, TPMS light is on, oil change due, front lower valance loose, both rails paint worn/dented, box floor has holes drilled/rusted, antenna mast missing-replaced with wire, left head light fogged, hood chips/missing air deflector, both bumpers dent/bent, left rear fenders dents/rust, right rear fenders road rash, left side doors dent/road rash/rust, right side doors road rash/dents, hole in roof 3 sealed, tailgate dented/right lower corner bent, spare tire missing, no first aid kit/fire extinguisher, windshield chips, left front seat worn/foam visible, holes drilled in front hump, rear seat stained/ripped, poor battery, minor exterior damage.>, As is, Where is	330,392 km	\$4,165	1GTHK29K58E210766
4,589.89 8-019	Van 2009 DODGE Grande Caravan SE 2WD 3.3L, V6, gas auto A/C, tilt, cruise, AM/FM/CD, power heated mirrors/ locks/ windows, rear HVAC keyless entry, 2 key fobs, 1 key, silver, TOW ONLY, FAILED SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. **Please note: the SGI Inspection currently provided is only valid for 30 days after the date of the inspection.**, 213,749 km, PROBLEMS: Front brakes, rotors causing brake squeak, rotted and rusted inside, hood paint bubbling/scratches/dents/stain, front bumper scratches, left front fender scratches/ molding loose, right rear fender cracks in paint/ rust, left doors rust/ scratches, right front door dents/ scratches, no first aid kit/ fire extinguisher, windshield chipped, left mirror housing cracked, poor battery and minor exterior damage.>, As is, Where is	213,749 km	\$1,391	2D8HN44E09R681752

Item #	Description	Kms	Min Price	Serial Number
1,100.00 8-008	Van 2007 FORD E350 2WD, wheel base 138 5.4L, V8, gas auto A/C, tilt, cruise, rear HVAC, power front windows/ locks, 2 keys Aftermarket AM/FM (damaged), no rear seat, grey, FOR PARTS ONLY, NO SGI INSPECTION.**THIS VEHICLE IS FOR RECYCLING PURPOSES ONLY AND NOT FOR RESALE. THIS VEHICLE CANNOT BE REGISTERED WITHIN ANY JURISDICTION. **, 169,700 km, PROBLEMS: Right lower ball joint, right outer tie rod, transfer case switch, ABS light on, air bag light, 3rd brake light on, check engine codes B1877 (safety belt, right retractor), B1881 (safety belt left side), P1233 (fuel pump driver) rear rotors, alignment, plate light, hood chips/scratches, both bumpers rusted/chips/scratches, left front fender road rash, left rear fender road rash/chips/dents/missing trim below tailgate doors, right front fender paint poor/dent/road rash/rust, rocker panels road rash/rust, left front door road rash, right side doors road rash/rust/crack/dents/rear right door missing inside handle and trim, head liner holes, missing roof vents, all interior trim broke/missing parts/soiled/warning chime stays on trailer hitch warning, windshield chips, poor battery, minor exterior damage.>, As is, Where is	169,700 km	\$253	1FBSS31L47DB24986
900.00 8-009	Van 2002 FORD Econoline F350, Super Duty 2WD, Chateau 7.3L, V8, diesel auto A/C, tilt, cruise, rear HVAC, AM/FM/CD, power locks/ front windows/ mirrors OEM front bumper, OEM rear cargo doors inside, side steps, hitch, trailer wiring, vehicle used for a laser based road data collection system, inside 24V power inverter, various cables and control panel, exterior various hard mounted equipment, white, FOR PARTS ONLY, NO SGI INSPECTION.**THIS VEHICLE IS FOR RECYCLING PURPOSES ONLY AND NOT FOR RESALE. THIS VEHICLE CANNOT BE REGISTERED WITHIN ANY JURISDICTION. **, 481,666 km, PROBLEMS: right front air bag missing, no air bag warning light, front wheel alignment, remote start non operational, hood chips/scratches, front bumper not OEM, rear bumper paint spots, roof large dent/paint peeling, holes in roof-sealed, tailgate not OEM rusting, missing jack, no first aid kit/fire extinguisher, windshield cracked, both wiper blades worn, left rear seat not secure, poor battery, minor exterior damage.>, As is, Where is	481,666 km	\$261	1FMNE31F62HA43575
REGINA, SaskBuilds and Procurement, SaskSurplus Sales Lot, 500 McLeod Street - Miscellaneous Items and Equipment.				
Contact SaskSurplus 306-787-2062 or 306-798-3306.				
No Bid * 4-101	Box, metal 20"w x 8"d x 16"h, grey, bolted to a removable metal base, hinged lid with a lock but no key. Fair		\$15	171,975
No Bid * 5-102	Box, Metal 20"w x 8"d x 16"h, grey, hinged lid, hole in lid, no lock. Fair		\$15	
No Bid * 7-101	Box, Metal Grey, hinged lid with a hole, lock, no key, 20"w x 8"d x 16"h. Fair		\$15	
No Bid * 7-102	Box, Metal Grey, hinged lid, no lock, 20"w x 8"d x 16"h. Fair		\$15	

Item #	Description	Kms	Min Price	Serial Number
1.01 8-131	Fax Machine, Brother IntelliFAX 2840 Operational (powers on, no noises, no further testing, AS IS), some scratches, wiped/reset, power cord included. Fair		\$1	U63274K2J273358
No Bid 8-173	Headache Rack, Aluminum Westcan 71"w x 22"d x 22"h, with mounting kit (kit may not be complete), removed from a 2015 Silverado. Good		\$75	
No Bid 8-111	Ladder Rack, Metal White, adjustable, with beacon. Fair		\$75	
No Bid 8-112	Platform with Storage, Wood 60"w x 31"d x 12"h, drawer under platform, back seat needs to be removed, custom made to fit behind front seat of a 2009 Chev Silverado extended cab. Good		\$1	
41.00 * 7-103	Seat Covers, Fia TR40 Series Wrangler, fabric Grey/Black, complete set for front 40/20/40 seat, removed from a 2007 Ram Quad Cab 430204, Includes head rest covers. Good		\$40	
No Bid * 7-104	Shelf, Stainless steel 2 shelves with particle board backing, 48 inches long, 48"w x 18"d x 36.5"h, 12 hooks attached to back. Good		\$25	
No Bid 8-121	Tailgate, OEM Chev Silverado, Metal White, slight scratches and dents, maybe compatible with 1999-2005 Silverado 1500, 2500, 3500. Good		\$200	
No Bid * 4-108	Tires, Set of 4 225/60R/16 Sumitomo HTR Enhance L/X. M+S. Manufacture date. Week 50, year 2016. Poor		\$40	
No Bid * 6-106	Tires, Set of 3 225/65R/16, Sumitomo Ice Edge. Snow Flake, M+S Manufacture date. Week 17, year 2017 Good		\$120	
No Bid * 6-178	Tires, Set of 4 225/65R/17, Goodyear Assurance Fuel Max. M+S Manufacture date. Week 22, Year 2018. Poor		\$40	
No Bid * 7-108	Tires, Set of 4 225/65R/16, Sumitomo Ice Edge, Snow flake, M+S Manufacture date. Week 18, year 2017. Fair		\$120	
12.00 * 7-111	Tire, 225/60R/16, Matrix Tour Multi Mile, M+S Manufacture date. Week 50, year 2013. Good		\$10	
No Bid * 7-112	Tires, Set of 4 225/60R/16, Sailum Inspire. M+S Manufacture date. Week 39, year 2019. Fair		\$90	
44.00 8-101	Tires, Set of 4 225/65R/16, Sumitomo Ice Edge, M+S, Snowflake Manufacture date. Week 21, year 2017. Poor		\$40	
188.01 8-102	Tires, Set of 4 225/65R/17, Goodyear Assurance Fuel Max, M+S Manufacture date. Week 30, year 2019. Good		\$160	
155.55 8-103	Tires, Set of 4 225/65R/17, Sumitomo HTR Enhance, M+S Manufacture date. Week 01, year 2020. Fair		\$120	
275.00 8-104	Tires, Set of 4 LT245/75R/16, Bridgestone V-Steel, Rib 265, M+S, Load Range E Manufacture date. Week 30, year 2020. Fair		\$120	

Item #	Description	Kms	Min Price	Serial Number
310.00 8-106	Tires, Set of 4 215/60R/16, Firestone Winterforce 2, M+S, Snowflake Manufacture date. Week 10, year 2017 Excellent		\$200	
177.77 8-107	Tires, Set of 4 225/55R/17, Goodyear Assurance, M+S Manufacture date. Week 48, year 2016. Good		\$160	
177.77 8-108	Tires, Set of 4 225/60R/16, Firestone, All Season, M+S One tire has a patch, manufacture date. Week 35, year 2020. Good		\$160	
No Bid 8-109	Tires, Set of 4 225/65R/16, Firestone All Season, M+S Manufacture date. Week 37, year 2021. Good		\$160	
No Bid 8-110	Tires, Set of 4 225/65R/17, Firestone Weathergrip, M+S, Snowflake Manufacture date. Week 31, year 2020. Poor		\$40	
No Bid 8-113	Tires, Set of 4 215/55R/17, Continental ProContact TX, M+S Manufacture date. Week 43, year 2021. Good		\$160	
No Bid 8-114	Tires, Set of 4 225/65R/16, Firestone All Season, M+S Manufacture date. Week 26, year 2021. Good		\$160	
No Bid 8-115	Tires, Set of 4 225/65R/17, Sumitomo Ice Edge, M+S, Snowflake Manufacture date. Week 24, year 2018. Good		\$160	
210.00 8-116	Tires, Set of 4 215/65R/16, Firestone All Season, M+S Manufacture date. Week 39, year 2021. Good		\$160	
No Bid 8-117	Tires, Set of 4 225/60R/16, Firestone FR710, M+S Manufacture date. Week 45, year 2015. Fair		\$100	
60.00 8-118	Tires, Set of 4 225/65R/16, Artic Claw Winter TXI, M+S, Snowflake 2 tires "fair", 2 tires "poor", manufacture date. Week 22, year 2016. Poor		\$60	
200.00 8-119	Tires, Set of 4 225/65R/16, Firestone Winterforce 2, M+S, Snowflake Manufacture date. Week 03, year 2020. Excellent		\$200	
177.77 8-120	Tires, Set of 4 225/65R/17, Kelly Winter Access, M+S, Snowflake Manufacture date. Week 31, year 2019. Good		\$160	
90.10 8-122	Tires, Set of 4 205/65R/15, Nokian Entyre 2.0, M+S 99HXL, manufacture date. Week 41, year 2016. Good		\$50	
310.00 8-123	Tires, Set of 4 215/60R/17, Sumitomo Ice Edge, Snowflake, M+S Manufacture date. Week 26, year 2018. Excellent		\$200	
212.00 8-124	Tires, Set of 4 225/65R/16, Firestone Winterforce 2, Snowflake, M+S Manufacture date. Week 02, year 2020. Excellent		\$200	
285.71 8-125	Tires, Set of 4 225/65R/17, Bridgestone Blizzack WS80, Snowflake, M+S Manufacture date. Week 01, year 2018. Good		\$160	
No Bid 8-126	Tires, Set of 4 225/65R/16, Firestone All Season, M+S Manufacture date. Week 34, year 2021. Fair		\$120	

Item #	Description	Kms	Min Price	Serial Number
248.70 8-127	Tires, Set of 4 225/65R/16, Firestone Winterforce 2, Snowflake, M+S Manufacture date. Week 03, year 2020. Excellent		\$200	
165.88 8-128	Tires, Set of 4 225/65R/16, Sumitomo Ice Edge, Snowflake, M+S Manufacture date. Week 21, year 2018. Fair		\$120	
250.00 8-129	Tires, Set of 4 225/65R/17, Sumitomo Ice Edge, Snowflake, M+S Manufacture date. Week 17, year 2019. Good		\$160	
155.50 8-174	Tool Box, Aluminum, Enthuze, Saddle, 205103-9-10 70"w x 19"d x 18"h, removed from a 2018 Silverado, 1 key. Good		\$150	
No Bid * 5-106	Topper, ARE, Fiberglass 68.5"w x 83.5"d x 20.5"h, color is Ford Stone Grey with slider side windows, removed from a 2019 Ford F150 XLT Crew Cab, has key unknown if lock works, has 4 hold down clamps. Good		\$1,100	801,410
No Bid * 7-115	Topper, Fiberglass, Range Rider White, side windows open in up direction, locks and 1 key, 61"w x 64"d, beacon on top, mounting bolts included, removed from a 2012 Chev Colorado #437001. Good		\$250	
No Bid * 3-132	File Cabinet, Lateral, metal 36"w x 18"d x 52.5"h, 4-drawer, dents and scratches from ware and tear, lockable with no key, grey. Fair		\$20	
2.00 8-132	Printer, Desktop Hewlett-Packard Color LaserJet CP1215 Operational (powers on, no noises, no further testing, AS IS), some scratches, wiped/reset, power cord included. Fair		\$1	CNAC85N1K2
5.00 8-133	Printer, Desktop Hewlett-Packard Color LaserJet CP1518ni Operational (powers on, no noises, no further testing, AS IS), some scratches, wiped/reset, power cord included. Fair		\$1	CNB0502837
12.25 8-134	Printer, Desktop Hewlett-Packard Color LaserJet CP1525NW Operational (powers on, no noises, no further testing, AS IS), some scratches, wiped/reset, power cord included. Fair		\$1	CNBF347225
1.27 8-135	Printer, Desktop Hewlett-Packard LaserJet P1606DN Operational (powers on, no noises, no further testing, AS IS), some scratches, front panel hinge broken, wiped/reset, power cord included. Fair		\$1	VNB3B23491
1.27 8-136	Printer, Desktop Hewlett-Packard LaserJet P1606DN Operational (powers on, no noises, no further testing, AS IS), some scratches, wiped/reset, power cord included. Fair		\$1	VNB3D81832
*WD 8-137	Printer, Desktop Hewlett-Packard LaserJet P1606DN Operational (powers on, no noises, no further testing, AS IS), some scratches, wiped/reset, power cord included. Fair		\$1	VNB3G17597

Item #	Description	Kms	Min Price	Serial Number
1.00 8-138	Printer, Desktop Hewlett-Packard LaserJet P1606DN Operational (powers on, no noises, no further testing, AS IS), some scratches, wiped/reset, power cord included. Fair		\$1	VNB3G17607
No Bid 8-139	Printer, Desktop Hewlett-Packard LaserJet P1606DN Operational (powers on, no noises, no further testing, AS IS), some scratches, wiped/reset, power cord included. Fair		\$1	VND3C65236
3.00 8-140	Printer, Desktop Hewlett-Packard LaserJet P1606DN Operational (powers on, no noises, no further testing, AS IS), some scratches, wiped/reset, power cord included. Fair		\$1	VND3C91193
No Bid 8-141	Printer, Desktop Hewlett-Packard LaserJet P1606DN Operational (powers on, no noises, no further testing, AS IS), some scratches, wiped/reset, power cord included. Fair		\$1	VND3F89130
2.00 8-142	Printer, Desktop Hewlett-Packard LaserJet P2055dn Operational (powers on, no noises, no further testing, AS IS), some scratches, wiped/reset, power cord included. Fair		\$1	CNBJ648571
No Bid 8-143	Printer, Desktop Hewlett-Packard LaserJet P4015X Operational (powers on, no noises, no further testing, AS IS), some scratches, tiny chunk out of front panel, wiped/reset, power cord included. Fair		\$1	CNDY351744
No Bid 8-144	Printer, Desktop Hewlett-Packard LaserJet P4015X Operational (powers on, no noises, no further testing, AS IS), some scratches, wiped/reset, power cord included. Fair		\$1	CNDY442714
No Bid 8-145	Printer, Desktop Hewlett-Packard LaserJet P4015X Operational (powers on, no noises, no further testing, AS IS), some scratches, wiped/reset, power cord included. Fair		\$1	CNDY817475
No Bid 8-146	Printer, Desktop Hewlett-Packard LaserJet P4015X Operational (powers on, no noises, no further testing, AS IS), some scratches, wiped/reset, power cord included. Fair		\$1	CNDY821651
No Bid 8-147	Printer, Desktop Hewlett-Packard LaserJet Pro M201DW Operational (powers on, no noises, no further testing, AS IS), some scratches, wiped/reset, power cord included. Fair		\$1	VNB3F40437
5.10 8-148	Printer, Desktop Hewlett-Packard LaserJet Pro M201DW Operational (powers on, no noises, no further testing, AS IS), some scratches, wiped/reset, power cord included. Fair		\$1	VNB3F40958
No Bid 8-149	Printer, Desktop Hewlett-Packard LaserJet Pro M201DW Operational (powers on, no noises, no further testing, AS IS), some scratches, wiped/reset, power cord included. Fair		\$1	VNB3G09225

Item #	Description	Kms	Min Price	Serial Number
31.55 8-150	Printer, Desktop Hewlett-Packard LaserJet Pro M203dw Operational (powers on, no noises, no further testing, AS IS), some scratches, wiped/reset, power cord included. Fair		\$1	VNB3G29784
6.01 8-151	Printer, Desktop Hewlett-Packard LaserJet Pro M402dn Operational (powers on, no noises, no further testing, AS IS), some scratches, wiped/reset, power cord included. Fair		\$1	PHBQD69233
6.20 8-152	Printer, Desktop Hewlett-Packard LaserJet Pro M404dn Operational (powers on, no noises, no further testing, AS IS), some scratches, wiped/reset, power cord included. Fair		\$1	PHBB261041
6.20 8-153	Printer, Desktop Hewlett-Packard LaserJet Pro M404dn Operational (powers on, no noises, no further testing, AS IS), some scratches, wiped/reset, power cord included. Fair		\$1	PHBB331908
6.30 8-154	Printer, Desktop Hewlett-Packard LaserJet Pro M404dn Operational (powers on, no noises, no further testing, AS IS), some scratches, wiped/reset, power cord included. Fair		\$1	PHDBB05021
31.55 8-175	Printer, Desktop MFP, Hewlett-Packard LaserJet Pro M227 FDN MFP Operational (powers on, no noises, no further testing, AS IS), some scratches, wiped/reset, power cord included. Fair		\$1	VNB3J18532
31.55 8-176	Printer, Desktop MFP, Hewlett-Packard LaserJet Pro M227 FDN MFP Operational (powers on, no noises, no further testing, AS IS), some scratches, wiped/reset, power cord included. Fair		\$1	VNB3J19590
40.00 8-177	Printer, Desktop MFP, Hewlett-Packard LaserJet Pro M475DN Operational (powers on, no noises, no further testing, AS IS), some scratches, wiped/reset, no power cord. Fair		\$1	CNC8DCSSPM
No Bid 8-178	Printer, Desktop, Hewlett-Packard LaserJet 4350DTN Operational (powers on, no noises, no further testing, AS IS), some scratches, wiped/reset, power cord included. Fair		\$1	CNRXB92843
No Bid 8-179	Printer, Desktop, Hewlett-Packard LaserJet 4350TN Operational (powers on, no noises, no further testing, AS IS), some scratches, wiped/reset, power cord included. Fair		\$1	CNRXB86421

Item #	Description	Kms	Min Price	Serial Number
15.00 8-180	Printer, Desktop, Hewlett-Packard LaserJet Enterprise 600 M602X Operational (powers on, no noises, no further testing, AS IS), some scratches, Small hole/indent on top panel, right side panel on bottom paper tray sticking out, wiped/reset, power cord included. Fair		\$1	CNCCFCF0K3
15.00 8-181	Printer, Desktop, Hewlett-Packard LaserJet P1102w Operational (powers on, no noises, no further testing, AS IS), some scratches, wiped/reset, power cord included. Fair		\$1	VNB3V45540
No Bid 8-182	Printer, Desktop, Hewlett-Packard LaserJet P1606DN Operational (powers on, no noises, no further testing, AS IS), some scratches, wiped/reset, power cord included. Fair		\$1	VNB3M11680
1.00 8-183	Printer, Desktop, Hewlett-Packard LaserJet Pro M201DW Operational (powers on, no noises, no further testing, AS IS), some scratches, wiped/reset, power cord included. Fair		\$1	VNB3F89195
31.55 8-184	Printer, Desktop, Hewlett-Packard LaserJet Pro M203dw Operational (powers on, no noises, no further testing, AS IS), some scratches, wiped/reset, power cord included. Fair		\$1	VNB5J02824
No Bid 8-155	Printer, Hewlett-Packard Color LaserJet 5550DTN Floor-model with wheels, operational (powers on, no noises, no further testing, AS IS), some scratches, wiped/reset, power cord included. Printer display shows, "Clean fuser input then replace black cartridge". Fair		\$1	JPDC522082
No Bid 8-156	Printer, Hewlett-Packard LaserJet 9050DN Floor model printer with wheels, operational (powers on, no noises, no further testing, AS IS), some scratches, wiped/reset, power cord included. Fair		\$1	JPRL8C3080
1.27 8-157	Printer, Large Desktop Hewlett-Packard Color LaserJet 3800DTN Operational (powers on, no noises, no further testing, AS IS), some scratches, wiped/reset, power cord included. Fair		\$1	CNYCH54134
11.27 8-158	Printer, Large Desktop Hewlett-Packard Color LaserJet CP4025 Operational (powers on, no noises, no further testing, AS IS), some scratches, wiped/reset, power cord included. Fair		\$1	JPDCFBH05Q
38.75 8-159	Printer, Large Desktop Hewlett-Packard Color LaserJet CP4025DN Operational (powers on, no noises, no further testing, AS IS), some scratches, wiped/reset, power cord included. Fair		\$1	JPBCCD602C

Item #	Description	Kms	Min Price	Serial Number
No Bid 8-160	Printer, Large Desktop Hewlett-Packard LaserJet Enterprise M651 DN Operational (powers on, no noises, no further testing, AS IS), some scratches, wiped/reset, power cord included. Fair		\$1	JPCCJ2K0GN
52.56 8-161	Printer, Multi Functional Desktop Hewlett-Packard Color LaserJet Pro M475DN MFP Operational (powers on, no noises, no further testing, AS IS), some scratches, wiped/reset, power cord included. Fair		\$1	CNB8D64S6Q
9.00 8-162	Printer, Multi Functional Desktop Hewlett-Packard LaserJet Pro 400 MFP M425DN Operational (powers on, no noises, no further testing, AS IS), some scratches, wiped/reset, power cord included. Fair		\$1	CNB6D5G0LB
9.00 8-163	Printer, Multi Functional Desktop Hewlett-Packard LaserJet Pro 400 MFP M425DN Operational (powers on, no noises, no further testing, AS IS), some scratches, wiped/reset, power cord included. Fair		\$1	CND8FCXDV8
10.00 8-164	Printer, Multi Functional Desktop Hewlett-Packard LaserJet Pro M1536 DNF MFP Operational (powers on, no noises, no further testing, AS IS), some scratches, wiped/reset, power cord included. Fair		\$1	CNG8FDP2SW
10.00 8-165	Printer, Multi Functional Desktop Hewlett-Packard LaserJet Pro M225DN MFP Operational (powers on, no noises, no further testing, AS IS), some scratches, wiped/reset, power cord included. Fair		\$1	CNB9H25CWP
9.00 8-166	Printer, Multi Functional Desktop Hewlett-Packard LaserJet Pro M225DN MFP Operational (powers on, no noises, no further testing, AS IS), some scratches, wiped/reset, power cord included. Fair		\$1	CNB9H7P6L2
9.00 8-167	Printer, Multi Functional Desktop Hewlett-Packard LaserJet Pro M225DN MFP Operational (powers on, no noises, no further testing, AS IS), some scratches, wiped/reset, power cord included. Fair		\$1	CNB9J5C2J3
42.22 8-168	Printer, Multi Functional Desktop Hewlett-Packard LaserJet Pro M276nw Operational (powers on, no noises, no further testing, AS IS), some scratches, wiped/reset, power cord included. Fair		\$1	CNF8G1Q05K
20.00 8-169	Printer, Multi Functional Desktop Hewlett-Packard LaserJet Pro M426FDN MFP Operational (powers on, no noises, no further testing, AS IS), some scratches, wiped/reset, power cord included. Fair		\$1	PHB8H8Y37V
20.00 8-170	Printer, Multi Functional Desktop Hewlett-Packard LaserJet Pro M426FDN MFP Operational (powers on, no noises, no further testing, AS IS), some scratches, wiped/reset, power cord included. Fair		\$1	PHB8J340DJ
16.00 8-171	Printer, Multi Functional Desktop Hewlett-Packard LaserJet Pro M428FDW MFP Operational (powers on, no noises, no further testing, AS IS), some scratches, wiped/reset, power cord included. Fair		\$1	MXBPN7Y22F

Item #	Description	Kms	Min Price	Serial Number
25.00 8-172	Printer, Multi Functional Desktop Hewlett-Packard LaserJet Pro M428FDW MFP Operational (powers on, no noises, no further testing, AS IS), some scratches, wiped/reset, power cord included. Fair		\$1	MXBPN7Z15H

Item #	Description	Kms	Min Price	Serial Number
BLACKSTRAP PROVINCIAL PARK, Parks Culture & Sport, Call for Directions				
Contact Allyssa Danchak 306-229-1656, allyssa.danchak@gov.sk.ca or Sean Antoniuk 306-371-1616				
1,320.57	8-656	Car 2007 CHEVROLET Cobalt LT FWD 2.2L, inline 4, gas auto A/C, tilt, cruise 195/60R 15, white, TOW ONLY, NO SGI Inspection. It is unknown if any repairs or safety concerns exist (if any). Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs if required. , unknown, km, PROBLEMS: Does not have a catalytic converter, motor, transmission, tires, brakes, battery, exterior, exhaust, windshield washer, wipers, lights, mirrors and horn all in unknown condition., As is, Where is	unknown, km	\$1 1G1AL55F177357087
1,525.60	8-659	Car 2009 CHRYSLER Sebring LX 2WD 2.4L, V6, gas auto A/C, tilt, cruise tire size 215/65 R16, white, TOW ONLY, NO SGI Inspection. It is unknown if any repairs or safety concerns exist (if any). Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs if required. , unknown, km, PROBLEMS: Does not have a catalytic converter, motor, transmission, tires, brakes, battery, exterior, exhaust, windshield washer, wipers, lights, and horn all in unknown condition., As is, Where is	unknown, km	\$1 1C3LC46BX9N573450
1,567.89	8-658	Truck 2008 DODGE 2500 4WD, Quad Cab 5.7L, V8, gas auto A/C, tilt, cruise LT 245 75/17, running boards, white, TOW ONLY, NO SGI Inspection. It is unknown if any repairs or safety concerns exist (if any). Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs if required. , 270, 294 km, PROBLEMS: Does not have a catalytic converter, body exterior damage, rust, interior worn, dirty, left side mirror broken, motor, transmission, tires, brakes, battery, exhaust, windshield washer, wipers, lights and horn all in unknown condition., As is, Where is	270, 294 km	\$1 3D7KS28D38G226889
700.00	8-657	Truck 2007 DODGE Dakota 4WD, Club Cab 3.7L, V6, gas auto A/C, tilt, cruise LT 245/75/16, chrome toolbox, unknown if toolbox has keys or if locks work, white, TOW ONLY, NO SGI Inspection. It is unknown if any repairs or safety concerns exist (if any). Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs if required. , 253, 269 km, PROBLEMS: Does not have a catalytic converter, 4 wheel drive non operational, body exterior and paint have rust, motor, transmission, tires, brakes, battery, exhaust, windshield washer, wipers, lights and horn all in unknown condition., As is, Where is	253, 269 km	\$1 1D7HW22K67S232392
7,777.77	8-661	Truck 2016 DODGE RAM 2500 4WD 6.7L, turbo inline 6, diesel `auto A/C, tilt, cruise Headache rack, LT 265/71R 17, white, TOW ONLY, NO SGI Inspection. It is unknown if any repairs or safety concerns exist (if any). Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs if required. , 311, 651 km, PROBLEMS: Does not have a catalytic converter, transmission needs repair, body exterior minor damage, paint some damage, interior in fair condition, motor, tires, battery, exhaust, windshield washer, wipers, lights, mirrors and horn all in unknown condition., As is, Where is	311, 651 km	\$1 3C6UR5HL9GG104082

Item #	Description	Kms	Min Price	Serial Number
1,214.16 8-655	Truck 2000 FORD F250 SuperDuty Super Cab 5.4L, V8, gas auto A/C, tilt, cruise LT 235/85R 16, running boards, headache rack, white, TOW ONLY, NO SGI Inspection. It is unknown if any repairs or safety concerns exist (if any). Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs if required. , 281,704 km, PROBLEMS: Does not have a catalytic converter. Motor, transmission, tires, brakes, battery, exterior, exhaust, lights, mirrors and horn all in unknown condition. Windshield washer and wipers, paint, and interior in fair condition., As is, Where is	281,704 km	\$1	1FTNX21L4YEC25946
1,111.00 8-660	Van 2012 DODGE Grand Caravan, SE 2WD 3.6L, 4 cylinder, gas auto A/C, tilt, cruise 216/70R 15, red, TOW ONLY, NO SGI Inspection. It is unknown if any repairs or safety concerns exist (if any). Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs if required. , unknown, km, PROBLEMS: Does not have a catalytic converter, motor, transmission, tires, brakes, battery, exterior, exhaust, windshield washer, wipers, lights, mirrors and horn all in unknown condition., As is, Where is	unknown, km	\$1	2C4RDGBG5CR272147
CANDLE LAKE PROVINCIAL PARK, Parks Culture and Sport, Call for Directions				
Contact Janelle Franc 306-929-8401, janelle.franc@gov.sk.ca				
1,749.49 * 7-548	Car 2008 CHEVEROLET Impala LS 2WD 3.5L, V6 gas auto AC, cruise, AM/FM 3 speed, GVW 2057kg, single tire, tire size, 225 60/R15 4 ply, white, TOW ONLY, NO SGI Inspection. It is unknown if any repairs or safety concerns exist (if any). Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs if required. , 232,161 km, Recent Repairs: PROBLEMS: Motor, brakes, battery, body, frame, paint, windshield, windshield wipers and horn are all in poor condition, may need batteries to start, minor exterior damage.> , As is, Where is	232,161 km	\$500	2G1WB58K481352045
930.41 * 7-540	Car 2002 CHEVEROLET Malibu 2WD 3.1L, V6 gas auto A/C, AM/FM, heated mirrors, power locks 3 speed, GVW 1385 kg, tire size 215/60R15, green, TOW ONLY, NO SGI Inspection. It is unknown if any repairs or safety concerns exist (if any). Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs if required. , 203,535 km, Recent Repairs: PROBLEMS: Motor, brakes, battery, body, frame, paint, windshield, windshield wipers and horn are all in poor condition, may need batteries to start, minor exterior damage.> , As is, Where is	203,535 km	\$500	1G1ND52J32M632377

Item #	Description	Kms	Min Price	Serial Number
535.00 * 7-566	Car 2006 CHRYSLER Sebring, Touring 2WD, 4 door 2.7L, V6, gas manual AC, AM/FM, CD player 3 speed, GVW 1917 kg, single tire, tire size, 205 60/R16, 4 ply, white, TOW ONLY, NO SGI Inspection. It is unknown if any repairs or safety concerns exist (if any). Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs if required. , 179,098 km, PROBLEMS: Motor, brakes, battery, body, frame, paint, windshield, windshield wipers and horn are all in poor condition, may need batteries to start, minor exterior damage.> , As is, Where is	179,098 km	\$500	1C3EL56R06N261127
130.00 * 7-567	Van 1994 PLYMOUTH Voyager 2WD 2.5L, inline 4, gas auto 3 speed, single tire, tire size, 195 75/R14, 3 ply, white, TOW ONLY, NO SGI Inspection. It is unknown if any repairs or safety concerns exist (if any). Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs if required. , 208,592 km, PROBLEMS: Motor, brakes, battery, body, frame, paint, windshield, windshield wipers and horn are all in poor condition, may need batteries to start, minor exterior damage.> , As is, Where is	208,592 km	\$100	2P4GH25K2RR666028
KENOSEE LAKE, Parks Culture & Sport, Box 220 Kenosee Lake				
Contact Leigh Potter 306-577-7810, leigh.potter@gov.sk.ca				
12,000.00 8-632	Tractor 1990 DEUTZ-ALLIS 7110 Front Wheel Assist 6.1L, Air cooled inline 6, diesel manual A/C, heat, 3 point hitch Leon 790 loader with grapple, 2 differentials, 20 speed, GVW 10,670 lbs, tire size 460/85R38, green, TOW ONLY, NO SGI Inspection. It is unknown if any repairs or safety concerns exist (if any). Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs if required. , 7,430 hrs, Recent Repairs: Alternator replaced at 7110 hrs, starter solenoid replaced 2021 PROBLEMS: Blowby from crankcase vent tube, engine lacks power, not used since 2021. hydraulic pumps worn out, loader is detached with grapple, air seat leaks, motor condition is unknown, battery is in poor condition, left mirror is broken., As is, Where is	7,430 hrs	\$10,500	74,387,008
KINDERSLEY, Agriculture, 1120-608 12th Avenue East				
Contact Harpreet kaur 306-463-5513, Harpreet.kaur2@gov.sk.ca				
No Bid 8-685	Camcorder, Canon, SX110 IS Black, 10x optical zoom power, memory cleared, no cassettes, unknown if operational. Good		\$1	1
No Bid 8-686	Camcorder, Canon, Vixia HF G20 Black, memory cleared, no cassettes, no battery charger, comes with a bag, unknown if operational. Good		\$1	1

Item #	Description	Kms	Min Price	Serial Number
LA RONGE, Saskatchewan Public Safety Agency, Land Operations, 800 Poirier St				
Contact Amelick Halkett 306-425-6651, amelick.halkett@gov.sk.ca				
1,789.00 * 7-528	Truck 1998 DODGE Ram 1500, Crew Cab 2WD, 8' Box 5.2L, V8, gas auto A/C, tilt, cruise, manual windows Standard differential, 6 speed, GVW 3334kg, single tire, tire size LT245/75R16, blue, TOW ONLY, NO SGI Inspection. It is unknown if any repairs or safety concerns exist (if any). Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs if required. , 238,135 km, Recent Repairs: Replaced drivers side window 2018 Needs battery, wiper blader need replacing, paint chipped and scratched, body exterior minor rust paint chips, minor exterior damage.>. , As is, Where is	238,135 km	\$500	3B7HC12Y5WG189414
MAPLE CREEK, Highways, Service St. (Highways Yard) or 500 HWY 21 N				
Contact Lorne Fiddler 306-778-8359, lorne.fiddler@gov.sk.ca or Tayler Sanderson, tayler.sanderson@gov.sk.ca				
3,050.00 8-548	Trailer 1987 ARMCO Flat Deck Tandem axle, single tire, tire size 14 x 24 12 ply, yellow, , , , As is, Where is		\$500	2AHPU76P8HZ000063
MELVILLE, Saskatchewan Crop Insurance Corporation, 484 Prince William Dr				
Contact Lindsey D. Pringle 639-398-2289, lindsey.pringle@scic.ca				
No Bid * 7-561	Fall Protection Lanyards, Lot of 3 Yellow. New- Unused		\$50	
No Bid * 7-560	Fall Protection Harnesses, Lot of 6 3 XXL, 3 small. New- Unused		\$50	
MOOSE JAW, Highways, 1 km south of Moose Jaw on Highway #2.				
Contact Al Froehlich 306-694-3775, allan.froehlich@gov.sk.ca or Tara Watson 306-694-3773, tara.watson@gov.sk.ca				
No Bid * 5-551	Packer/Roller 1979 Massey SP912 Self propelled roller Ford 300GF, 118hp, inline 6, gas Hydrostatic Tire size 7.50/15, 12 ply, yellow, , 4454 hrs, PROBLEMS: 2 flat tires, valve cover leak, leak at distributor, water holding tank rusty with holes, steering pump leak., As is, Where is	4454 hrs	\$1,500	335
122.00 8-666	Snow Plow Attachment, 1977, Frink Roll Over 12 foot. Broken Repairable		\$1	17,197
121.00 8-667	Snow Plow Attachment, Roll Over 11 foot Broken Repairable		\$1	R08-15766
NORTH BATTLEFORD, SaskBuilds and Procurement, Accommodations, 1 Jersey St (Sask Hosp).				
Contact Dan Nahirney 306-440-4144, dan.nahirney@gov.sk.ca.				
No Bid * 1-849	Water Meter, Neptune Tru/Flo 6 inch Compound Meter 5 years old with 5 years warranty left, comes with strainer and TRICONE 420, TRICON E (4-20MA) XMITTERS, operational. Good		\$1	
No Bid * 1-850	Water Meter, Neptune Tru/Flo 6 inch Compound Meter 5 years old with 5 years warranty left, comes with strainer and TRICONE 420, TRICON E (4-20MA) XMITTERS, operational. Good		\$1	

Item #	Description	Kms	Min Price	Serial Number
OUTLOOK, Agriculture, 410 Saskatchewan Ave. West.				
Contact Tammie Wood 306-867-5500, tammie.wood@gov.sk.ca				
225.00	8-687	Chairs, Lot of 10 Boardroom Black, faux leather, 5 castors, with arms. Good	\$20	
No Bid	8-688	Hutch, Pepperdust 72 1/8"w x 17 5/8"d x 42"h, 4 doors, 1 shelf. Good	\$1	
No Bid	8-689	Hutch, Pepperdust 72 1/8"w x 17 5/8"d x 42"h, 4 doors, 1 shelf. Good	\$1	
PRINCE ALBERT, Corrections Policing & Public Safety, 3021 - 1st Ave W				
Contact Don Balan 306 961-8232, donald.balan@gov.sk.ca or Dean Schmalz dean.schmalz@gov.sk.ca				
5.80	8-549	Container, Aervoid 5 gallon. Poor	\$1	
No Bid	8-550	Container, Lot of 9 Stainless Steel 9"w x5"d x6"h, 1 gallon. Poor	\$1	
8.80	8-551	Convection Oven, Bakers Pride, Single Unknown if operational, 208v. Poor	\$1	
8.80	8-552	Convection Oven, Bakers Pride, Single Unknown if operational, 208v. Poor	\$1	
8.80	8-553	Convection Oven, South Bend Marathon Gold Single Unknown if operational, 30"w x30"d x29"h, 208v. Poor	\$1	
12.88	8-554	Convection Oven, Southbend, Marathon Gold Double Unknown if operational, 30"w x30"d x64"h, 208v. Poor	\$1	
12.88	8-555	Convection Oven, Southbend, Marathon Gold Double Unknown if operational, 30"w x30"d x64"h, 208v. Poor	\$1	
12.88	8-556	Convection Oven, Southbend, Marathon Gold Double Unknown if operational, 30"w x30"d x64"h, 208v. Poor	\$1	
12.88	8-557	Convection Oven, Southbend, Marathon Gold Double Unknown if operational, 30"w x30"d x64"h, 208v. Poor	\$1	
12.88	8-558	Convection Oven, Southbend, Marathon Gold Single Unknown if operational, 30"w x30"d x29"h, 208v. Poor	\$1	
12.88	8-559	Convection Oven, Southbend, Marathon Gold Single Unknown if operational, 30"w x30"d x29"h, 208v. Poor	\$1	
12.88	8-560	Convection Oven, Southbend, Marathon Gold Single Unknown if operational, 30"w x30"d x29"h, 208v. Poor	\$1	
12.88	8-561	Convection Oven, Southbend, Marathon Gold Single Unknown if operational, 30"w x30"d x29"h, 208v. Poor	\$1	
12.88	8-562	Convection Oven, Southbend, Marathon Gold Single Unknown if operational, 30"w x30"d x29"h, 208v. Poor	\$1	
12.88	8-563	Convection Oven, Southbend, Marathon Gold Single Unknown if operational, 30"w x30"d x29"h, 208v. Poor	\$1	
12.88	8-564	Convection Oven, Southbend, Marathon Gold Single Unknown if operational, 30"w x30"d x29"h, 208v. Poor	\$1	

Item #	Description	Kms	Min Price	Serial Number
12.88 8-565	Convection Oven, Southbend, Marathon Gold Single Unknown if operational, 30"w x30"d x29"h, 208v. Poor		\$1	
12.88 8-566	Convection Oven, Southbend, Marathon Gold Single Unknown if operational, 30"w x30"d x29"h, 208v. Poor		\$1	
12.88 8-567	Dishwasher, Lot of 2 Frigidaire, FBD Unknown if operational, 2400w. Poor		\$1	
12.88 8-568	Dishwasher, Lot of 2 Frigidaire, FBD Unknown if operational, 2400w. Poor		\$1	
12.88 8-569	Dishwasher, Lot of 2 Frigidaire, FBD Unknown if operational, 2400w. Poor		\$1	
12.88 8-570	Dishwasher, Lot of 2 Frigidaire, FBD Unknown if operational, 2400w. Poor		\$1	
12.88 8-571	Dishwasher, Lot of 2 Frigidaire, FBD Unknown if operational, 2400w. Poor		\$1	
12.88 8-572	Dishwasher, Lot of 2 Frigidaire, FBD Unknown if operational, 2400w. Poor		\$1	
12.88 8-573	Dishwasher, Lot of 2 Frigidaire, FBD Unknown if operational, 2400w. Poor		\$1	
12.88 8-574	Dishwasher, Lot of 2 Frigidaire, FBD Unknown if operational, 2400w. Poor		\$1	
No Bid 8-575	Dishwasher parts, EBD 2400 W Assorted Poor		\$1	
28.88 8-576	Food Cart, Stainless Steel With wheels. Poor		\$1	
28.88 8-577	Food Cart, Stainless Steel With wheels. Poor		\$1	
3.00 8-578	Food Container, Cambro, insulated, plastic 2 gallon. Poor		\$1	
667.67 8-579	Hydro Brush, Arieas, Subaru 9.5hp motor Needs new battery. Good		\$50	
750.00 8-580	Loader Fork, Clark With frame, yellow. Poor		\$1	
8.88 8-581	Pot, Aluminum 16"dia x 15 1/2" deep. Poor		\$1	
8.88 8-582	Pot, Aluminum 5 gallon. Poor		\$1	
12.69 8-583	Pot, Stainless Steel 5 gallon. Poor		\$1	
76.00 8-584	Pressure Washer, Electric, Baldor motor No pressure, engine works. Poor		\$1	
12.88 8-585	Thermal Dispenser, Aervoid 2 gallon. Poor		\$1	
12.88 8-586	Thermal Dispenser, Aervoid, stainless steel 10 gallon. Poor		\$1	
12.88 8-587	Thermal Dispenser, Aervoid, stainless steel 3 gallon. Poor		\$1	

Item #	Description	Kms	Min Price	Serial Number
PRINCE ALBERT, Highways, Northern Operations, 81 N. Industrial Dr.				
Contact Cory Palko 306-960-5152, cory.palko@gov.sk.ca.				
5,239.00 * 7-555	Trailer, 1996JC JC40Flat Deck Tandem axle, dual tire, tire size 255/70R22.5, GVW 40000 LbsyellowPROBLEMS: Tires poor. As is, Where is		\$5,000	2J9C3X4B7SK001029
5,266.00 * 7-554	Trailer , 1995 JC40Flat Deck Tandem axle, dual tire, tire size 255/70R22.5, GVW 40000 LbsyellowPROBLEMS: Tires poor. As is, Where is		\$5,000	2J9C3X4B3SK001030
6.00 * 7-508	Grader Fenders, Set of 2 John Deere, 2023, Plastic Rear, left and right, black Good		\$1	
6.00 * 7-509	Grader Fenders, Set of 2 John Deere, 2023, Plastic Rear, left and right, black Good		\$1	
PRINCE ALBERT, Saskatchewan Public Safety Agency, 2120 Central Ave N				
Contact Bob Northey 306-930-8719, bob.northey@gov.sk.ca or Brent Zbaraschuk 306-940-7075				
2,889.88 8-638	Piping, Irrigation, 6"dia x 30' Equipment has not been used for the past 3+ years. Good		\$1	
3,889.88 8-640	Trailer, 1974, Homebuilt, with 6"dia x 30' Irrigation Piping (75+ per trailer) 8' x 30' double axel triler with , 1 Hercules ST235/80/R16 in good shape - BF Goodrich 31x10.5/R16/16.5LT in fair shape, 1 Ranger AT 33x12.5?R16/16.5LT, and one 16' rim with no tire, equipment and trailer have not been used for the past 3+ years. Good		\$2,500	904,986
5,678.00 8-642	Trailer, 1974, Homebuilt, with 6"dia x 30' Irrigation Piping (75+ per trailer) 8' x 30' triple axel, 3 Dayton Timberline 9.5R16.5 LT M/S good shape, 1 BAJA Widetrack 9.5R16.5 LT M/S good shape , 1 Powerking 9.5R16.5 LT good shape, 1 Bridgestone 9.5R16.5 LT good shape, equipment and trailer have not been used for the past 3+ years. Good		\$2,500	904,995
5,678.00 8-641	Trailer, 1974, transport, with 6"dia x 30' Irrigation Piping (75+ per trailer) 8' x 30' triple axel, with 2 Bridgestone LT235/85/R16 fair shape - 2 BAJA A/S Lt235/85/R16 Fair with slight checking, 2 BAJA Lt235/85/R16 good shape, equipment and trailer have not been used for the past 3+ years. Good		\$2,500	SASK90577000641
3,889.88 8-639	Trailer, 1988, transport, with 6"dia x 30' Irrigation Piping (75+ per trailer) 8' x 30' double axel triler with 2 Hercules ST235/80/R16 in good shape - 1 Powerking 9.5R16LT in good shape - 1 Wilderness 31x10.5/50/R16 off of rim, equipment and trailer have not been used for the past 3+ years. Good		\$2,500	2AHT425M3JZ000101
PRINCE ALBERT, Saskatchewan Public Safety Agency, 2120 Central Ave N				
Contact Camille Harrison, 306-940-6158, camille.harrison@gov.sk.ca or Mike McColgan 306-940-8587, michael.mccolgan2@gov.sk.ca				
No Bid 8-643	Chair, Lot of 2 Office, swivel 5 caster, with adjustable arms, blue. Poor		\$1	SERM 10-28-26

Item #	Description	Kms	Min Price	Serial Number
REGINA, Agriculture, 3085 Albert Street				
Contact Jennifer Mackinnon 306-787-2150, jennifer.mackinnon@gov.sk.ca				
No Bid 8-700	Decorations, Lot of 5 Wooden 10" w x 10" h, painted flowers, with curved front. Good		\$1	
21.50 8-701	Printer Cabinet, Laminated 21 1/4" w x 19" d x 31" h, one large open shelf on top, six open shelves in the middle, bottom two doors with magnetic closure. Fair		\$1	
21.00 8-702	Round Table, Wooden 53 1/2" dia x 29" h, water stains/scars on top. Fair		\$1	
REGINA, Agriculture, 226-3085 Albert Street				
Contact Jennifer Macwan 306-798-0365, jennifer.macwan2@gov.sk.ca				
No Bid 8-703	TV, Lot of 3 Memorex 14" w x 14" h, black, unknown if operational. Fair		\$1	
No Bid 8-704	Conference Phone, Lot of 5 Polycorn Included all cords, extensions and associated parts, unknown if operational. Broken Repairable		\$1	
REGINA, Agriculture, 329-3085 Albert Street.				
Contact Yvonne Bachelu 306-787-4325, yvonne.bachelu@gov.sk.ca				
41.00 8-694	Chairs, Lot of 3 Fabric, plastic Blue, height adjustable, with armrests, 5 castors. Fair		\$1	
41.00 8-695	Chairs, Lot of 3 Fabric, plastic Dark Blue, with armrests, 5 castors. Fair		\$1	
No Bid 8-696	Printing Calculator, AT&T, 12-digit, plastic 7" w x 8" d, Grey, 12v plug-in adapter or 4 AA batteries, does not print, operational. Fair		\$1	
10.00 8-697	Printing Calculator, Lot of 5 Sharp, EL-2615PIII 8.5" w x 12" d x 3.25" h, 12 Digit, built-in plug-in, prints, operational. Good		\$1	9D001181
No Bid 8-698	Printing Calculator, Texas Instruments, T1-5045 SV 8" w x 9" d, built-in plug-in, 12 Digit, 2 color super view, does not print, operational. Fair		\$1	139118 T-1196D
5.10 8-699	Speakers, 1 set Harmon/Kardon, HK206 8" h, black, aux plug-in, operational. Good		\$1	
REGINA, Corrections Policing and Public Safety 217 College W - 3737 Wascana Parkway				
Contact Cheryl McLean Keil, 306-787-4200, cheryl.mcleankeil@gov.sk.ca or Melanie Hart 306-787-8871, melanie.hart@gov.sk.ca				
21.00 * 6-509	Teleprompter, Tripod/phone/camera mounted Includes cloth hood for protection. New- Unused		\$20	
REGINA, Energy and Resources, 201 Dewdney Ave E				
Contact Kelly Laverdiere 306-787-2622, Kelly.Laverdiere@gov.sk.ca or Shelby Lamontagne 306-787-1178 shelly.lamontagne@gov.sk.ca				
18.00 8-501	Bulletin Boards, Lot of 2 Aluminum, cork, polyester 22" w x 70" d x 1/2" thick, grey, cork is scratched on back of one.		\$3	
No Bid 8-502	Chairs, Lot of 23 Folding, metal 20" w x 17" d x 30" h, grey, paint chips, dented and scuffed. some held together with duct tape. Fair		\$5	
81.00 8-503	Desk, Metal, wood 60" w x 30" d x 29" h, beige and brown. Fair		\$5	
61.00 8-504	Desk, Wood, vinyl 24" w x 36" d x 28" h, brown, some rust on right side. Fair		\$2	
No Bid 8-505	Desk, Wood 34" w x 60" d x 31" h, brown, stain on top, some scuffs and scratches. Fair		\$5	

Item #	Description	Kms	Min Price	Serial Number
No Bid 8-506	Desk , Metal L - shaped side only, 42"w x 20"d x 29"h, beige, has a few Scuff marks on the base, does not come with other half of desk.		\$1	
61.00 8-507	Desk , Wood, laminate 34"w x 60"d x 31"h, brown, middle left drawer doesn't work, some chips. Fair		\$5	
No Bid 8-508	Desk Attachment, Wood 38.5"w x 14"d x 29"h, does not have legs, black . Fair		\$1	
No Bid 8-509	Desk Mount, Adjustable for keyboard, mouse 26"w x 27"d x 3h, black. Fair		\$1	
52.50 8-510	Drafting Ruler, Aluminum 65"w x 4"d, with 2" wood case Fair		\$5	
100.00 8-511	File Cabinet, Index card, metal 30"w x 44"d x 74"h, grey, bottom of door is dented. Fair		\$1	
No Bid 8-512	File Cabinet, Metal, 2 drawer, vertical 27"w x 30"d x 27"h, grey, no key, unknown if locks are operational. Fair		\$1	
No Bid 8-513	File Cabinet, Metal, lateral, 3 drawer 18"w x 36"d x 40.5"h, beige, masking tape covering unit, rust stains on top, locks, no key. Fair		\$1	
26.82 8-514	File Cabinet, Metal, lateral, 4 drawer 36"w x 19"d x 53"h, paint scuffs and tape residue, beige, locks, no key. Fair		\$1	
No Bid 8-515	File Cabinets, Lot of 5 4 drawer, vertical, metal 20"w x 28"d x 51"h, beige and brown, bottom drawer dented and doesn't open on one unit. Some scuffs and small dents on other units, no lock or keys. Broken Repairable		\$1	
No Bid 8-516	File Cabinets, Lot of 5 4 drawer, vertical, metal 20"w x 28"d x 51"h, beige and grey, some scuffs and small dents, all drawers open, some do not lock. Broken Repairable		\$1	
No Bid 8-517	File Cabinets, Lot of 2 4 drawer, vertical, metal 20"w x 28"d x 51"h, brown, missing hardware and tracks, no lock or leys. Fair		\$2	
10.00 8-518	File Cabinets, Lot of 5 4 drawer, vertical, metal 20"w x 28"d x 51"h, green and brown, bottom drawer dented and doesn't open on one unit, some scuffs and small dents, some do not lock. Broken Repairable		\$1	
No Bid 8-519	File Cabinets, Lot of 15 Metal 50"w x 15"d x 15"h, brown, bottom right unit is missing front door, unknown if all are lockable or have keys. Fair		\$1	
No Bid 8-520	File Folders, Lot of approx. 50-60 Plastic 15"w x 16"d x 3"h, orange and black. Fair		\$1	
6.00 8-521	Index Card Box, Core-Steel 16"w x 15"d x 6h, grey. Fair		\$1	
No Bid 8-522	Light Bar, Metal 25"w x 4"d x 1'5"h, black, non operational. Fair		\$1	
*MT 8-523	Map File Cabinet, Flat, Hamilton 55"w x 43"d x 51"h, grey and silver. Fair		\$5	
*MT 8-524	Map File Cabinet, Lot of 2 Flat, metal 54"w x 39"d x 31"h, grey, some light scuffs and tape reside. Fair		\$2	
42.18 8-525	Map File Cabinet, Flat, metal 54"w x 39"d x 31"h, drawers on the left side do not open, middle drawer right side is broken, grey. Fair		\$2	

Item #	Description	Kms	Min Price	Serial Number
100.00 8-526	Map File Cabinet, Flat, metal with fabric protectors 54"w x 42"d x 36"h, grey, dented, bent, some drawers do not open. Fair		\$1	
101.37 8-527	Map File Cabinet, Flat, metal with fabric protectors 55"w x 45d x 48"h, grey, top handle is bent. Fair		\$5	
7.00 8-528	Map Stand, Wood, 4 caster 38.5"w x 14"d x 29"h, brown. Fair		\$6	
7.00 8-529	Map Stand, Lot of 2 Wood, 4 caster 72"w x 36"d x 40.5"h, paint and water stains on both, brown. Fair		\$5	
No Bid 8-530	Microscope Accessories, Lot of approx. 10 Assorted, unknown if operational, microscope not included. Fair		\$2	
2.00 8-531	Microscope Case, with accessories, wood Microscope not included, 10"w x 12"d x 30"h, scratch on front, light brown. Fair		\$1	
2.01 8-532	Microscope Transformers, with lamps glass, metal and plastic 20"w x 12"d x 12"h, black, silver and white, unknown if operational.		\$1	
No Bid 8-533	Mobile Storage, Lot of 4 ProSource, High Density, metal and plastic 31"w x 82"d x 82"h, 3"thick, beige and black, some scuffs and small dents, all drawers open. Fair		\$1	
3.10 8-534	Monitor Stands, Lot of 4 Brother, Metal and Plastic 10"w x 10"d x 14"h, black. Fair		\$2	
No Bid 8-535	Poster Tubes, Lot of 10 Cardboard and plastic Approx. 48"w x approx. 54"d, brown, black and pink. Fair		\$5	
5.00 8-536	Printer, Brother 16"w x 16"d x 13"h, operational, memory has been wiped, black. Fair		\$2	
1.10 8-537	Shelves, Lot of 2 Wood 48"w x 24"d x 72"h, cream, paint chips and scuff, water rings on top of one unit. Fair		\$1	
51.00 8-538	Shelving Unit, Lot of 2 Metal 121"w x 25"d x 78"h, grey, bent, bottom bracket not connected on one unit. Fair		\$1	
No Bid 8-539	Shelving Unit, Unassembled, alluminum, vinyl, wood 30"w x 30"d x 76", beige and brown, missing hardware, dents at top of alluminum panels. Fair		\$1	
No Bid 8-540	Storage Box, Wood 24"w x 48"d x 28"h, orange and brown. Fair		\$1	
6.00 8-541	Storage Box, Wood, metal 34"w x 30"d x 24"h, beige, water stains and scuff marks. Fair		\$1	
33.00 8-542	Table, Elite, drafting, vinyl, metal 60"w x 38"d x 54"h, white and beige, top has some scratches and tape residue. Fair		\$5	
21.00 8-543	Table, Metal, wood 60"w x 20"d x 30"h, brown, black. Broken Repairable		\$5	
No Bid 8-544	Table, Wood, metal, folding 36"w x 48"d x 30"h, brown and black, top is chipped, comes with foam core topper. Fair		\$1	
31.00 8-545	Table, Drafting, Mayline, oak 66"w x 36"d x 36"h, brown. Fair		\$2	
No Bid 8-546	White Boards, Lot of 5 Wood 32"w x 56"d x 24"h, white and brown, scratched and has paint on back. Fair		\$1	

Item #	Description	Kms	Min Price	Serial Number
No Bid 8-547	White Boards, Lot of 5 Wood 32"w x 56"d x 24"h, white and brown, scratched and has paint on back. Fair		\$1	
REGINA, Highways, 1610 Park St				
Contact Cory Obleman 306-526-9135, cory.obleman@gov.sk.ca				
221.00 8-669	Sign Posts, Lot of 50-60 Wooden Some treated/painted, some broken, 4"w x 6"d x 8 to 14'h approximately, approximate weight of lift is 6500 lbs; must bring deck over trailer for assistance with loading; if deck over trailer cannot be provided loading is responsibility of buyer. Ministry staff will not load any trailer deemed unsafe to load. Trailers with fenders will not be loaded by Ministry staff. Fair		\$1	
221.00 8-670	Sign Posts, Lot of 50-60 Wooden Some treated/painted, some broken, 4"w x 6"d x 8 to 14'h approximately, approximate weight of lift is 6500 lbs; must bring deck over trailer for assistance with loading; if deck over trailer cannot be provided loading is responsibility of buyer. Ministry staff will not load any trailer deemed unsafe to load. Trailers with fenders will not be loaded by Ministry staff. Fair		\$1	
221.00 8-671	Sign Posts, Lot of 50-60 Wooden Some treated/painted, some broken, 4"w x 6"d x 8 to 14'h approximately, approximate weight of lift is 6500 lbs; must bring deck over trailer for assistance with loading; if deck over trailer cannot be provided loading is responsibility of buyer. Ministry staff will not load any trailer deemed unsafe to load. Trailers with fenders will not be loaded by Ministry staff. Fair		\$1	
221.00 8-672	Sign Posts, Lot of 50-60 Wooden Some treated/painted, some broken, 4"w x 6"d x 8 to 14'h approximately, approximate weight of lift is 6500 lbs; must bring deck over trailer for assistance with loading; if deck over trailer cannot be provided loading is responsibility of buyer. Ministry staff will not load any trailer deemed unsafe to load. Trailers with fenders will not be loaded by Ministry staff. Fair		\$1	
221.00 8-673	Sign Posts, Lot of 50-60 Wooden Some treated/painted, some broken, 4"w x 6"d x 8 to 14'h approximately, approximate weight of lift is 6500 lbs; must bring deck over trailer for assistance with loading; if deck over trailer cannot be provided loading is responsibility of buyer. Ministry staff will not load any trailer deemed unsafe to load. Trailers with fenders will not be loaded by Ministry staff. Fair		\$1	
REGINA, Immigration and Career Training, 10th Floor, 2103 - 11th Avenue.				
Contact Kayla Swicheniuk 306-787-5014, kayla.swicheniuk@gov.sk.ca or Verna Ziegler 306-787-2580, Verna.Ziegler@gov.sk.ca				
100.00 8-683	File Cabinet, 5 drawer, lateral 36"w x 19"d x 65.5"h, top 2 shutter doors and the other 3 are sliding drawers, beige, with key. Good		\$5	
31.00 8-684	File Cabinet, 5 drawer, lateral 36"w x 19"d x 67"h, one shutter door and the other 4 are sliding drawer, beige, no key. Good		\$5	

Item #	Description	Kms	Min Price	Serial Number
REGINA, Labour Relations and Workplace Safety, 300 1870 Albert St				
Contact Waneta Hardy 306-798-0312, waneta.hardy@gov.sk.ca or Keya Patel 306-787-1869, keya.patel@gov.sk.ca				
No Bid 8-662	Binders, Lot of 4 Plastic Black and white, 3.5" and 4" Fair		\$1	
No Bid 8-663	Chair , Swivel, with arms Plastic frame, 5 caster, black fabric. Fair		\$1	
No Bid 8-664	Chair , Swivel, with arms Plastic frame, 5 caster, teal fabric. Fair		\$1	
No Bid 8-665	Table, Metal 27.5"w x 24"d x 30"h, 2 shelves, with wheels, beige. Fair		\$1	
REGINA, Saskatchewan Liquor and Gaming Authority, 12252 Ewing Ave				
Contact Al Kentz 306-537-2462, akentz@slga.com or Todd Leurur 306-510-4368, tleurur@slga.com				
801.00 8-705	Pallet Jack , Raymond, 102T-F45L Built in charger, battery poor, unknown if operational. Broken Repairable		\$50	102-10-16287
801.00 8-706	Pallet Jack , Raymond, 102T-F45L Built in charger, battery poor, unknown if operational. Good		\$50	102-14-33373
200.00 8-707	Power Lift Truck, Walkie Rider, Hyster, B602AC Does not have charger,walk behind, hours unknown, unknown if operational. Broken Repairable		\$50	B230N03706J
200.00 8-708	Power Lift Truck, Walkie Rider, Hyster, B602AC Does not have charger,walk behind, hours unknown, unknown if operational. Broken Repairable		\$50	B230N03713J
200.00 8-709	Power Lift Truck, Walkie Rider, Raymond, 8410 Does not have charger,walk behind, hours unknown, unknown if operational. Poor		\$50	841-1312447
75.00 8-710	Power Lift Truck, Walkie Rider, Raymond, 8410 Does not have charger,walk behind, hours unknown, unknown if operational. Beyond Repair		\$1	841-1312453
200.00 8-711	Power Lift Truck, Walkie Rider, Raymond, 8410 Does not have charger,walk behind, hours unknown, unknown if operational. Poor		\$50	
200.00 8-712	Power Lift Truck, Walkie Rider, Raymond, 8410 Does not have charger,walk behind, hours unknown, unknown if operational. Poor		\$50	840-0771345
200.00 8-713	Power Lift Truck, Walkie Rider,, Hyster, B602AC Does not have charger,walk behind, hours unknown, unknown if operational. Broken Repairable		\$50	B230N03705J
SASKATOON, Corrections, Policing and Public Safety, SCC, 910 60th St. E				
Contact Renee Pound 306-956-8817, renee.pound@gov.sk.ca or Danielle Corriveau 306-956-8869 danielle.corriveau@gov.sk.ca.				
60.00 8-588	Angle, Lot of 2 Aluminum 2"w x 2"d x 3/16" thick, 1 piece 8' length and 1 piece 9' length, total 17' length. Good		\$51	
5.55 8-589	Angle, Steel 1"w x 1"d x 1/8"thick, 6' length. Good		\$3	
100.00 8-590	Angle, Steel 3"w x 3"d x 3/8"thick, 20' length. Good		\$78	
14.58 8-591	Angle , Steel 4"w x 3"d x 1/4" thick, 8' length. Good		\$10	

Item #	Description	Kms	Min Price	Serial Number
51.55 8-592	Angle , Steel 4"w x 4"d x 1/4" thick, 9' length. Good		\$47	
327.00 8-593	Assorted Steel, Assorted steel, sheet metal and sizes, include rack. Good		\$1	
12.76 8-594	Beam, Steel 4"w x 7' length. Fair		\$10	
10.76 8-595	Channel, Steel 6", 9' length. Fair		\$5	
67.00 8-675	Deep Freeze, Frgidair 61 1/4"w x 28 1/2"d x 35"h, white, operational, dented on top and sides. Fair		\$1	
50.00 8-676	Deep Freeze, 61 1/2"w x 27"d x 35"h, tan, operational, rusty on top and dented on sides. Fair		\$1	
15.88 8-596	Flag Pole, Steel 21' length. Fair		\$1	
101.00 8-597	Flatbar, Lot of 3 Steel 1 1/2"w x 1/8"d, 3 pieces 20' length each, total 60' length. Good		\$42	
131.76 8-598	Flatbar, Lot of 6 Steel 1 1/4"w x 1/4"d, 6 pieces 20' length each, total 120' length. Good		\$69	
150.76 8-599	Flatbar, Lot of 9 Steel 1 1/4"w x 1/8"d, 9 pieces 20' length each, total 180' length. Good		\$44	
21.76 8-600	Flatbar, Steel 1 1/4"w x 3/16"d, 20' length. Good		\$11	
55.00 8-601	Flatbar, Lot of 4 Steel 1"w x 1/4"d, 4 pieces 20' length each, total 80' length. Good		\$36	
103.00 8-602	Flatbar, Lot of 4 Steel 2"w x 3/16"d, 4 piece 20' length each, total 80' length. Good		\$70	
77.77 8-603	Flatbar, Lot of 2 Steel 2"w x 3/8"d, 2 pieces 20' length each, total 40' length. Good		\$61	
123.00 8-604	Flatbar, Lot of 4 Steel 3/4"w x 1/8"d, 3 pieces 20' length and 1 piece 14' length, total 74' length. Good		\$46	
170.00 8-605	Flatbar, Lot of 2 Steel 4"w x 1/4"d, 2 piece 20' length each, total 40' length. Good		\$92	
No Bid * 4-634	Floor Cleaner, Extract-Away, metal yellow, unknown if operational, 13.5 amps, 60 cycles, 712 hours. Poor		\$1	EI151-032
No Bid * 6-561	Grating, Steel, oxide primer Some used, 1" w x 1/8" thick, assorted sizes, 24" x 36", 48" x 36", 12" x 36", 12" x 120". Good		\$544	
16.88 8-606	Ladder , Steel 18"w x 10'h. Fair		\$1	

Item #	Description	Kms	Min Price	Serial Number
66.88 8-678	Medical Cart, Harloff, steel Metal, on swivel casters. Frame is 37 1/2" x 22 3/4" x 38 1/4" tall. Has four pull out drawers. 37 1/2"w x 22 3/4"d x 38 1/4"h, 4 pull out drawers, red, on swivel casters. Good		\$1	48,591
11.00 * 1-731	Microwave, Samsung 30"w x 15.5"d x 17"h, operational. Good		\$1	
58.88 8-607	Parts Washer, Hydra Clean, steel 32"w x 17"d x 37"h, unknown if operational. Fair		\$1	
88.88 8-608	Pipe, Lot of 3 Schedule 40, steel 1 1/2" dia, 2 pieces 21' length and 1 piece 6' length, total 48' length. Good		\$79	
222.22 8-609	Pipe, Lot of 10 Schedule 40, steel 1 1/4" dia, 1 piece 24' length, 6 piece 20' lengths, 1 piece 18' length, 1 piece 13' length and 1 piece 6' length, total 181' length. Good		\$217	
18.88 8-610	Pipe, Lot of 2 Schedule 40, steel 1/2" dia, 1 piece 9' length and 1 piece 8' length, total 17' length. Good		\$15	
88.88 8-611	Pipe, Lot of 2 Schedule 40, steel 2" dia, 1 piece 21' length and 1 piece 14' length, total 35' length. Good		\$77	
5.88 8-612	Pipe, Lot of 2 Steel 1 piece 6" dia x 5' length, 90 degree elbow on one end and 1 piece 6" dia x 103" length, 90 degree elbows on both ends. Fair		\$5	
55.55 8-613	Plate, Steel 10"w x 8' length x 1/4" thick. Fair		\$1	
155.55 8-614	Rack, Steel 199"w x 48"d x 95"h, 6 shelves. Fair		\$1	
65.00 8-615	Rod, Lot of 2 Hot roll, steel 1"d, 2 piece 16' length each, total 32' length. Good		\$28	
18.88 8-616	Rod, Lot of 4 Steel 1/2"d, 4 pieces 20' length each, total 80' length. Good		\$13	
No Bid * 5-521	Sheet Metal, Lot of 3 Steel 48"w x 120"d x 11ga, perforated, 1/4" holes. Good		\$1,213	
No Bid * 5-522	Sheet Metal, Lot of 4 Steel 48"w x 120"d x 11ga, perforated, 3/16" holes. Good		\$1,617	
No Bid * 5-523	Sheet Metal, Lot of 2 Steel 48"w x 120"d x 11ga, perforated, 3/8" holes. Good		\$733	
188.88 8-617	Shelf, Steel 101"w x 96"d x 96"h, 8 shelves. Fair		\$1	
255.55 8-618	Steel Sheet, Expanded metal Assorted expanded metal, flattened and raised. Fair		\$250	
33.33 8-619	Tube, Aluminum, square 2"w x 2"d x .188 thick, 6' length, rounded corner. Good		\$30	

Item #	Description	Kms	Min Price	Serial Number
8.88 8-620	Tube, Steel, round 1 1/2"d x 16 gauge x 8' length. Good		\$5	
18.88 8-621	Tube, Lot of 3 Steel, round 1 1/4"d x 16 gauge, 1 piece 20' length and 1 piece 6' length, total 26' length, 6' piece has some dents and is not straight. Good		\$17	
19.99 8-622	Tube, Steel, round 2"d x 16 gauge x 9' length. Good		\$18	
145.55 8-623	Tube, Lot of 3 Steel, round 3"d x 16 gauge, 2 piece 20' length each and 1 piece 9' length, total 49' length. Good		\$140	
222.22 8-624	Tube, Lot of 3 Steel, round 5"d x 16 gauge, 2 piece 20' length each and 1 piece 12' length, total 52' length. Good		\$216	
202.55 8-625	Tube, Lot of 5 Steel 4"w x 4"d x 1/4" thick, 4 pieces 20' lengths and 1 piece 18' length, total 98' length. Fair		\$10	
58.88 8-626	Tube, Steel, rectangular 1 1/2"w x 3"d x .125 thick, 15' length. Good		\$50	
75.00 8-627	Tube, Lot of 6 Steel, rectangular 2"w x 1"d x 1/8"thick, 1 piece 15' length, 4 pieces 8' lengths and 1 piece 7' length, total 46' length. Fair		\$51	
933.33 8-628	Tube, Lot of 23 Steel, rectangular 2"w x 4"d x .125 thick, 11 piece 20' length, 3 piece 10' length, 6 piece 7' length and 3 piece 3' length, total 301' length. Good		\$875	
81.00 8-629	Tube, Lot of 2 Steel, rectangular 3"w x 2"d x .125 thick, 1 piece 15' length and 1 piece 14' length, total 29' length. Good		\$62	
118.55 8-630	Tube, Lot of 11 Steel, rectangular 3"w x 2"d x .188 thick, 1 piece 24' length, 1 piece 20' length, 1 piece 14' length, 1 piece 15' length, 1 piece 8' length, 1 piece 7' length, 4 pieces 6' lengths and 1 piece 4' length, total 116' length. Good		\$56	
55.58 8-631	Tube, Steel, rectangular 3"w x 3"d x .188 thick, 10' length. Good		\$47	
13.33 8-633	Tube, Steel, rectangular 4"w x 6"d x .188 thick, 5' length. Fair		\$10	
25.00 8-634	Tube, Lot of 2 Steel, square 1 1/2"w x 1 1/2"d x .125 thick, 1 piece 11' length and 1 piece 6' length, total 17' length. Good		\$12	
36.66 8-635	Tube, Lot of 2 Steel, square 1 1/4"w x 1 1/4"d x 1/8"thick, 1 piece 19' length and 1 piece 13' length, total 32' length. Fair		\$25	
160.00 8-636	Tube, Lot of 2 Steel, square 1"w x 1"d x 1/8"thick, 2 pieces 22' length each, total 44' length. Good		\$44	
88.88 8-637	Tube, Lot of 3 Steel, square 2"w x 2"d x .125 thick, 2 piece 20' length and 1 piece 13' length, total 53' length. Fair		\$10	

Item #	Description	Kms	Min Price	Serial Number
10.76 8-651	Tube , Steel, square 2"w x 2"d x 0.83 thick, total 9' length. Fair		\$5	
10.76 8-652	Tube , Steel, square 3"w x 3"d x .125 thick, total 8' length. Fair		\$5	
No Bid * 4-654	Washer and Dryer, Lot of 2 Whirlpool, Washer YWED5620HWI, Dryer WFW560CHW2 door cracked on washer and missing detergent drawer, was operational when placed in storage. Fair		\$1	washer MX3827613, dryer CX4000518
*MT 8-679	Washer/Dryer Set, Huebsch, stackable, YTEE5ASP285CW01 26 3/4"w x 27 3/4"d x 78 1/4"h, operational. Good		\$1	2,208,006,115
*MT 8-680	Washer/Dryer Set, Huebsch, stackable, YTEE5ASP285CW01 26 3/4"w x 27 3/4"d x 78 1/4"h, dryer is operational, washer has a code and is missing a door. Good		\$1	2,212,011,299
*MT 8-681	Washer/Dryer Set, Huebsch, stackable, YTEE5ASP285CW01 26 3/4"w x 27 3/4"d x 78 1/4"h, dryer is operational, washer is missing a door. Good		\$1	2,209,019,655
*MT 8-682	Washer/Dryer Set, Huebsch, stackable, YTEE5ASP285CW01 26 3/4"w x 27 3/4"d x 78 1/4"h, operational. Good		\$1	2,210,004,589
67.00 8-653	Weeping Tile , Plastic 4"dia x 88' long, include sock. Fair		\$1	
1.50 8-674	Bussiness Card File, Rolodex, plastic Black, has some sleeves on paper tabs. Good		\$1	
No Bid 8-677	Desk, Wood, steel 23 3/4"w x 18 3/4"d x 34"h, on casters, slide out keyboard tray. Good		\$1	
SASKATOON, Corrections, Policing and Public Safety, 1302 Killburn Ave				
Contact Petrina Hamilton 306-933-6847, petrina.hamilton@gov.sk.ca or Eleanor Espiritu 306-933-5050, eleanor.espiritu@gov.sk.ca				
2,688.00 8-654	Tilting Kettle, Vulcan, metal 25 gallon, floor mounted, steamer disk needs to be replaced. Good		\$2,500	A9259-3T-1735
SOUTHEND Corrections Policing and Public Safety 15 College Dr				
Contact Nolan Hoggarth 306-758-6254, nolan.hoggarth@gov.sk.ca				
5.56 * 6-515	Sonar Head Unit, Eagle, SupraPro ID Unknown if operational. Poor		\$1	7,239,602
No Bid * 6-516	Sonar Head Unit , Hummingbird, LCR400 ID Unknown if operational. Poor		\$1	3,197,452
5.55 * 6-517	Sonar Kit, Eagle, SupraPro ID Unknown if operational, includes head unit, case, and transducer. Poor		\$1	7,373,821
TISDALE, Agriculture, 1105 - 99th Street.				
Contact Teresa Casavant 306-878-8842, teresa.casavant@gov.sk.ca or Judy Ewen 306-878-8843, judy.ewen@gov.sk.ca				
10.00 8-690	Bookshelf, Pepperdust 9"w x 8.5"d x 56"h, 5 staggered shelves, wood trim. Fair		\$1	
No Bid 8-691	Coffee Urn, Regal, metal 11"dia x 20"h, silver, unknown if operational. Fair		\$1	
No Bid 8-692	Keyboard Tray, Fellowes, metal Black, 19"w x 10.5"d, attched adjustable mouse tray (8.5"w x 10.5"d, adjusts 3" right). Fair		\$1	

Item #	Description	Kms	Min Price	Serial Number
227.50 8-693	Storage Cabinet, Lot of 2 Metal 37"w x 20"d x 39"h, 2 door, 2 shelves, off-white, no key. Fair		\$1	
YORKTON, Highways, Fleet Services, 245 York Rd E				
Contact Brian Perih 306-786-1651 brian.perih@gov.sk.ca or Ed Patzwald 306-786-1687 ed.patzwald@gov.sk.ca.				
12.77 8-644	Grader Fenders, Set of 4 Motor Grader Brand Includes mounting brackets, unsure of fitment Fair		\$1	
12.77 8-645	Roller Tires, Lot of 13 8.590-15K, on HD rim Foam filled, some are poor condition, holes in tread on some, some are still useable, removed from WRT roller packer. Poor		\$1	
1.77 8-648	Shelving, Approx Lot of 25-30 Metal Missing uprights, 36"w X 24"d, grey. Fair		\$1	
65.00 8-649	Tire, Hercules, 11R22.5 Manufacture date. Week 15, year 2017. Poor		\$1	
88.26 8-650	Tire, Michelin, 425/65R22.5 Manufacture date. Week 15, year 2020. Poor		\$1	
No Bid 8-646	Tractor Tires, Lot of 7 16x6.50-8NHS on rim Unused tire/rim combination, some hold air, some tires off the bead. Poor		\$1	
No Bid 8-647	Truck Box, 2009 F-350 eight foot dual tire Front stake pockets broken out, lights missing, tailgate missing, holes in floor of box, box floor dented bad/ cracked fender flairs, front wall of box broken. Poor		\$1	

Item #	Description	Kms	Min Price	Serial Number
1,843.26 8-715	Gravel Truck 2000 MACK RD688S 4WD, center chain dump box, 12L Mack E7-350, inline 6, diesel manual tilt, cruise Tandem axle, 10 speed, locking differential, GVW 39,500 kg, wheel base 214, dual tire, tire size 11R22.5, yellow, TOW ONLY, NO SGI Inspection. It is unknown if any repairs or safety concerns exist (if any). Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs if required. , 463,867 km, PROBLEMS: Frame issues, frame very thin and cracked at rear hitch plate gussets, subframe for box cracked and collapsing, no hose on clutch release bearing, transmission mounts poor, front motor mount poor, exhaust pipe hitting frame under cab, hoist cylinder leaking, does not start on first try, steer hub oil level low, steering gear leaking from sector shaft and worn out, lower trunnion for hoist mount loose, intake pipe fallen down, broke, pyrometer sensor and wearing into intake pipe/heat shield resting on exhaust pipe, cup spinning in yoke on pump driveshaft front yoke, steering has tight spot, wiper vibrators fallen off hanging by wires from wiper arms, drivers mirror loose on bracket, passenger mirror broken, hood light bracket loose, breaking out of hood, fog light cracked, hydraulic reservoir cap missing, hoist cylinder leaking, no fire extinguisher, drivers seatbelt damaged, no heat in cab, muffler loose, hood missing x-brace, air dryer not secure at top (bolt broken or missing), rust jacking on wing frame, rust jacking behind cross member under cross conveyor, rust jacking on plow frame, passenger door rusted through at bottom batteries fail load test, brakes and battery poor., As is, Where is	463,867 km	\$1,500	1M2P267C5YM049822

Item #	Description	Kms	Min Price	Serial Number
1,843.26 8-714	Gravel Truck 2002 VOLVO VHD64F 4WD, center chain dump box D12, inline 6, diesel manual tilt, cruise Wheel base 224, tandem axle, 10 speed, Meriter RT40-145 differential, GVW 39,500 kg, dual tire, tire size 11R22.5, yellow, TOW ONLY, NO SGI Inspection. It is unknown if any repairs or safety concerns exist (if any). Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs if required. , 16,906 hrs, PROBLEMS: Tarp and compements need to be replaced,transmission mounts, transmission issues likely needs transmission replaced, rust jacking on repaired frame that needs repair, AC non operational, charge air cooler needs replacing, all heater control cables need replacement front and rear shocks need to be replaced, doors need repair issues latching shut, left mirror need to be replaced, oil leak on rear of engine, turbo needs to be replaced, hood fender flairs, cab air bags need to be replaced, heater core and block heater, all air tanks corroded through, clutch master and slave cylinders need to be replaced, exhaust needs to be replaced, steering box and cylinder assembly, power steering pump, all battery cables need to be replaced, belts, pulleys, and tensioners for fan and alternator need to be replaced, starter needs to be placed, oil pan gaske, valve cover gasket, horns, wind shield wiper linkage and motorneed to b replaced, all leveling valves need replacement; upper and lower rear torque arms need replacement, instrument cluster needs to be replaced, motor, brakes, battery, interior, and lights in poor condition., As is, Where is	16,906 hrs	\$1,500	4V5KC9GG12N329867
1,628.00 8-668	Trailer, 2008 MAJESTIC H270 Flat deck Tandem axle, single tire, tire size, LT235/85R16PROBLEMS: Unit is rusted, deck structure rusted through in areas, deck, tires and lights in poor condition, missing mud flaps one brake does not work. As is, Where is		\$100	2M9FS42E88R151400