

SALE SUMMARY LIST

PLEASE NOTE: Every effort has been made to accurately describe items and their condition; however, additional problems may exist, items may not be complete or exactly as described. Bidders are deemed to have reviewed the Terms and Conditions on bid forms and relied entirely on their own inspection and evaluation prior to bidding. Vehicles and equipment are sold "AS IS, WHERE IS", there is no implied or express warranty.

Visit www.SaskSurplus.ca for pictures and link to download Bid Form.

- Items identified with * have been on a previous sale and will be listed first on www.SaskSurplus.ca web site.
- SaskBuilds and Procurement, SaskSurplus, reserves right to have unadvertised minimum selling prices on items.

It is the Bidder's responsibility to review the terms and conditions of sale on the Offer to Purchase, Bid Form.

Bid Forms are available from www.SaskSurplus.ca or from the SaskSurplus Sales Lot, 500 McLeod Street, Regina, SK.

Bid Forms can be submitted in the following ways:

- by deposit in the bid box at the SaskSurplus Sales Lot,
- by fax to 306-787-2092; by phone 306-787-2062 or 306-787-2238,
- by email to sasksurplus@gov.sk.ca, or
- by mail, addressed to: Ministry of SaskBuilds and Procurement, SaskSurplus, 500 McLeod Street, Regina, SK S4N 4Y1.

(If mailing your bid, please allow sufficient time for bid to be received.)

- Bids received after close date and time cannot be accepted.

MT = (Ministry Transfer) This means that the item has been claimed by another ministry and automatically transferred to the ministry.

WD = (Withdrawn) This can happen if the item was requested to be removed by the seller.

No Bid = Items that did not receive any bids are normally carried forward to the next sale or may be withdrawn.

Item #	Description	Kms	Min Price	Serial Number
REGINA, SaskBuilds and Procurement, SaskSurplus Sales Lot, 500 McLeod Street - Vehicles				
Contact SaskSurplus 306-787-2062 or 306-798-3306.				
5,228.88 5-005	Car 2008 CHEVROLET Impala LS FWD 3.5L, V6, gas auto A/C, tilt, cruise, AM/FM/CD player, power mirrors/locks/windows/left front seat/trunk release, keyless entry, 2 keys, 2 fobs , grey, TOW ONLY, This vehicle has a FAILED SGI Inspection. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in "As is, where is" condition., 170,301 km, , KNOWN PROBLEMS and OBSERVATIONS: Sway bar broken left side-fresh break, rocker panels starting to rust but passed, small rust on left front door, poor battery. Hood scratches/chips, front bumper scratches/chips, left front fender scratches, left rear fender dents, all doors rust at bottom, roof dull spots, trunk lid rust/scratches, wheel covers peeling, no first aid kit/fire extinguisher, windshield chips, minor exterior damage.> , As is,	170,301 km	\$993	2G1WB58K681357893
4,677.00 5-017	Car 2013 CHEVROLET Impala LS FWD 3.6L, V6, gas auto A/C, tilt, cruise, AM/FM/CD player, power locks/mirrors/windows/left front seat/trunk release, keyless entry-2 fobs, 2 keys , grey, TOW ONLY, This vehicle has a FAILED SGI Inspection. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in "As is, where is" condition., 191,559 km, , KNOWN PROBLEMS and OBSERVATIONS: Park brake sticks on, right rear caliper seized, wiper blades streaky, poor battery. Hood hail/chips/scratches, rear bumper scratches, roof hail, no firs aid kit/fire extinguisher, windshield chips/pitted, minor exterior damage.> , As is, Where is	191,559 km	\$2,454	2G1WA5E35D1169179
4,228.88 5-006	Car 2013 CHEVROLET Impala LS FWD 3.6L, V6, gas auto A/C, tilt, cruise, AM/FM/CD player, power mirrors/locks/windows/left front seat/trunk release, keyless entry, 1 key, 1 fob , white, TOW ONLY, This vehicle has a FAILED SGI Inspection. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in "As is, where is" condition., 223,725 km, , KNOWN PROBLEMS and OBSERVATIONS: Rear pads and rotors, front brake pulsates, front rotors, poor battery. Grille lower broken, hood chips, left side doors rust at bottom, roof rust spots/scratches, no first aid kit/fire extinguisher, windshield small chips, minor exterior damage.> , As is, Where is	223,725 km	\$1,136	2G1WA5E33D1248740

Item #	Description	Kms	Min Price	Serial Number
1,566.60 5-008	<p>SUV 2015 CHEVROLET Tahoe 2WD 5.3L, V8, gas auto A/C, tilt, cruise, AM/FM, power front seats/locks/windows/mirrors/rear HVAC- no rear seat controls, keyless entry, 1 key, 1 fob driving lights, side steps, hitch, trailer wiring, 5 passengers has back seat with belts, no jump seat, white, TOW ONLY, This vehicle has a FAILED SGI Inspection. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in "As is, where is" condition., 243,572 km, , KNOWN PROBLEMS and OBSERVATIONS: Engine seized, rear wheels do not spin, ABS light on, front wheel alignment needed, traction light on, engine oil dirty, transmission fluid dirty, missing rear trim at hatch, rear washer fluid leaks inside vehicle, parking brakes are not stuck on at mechanism, no horn, left wiper blade, rear washer fluid non-operational, driver seat belt frayed, both rear lock/unlock knobs in door missing, both rear plate lights, driving lights non-operational, both reverse lights non-operational, poor battery.</p> <p>Both bumpers' holes drilled/scratches/chips, left rear door power window switches do not work/missing lock, right rear door missing unlock buttons, roof holes drilled in above side door, 7 holes in roof sealed, tailgate scratches/glass scratched, no first aid kit/fire extinguisher, windshield large stone bruise/chips, missing air filter housing, may be missing other engine components, various interior molding cut or holes drilled, missing left and right quarter panel moldings, dash missing molding and holes drilled holes in head liner, minor exterior damage.>, As is, Where is</p>	243,572 km	\$244	1GNLC2ECOFR584026
5,977.00 * 4-004	<p>Truck 2018 CHEVROLET Silverado 1500 4WD, Crew Cab, 6.5' box 5.3L, V8, gas auto A/C, tilt, cruise, AM/FM, power locks/windows/mirrors, keyless entry-2 keys, 2 fobs mud flaps, side steps, tow hooks, hitch, trailer wiring, OEM Trailer Brakes, box liner, headache rack, has a back seat, black, TOW ONLY, This vehicle has a FAILED SGI Inspection. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in "As is, where is" condition., 262,567 km, , KNOWN INSPECTION PROBLEMS: Engine light on, transmission poor/failure, hard shifting-2 gear, engine oil over filled, transfer case fluid a little dirty, front wheel alignment needed, windshield cracked, both license plate lights, poor battery.</p> <p>KNOWN PROBLEMS: Hood chips/scratches, both bumpers chips/scratches, left front fender scratches, left rear fender road rash/rust/dents, right front fender chips, right rear fender road rash/rust/dents, all door road rash/chips, right front door missing some "Silverado" letters, roof chips/scratches, tailgate chips/scratches, no first aid kit/fire extinguisher, left front mirror housing broke, minor exterior damage.>, As is, Where is</p>	262,567 km	\$3,916	3GCUKNEC8JG155940

Item #	Description	Kms	Min Price	Serial Number
4,166.60 5-019	Truck 2014 DODGE Ram 2500 4WD, Crew Cab, 6'3" box 5.7L, V8, gas auto A/C, tilt, cruise, AM/FM, power windows/locks, keyless entry, 2 key fobs Grille inserts, front tow hooks, side steps, mud flaps, hitch, trailer wiring, OEM trailer brakes, has a back seat, white, TOW ONLY, This vehicle has a FAILED SGI Inspection. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in "As is, where is" condition., 224,272 km, , KNOWN PROBLEMS and OBSERVATIONS: Transmission problems when cold, both front fenders, left outer tie rod, tie rod at pitman arm, rear shocks, all 4 tires, manifold leaks, front pads & rotors, alignment, poor battery. Hood chips, front bumper rust spots, rear bumper bent/rust spots, front fenders rust, left rear fender road rash/dents/rust, right rear fender road rash rust, rocker panels road rash rust, left front door glass scratched, right rear door missing inside molding, roof scratches, hole in roof 5 sealed, tailgate chips/rust/molding broke/dents, wheel wrench/jack under back seat, no first aid kit/fire extinguisher, windshield small chips, left front seat soft/sagging, holes drilled in rear seat hump/dash head, liner ripped and holes, B pillars inside moldings modified, holes drilled in roof above B pillar, back of cab dented/scratched, holes drilled in both box rails, missing jump seat, minor exterior damage.>, As is, Where is	224,272 km	\$1,897	3C6TR5CT8EG193028
3,766.60 5-009	Truck 2015 DODGE Ram 2500 4WD, crew cab, 6'3"box 5.7L, V8, gas auto A/C, tilt, cruise, AM/FM, power heated mirrors, power locks/windows, keyless entry, 2 key fobs has back seat no jump seat, front cupholder modified, grille inserts, front tow hooks, side steps, mud flaps, hitch, trailer wiring, OEM trailer brakes, white, TOW ONLY, This vehicle has a FAILED SGI Inspection. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in "As is, where is" condition., 207,154 km, , KNOWN PROBLEMS and OBSERVATIONS: Engine noise present, engine tick, engine codes P0305, cylinder 5 misfire, active needs engine, front/rear wheel alignment out of spec, windshield cracked, center high mount brake lamp non-operational, battery not held down, poor battery. Right rear fender dents/scratches, right rear doors holes drilled inside around window frame, roof scratches, 2 holes in roof sealed, tailgate dents/scratches, no first aid kit/fire extinguisher, holes drilled in roof above right and left doors, B-pillar moldings modified, right rear window non-operational from left front switch or right rear switch, minor exterior damage.>, As is, Where is	207,154 km	\$1,965	3C6TR5CT8FG544764

Item #	Description	Kms	Min Price	Serial Number
7,005.00 5-011	Truck 2014 DODGE Ram 2500 4WD, crew cab, 6'3" box 5.7L, V8, gas auto A/C, tilt, cruise, AM/FM, power mirrors/windows/locks, keyless entry, 2 key fobs, 1 key for toolbox headache rack with beacon and wigwags all operational, wig wags front and rear all operational, grille inserts, front tow hooks, sidestep, hitch, trailer wiring, OEM trailer brakes, has back seat, Brute Gull Wing toolbox condition fair, brown, TOW ONLY, This vehicle has a FAILED SGI Inspection. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in "As is, where is" condition., 273,664 km, , KNOWN PROBLEMS and OBSERVATIONS: Both front wheel bearing, left upper ball joint, alignment needed, poor battery, right backup light non-operational. Front bumper pitted, rear bumper pitted/dents, left and right front fender rust, left and right rear fender chips/scratches/dents, left side doors dents/chips, right side door dents/chips/scratches, roof dents/chips/antenna, one hole in roof sealed, tailgate scratches/dents/chips, no first aid kit/fire extinguisher, windshield chips, left front cushion hole, minor exterior damage.>, As is, Where is	273,664 km	\$6,361	3C6TR5CT0EG207665
3,566.60 5-012	Truck 2015 DODGE Ram 2500 ST 4WD, crew cab, 6'3" box 5.7L, V8, gas auto A/C, tilt, cruise, AM/FM, power windows/locks/mirrors, keyless entry-1 key fob front grille inserts, front tow hooks, mud flaps, side steps, hitch, trailer wiring, OEM trailer brakes, has back seat, missing jump seat, white, TOW ONLY, This vehicle has a FAILED SGI Inspection. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in "As is, where is" condition., 229,430 km, , KNOWN PROBLEMS and OBSERVATIONS: Check engine light on codes P0734/P0731/P0732/P0733, gear ratio errors, front pads and rotors, transmission has no forward gears, both upper ball joints, both front wheel joints, rear links, rear pads and rotors, TPMS light on rear right sensor, pulsation/vibration, right front marker light, moisture in left head lights and left tail light assemblies, rear right window switch broken, bolt on driver seat, loose nuts on passenger seat, poor battery. Front bumper rust, rear bumper dents/bent/scratches/rust, left and right rear fender road rash, rocker panels road rash, roof scratches, 5 holes in rood sealed, tailgate molding broken, missing wheel wrench, no first aid kit/fire extinguisher, windshield small chips, rear seat hole, holes drilled in dash, holes drilled in rear right door window frame in area above all doors, right inside B-pillar molding modified, holes drill in rear floor, missing lower valance, holes drilled in box rails, minor exterior damage.>, As is, Where is	229,430 km	\$1,857	3C6TR5CT2FG544761

Item #	Description	Kms	Min Price	Serial Number
5,170.00 5-013	Truck 2015 DODGE Ram 2500 ST 4WD, crew cab, 6'3" box 5.7L, V8, gas auto A/C, tilt, cruise, AM/FM, power heated mirrors, power locks/windows, keyless entry, 1 key fob grille inserts, front tow hooks, mud flaps, side steps, hitch, trailer wiring, OEM trailer brakes, has back seat, blue, TOW ONLY, This vehicle has a FAILED SGI Inspection. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in "As is, where is" condition., 191,705 km, , KNOWN PROBLEMS and OBSERVATIONS: Check engine light on, misfire, codes P0305 cylinder 5 misfire, P0300 multiple misfires, manifold leaks, exhaust leaks, low compression in 2 cylinders, left upper ball joint, front pads and rotors, rear pads and rotors, drive belt, tires cupped, poor battery. Hood scratches/chips, front bumper rusted, rear bumper rust/pitted/scraped, left front fender scratches, rear right fender scrape, left rear taillight scraped, rocker panels rusted, roof small chips, no first aid kit/fire extinguisher, windshield chips/bruise, minor exterior damage.>, As is, Where is	191,705 km	\$1,902	3C6TR5CT5FG569427
21,757.00 5-014	Truck 2016 DODGE Ram 3500 4WD, crew cab, 8' box 6.7L, Inline 6, diesel auto A/C, tilt, cruise, AM/FM, power heated trailer tow mirrors, power windows/locks, keyless entry, 2 key fobs front tow hooks, grille inserts, side steps, hitch, trailer wiring, OEM trailer brakes, box liner, headache rack with beacon wigwags and grille wigwags all operational, has a back seat, white, TOW ONLY, This vehicle has a FAILED SGI Inspection. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in "As is, where is" condition., 238,303 km, , KNOWN PROBLEMS and OBSERVATIONS: Check engine light on codes P0562 battery voltage low, P0513 key immobilizer, both front wheel bearings, rear pads and rotors, all 4 tires, alignment needed, poor battery. Hood chips, front bumper rust spots, rear bumper rust spots/bent, all fenders road rash/dents, left front door chips, left rear door paint splattered on inside, tailgate molding broken/dents/scratches, no first aid kit/fire extinguisher/wheel wrench/jack/spare tire, left front seat sagging, all wheel covers loose in back seat, both box rails damaged, minor exterior damage.>, As is, Where is	238,303 km	\$9,999	3C63R3GL4GG246955

Item #	Description	Kms	Min Price	Serial Number
5,000.00 5-001	<p>Van 2007 Chevrolet Express 3500 Cargo RWD 6.0L, V8, gas auto A/C, tilt, cruise, rear aux heat, AM/FM, power locks, 1 key hitch, trailer wiring, electric trailer brake, operational beacon, roof rack, computer stand, shelf, cargo barrier, map box (lid loose), white, TOW ONLY, This vehicle has a FAILED SGI Inspection. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in "As is, where is" condition., 181,649 km, , KNOWN PROBLEMS and OBSERVATIONS: Pitman & idler arm loose, battery tray broken, air bag light on, exterior handle on right rear door broken, windshield gasket loose, high mount brake light not working, right rear tire below minimum tread depth, rear brake pads 2mm, front and rear wheel alignment needed, poor battery.</p> <p>Grille cracked, hood paint poor, both bumpers' rusted/dented/bent, left front fender paint poor, left rear fender scratches/dents, right side fenders paint poor, left rocker panel dented/road rash, left front door paint poor, right side doors paint poor/dents, roof rust, 3 holes in roof sealed, tailgate paint poor/dents/glass fogged, no first aid kit/fire extinguisher, windshield chips/gasket loose, left front seat worn/sagging/vinal cracked, left sun visor broke, minor exterior damage.>, As is, Where is</p>	181,649 km	\$2,125	1GCHG35UX71232881
7,000.00 5-002	<p>Van 2007 Chevrolet Express 3500 Cargo RWD 6.0L, V8, gas auto A/C, tilt, cruise, AM/FM, rear aux heater, power locks, 3 keys hitch, trailer wiring, electric trailer brakes, roof rack with beacon, map box, shelf, cargo barrier, white, TOW ONLY, This vehicle has a FAILED SGI Inspection. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in "As is, where is" condition., 122,956 km, , KNOWN PROBLEMS and OBSERVATIONS: Pitman & idler arm loose, left right rear exhaust, front and rear alignment needed, blower motor not working on high speed, molding around windshield loose, right front marker light not working, high mount brake light not working, driver arm rest broken, headline loose, poor battery.</p> <p>Hood chips/dents, front bumper chips/scratches, rear bumper bent, left front fender paint poor, left rear fender chips/scratches, right front fender paint poor, right rear fender rusted/dents/paint poor, both dog legs rusted, rocker panels rusted, right side door dents/paint poor, roof rust, 3 holes in roof sealed, tailgate paint poor/chips/dents/windows fogged, spare tire loose in back may not be compatible with vehicle, wheel wrench/jack loose in back, no first aid kit/fire extinguisher, windshield chips/rubber gasket loose, left front seat worn/sagging/vinal cracked, left front seat back cushion worn/frame visible, left front inside door handle/arm rest broke, minor exterior damage.>, As is, Where is</p>	122,956 km	\$2,939	1GCHG35U071233716

Item #	Description	Kms	Min Price	Serial Number
14,300.00 5-003	<p>Van 2008 GMC Savana 3500 Cargo RWD 6.0L, V8, gas auto A/C, tilt, cruise, rear aux heat, AM/FM, power front windows/locks, 1 key trailer tow mirrors, hitch, trailer wiring, electric trailer brakes, foam material sprayed in cargo area, cargo barrier, beacon non-operational, white, TOW ONLY, This vehicle has a FAILED SGI Inspection. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in "As is, where is" condition., 102,672 km, , KNOWN PROBLEMS and OBSERVATIONS: Pitman arm loose, idler arm loose, left rear spring broken, need front and rear alignment, tires poor, left front weather strip hanging, left windshield washer non-operational, right front wiper blade needs replacing, poor battery. Hood paint poor, front bumper chips/scratches, rear bumper pad loose/bent, left front fender chips, left rear fender road rash, right rear fender paint poor, left front door paint peeling/weather strip loose/handle loose, right side doors chips/scratches/dents, roof rust spots/scratches, 1 hole in roof sealed, tailgate paint poor/chips/dents, wheel wrench/jack missing, windshield chips, left front seat soft/sagging, left rear quarter extension loose, minor exterior damage.>, As is, Where is</p>	102,672 km	\$2,920	1GTHG35K381209359

Item #	Description	Kms	Min Price	Serial Number
REGINA, SaskBuilds and Procurement, SaskSurplus Sales Lot, 500 McLeod Street - Miscellaneous				
Contact SaskSurplus 306-787-2062 or 306-798-3306.				
285.00 5-159	Air Compressor, Webster , Orange, 4.5L, unknown if operational. Fair		\$1	26,213
6.10 * 3-106	Antenna,, Vehicle roof top magnetic base, 33" mast, 142" cable, condition unknown. Fair		\$5	
1,775.00 5-158	ATV,1994YamahaYFM350 Big Bear4WD,350cc, 1 cylinder, 4 stroke, gas standard electric start, runs pretty good due to low hours. too boxgreen84.5 hrs. KNOWN PROBLEMS: Parked outside it's entire life, paint/plastics are very faded, frame is very rusted, body exterior poor, seat cushion worn. cushion visible. As is. Where is	84.5 hrs.	\$500	JY43HNN00RA169484
2.00 5-108	Base Mounts,Lot of 3metal, Black, for handheld radio. Fair		\$1	HLN7002A
3.00 5-109	Base Mounts,Lot of 5metal, Black, for handheld radio. Fair		\$1	HLN7002A
3.00 5-110	Base Mounts,Lot of 5metal, Black, for handheld radio. Fair		\$1	HLN7002A
30.00 5-111	Base, Handhelds, Chargers,Set of 6Motorola XTL 2500, M21KSM9PW1AN (base), Motorola XTS 2500 3 VHF (handheld), 1 charger, 2 microphones, 1 base, 1 handheld, and 1 antenna, radio crystals are scrambled, operational. Fair		\$1	2,261,570
30.00 5-112	Base, Handhelds, Chargers,Set of 6Motorola XTL 2500, M21KSM9PW1AN (base), Motorola XTS 2500 3 VHF (handheld), 1 charger, 2 microphones, 1 base, 1 handheld and 1 antenna, radio crystals are scrambled, operational. Fair		\$1	2,261,555
30.00 5-113	Base, Handhelds, Chargers,Set of 6Motorola XTL 2500, M21KSM9PW1AN (base), Motorola XTS 2500 3 VHF (handheld), 1 charger, 2 microphones, 1 base, 1 handheld and 1 antenna, radio crystals are scrambled, operational. Fair		\$1	2,261,602
150.00 5-114	Base, Handhelds, Chargers,Set of 31Motorola XTL 2500, M21KSM9PW1AN (base), Motorola XTS 2500 3 VHF (handheld), 10 chargers, 10 microphones, 5 bases, 5 handhelds and 1 antenna, radio crystals are scrambled, operational. Fair		\$1	2,261,699
150.00 5-115	Base, Handhelds, Chargers,Set of 31Motorola XTL 2500, M21KSM9PW1AN (base), Motorola XTS 2500 3 VHF (handheld), 10 chargers, 10 microphones, 5 bases, 5 handhelds, and 1 antenna, radio crystals are scrambled, operational. Fair		\$1	2,261,579
150.00 5-116	Base, Handhelds, Chargers,Set of 31Motorola XTL 2500, M21KSM9PW1AN (base), Motorola XTS 2500 3 VHF (handheld), 10 chargers, 10 microphones, 5 bases, 5 handhelds, and 1 antenna, radio crystals are scrambled, operational. Fair		\$1	2,261,585
150.00 5-117	Base, Handhelds, Chargers,Set of 31Motorola XTL 2500, M21KSM9PW1AN (base), Motorola XTS 2500 3 VHF (handheld), 10 chargers, 10 microphones, 5 bases, 5 handhelds, and 1 antenna, radio crystals are scrambled, operational. Fair		\$1	2,261,613
300.00 5-118	Base, Handhelds, Chargers,Set of 46Motorola XTL 2500, M21KSM9PW1AN (base), Motorola XTS 2500 3 VHF (handheld), 10 chargers, 15 microphones, 10 bases, 10 handhelds, and 1 antenna, radio crystals are scrambled, operational. Fair		\$1	2,261,573

Item #	Description	Kms	Min Price	Serial Number
300.00 5-119	Base, Handhelds, Chargers,Set of 46Motorola XTL 2500, M21KSM9PW1AN (base), Motorola XTS 2500 3 VHF (handheld), 10 chargers, 15 microphones, 10 bases, 10 handhelds, and 1 antenna, radio crystals are scrambled, operational. Fair		\$1	2,261,659
300.00 5-120	Base, Handhelds, Chargers,Set of 46Motorola XTL 2500, M21KSM9PW1AN (base), Motorola XTS 2500 3 VHF (handheld), 10 chargers, 15 microphones, 10 bases, 10 handhelds, and 1 antenna, radio crystals are scrambled, operational. Fair		\$1	2,261,660
300.00 5-121	Base, Handhelds, Chargers,Set of 46Motorola XTL 2500, M21KSM9PW1AN (base), Motorola XTS 2500 3 VHF (handheld), 10 chargers, 15 microphones, 10 bases, 10 handhelds, and 1 antenna, radio crystals are scrambled, operational. Fair		\$1	2,261,674
31.23 5-122	Base, Handhelds, Chargers,Set of 6Motorola XTL 2500, M21KSM9PW1AN (base), Motorola XTS 2500 3 VHF (handheld), 2 chargers, 2 microphones, 1 base, 1 handheld, and 1 antenna, radio crystals are scrambled, operational. Fair		\$1	2,261,562
30.00 5-123	Base, Handhelds, Chargers,Set of 7Motorola XTL 2500, M21KSM9PW1AN (base), Motorola XTS 2500 3 VHF (handheld), 2 chargers, 2 microphones, 1 base, 1 handheld, and 1 antenna, radio crystals are scrambled, operational. Fair		\$1	2,261,636
150.00 5-124	Base, Handhelds, Chargers,Set of 29Motorola XTL 2500, M21KSM9PW1AN (base), Motorola XTS 2500 3 VHF (handheld), 8 chargers, 10 microphones, 5 bases, 5 handhelds and 1 antenna, radio crystals are scrambled, operational. Fair		\$1	2,261,558
150.00 5-125	Base, Handhelds, Chargers,Set of 29Motorola XTL 2500, M21KSM9PW1AN (base), Motorola XTS 2500 3 VHF (handheld), 8 chargers, 10 microphones, 5 bases, 5 handhelds, and 1 antenna, radio crystals are scrambled, operational. Fair		\$1	2,261,577
150.00 5-126	Base, Handhelds, Chargers,Set of 27Motorola XTL 2500, M21KSM9PW1AN (base), Motorola XTS 2500 3 VHF (handheld), 8 chargers, 8 microphones, 5 bases, 5 handhelds, and 1 antenna, radio crystals are scrambled, operational. Fair		\$1	2,261,539
150.00 5-127	Base, Handhelds, Chargers,Set of 27Motorola XTL 2500, M21KSM9PW1AN (base), Motorola XTS 2500 3 VHF (handheld), 8 chargers, 8 microphones, 5 bases, 5 handhelds, and 1 antenna, radio crystals are scrambled, operational. Fair		\$1	2,261,567
150.00 5-128	Base, Handhelds, Chargers,Set of 27Motorola XTL 2500, M21KSM9PW1AN (base), Motorola XTS 2500 3 VHF (handheld), 8 chargers, 8 microphones, 5 bases, 5 handhelds, and 1 antenna, radio crystals are scrambled, operational. Fair		\$1	2,261,583
150.00 5-129	Base, Handhelds, Chargers,Set of 17Motorola XTL 2500, M21KSM9PW1AN (base), Motorola XTS 2500 3 VHF (handheld), 8 chargers, 8 microphones, 5 bases, 5 handhelds, and 1 antenna, radio crystals are scrambled, operational. Fair		\$1	2,261,589
150.00 5-130	Base, Handhelds, Chargers,Set of 27Motorola XTL 2500, M21KSM9PW1AN (base), Motorola XTS 2500 3 VHF (handheld), 8 chargers, 8 microphones, 5 bases, 5 handhelds, and 1 antenna, radio crystals are scrambled, operational. Fair		\$1	2,261,599
150.00 5-131	Base, Handhelds, Chargers,Set of 27Motorola XTL 2500, M21KSM9PW1AN (base), Motorola XTS 2500 3 VHF (handheld), 8 chargers, 8 microphones, 5 bases, 5 handhelds, and 1 antenna, radio crystals are scrambled, operational. Fair		\$1	2,261,648

Item #	Description	Kms	Min Price	Serial Number
150.00 5-132	Base, Handhelds, Chargers, Set of 27 Motorola XTL 2500, M21KSM9PW1AN (base), Motorola XTS 2500 3 VHF (handheld), 8 chargers, 8 microphones, 5 bases, 5 handhelds, and 1 antenna, radio crystals are scrambled, operational. Fair		\$1	2,261,653
150.00 5-133	Base, Handhelds, Chargers, Set of 27 Motorola XTL 2500, M21KSM9PW1AN (base), Motorola XTS 2500 3 VHF (handheld), 8 chargers, 8 microphones, 5 bases, 5 handhelds, and 1 antenna, radio crystals are scrambled, operational. Fair		\$1	2,261,696
150.00 5-134	Base, Handhelds, Chargers, Set of 27 Motorola XTL 2500, M21KSM9PW1AN (base), Motorola XTS 2500 3 VHF (handheld), 8 chargers, 8 microphones, 5 bases, 5 handhelds, and 1 antenna, radio crystals are scrambled, operational. Fair		\$1	2,261,710
150.00 5-135	Base, Handhelds, Chargers, Set of 27 Motorola XTL 2500, M21KSM9PW1AN (base), Motorola XTS 2500 3 VHF (handheld), 8 chargers, 8 microphones, 5 bases, 5 handhelds, and 1 antenna, radio crystals are scrambled, operational. Fair		\$1	2,261,556
150.00 5-136	Base, Handhelds, Chargers, Set of 27 Motorola XTL 2500, M21KSM9PW1AN (base), Motorola XTS 2500 3 VHF (handheld), 8 chargers, 8 microphones, 5 bases, 5 handhelds, and 1 antenna, radio crystals are scrambled, operational. Fair		\$1	2,261,581
20.00 5-137	Battery Packs, Lot of 9 Motorola 9V, AA Alkaline Battery Pack, For handheld radio, operational. Fair		\$1	NNTN6686B
510.00 * 4-101	Brake Lathe , RJM, RJ West, Model no. 9150-1ME, A piece of machinery that corrects the thickness variations on a rotor, with lamp and storage area, accessories in separate metal box. Excellent		\$500	153,140,387
7.00 5-138	Chargers, Lot of 2 Handheld, For Motorola, operational. Fair		\$1	WPLN4243A
30.00 5-139	Chargers, Lot of 6 Impres Adaptive , For handheld radio, no power cords, operational. Fair		\$1	10273776730097MKM01
120.00 5-140	Chargers, Handhelds, Microphones, Set of 25 Motorola XTS 2500 3 VHF (handheld), 9 chargers, 8 microphones, and 8 handhelds, radio crystals are scrambled, operational. Fair		\$1	1,376
3.00 5-141	Duty Belt, Lot of 22, Belt accessories, 22 Motorola belt clips. Fair		\$1	HLN6853A
2.00 * 4-133	Duty Belt Accessories, Radio holder belt clips, With spring clip which attaches to battery pack. Good		\$1	
6.99 5-142	Duty Belt Pouches, Lot of 12, Belt accessories, 10 duty belt pouches, 1 suspender and 1 duty belt. Fair		\$1	
10.00 5-143	Ear Buds, Lot of 11, Wired, for handheld radio, operational. Fair		\$1	
No Bid * 3-134	Floor Insert, 2015, Chevrolet Suburban, Interior rear floor cabin insert, black. Excellent		\$1	
75.75 5-161	Generator, Briggs and Stratton, 5000W, 282255-1, Generac, Blue, 11 hp, 120-240 volts, two 15 amp plug-ins, 1 120/240 vplug-in, 4 cycle, unknown if operational. Fair		\$1	696,872
84.50 5-162	Generator, Briggs and Stratton, 5000W, 8225-1, Generac, Blue, 11 hp, 120-240 volts, two 15 amp plug-ins, 1 120/240 vplug-in, 4 cycle, unknown if operational. Poor		\$1	696,871

Item #	Description	Kms	Min Price	Serial Number
80.50 5-160	Generator, Briggs and Stratton, 5000W, 8711-0, Generac, Brown, 11 hp, 120-240 volts, two 15 amp plug-ins, 1 120/240 v plug-in, 4 cycle, unknown if operational. Fair		\$1	721,016
285.00 5-163	Generator, Honda EM, 3000W, Red, 21.7 A plug-in, 2 20 amp plug-ins, operational, hours unknown. Good		\$1	EZGL-1034204
285.00 5-164	Generator, Honda EM, 3000W, Red, 21.7 A plug-in, 2 20 amp plug-ins, operational, hours unknown. Good		\$1	EZGL-1039343
200.00 5-144	Handhelds and Microphones, Set of 28 Motorola XTS 2500 3 VHF (handheld), 14 handhelds and 14 microphones, radio crystals are scrambled, operational. Fair		\$1	407CLK0079
120.00 5-145	Handhelds and Microphones, Set of 18 Motorola XTS 2500 3 VHF (handheld), 8 handhelds and 10 microphones, radio crystals are scrambled, operational. Fair		\$1	407CLK0075
120.00 5-146	Handhelds and Microphones, Set of 16 Motorola XTS 2500 3 VHF (handheld), 8 handhelds and 8 microphones, radio crystals are scrambled, operational. Fair		\$1	407CLK0110
400.00 5-147	Handhelds, Chargers, Microphones, and Holster, Set of 1 Motorola APX 4000R (handheld), 2 chargers, 4 microphones, 4 handhelds, and 1 leather radio holster, radio crystals are scrambled, operational. Fair		\$1	426CSX8032
5.00 5-148	Holsters, Lot of 2 Motorola XTS 2500 3 VHF, For handheld, leather. Fair		\$1	4,205,857,809
3.00 5-149	Holsters, Lot of 5 Motorola XTS 2500 3 VHF, For handheld, leather. Fair		\$1	4,205,857,809
6.99 5-150	Holsters, Lot of 5 Motorola XTS 2500 3 VHF, For handheld, leather. Fair		\$1	4,205,857,809
6.99 5-151	Holsters, Lot of 5 Motorola XTS 2500 3 VHF, For handheld, leather. Fair		\$1	4,205,857,809
3.00 5-152	Holsters, Lot of 5 Motorola XTS 2500 3 VHF, For handheld, leather. Fair		\$1	4,205,857,809
3.00 5-153	Holsters, Lot of 5 Motorola XTS 2500 3 VHF, For handheld, leather. Fair		\$1	NNTN4115A
107.00 5-101	Ladder Rack, Weather Guard, Assembled with beacon, beacon may be non-operational, white. Fair		\$100	410,258
40.00 5-102	Ladder Rack, Weather Guard, Not assembled, may be missing parts, beacon may be non-operational, white. Fair		\$30	410,720
6.99 5-154	Pouches, Lot of 4 nylon, For radio. Fair		\$1	PMLN6802A
5.50 * 3-108	Power Inverter, Prowatt 150, 150 watts of portable AC power, 1 AC output, on/off switch, condition unknown, may not be complete. Poor		\$5	
5.50 * 3-109	Power Inverter, Samlexpower 450, 450 watts, 2 AC outputs, on/off switch, condition unknown, may not be complete. Poor		\$5	
10.00 5-155	Radios, Motorola, Relay box, microphone, switch station, radio crystals are scrambled, operational. Fair		\$1	RDS-RK
20.00 5-156	Radios, Motorola XTL 2500, face plate, radio crystals are scrambled, operational. Fair		\$1	HLN6912B
21.00 5-157	Radios, Motorola, Knwood, 2-way, microphone and base, radio crystals are scrambled, operational. Fair		\$1	20,400,103
25.00 * 3-120	Seat, 2013, Dodge Ram 3500, Rear, grey. Excellent		\$1	

Item #	Description	Kms	Min Price	Serial Number
No Bid * 3-123	Seat,2014, Dodge Ram 4500, Rear, grey. Excellent		\$1	
No Bid * 3-124	Seat,2014, Dodge Ram 4500, Rear, parts, winter grille cover included, grey. Excellent		\$1	
25.00 * 3-125	Seat,2014, Dodge Ram 5500, Rear, grey. Excellent		\$1	
No Bid * 3-126	Seat,2015, Chevrolet Silverado 2500, Rear, grey. Excellent		\$1	
No Bid * 3-127	Seat,2015, Dodge Ram 2500, Rear, grey. Excellent		\$1	
No Bid * 3-128	Seat,2015, Dodge Ram 4500, Rear, grey. Excellent		\$1	
No Bid * 3-130	Seat,2016, Chevrolet Suburban, Rear, black. Excellent		\$1	
No Bid * 3-131	Seat,2016, Dodge Ram 3500, Rear, grey. Excellent		\$1	
No Bid * 3-133	Seat,2018, Chevrolet Suburban, Rear, black. Excellent		\$1	
5.88 * 3-162	Shovel,Jobmate, Plastic scoop, 38"L, wooden shaft, D handle. Good		\$5	
5.88 * 3-163	Shovel,Melnor, Plastic scoop, 38"L, 2 piece metal shaft, D handle. Good		\$5	
112.12 5-103	Tailgate,Ram, OEM. Suitable for parts, white, may be compatible with 2016 model Rams, missing top guard (molding), dented, bent, scratches, rust spots. Poor		\$25	
963.04 * 4-102	Tire Changer,FMC Corp, With air, accessories in separate metal box, steel rims only, operational. Good		\$500	L1200007
180.01 * 4-118	Tires,Set of 4205/70R/16, Firestone Destination LE3, M+S, Manufacture date. Week 07, year 2020. Good		\$180	
105.00 * 4-119	Tires,Set of 4225/60R/16, BF Goodrich Winter T/A KSI, Snowflake, Manufacture date. Week 11, year 2021. Poor		\$40	
161.02 5-105	Tires,Set of 4225/60R/16, Firestone FR710, M+S, Manufacture date. Week 02, year 2017. Good		\$160	
186.00 5-106	Tires,Set of 4225/60R/16, Sumitomo Ice Edge, Snowflake, M+S, Manufacture date. Week 17, year 2019. Excellent		\$180	
188.00 5-107	Tires,Set of 4225/60R/18, Michelin Primacy A/S, M+S, Manufacture date. Week 44, year 2021. Fair		\$130	
215.00 * 4-121	Tires,Set of 4225/60R/18, Michelin Primary AIC, M+S, Manufacture date. Week 50, year 2021. Good		\$180	
160.00 5-104	Tires,Set of 4 235/65R/17, Continental Cross Contact, M+S, Manufacture date. Week 08, year 2021. Fair		\$120	
1,000.00 5-165	Trailer,1994Wylie, Steel frame wood deck, 2.5" pintle ring, 78"w x 8'l x 55"h, 9 plug-in connector, tire size ST225/75R15, grated ramp, front grated barrier, single axle, two side compartments behind each wheel well. KNOWN PROBLEMS: Rust/scratches. As is, Where is		\$500	2W9UB08N5Q1005004

Item #	Description	Kms	Min Price	Serial Number
751.00 5-166	Trailer,1994Wylie, Steel frame wood deck, 3" pintle ring, 78"w x 8'l x 33"h, 9 plug-in connector, tire size ST225/75R15, single axle, no ramp, two side compartments behind each wheel well. KNOWN PROBLEMS: Rust/scratches, dent on front face wall. As is, Where is		\$500	2W9UB08N3Q1005003
1,100.00 * 4-110	Wheel Balancer,Sun Computer, Sun Electric, Model no. CWB-1762, With hood, weight tray, and electronic display, accessories in separate metal box with weights, operational. Excellent		\$1,000	1086A1910
50.00 * 1-105	Desk,Steelcase, Disassembled, main 63"w x 30"d x 30"h, L-side unknown 44"w 24"d x 30"h, desk comes with two drawers no keys, modesty panels, surface tops and gables comes with instruction booklet, scratches (wear and tear). Fair		\$20	

Item #	Description	Kms	Min Price	Serial Number
BESNARD LAKE, Corrections Policing and Public Safety 20-17-02-W3				
Contact Tiffany Pocha 306-953-3162, tiffany.pocha@gov.sk.ca or Kim Barnes 306-425-4014, kim.barnes@gov.sk.ca				
No Bid * 4-527	Bowflex, Xtreme, Missing cables, and top bar, unknown if operational. Broken Repairable		\$50	
No Bid * 4-528	Dumbbells, Lot of 2 Hex, metal, 55 lbs. Good		\$55	
No Bid * 4-529	Dumbbells, Lot of 2 Hex, metal, 60 lbs. Good		\$60	
No Bid * 4-530	Dumbbells, Lot of 2 Hex, metal, 65 lbs. Good		\$65	
No Bid * 4-531	Dumbbells, Lot of 2 Hex, metal, 75 lbs. Good		\$75	
No Bid * 4-532	Dumbbells, Lot of 2 Hex, metal, 85 lbs. Good		\$85	
No Bid * 4-533	Dumbbells, Lot of 2 Hex, metal, 95 lbs. Good		\$95	
No Bid 5-507	Milk Cooler, Silver King, SKMAJ1CA, 15.25" l x 17.25" w x 39.5" h, operational. Good		\$1,500	BRDP336904A
No Bid 5-506	Toaster, Omcan, 19938, Commercial 10" wide, conveyor with 3" opening, 120 V, 1800W, operational. Good		\$200	68,351,810,136,027
No Bid * 4-534	Weights, Lot of 2 plastic, 15 lb. Good		\$15	
No Bid * 4-535	Weights, Lot of 2 plastic, 15 lb. Good		\$25	
BIG RIVER, Saskatchewan Public Safety Agency, PO Box 249, 20J 0E0				
Contact Alan Dunn 306-469-2500, alan.dunn@gov.sk.ca or Phane Ray 306-469-2504, phane.ray@gov.sk.ca				
15.00 * 4-538	Drafting Table, wood, melamine, 60" l x 37.5" w, adjustable angles and height, operational. Good		\$1	
10.00 * 4-539	Miter Saw, metal, With cutting depth adjustment, angle selection lever, wood cutting blade, blue, manual, operational. Good		\$1	
50.00 * 4-536	Windows, Lot of 2 Plastic, 31.5" w x 31.5" h, for 2" x 4" construction, with glass, unknown condition, fittings not included. Fair		\$1	
CUTBANK, Water Security Agency, SE-12-27-07-W3				
Contact Ayold Elgersma 306-631-0460, ayold.elgersma@wsask.ca or Jason Eliason 306-620-6377, jason.eliason@wsask.ca				
2,588.91 5-502	ATV 2000 YAMAHA Kodiak 4x4 400 cc, gas auto front mount winch, tire size, front 25 x 8 x 12, back 25 x 10 x 12, green, , unknown hrs, , KNOWN PROBLEMS: Paint faded, scratches and chips, As is, Where is	unknown	\$300	JY4AJ03W2YA033474
No Bid * 4-513	Chairs, Lot of 12 Metal, fabric, Brown, grey, no wheels, with arms, 6 stackable and 6 non stackable. Fair		\$1	
No Bid * 4-515	Inclinometer Reel, HMA Geotechnical system, 2014, Type UMI 40 G , Includes attachments, hand control, foot control & auto stop pulley, 1/28 ratio, 12 DC EMP Motor (M5-7172703), clock wise - 500ft, operational. Excellent		\$200	53,008,186

Item #	Description	Kms	Min Price	Serial Number
4,860.00 5-503	Lawn Mower 2010 JOHN DEERE Z910A 2WD, zero turn 22 hp, Kawasaki, gas hydrostatic 48" deck adjustable rollbar, green, , 425 hrs, , KNOWN PROBLEMS: Needs new battery, seat torn, deck side-shoot damaged, deck paint scrapes., As is, Where is	425 hrs	\$4,700	TC910AF010681
320.00 * 4-518	Paint Sprayer, Airless, 2002, Graco King, 245-111, Ratio 56:1, input/output psi 100/5600, build in wheel cart 259 lbs, unknown if operational. Fair		\$300	Series G02A
25,100.00 5-505	Tractor 1981 JOHN DEERE 4240 2WD 7.6L, V6, diesel manual A/C, heater, tilt, dual hydraulics quad range transmission, 16 speed partial power shift, dual tires, tire size dual rear 20.8-34 front 10.00-16, tire ply 8, green, , 6630 hrs, , KNOWN PROBLEMS: Needs air conditioner repair, fuel and hydraulic leaks, motor/transmission/front tires/body exterior/exhaust/windshield glass good, rear tires poor, brakes/lights/horn unknown, needs battery, windshield washer & wipers/interior fair, paint faded, mirrors missing, minor exterior damage.>, As is, Where is	6630 hrs	\$3,500	4240H022217R
12,610.00 5-504	Tractor 1990 JOHN DEERE 2155 Front Wheel Assist 4x4 2.9L, V3, diesel 8 speed non-synchronized 3 point hitch single tire, rear 16.9-28 front 9.5-24, green, , 3870 hrs, , KNOWN PROBLEMS: Needs 12V battery, seat fabric missing/bad, motor/transmission/body exterior good when parked approx. 4 years ago, tires - rear fair, front cracked/poor, brakes unknown, exhaust good, paint faded, minor exterior damage.>, As is, Where is	3870 hrs	\$1,000	XL02155F704437X
4,000.47 5-501	Gravel Truck 1983 GMC 7000 2WD V8, gas, 366 cc manual 13' steel box with removable gravel dump gate 10 ton power take off (PTO) winch, 25 ton scissor hoist, dual cylinder, GVW, 24500 lb, 5 speed, single axle, wheel base 168", standard differential, dual tire, tire size - front 10.00 R20, back 9.00 R20, front 16 ply, rear 10 ply, blue, TOW ONLY, NO SGI Inspection. It is unknown if any repairs or safety concerns exist (if any). Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs if required. , 94,533 km, , KNOWN PROBLEMS: Battery poor, needs to be replaced, fuel leak at carburetor, old fuel in tank, grill cracked, exterior and paint rust, windshield washer and wipers need to be replaced, seat torn and dash cracked, minor exterior damage.>, As is, Where is	94,533 km	\$200	1GDJ7D1B6DV504581

Item #	Description	Kms	Min Price	Serial Number
11,177.00 5-518	SUV 2010 JEEP Wrangler Sahara 4WD, 2 door 3.8L, V6, gas auto Air, cruise, tilt, power windows, power locks, command start wheel base 95.4', differential type Dana 44HD/Dana 30 tire size LT275/65/18 (studded winter), load range E, set of summer tires included, Red Rock Crystal Pearl, TOW ONLY, NO SGI Inspection. It is unknown if any repairs or safety concerns exist (if any). Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs if required. , 104,892 km, , KNOWN PROBLEMS: motor/transmission/brakes/battery/exhaust/windshield glass/windshield wipers & washers/lights/mirrors/horn good tires good (75% tread on both sets), body exterior 2 minor dents on side of cowl, paint some scratches, interior dirty/some scratches/missing floor mats, minor exterior damage.>, As is, Where is	104,892 km	\$3,000	1J4AA5D12AL147061
4,160.00 5-521	Truck 2012 CHEVROLET Silverado 1500 4WD, Crew Cab, short box 5.3L, V8, gas Auto A/C, cruise, tilt single axle, single tire 265/70R/17, grey, TOW ONLY, NO SGI Inspection. It is unknown if any repairs or safety concerns exist (if any). Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs if required. , 199,305 km, , KNOWN PROBLEMS: Transfer case issue, will not always engage, motor fair, transmission/tires/brakes/battery/exhaust/windshield washer & wipers/mirrors/horn/interior good, body exterior small rust spots/trim missing, windshield glass chips, paint chips and brown door, lights one headlight burnt out, minor exterior damage.>, As is, Where is	199,305 km	\$1,000	3GCPKSE79CG137464
DUCK MOUNTAIN PROVINCIAL PARK, Corrections Policing and Public Safety, Call for Directions				
Contact Travis Hourd 639-941-7074, travis.hourd@gov.sk.ca				
277.00 5-570	Bear Trap,Culvert style, 10' x 3'. Swing door is operational, damaged coupler, no safety chains, no lights. no danger to public, buyer responsible for anything caught in trap. Poor		\$1	
MOOSE JAW, Highways, 1 km South of Moose Jaw on Hwy. 2				
Contact Al Froehlich 306-694-3775, allan.froehlich@gov.sk.ca or Tara Watson 306-694-3773, tara.watson@gov.sk.ca				
No Bid * 4-525	Crane 1949 Hyster Karry 4 cylinder, gas manual , yellow, , unknown hrs, , KNOWN PROBLEMS: Does not run, some tires flat, lights, motor and transmission in unknown condition, brakes unknown if operational, battery is poor, missing mirrors, horn non-operational.>. As is, Where is	unknown hrs	\$1,000	42,840
251.01 * 4-522	Roller 1976 Massey SP912 Self propelled Ford 300, inline 6, gas Funk, 4 speed tire size, 7.5 x15, 14 ply, yellow, , unknown hrs, , KNOWN PROBLEMS: Motor, transmission, brakes, and battery all condition unknown, possible parts missing like transmission, tires etc., tires, body, paint, exhaust all in poor condition, lights non-operational.>, As is, Where is	unknown hrs	\$100	239

Item #	Description	Kms	Min Price	Serial Number
297.00 * 4-524	Roller 1976 Massey SP912 Self propelled Ford 300, inline 6, gas Funk, 4 speed , yellow, , unknown hrs, , KNOWN PROBLEMS: Motor, transmission, brakes, and battery unknown condition, body, paint and exhaust all in poor condition, lights non-operational., As is, Where is	unknown hrs	\$100	S114248
277.00 * 4-523	Roller 1977 Massey SP912 Self propelled Ford 300, inline 6, gas Funk, 4 speed tire size, 7.5 x15, 14 ply, yellow, , unknown hrs, , KNOWN PROBLEMS: Motor, transmission, brakes, and battery all unknown condition, tires, body, paint and exhaust all in poor condition, lights non-operational, may be missing parts.>, As is, Where is	unknown hrs	\$100	283
NIPAWIN, Water Security Agency, 300 Timber Dr				
Contact Ayold Elgersma 306-631-0460, ayold.elgersma@wsask.ca or Water Security Agency 306-862-1750.				
39.33 * 3-502	Culvert,metal,galvanized, 46"diameter x 96" length, corrugated with rust. Poor		\$10	
No Bid * 3-503	Culvert Collar,metal, 36" diameter, with some rust. Good		\$10	
No Bid * 3-504	Culvert Collar,metal, 48"diameter, with some rust. Good		\$10	
No Bid * 3-510	Culvert Gate,metal, 28" diameter yellow, with some rust. Good		\$10	
No Bid * 3-509	Culvert Gate,metal, 43" diameter, yellow, with some rust. Good		\$10	
No Bid * 3-512	Culvert Gates, Lot of 3 metal, 26" diameter, yellow, with some rust. Good		\$10	
No Bid * 3-513	Culvert Insert with Gate,metal, 13" length, 26" diameter, with some rust, no fittings included. Fair		\$10	
No Bid * 3-514	Culvert Insert with Gate,metal, 50" length, 43" diameter, with some rust, manual wheel and screw opener included. Fair		\$10	
No Bid * 3-516	Hoist, Stationary Frame, Not certified, frame 8' 7" length, base 6' w x 6' d. Fair		\$300	
No Bid * 3-520	Tool Box, Yukon Elite, aluminium, For truck box, 56.4" w x 14.4" d x 14.4" h, locks, no key. Good		\$25	
25.00 * 3-521	Tool Box, Yukon Elite, aluminium, For truck box, 68.4" w x 18" d x 15.6" h, locks, no key. Good		\$25	
PREECEVILLE, Corrections Policing and Public Safety, 239 Hwy Ave E				
Contact John Petryshyn 306-547-7530, johnny.petryshyn@gov.sk.ca or Nathan Dutchak 306-590-7636, nathan.dutchak@gov.sk.ca				
33.33 5-581	Hunting Camp Accessories, Lot of 8 Assorted, Tarp garage, unknown condition, with polls, 5 folding chairs, propane broiler, operational, 1 plastic barrel, 2 metal barrels, barrels were storing the items and hidden in the forest, clean of previous material to store current items. Poor		\$1	
38.00 5-582	Tree stands, Lot of 3 Homemade, metal, Approx. 10' high, welded ladder with plywood seats. Poor		\$1	

Item #	Description	Kms	Min Price	Serial Number
58.13 5-583	Truck Tool Box,Challenger Aluminum, 13" w x 13" d x 48" h, lid has dent, does not close properly, no keys for lock, locks don't work. Broken Repairable		\$1	
No Bid 5-584	Truck Tool Box,Challenger, Aluminum, 13" w x 13" d x 60" h, latch is non operational, no keys for lock. Broken Repairable		\$1	
PRINCE ALBERT, Highways, 81 North Industrial Dr.				
Contact Rob Allard 306-960-3953, robert.allard@gov.sk.ca				
401.00 5-523	Snow Plow,Attachment, Monroe, MP41R12-ISCT, 12', two way with trip. Poor		\$1	07-03-1074
103.99 5-524	Snow Plow,Attachment, Monroe, MP41R12-ISCT, 12', two way with trip. Poor		\$1	08 03 1119
103.99 5-525	Snow Plow,Attachment, WBM, 196-995-008, 12', two way with trip. Poor		\$1	3-69561-2
103.99 5-526	Snow Plow,Attachment, WBM, 196-995-12, 12', two way with trip. Poor		\$1	3-90907-1
8,491.00 5-520	Wheel Loader 1990 CASE W11B 4WD 3.9L, inline4, diesel Powershift heater standard differential, single tire, tire size 15/19.5, approx. weight 12,700 lbs, yellow, , unknown hrs, , KNOWN PROBLEMS: All pins and bushings are worn out, cab has rust on the inside, unit has oil leaks, motor/transmission/brakes/exhaust/windshield glass/windshield washer & wipers/lights/mirrors/horn fair, tires/battery/body exterior/paint/interior poor, minor exterior damage > As is, Where is	unknown hrs	\$6,000	W11BJAK0017491
10,013.00 5-522	Wheel Loader 1991 CASE W11B 4WD 3.9L, inline4, diesel Powershift heater standard differential, 3 speed, single tire, tire size 15/19.5, approx. weight 12,700 lbs, yellow, , 887 hrs, , KNOWN PROBLEMS: Brakes are soft, all pins and bushings are worn out, cab has rust inside, unit has oil leaks, motor/transmission/exhaust/windshield glass/windshield washer & wipers/lights/mirrors/horn fair, tires/brakes/battery/body exterior/paint/interior poor, minor exterior damage.>, As is, Where is	887 hrs	\$6,000	W11BJAK0025047
4,500.00 * 4-570	Trailer 1976 Miller OT32 Tandem axle trailer, dual tire 8'6"w x 22' deck, yellow, TOW ONLY, NO SGI Inspection. It is unknown if any repairs or safety concerns exist (if any). Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs if required. , 160,086 km, , KNOWN PROBLEMS: Unknown problems non current safety inspection must be inspected before plating TOW ONLY, tires poor, brakes/body exterior/paint/lights fair, minor exterior damage.>, As is, Where is	160,086 km	\$3,000	19,100
PRINCE ALBERT, Saskatchewan Public Safety Agency, 2120 Central Ave N				
Contact Keri Roles 306-930-8305, keri.rolles@gov.sk.ca or Duane Barlow 306-953-3409, duane.barlow@gov.sk.ca				
No Bid * 3-544	Desk,Set of 4wood, L-shape, Grey, 3 piece desks with a left side hutch - approx. 84" w x 78" d x 28.5" h and 1 hutch approx. 42" w x 42" d. Good		\$1	

Item #	Description	Kms	Min Price	Serial Number
PRINCE ALBERT, Saskatchewan Public Safety Agency, 2120 Central Ave N				
Contact Wanda Dickie 306-953-3434, wanda.dickie@gov.sk.ca or Tammy Lukaszuk 306-953-3392, tammy.lukaszuk@gov.sk.ca				
No Bid * 3-546	Desk Extension,pepperdust, Left hand, 30" w x 48" d x 29" h. Good		\$1	
No Bid * 3-547	Desk Extension,pepperdust, Left hand, 42" w x 20" d x 28" h. Good		\$1	
No Bid * 3-553	Pedestal,pepperdust, 3 drawer, lateral, 24" d x 16.5" w x 26.5" h, no key for the lock, wheels are broken, bottom drawer has stain. Fair		\$1	
PRINCE ALBERT, Saskatchewan Public Safety Agency, 2120 Central Ave N				
Contact Suzanne Goota 306-941-7217, suzanne.goota2@gov.sk.ca or Karla Ens 306-953-3416, karla.ens@gov.sk.ca				
No Bid * 3-558	File Cabinet,metal, 4 drawer, lateral, Beige, no keys for the lock, 36" w x 19" d x 67" h. Good		\$1	
REGINA, Agriculture, 1610 Park St				
Contact James Bush 306-798-0100, james.bush@gov.sk.ca				
No Bid * 1-502	Autopipetting Robot Tecan Computer Controlled Liquid Handling Robot 42" x 41" x 44". This needs software to function, and software is on a flash drive that is included. There is no training manual, but usually Tecan would come out and train users on it. There is no risk to sell to public. Operational. Good		\$25,000	
REGINA, Immigration and Career Training, 10th Floor, 2103 - 11th Avenue				
Contact Verna Ziegler 306-787-2580, verna.ziegler@gov.sk.ca or Kayla Swicheniuk 306-787-5014, kayla.swicheniuk@gov.sk.ca				
No Bid * 3-590	Shelf ,wooden, Brown, removable shelves, 29.5" w x 12" d x 24" h. Fair		\$5	
REGINA, Innovation Saskatchewan, 1 Research Dr				
Contact Azmina Punjani 306-551-5106, azmina.punjani@innovationsask.ca or Nick Wilkes 306-539-9022, nick.wilkes@innovationsask.ca				
No Bid 5-585	Generator,1989, Onan, Genset, KTA50-G3 - 1250 KTA53 1250 DFCL 60Hz, Cummins, KTA50-G3, type V, 16 cylinder, 4 cycle, direct injection diesel. Aspiration, turbocharged & aftercooled, compression ratio: 13:9:1, regenerative power, 207 kW, injection system, Cummins PT direct injection, 1850 BHP, 1380 kW, displacement, 3067 cu in 50.3 L, bore 6.25 in 150 mm, stroke, 6.25 in 159 mm, piston speed, 1875 ft/min 9.5 m/s, BMEP, 257 psi 1769 kPa. Onan 1250 DFCL-H/36359E, Simmax PPC 7000 power plant controller. V type, 16 cylinder. #2 diesel,. rating 60 Hertz, output 1250 kW 1563 kVA, operational. Will be decommissioned after sale, for uninstallation and loading. *Appointment must be scheduled for viewing and for pickup Fair		\$20,000	L897101432

Item #	Description	Kms	Min Price	Serial Number
REGINA, Justice and Attorney General, 515 Henderson Dr				
Contact Cael Halayka 306-539-1975, cael.halayka@gov.sk.ca or Aaron Wilgosh, aaron.wilgosh@gov.sk.ca				
20.00	5-587	Chair,leather, swivel, Black, 22" l x 25" w x 48" h. Fair	\$1	
No Bid	5-588	Chair,plastic, Tan, 19.5" l x 18.25" w x 30.5" h, no arms. Excellent	\$1	
1.00	5-589	Chair,plastic, metal, Blue, 22" l x 23" w x 33" h. Good	\$1	
5.00	5-590	Chair,swivel, Black 19" l x 23" w x 39" h. Fair	\$1	
30.00	5-591	Chair,swivel, Black, 20" l x 27" w x 42" h. Excellent	\$1	
No Bid	5-592	Chair,swivel, Blue, 5 caster, 19" l x 23" w x 31" h. Good	\$1	
No Bid	5-593	Chair,swivel, Grey 18.5" l x 23.5" w x 39.5" h. Good	\$1	
2.00	5-594	Chair,swivel, Grey, 18" l x 24" w x 38" h. Fair	\$1	
8.89	5-595	Chairs,3 seat, bench, Blue, 20" l x 65" w x 31" h. Fair	\$1	
54.75	5-596	Chairs,Lot of 10stackable, Black, 19" l x 18" w x 31.5" h. Excellent	\$1	
15.00	5-597	Chairs,Lot of 10stackable, Black, 19" l x 18" w x 31.5" h. Excellent	\$1	
10.99	5-598	Chairs,Lot of 10stackable, Black, 19" l x 18" w x 31.5" h. Excellent	\$1	
10.99	5-599	Chairs,Lot of 10stackable, Black, 19" l x 18" w x 31.5" h. Excellent	\$1	
10.99	5-600	Chairs,Lot of 10stackable, Black, 19" l x 18" w x 31.5" h. Excellent	\$1	
10.99	5-601	Chairs,Lot of 10stackable, Black, 19" l x 18" w x 31.5" h. Excellent	\$1	
30.00	5-602	Chairs,Lot of 11stackable, Black, 19" l x 18" w x 31.5" h. Excellent	\$1	
3.00	5-603	Chairs,Lot of 3swivel, Blue, 5 caster, 19" l x 23" w x 31" h. Excellent	\$1	
25.00	5-604	Chairs,Lot of 4swivel, Blue, 5 caster, 19" l x 23" w x 31" h. Good	\$1	
90.00	5-605	Chairs,Lot of 2swivel, Blue, 5 caster, 19.5" l x 28" w x 42.5" h. Excellent	\$1	
150.00	5-606	Chairs,Lot of 11swivel, Blue, 5 caster, 20" l x 25" w x 43" h. Excellent	\$1	
No Bid	5-607	Chairs,Lot of 2, Blue, 22.5" l x 23" w x 33" h. Good	\$1	
1.00	5-608	Chairs,Lot of 2, Green, 22" l x 23" w x 33" h. Good	\$1	
No Bid	5-609	Desks,Lot of 2wood, with light, brown, 25" l x 49" d x 60" h. Fair	\$1	
101.00	5-610	Desks,Lot of 2wood, Pepperdust, 72" l x 36" w x 29" h. Good	\$1	
25.00	5-611	Table,wood, metal, Brown, round, 41.5" diameter x 29" h. Excellent	\$1	
25.00	5-612	Table,wood, metal, Brown, round, 42" diameter x 29" h. Excellent	\$1	
5.00	5-613	Table,wood, metal, Brown, round, 48" diameter x 29.5" h. Excellent	\$1	

Item #	Description	Kms	Min Price	Serial Number
REGINA, Labour and Relations Workplace Safety, 300-1870 Albert Street				
Contact Brandon Darmochid 306-527-1709, brandon.darmochid@gov.sk.ca or Kristen Hill 306-798-0312, Kristen.hill7@gov.sk.ca				
No Bid	5-572	Cabinet, Wood, metal, 42" l x 14" w x 36" h, sliding doors. Fair	\$1	
3.80	5-573	Chair, Mesh, 5 castor, dual arm, adjustable, black. Fair	\$1	
No Bid	5-574	Chairs, Lot of 2, 5 castor, dual arm, adjustable, black. Fair	\$1	
No Bid	5-575	Filing Cabinet, Lateral, metal, 3 drawers, 36" l x 18" w x 39.25" h. Fair	\$1	
No Bid	5-576	Filing Cabinet, Lateral, metal, 3 drawers, 36" l x 18" w x 40.5" h. Fair	\$1	
No Bid *	4-571	Fridge, 20.5" w x 21" d x 32" h, plug in, would need repair as cold air does not work, not	\$1	
No Bid	5-577	Keyboard Holder, Under desk mount, 30" w x 10" d. Fair	\$1	
No Bid	5-578	Keyboard Holder, Under desk mount, 30" w x 15" d. Fair	\$1	
No Bid	5-579	Keyboard Holder, With mount, 21" w, 11 1/4" l, black. Fair	\$1	
No Bid	5-580	Office Supplies, Lot of 8 Assorted, 2 file holders, pen caddy, 5 keyboards. Fair	\$1	
REGINA, Saskatchewan Liquor and Gaming Authority, 1702 Park St				
Contact Kristen Nelson 306-787-0179, knelson@slga.com or Sherrie Sawin 306-787-3097, ssawin@slga.com				
No Bid *	4-544	Chair, fabric, Navy, 5 casters, adjustable arms/seat height, minor damage on one armrest. *NOTE: Online viewing only & 24 hours' notice for pick-up required. Fair	\$5	
5.00 *	4-547	Chairs, Lot of 2 fabric, Green, 5 casters, only height is adjustable. *NOTE: Online viewing only & 24 hours' notice for pick-up required. Good	\$5	
No Bid *	4-548	Chairs, Lot of 4 fabric, Grey, 5 casters, adjustable arms/seat height. *NOTE: Online viewing only & 24 hours' notice for pick-up required. Fair	\$10	
No Bid *	4-549	Chairs, Lot of 3 fabric, Grey, 5 casters, only height is adjustable. *NOTE: Online viewing only & 24 hours' notice for pick-up required. Fair	\$8	
16.00 *	2-560	Hutch, solid wooden, 36" w x 19.75" d x 65" h, top 2 door vertical, bottom 2 drawer lateral, no key. *NOTE: Online viewing only & 24 hours' notice for pick-up required. Good	\$15	
REGINA, SaskTel, 355 Longman Cres				
Contact Graeme Henneberg 306-221-3480, graeme.henneberg@sasktel.com or Isaac Ziegler 306-550-4187, isaac.ziegler@sasktel.com				
300.00	5-567	Utility Body, Brand FX, Fiberglass, 8' l x 9' w x 41" h, bed 54" l x 74" w x 26" h, white, one door does not lock needs to be adjusted, padlock not included. Beyond Repair	\$1	0925644
857.00	5-568	Utility Body, Brand FX, Fiberglass, 80" l x 8' w x 42" h, bed 49" l x 66" w x 25" h, white, one door does not lock needs to be adjusted, padlock not included. Fair	\$500	1,133,518
306.00	5-569	Utility Body, Brand FX, Fiberglass, 94" l x 9' w x 42" h, bed 54" l x 74" w x 26" h, white, no locks. Broken Repairable	\$1	0717085

Item #	Description	Kms	Min Price	Serial Number
REGINA, Trade and Export Development, 300 2103 11th Ave				
Contact Nolan Schauerte 306-787-8712, nolan.schauerte@gov.sk.ca or Tosin Fatoyinbo 306-510-2943, tosin.fatoyinbo2@gov.sk.ca				
No Bid 5-541	Camera,2002, Nikon, Coolpix 5700, Eight times zoom, five megapixel, released in 2002, operational, memory has been removed, sometimes does not take photos. Broken Repairable		\$1	5,004,039
55.50 5-542	Camera,2010, Cannon, Rebel EOS T2I, 18 megapixel, 3x zoom, released in 2010, unknown if operational/functional, memory has been removed, missing a battery charger. Fair		\$1	322,100,503
No Bid 5-543	Desk,laminate, Grey, L-shape, 72"w x 80"d 'x 29"h, includes locking pedestal, unlocked but is missing key, the desk is currently taken apart and ready to move. Good		\$1	
No Bid 5-544	Desk,laminate , Grey, L-shape, 72"w x 80"d 'x 29"h, includes vertical storage, desk light, and keyboard tray, the desk is currently taken apart and ready to move. Good		\$1	
No Bid 5-545	File Cabinet,metal , Beige, 4 drawer, 36"w x 18"d x 52"h, missing the key but is unlocked, vertical. Good		\$1	
No Bid 5-546	File Cabinet,metal , Beige, 5 drawer, 36"w x 18"d x 65"h, missing the key but is unlocked, vertical. Good		\$1	
SASKATOON, Corrections, Policing and Public Safety, SCC, 910 60th St. E				
Contact Renee Pound 306-956-8817, renee.pound@gov.sk.ca or Danielle Corriveau 306-956-8869 danielle.corriveau@gov.sk.ca.				
No Bid * 4-551	Tray,Lot of 40Steel, Food tray, 12 1/2" l x 15 1/4" w. Good		\$1	
No Bid 5-551	Cabinet,Lot of 3Particle Board, Minor water damage on bottom. 36" l x 18.25" w x 38.5" h. Fair		\$1	
No Bid 5-552	Cabinet,Particle Board, Two shelves, 14.25" l x 30" w x 30" h. Good		\$1	
No Bid 5-553	Chairs,Lot of 4Leather, Black. Poor		\$1	
No Bid 5-554	File Folders,Lot of 11Paper, 10 boxes of 10 and one box of 6 of the Pendeflex end tab classification folders. Excellent		\$1	
6.00 5-555	Medical Bags,Lot of 2Ferno, One is for oxygen cylinder and one P866438-00 trauma first aid kit bag. Fair		\$1	
No Bid 5-556	Organization Bins,Lot of 7Metal, Black, two metal trays, two plastic trays, one wall file holder and plastic dividers. Good		\$1	
No Bid 5-557	Pedestal,Lot of 2Particle Board, Casters are broken on bottom, 15.5" l x 21 .75" w x 27" h, locks, no key. Fair		\$1	
No Bid 5-558	Pedestal,Particle Board, Pepperdust, three drawer pedestal, no lock or cylinder, 17.5" l x 24.5" w x 26" h. Fair		\$1	
189.00 5-559	Portable Sink,Stainless Steel, 4 swivel casters, 26 1/2" l x 30 1/2" w x 23 1/2" h, the overall height is 31 1/2" h, frame is 38" l x 26" w x 8" h. Good		\$1	

Item #	Description	Kms	Min Price	Serial Number
8.00 5-560	Pressure Cooker,Aluminum, No. 7, 13 imperial quarts, unknown if operational. Fair		\$1	
No Bid 5-561	Wi-Fi Adapters,D-Link, One AC1300MU-MIMO Wi-fi Nano USB adapter and one AC600MU-MIMO Wi-fi Nano USB adapter, unopened Excellent		\$1	
SASKATOON, Highways, 126 105th St E				
Contact Richard Leibel 306-933-5262, richard.leibel@gov.sk.ca or Shaun Bowditch 306-933-5265, shaun.bowditch@gov.sk.ca				
No Bid 5-527	Air Purifier,1997 NEOT, RP050BNA, Non-operational. Fair		\$1	RP-01-2205
No Bid 5-528	Air Purifier,1997 NEOT, RP050BNA, Non-operational. Fair		\$1	RP-01-2206
215.00 5-529	Stands,Lot of 4Tripod, Westward, Under hoist, Lift capacity 2 tons, max height 76", base size 5-1/4" x 1-1/2". Good		\$1	
SASKATOON, Saskatchewan Polytechnic, 1130 Idylwyld Dr. N				
Contact Chris Perry 306-659-4126, perrychr@saskpolytech.ca				
No Bid * 4-503	Electric Motor,Baldor, Industrial , .5hp, 230/460 volt, 3 phase, 1725 rpm, frame 56C, Shaft 5/8", operational. Good		\$5	W0912162318
13.00 * 4-504	Electric Motor,Dayton, 33hp, 208-220/440 volt, 3 phase, 1725 rpm, frame 56, Shaft 5/8", operational. Good		\$2	111.762-20
No Bid * 4-505	Electric Motor,Hyundai, HJS215SR234, 10hp, 575 volt, 3 phase, 2700 rpm max, frame 215T, Shaft 1 3/8", operational. Good		\$10	
13.00 * 4-506	Electric Motor,Nidec, 661817, 5hp, 575 volt, 3 phase, 1740 rpm, frame 184T, Shaft 1 1/8", DP enclosure, operational. Good		\$5	
No Bid * 4-507	Electric Motor,Teco , 3hp, 575 volt, 3 phase, 1755 rpm, frame 182T, Shaft 1 1/8", operational. Good		\$3	JSP3079073023

Item #	Description	Kms	Min Price	Serial Number	
SASKATOON, Saskatchewan Research Council, 111 Research Dr					
Contact Roger Dauvin 306-385-4035, roger.dauvin@src.sk.ca					
2,600.00	5-517	Van 2003 GMC Savana 3500 Ext 2WD 6L, V8, gas auto A/C, tilt, cruise, GVW 6001, single axles, wheel base 135", single tire 245/75R16 Roof Rack and Ladder, white, TOW ONLY, NO SGI Inspection. It is unknown if any repairs or safety concerns exist (if any). Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs if required. , 253,639 km, Recent Repairs: Battery new in 2023, KNOWN PROBLEMS: body panels with rust, exterior ladder and roof rack (aluminum), battery tender installed, coolant leak, potential electrical short causing battery drain, interior back has wear & tear from use, motor runs, transmission no issues, tires less than 10,000 km on tires, brakes/lights/horn functional, body exterior rust along doors and front/rear, exhaust intact, windshield glass has crack/divet, windshield washer & wipers functional, interior cloth/drivers seat has limited adjustment capacity, mirrors - power adjusted exterior mirrors and manual rearview mirror.>, As is, Where is	253,639 km	\$1	1GKHG39U431227233
SASKATOON, Saskatchewan Research Council, 820 51 St E					
Contact Roger Dauvin 306-385-4035, roger.dauvin@src.sk.ca					
6,776.00	5-586	Storage Building, Double Truss, 30' l x 80' d x 20' h, never erected, material is on pallets and ready for pick-up. Fair		\$5,000	
SASKATOON, Trade and Export Development, 219 Robin Cres					
Contact Nolan Schauerte 306-787-8712, nolan.schauerte@gov.sk.ca or Tosin Fatoyinbo 306-510-2943, tosin.fatoyinbo2@gov.sk.ca					
99.99	5-548	Paper Shredder, 2502, Destroyit, Grey, 20" w x 18" d x 35" h, old unit, operational. Good		\$1	
111.11	5-547	Paper Shredder, 3803CC, Destroyit, Grey, 24.5" w x 18.5" d x 37.5" h, old unit, operational. Good		\$1	
SMEATON, Saskatchewan Public Safety Agency, Call for Directions					
Contact Eric Pulvermacher 306-426-2610, epulvermacher@gov.sk.ca					
2.00	5-508	Generator, Champion, 42451, 80 cc, wrong oil was used, does not start, took to be repaired and was told cannot be repaired, non-operational. Poor		\$1	
2.00	5-509	Generator, Champion, 42451, 80 cc, wrong oil was used, does not start, took to be repaired and was told cannot be repaired, non-operational. Poor		\$1	
56.00	5-510	Grinder, Powerful Men, HG6A, Missing guards, operational. Fair		\$50	9,070,119
No Bid	5-511	Lawnmower, Craftsman, 944.361210, Air filter cover missing, non-operational. Poor		\$1	052411M 004626
1.00	5-512	Lawnmower, Troy-Bilt, Does not start, taped cables, non-operational. Poor		\$1	
1.00	5-513	Lawnmower, Troy-Bilt, 11A-A22Q563, Missing guard, pull chord broken, missing air filter compartment, non-operational. Poor		\$1	1D062K11237

Item #	Description	Kms	Min Price	Serial Number
205.55	5-514	Lawnmower Motor, Briggs & Stratton, 215802, 10.5 hp, non-operational. Good	\$100	
No Bid	5-515	Pressure Washer, Briggs & Stratton, 020806, Power hose missing, took in for repairs and was informed that it cannot be repaired, non-operational. Poor	\$1	1,017,435
SPIRITWOOD, Corrections Policing and Public Safety, 116 1st St. E				
Contact Brendon Smith 306-883-8513, brendon.smith@gov.sk.ca or Jason Reddekopp 306-883-8505, jason.reddekopp@gov.sk.ca				
222.22	5-516	Snowmobile Trailer, 1994 metal frame wood deck 8' w x 10' l, KNOWN PROBLEMS: Poor condition with flat tires. As is, Where is	\$1	4TCSS1105SA052389
WEYBURN, Justice and Attorney General, 301 Prairie Ave * Online Viewing Only*				
Contact Kevin Duxbury 306-861-6839, kevin.duxbury@gov.sk.ca or Garth Stuart 306-861-3612, kenneth.stuart@gov.sk.ca				
No Bid	5-530	Desk, Corner piece, Pepperdust, 42" l x 42" w x 29" h. Good	\$1	
No Bid	5-531	Desk, Wood, 1 drawer, 60" l x 30" w x 29" h, brown. Good	\$1	
5.00	5-532	Desk, Wood, 2 drawer, 60" l x 34" w x 30.5" h. Good	\$1	
No Bid	5-533	Desk, Wood, 5-drawer, 72" l x 36" w x 29" h, brown. Good	\$1	
No Bid	5-534	Desk, Wood, 6 drawer with center panel, 54" l x 30" w x 31" h. Good	\$1	
No Bid	5-535	Desk, Wood, 7 drawer, 54" l x 30" w x 29" h, locks, no key. Good	\$1	
No Bid	5-536	Desks, Lot of 2 Right side wing, Pepperdust, 60" l x 30" w x 29" h. Good	\$1	
No Bid	5-537	File Cabinet, Metal, lateral, 32" l x 18" w x 79" h. Good	\$1	
No Bid	5-538	File Cabinet, Lot of 5 Metal, vertical, 4 drawer, 19" l x 28" w x 51" h, locks, no key. Good	\$1	
No Bid	5-539	Hutch,, Pepperdust, 60" l x 17.75" w x 42" h. Good	\$1	
No Bid	5-540	Table, Wood, metal frame, Black top, 60" l x 30" w x 29" h. Good	\$1	
YORKTON, Agriculture, 38 - 5th Ave N				
Contact Ogonnaya Oji Maleschuk, ogonnaya.maleschuk@gov.sk.ca				
No Bid	* 4-578	Chair, Office, Grey cloth with adjustable armrest & wheels - about 51" length. Fair	\$1	
No Bid	* 4-579	Chair, Office, Grey cloth with adjustable armrest & wheels - about 51" length. Poor	\$1	
No Bid	* 4-580	Garbage Bin, Stainless Steel, Fair	\$1	

Item #	Description	Kms	Min Price	Serial Number
YORKTON, Parks Culture and Sport, Highways Maintenance Yard, 245 York Rd E				
Contact Ed Patzwald 306-786-1687, ed.patzwald@gov.sk.ca or Brian Perih 306-786-1651, brian.perih@gov.sk.ca				
2,357.00	5-519	Trailer 1999 TRAILTECH TD220 Flat Deck Beavertail, ramps, pintle hitch GVW 20,909 kg, dual 955 km tire, tire size 225/70R22.5, tire ply size 5 , yellow, , 955 km, , KNOWN PROBLEMS: Very rusty, deck removed for structural inspection/repairs, frame really thin at the front where it is welded into a V. There is a significant loss of material inside the frame. Hitch plate is twisted, lots of corrosion behind the fishplates front and back. Supports under deck checker plate corroded through, rust jacking on deck checker plates, ramps broken, bent and twisted, ramp mounts worn bad, rear tubing for lights rusted through below the lights, outer deck support above RH wheels cracked, frame at the front has holes drilled/punched out of the flanges.> As is, Where is	\$1	2CU4C4XN2X2005744
YORKTON, Highways, 245 York Rd E				
Contact Ed Patzwald 306-786-1687, ed.patzwald@gov.sk.ca or Brian Perih 306-786-1651, brian.perih@gov.sk.ca				
325.00	5-562	Message Board,2003, American Signal, CMST331, Non-operational. Broken Repairable	\$50	1A9BS331832228407
151.00	5-563	Plow Attachment,1990 Tenco, one way, Has cracks, dents and corroded material. Poor	\$50	116-TE-03
151.00	5-565	Plow Attachment,1993, Frink, 15121, on way, Has cracks, dents and corroded material. Poor	\$50	15,121
151.00	5-566	Plow Attachment,1997, Frink, 16416, on way, Has cracks, dents and corroded material. Poor	\$50	16,416
151.00	5-564	Plow Attachment,2004, Tenco, TC104, one way, Has cracks, dents, corroded material, wheels may require attention. Poor	\$50	10,078
5,100.00	5-549	Wheel Loader 1999 Hyundai HL 743-3 4WD Cummins B 5.9-C, Inline 6, diesel auto A/C GVW 13,000, 8 gears, tires single, tire size 20.5 x 25, yellow, , 3,001 hrs, , KNOWN PROBLEMS: Possible ROPS issue, oil leaks, needs new turbo, needs many hydraulic hoses replaced, loses coolant especially in winter, possible transmission issues as it misses shifts, poor tires/transmission/motor/windshield wipers washer, cab is very rusted out, fenders rusted out, entire unit very rusty, lights do not work, horn does not work, needs new batteries, minor exterior damage > As is, Where is	\$1,500	L701FD10346
9,469.00	5-550	Wheel Loader 1994 Komatsu WA 180 4WD Cummins, 610T, 118 horse power, Inline 6, diesel auto Heater 3 speed power shift, tires single, tire size 17.5 x 25, ply 12, yellow, , 5,545 hrs, , KNOWN PROBLEMS: Transmission has oil leaks, poor motor/windshield/lights, possible ROPS issue, entire unit very rusty, cab is very rusted out, engine cover is rusted out, exhaust very rusted out and leaking, broken left hand front window, needs wipers, lights not working, horn not working, needs new batteries, minor exterior damage>., As is, Where is	\$25	A75529

Item #	Description	Kms	Min Price	Serial Number
16,787.00 5-571	Yard Loader 2001 CASE 621C 4WD Cummins 5.9L, 6 cylinder, diesel auto A/C automatic 4 speed, differential type ZF, single tire, tire size 20.5/25 tubeless, tire ply 12, yellow, , 6,388 km, , KNOWN PROBLEMS: Flywheel housing broken and needs repair, main hydraulic valve leaking, alternator needs to be replaced, some light do not work, wiring need repair, issues has a couple of spots in need or rust repair, motor mounts needs replacing, drivers side door not on unit and missing glass, tires flat, minor exterior damage.>, As is, Where is	6,388 km	\$1,000	JEE0122961
YORKTON, Water Security Agency, 269 Hamilton Rd.				
Contact Karen Ayers 306-551-9487, karen.ayers@wsask.ca or Ayold Elgersma 306-631-0460, ayold.elgersma@wsask.ca				
No Bid * 4-567	Truck Tool Box,UWS, Metal, 60"l x 29"d x 14"h, no key. Good		\$1	