

SALE SUMMARY LIST

PLEASE NOTE: Every effort has been made to accurately describe items and their condition; however, additional problems may exist, items may not be complete or exactly as described. Bidders are deemed to have reviewed the Terms and Conditions on bid forms and relied entirely on their own inspection and evaluation prior to bidding. Vehicles and equipment are sold "AS IS, WHERE IS", there is no implied or express warranty.

Visit www.SaskSurplus.ca for pictures and link to download Bid Form.

- Items identified with * have been on a previous sale and will be listed first on www.SaskSurplus.ca web site.
- SaskBuilds and Procurement, SaskSurplus, reserves right to have unadvertised minimum selling prices on items.

It is the Bidder's responsibility to review the terms and conditions of sale on the Offer to Purchase, Bid Form.

Bid Forms are available from www.SaskSurplus.ca or from the SaskSurplus Sales Lot, 500 McLeod Street, Regina, SK.

Bid Forms can be submitted in the following ways:

- by deposit in the bid box at the SaskSurplus Sales Lot,
- by fax to 306-787-2092; by phone 306-787-2062 or 306-798-3300,
- by email to sasksurplus@gov.sk.ca, or
- by mail, addressed to: Ministry of SaskBuilds and Procurement, SaskSurplus, 500 McLeod Street, Regina, SK S4N 4Y1.

(If mailing your bid, please allow sufficient time for bid to be received.)

- Bids received after close date and time cannot be accepted.

MT = (Ministry Transfer) This means that the item has been claimed by another ministry and automatically transferred to the ministry.

WD = (Withdrawn) This can happen if the item was requested to be removed by the seller.

No Bid = Items that did not receive any bids are normally carried forward to the next sale or may be withdrawn.

Item #	Description	Kms	Min Price	Serial Number	
REGINA, SaskBuilds and Procurement, SaskSurplus Sales Lot, 500 McLeod Street - Vehicles					
Contact SaskSurplus 306-787-2062 or 306-798-3306, sasksurplus@gov.sk.ca					
1,855.99	9-001	Car 2007 CHEVROLET Impala FWD 3.5L, V6, gas auto A/C, tilt, cruise, AM/FM/CD player, power mirrors/locks/windows/trunk release/left front seat, keyless entry-2 fobs, 2 keys, grey, TOW ONLY – This vehicle has a VERY UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Body Integrity Inspection and a Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in "As is, where is" condition., 252,275 km, , KNOWN PROBLEMS and OBSERVATIONS: Both rockers' panels rusted out. Grille chrome poor, hood scratches/chips, both bumpers cracked/road rash, rear bumper paint poor/scratches, left front fender scratches/road rash, left rear fender rust, right front fender rust, rocker panels rusted out, left side doors rust at bottom, left front door loose at hinge or pins, right front doors paint chips, right rear door paint chips/rust inside bottom, roof rust/scratches, trunk lid rust/scratches, no first aid kit/fire extinguisher, windshield chips, missing 4-wheel covers, poor battery, minor exterior damage.>, As is, where is	252,275 km	\$1,437	2G1WB58K979408397
4,680.80	9-010	Car 2017 CHEVROLET Malibu Hybrid FWD 1.8L, inline 4, gas auto A/C, tilt, cruise, AM/FM, power mirrors/windows/locks/left front seat, keyless entry-2 key fobs temporary tire sealant and compressor kit missing some components, white, TOW ONLY – This vehicle has a VERY UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Body Integrity Inspection and a Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in "As is, where is" condition., 208,058 km, , KNOWN PROBLEMS and OBSERVATIONS: Exhaust shield damaged/loose, vin-use scan tool to confirm vin, heat shield, no spare, left rear rocker panel corner rusted out, both rocker panels. Hood scratches, both bumpers' chips/scratches, both dog legs road rash/rust, both rocker panels rust/road rash, left front door chrome molding loose, left rear door road rash, right side doors dents, right front and rear doors moldings fading, no spare tire/wheel wrench /jack/first aid kit/fire extinguisher, windshield chips, poor battery, minor exterior damage.>, As is, where is	208,058 km	\$3,124	1G1ZJ5SUXHF218952

Item #	Description	Kms	Min Price	Serial Number
4,678.08 9-003	<p>SUV 2013 CHEVROLET Tahoe 4WD 5.3L, V8, gas auto dual zone A/C, tilt, cruise, rear HVAC, power locks/mirrors/windows/front seat, keyless entry-2 keys, 2 fobs 5 passenger, grille inserts, tow hooks, side steps, mud flaps, hitch, trailer wiring, grey, TOW ONLY –</p> <p>This vehicle has a VERY UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Body Integrity Inspection and a Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in "As is, where is" condition., 232,575 km, ,</p> <p>KNOWN PROBLEMS and OBSERVATIONS: Power steering rack/pinion leaking, both exhaust manifolds broken bolts, left lower ball joints, front pads/rotors, rear pads/rotors, rear washer hose, rear shocks, alignment parts needed, rear park brake does not hold, both rear park brake cables, left plate light, left daytime light, rear defogger, left mirror broken, left front body missing rubber, driver door binding, no radio display, surface rust on rockers and floor boards, recommend tires, windshield washer cap missing.</p> <p>Hood chips/dents, front bumper broke, rear fender broke, left side fenders scratches, left and right dog legs road rash/rust, both rocker panels surface rust/floor board, left side door scratches/dents, right side doors rusted/scratches, roof chips/dents, tailgate rust/scratches/washer/rear glass scratched/rear defogger, spare tire loose in back may not be compatible with vehicle, jack missing, no first aid kit/fire extinguisher, windshield small chips, left mirror damaged, left front seat frame visible/sagging, poor battery, minor exterior damage.>, As is, where is</p>	232,575 km	\$1,512	1GNSK4E04DR246660

Item #	Description	Kms	Min Price	Serial Number
1,801.00 9-004	<p>SUV 2015 DODGE Durango 4WD 5.7L, V8, gas auto A/C, tilt, cruise, AM/FM/Bluetooth, rear HVAC, power heated mirrors, power locks/windows/front left seat, keyless entry-2 key fobs 5 passengers, hitch, trailer wiring, white, TOW ONLY –</p> <p>This vehicle has a VERY UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Body Integrity Inspection and a Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in "As is, where is" condition., 173,942 km, ,</p> <p>KNOWN PROBLEMS and OBSERVATIONS: Transmission cooler, power steering pressure hose, loud drive train tick on left side cylinder #7 collapsed lifter, engine misfire and check engine light on, both inner tie rods worn, left exhaust manifold cracked and leaking, left rear shock leaked out, front/rear wheel alignment needed, front bumper broken, rear doors do not open from inside.</p> <p>Hood chips/paint bubbling, front bumper broken, right front fender road rash/rust, right rear door road rash/rust, missing lock button hardware for rear doors, roof small chips, 1 hole in roof sealed, tailgate glass scratched, no first aid kit/fire extinguisher, windshield chips, left front seat missing trim, left front seat back panel off/loose in rear, left/right B pillar inside trim modified, hole in head liner, poor battery, minor exterior damage.> , As is, where is</p>	173,942 km	\$784	1C4SDJFT1FC153871
1,328.00 9-005	<p>SUV 2008 JEEP Commander Sport 4WD 3.7L, V6, gas auto A/C, tilt, cruise, AM/FM/CD player, 273,428 km power heated mirrors, power locks/windows, keyless entry-2 key fobs hitch, 7 passenger, grey, TOW ONLY –</p> <p>This vehicle has a VERY UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Body Integrity Inspection and a Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in "As is, where is" condition., 273,428 km, ,</p> <p>KNOWN PROBLEMS and OBSERVATIONS: Left lower ball joint, front struts, left rear axle seal, transmission pan leaking, oil change light on, rear pads/rotors contaminated, front pads/rotors, clunk in front end, lube oil and filter dirty, park brake light on, tire light on, no brake light when applied, park brake does not hold, driver doors binding upper hinge, both rocker panels rusted through.</p> <p>Hood dents/scratches, front bumper cracked, front and rear bumpers' scratches, left rear fender scratches, rocker panels rust through, left front door binds, roof scratches, left front seat trim loose, no first aid kit/fire extinguisher, windshield chips, poor battery, minor</p>	273,428 km	\$914	1J8HG48K18C225171

Item #	Description	Kms	Min Price	Serial Number
1,546.00 9-006	<p>SUV 2008 JEEP Commander Sport 4WD 3.7L, V6, gas auto A/C, tilt, cruise, AM/FM/CD player/Bluetooth, power heated mirrors, power locks/windows/left front seat, keyless entry-2 key fobs 7 passengers, grille inserts, driving lights, hitch, trailer wiring, red, TOW ONLY –</p> <p>This vehicle has a VERY UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Body Integrity Inspection and a Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in "As is, where is" condition., 236,415 km, ,</p> <p>KNOWN PROBLEMS and OBSERVATIONS: Right front CV joints, front and rear pads/rotors, alignment needed, rockers.</p> <p>Water pump, transmission pan leaking, front axles, brakes all around, hood paint peeling/chips, both bumpers pitted/scratched, left front fender chips, right rear fender molding cracked, rocker panels PMVI, left front door dents, left rear door rust/road rash, right side doors road rash, tailgate scratches/missing the letter "p", no first aid kit/fire extinguisher, windshield chips, left mirror housing hole, poor battery, minor exterior damage.>, As is, where is</p>	236,415 km	\$1,227	1J8HG48K98C225161
5,662.00 9-014	<p>Truck 2015 CHEVROLET Silverado 1500 4WD, crew cab, 6'6" box 4.36L, V6, gas auto A/C, tilt, cruise, AM/FM, power mirrors/locks/windows, keyless entry-2 fobs, 2 keys grille inserts, front tow hooks, side steps (paint poor), mudflaps, hitch, trailer wiring, OEM trailer brake, white, TOW ONLY –</p> <p>This vehicle has an UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in "As is, where is" condition., 355,907 km, ,</p> <p>KNOWN PROBLEMS and OBSERVATIONS: Left lower ball joint loose and right lower ball joint loose, sway bar bushing loose, exhaust manifold leak-broken bolts, exhaust flex pipe damaged, service trailer brake system-light on-harness cut/removed, windshield cracked, front bumper valance push in/damaged, both plate lights non-operational, left lower marker bulb non-operational.</p> <p>Head lights fogged, hood road rash, front bumper road rash, rear bumper road rash/dents, left side fenders road rash/rust/dents, right front fender road rash, right rear fender rust/road rash, left front door rust, left rear door paint poor/dents, right front door rust/road rash, right rear door paint poor/road rash, roof paint chips, tailgate will not open/road rash/dents, no first aid kit/fire extinguisher, windshield cracked/chipped, front lower valance bent, A-pillar paint poor, holes drilled in box rails, paint in box poor, poor battery, minor exterior damage.>, As is, where is</p>	355,907 km	\$5,661	3GCUKPEH6FG369632

Item #	Description	Kms	Min Price	Serial Number
4,665.50 * 7-007	<p>Truck 2018 CHEVROLET Silverado 1500 4WD, crew cab, 6'6" box 5.3L, V8, gas auto A/C, tilt, cruise, AM/FM, power mirrors/locks/windows, keyless entry-1 key, 1 fob front tow hooks, wigwags on grille/headache rack, side steps, mud flaps, hitch, trailer wiring, OEM trailer brakes, box liner, headache rack, beacon, Brute tool-box commercial class 1 key locks intermittent, has back seat, grey, TOW ONLY –</p> <p>This vehicle has an UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in "As is, where is" condition., 387,040 km, , KNOWN PROBLEMS and OBSERVATIONS:</p>	387,040 km	\$1,886	3GCUKNEC5JG158729
9,145.45 * 8-004	<p>Truck 2015 DODGE Ram 2500 4WD, crew cab, 6'4" box 5.7L, V8, gas auto A/C, tilt, cruise, AM/FM, power heated mirrors, power windows/locks, keyless-2 key fobs, 2 keys for toolbox front tow hooks, grille inserts, side steps, mud flaps, hitch, trailer wiring, OEM trailer brakes, headache rack with beacon, box liner, Brute Gullwing toolbox-fair condition, has back seat, white, TOW ONLY –</p> <p>This vehicle has an UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in "As is, where is" condition., 293,041 km, , KNOWN PROBLEMS and OBSERVATIONS:</p> <p>Both upper ball joints slight play, park brake will not hold in reverse.</p> <p>Hood chips, front bumper rust spots, rear bumper rust/dent/missing sensor, left and right rear fender road rash/chips, rocker panels both road rash/surface rust, right front door dents, roof small rust spots, 1 hole in roof sealed, tailgate chips/dents/molding broke, wheel wrench/jack loose under back seat, no first aid kit/fire extinguisher, windshield chip, left front seat worn at seam, poor battery, minor exterior damage.>, As is, where is</p>	293,041 km	\$8,137	3C6TR5CT3FG592348

Item #	Description	Kms	Min Price	Serial Number
4,271.60 9-022	<p>Truck 2015 DODGE/RAM 2500 4WD, crew cab, 6'4" box 5.7L, V8, gas auto A/C, tilt, cruise, aftermarket AM/FM/CD player, power heated mirrors, power locks/ windows, keyless entry-2 key fobs grille inserts, front tow hooks, side steps, mud flaps, hitch, trailer wiring, OEM trailer brake, box liner, headache rack, has back seat, brown, TOW ONLY –</p> <p>This vehicle has an UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in "As is, where is" condition., 209,807 km, , KNOWN PROBLEMS and OBSERVATIONS:</p> <p>Headlights not properly adjusted, headlights are loose.</p> <p>Needs new engine, piston slap is retarding timing in cold weather, lacks power to accelerate until warm, B pillar inside trim modified, hood stone chips, front bumper rust, rear bumper rust/dents/scratches, left rear fender dents/scratches, right front fender dent/scratches, right rear fender rust, 1 hole sealed in roof, tailgate dents/scratches/molding broke, no first aid kit/fire extinguisher, windshield chips, holes drilled in box rails, hole in head liner, poor battery, minor exterior damage.>, As is, where is</p>	209,807 km	\$3,931	3C6TR5CT4FG674850
No Bid 9-016	<p>Truck 2015 DODGE/RAM 2500 4WD, crew cab, 6'5" box 5.7L, V8, gas auto A/C, tilt, cruise, AM/FM, power heated mirrors, power locks/windows, keyless entry-1 key fob front tow hooks, grille inserts, mud flaps, sidestep, hitch, trailer wiring, OEM trailer brake, headache rack with beacon, front and rear wig wags-operational, has back seat, white, TOW ONLY –</p> <p>This vehicle has an UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in "As is, where is" condition., 291,726 km, , KNOWN PROBLEMS and OBSERVATIONS:</p> <p>Right headlight has water and loose.</p> <p>Hood chips, both bumpers chips/scratches, left rear fender paint worn/road rash/chips/ dents/rust, right rear fender dents/scratches, both rocker panels road rash, roof black sealant on roof, one hole sealed antenna, tailgate hard to open/chips/dents/molding loose, spare tire loose in box may not be compatible with vehicle, no first aid kit/fire extinguisher, windshield chips, small holes in left front seat, front of box bent, box rusted badly/ scratched, beacon does not work, poor battery, minor exterior damage.> , As is, where is</p>	291,726 km	\$8,767	3C6TR5CT7FG592353

Item #	Description	Kms	Min Price	Serial Number
No Bid 9-017	<p>Truck 2016 DODGE/RAM 2500 4WD, crew cab, 6'5" box 5.7L, V8, gas auto A/C, tilt, cruise, AM/FM, power heated mirrors, power locks/windows, keyless entry-2 key fobs front tow hooks, grille inserts, side steps, mud flaps, hitch, trailer wiring, OEM trailer brake, box liner, headache rack, wigwags front and rear, has back seat, white, TOW ONLY –</p> <p>This vehicle has an UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in "As is, where is" condition., 297,316 km, , KNOWN PROBLEMS and OBSERVATIONS:</p> <p>TPMS light on, left headlight assembly full of water.</p> <p>Hood hail, front bumper scratches/chips, rear bumper dents/scratches/rust, left rear fender dents/scratches/road rash, right rear fender dents/road rash, both rocker panels road rash, left front door dents, left rear door scratches, right front door scratch, roof hail, tailgate dents/rust/bent/chips/molding loose, spare on rear left, wheel wrench/jack loose under back seat, no first aid kit/fire extinguisher, windshield chips, back seat soiled, left front floor mat worn, front of box bent, left cab corner dents, left rear seat floor storage lid broke, missing left rear wheel hub cap, left front headlights moisture, wigwags non-operational, poor battery, minor exterior damage.>, As is, where is</p>	297,316 km	\$8,438	3C6TR5CT4GG118572
4,371.60 9-011	<p>Truck 2016 DODGE/RAM 2500 4WD, crew cab, 6'5" box 5.7L, V8, gas auto A/C, tilt, cruise, AM/FM, power heated mirrors, power locks/windows, keyless entry-2 key fobs grille inserts, wig wags front and rear, front tow hooks, side steps, mud flaps, hitch, trailer wiring, OEM trailer brakes, box liner, has a back seat, white, TOW ONLY –</p> <p>This vehicle has an UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in "As is, where is" condition., 237,597 km, , KNOWN PROBLEMS and OBSERVATIONS:</p> <p>Check engine light on codes: P0300, P0113 intake air temperature, P0303 misfire cylinder #3, manifold leak, exhaust leak, rear links, note both upper ball joints within spec 5.</p> <p>Note: Exhaust push rod does not move as much as other cylinders-cam shaft has likely wiped exhaust lobe, hood chips, front bumper pitted/bent, rear bumper rusted/dented, left front fender rusted/chips, left rear fender dents/rust/road rash, right front fender rusted, right rear fender dents/road rash/rust, rocker panels road rash/rust, left front door sill paint worn, tailgate rust/chips, no first aid kit/fire extinguisher, windshield chips, left mirror housing broke, latch on left rear storage broke, missing head rest on rear seat, poor battery, minor exterior damage.>, As is, where is</p>	237,597 km	\$4,125	3C6TR5CT6GG118573

	Item #	Description	Kms	Min Price	Serial Number
No Bid	9-021	<p>Truck 2017 DODGE/RAM 2500 4WD, crew cab, 8' box 5.7L, V8, gas auto A/C, tilt, cruise, AM/FM, power heated tow mirrors, power locks/windows, keyless entry-2 key fobs side steps, mud flaps, hitch, trailer wiring, OEM trailer brake, headache rack, has back seat, white, TOW ONLY –</p> <p>This vehicle has an UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in "As is, where is" condition., 313,884 km, , KNOWN PROBLEMS and OBSERVATIONS: Left upper and lower ball joints have play, right upper ball joint play, left and right outer tie rod play, front shock for drag link leaked out, steering shocks, left rear axle seal leak, E-brake doesn't hold, driver switch door lock/unlock switch intermittent works, 4x4 intermittent, note drive door weather strip coming off.</p> <p>Grille loose, hood chips/dents, front bumper modified cross/chips, rear bumper dents, left rear fender road rash/dents, right rear fender road rash/dents/rust, left front door chips/weather strip, left rear door dents/chips, 3 holes in roof sealed, tailgate chips/scratches/dents, no first aid kit/fire extinguisher, windshield chips, hole in right rear seat head rest, center lower dash modified, no hub caps, poor battery, minor exterior damage.>, As is, where is</p>	313,884 km	\$9,411	3C6TR5HT9HG636154
No Bid	9-019	<p>Truck 2017 FORD F250 SD 4WD, crew cab, 6'10" box 6.2L, V8, gas auto A/C, tilt, cruise, aftermarket AM/FM radio, power heated trailer tow mirrors, power locks/windows, keyless entry-2 key fobs front tow hooks, side steps, mud flaps, hitch, trailer wiring, OEM trailer brake, box liner, headache rack, has back seat, white, TOW ONLY –</p> <p>This vehicle has an UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in "As is, where is" condition., 334,118 km, , KNOWN PROBLEMS and OBSERVATIONS: Exhaust manifold, front shocks, left outer tie rod, alignment needed, rear brake line not secured.</p> <p>Grille holes drilled, hood dents/stone chips, front bumper chips, rear bumper rusted/holes drilled, left front fender chips, left rear fender scratch, right rear fender small dents, left front door dents, tailgate chips/small dents, no first aid kit/fire extinguishers, windshield chips, left front seat sagging, holes drilled in box rails, front valance broken, poor battery, minor exterior damage.>, As is, where is</p>	334,118 km	\$16,146	1FT7W2B60HEE88021

Item #	Description	Kms	Min Price	Serial Number
No Bid * 8-011	<p>Truck 2018 FORD F250 SD 4WD, crew cab, 6'10" box 6.2L, v8, gas auto A/C, tilt, cruise, after market AM/FM, power heated trailer tow mirrors, power windows/locks, keyless entry-2 key fobs front tow hooks, side steps, mud flaps, hitch, trailer wiring, OEM trailer brakes, box liner, headache rack with beacon and wigwags, has back seat, grey, TOW ONLY –</p> <p>This vehicle has an UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in "As is, where is" condition., 318,842 km, , KNOWN PROBLEMS and OBSERVATIONS:</p> <p>Left tire worn out, front pads/rotors 3mm, wipers streaky, note hood ajar lights stay on. Grille broken, hood chips/scratches, both bumpers' scratches/chips/rust spots, all fenders scratches/chips, left side doors chips/scratches, right side doors parking lot dent, 1 tape covering hole in roof, tailgate dent/scratches/chips, spare tire loose in box may not be compatible with vehicle, no first aid kit/fire extinguisher, windshield chips left front seat sagging, broken wig wag on grille, exhaust noisy, back up assist not working, poor battery, minor exterior damage.>, As is, where is</p>	318,842 km	\$13,979	1FT7W2B69JEB32639
8,621.51 9-013	<p>Truck 2013 FORD F350 SD 4WD, crew cab, 8' box 6.2L, V8, gas auto A/C, tilt, cruise, AM/FM/CD player, power heated trailer tow mirrors, power windows/locks, keyless entry-2 key fobs grille inserts, side steps, mud flaps, hitch, trailer wiring, OEM trailer brakes, headache rack, beacon- not working, low racks on box rails, box liner, has a back seat, grey, TOW ONLY –</p> <p>This vehicle has an UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in "As is, where is" condition., 272,023 km, , KNOWN PROBLEMS and OBSERVATIONS:</p> <p>Check engine light on codes: P0171 & P0174 system to lean B1 + B2, both headlights foggy. Hood chips/scratches, both bumpers' rusted/scratches, left front fender chips, left rear fender scratches/road rash/dents, right front fender rust, right rear fender dents/road rash/scratches, both rocker panels road rash, left side doors chips rust inside bottom, left front door weather strip ripped, left rear door weather strip loose/missing inside lock button, right side doors chips/scratches/rust inside bottom, roof rust spots/small metal disc on roof, tailgate chips/scratches, no first aid kit/fire extinguisher, windshield chips, left front seat worn/foam visible, head lights fogged, poor battery, minor exterior damage.>, As is, where is</p>	272,023 km	\$8,610	1FT8W3B69DEA28148

Item #	Description	Kms	Min Price	Serial Number
3,278.08 9-008	<p>Truck 2013 DODGE Ram 1500 4WD, quad cab, 6'4" box 4.7L, V8, gas auto A/C, tilt, cruise, AM/FM, power mirrors/locks/windows, keyless entry-2 key fobs, 2 keys tow hooks, side steps, mud flaps, trailer wiring, hitch, headache rack, has back seat, silver, TOW ONLY –</p> <p>This vehicle has a VERY UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Body Integrity Inspection and a Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in "As is, where is" condition., 304,724 km, ,</p> <p>KNOWN PROBLEMS and OBSERVATIONS: Right lower ball joint, alignment (parts required), oil change, right rocker panel has rust holes, left rocker panel rocker has surface rust, stone chips in windshield.</p> <p>Hood chips/paint bubbling/hail, rear bumper dent/out of alignment, left front fender rust, left rear fender rust/road rash, right rear fender rust/road rash/dents, left rocker panel rust, right rocker panel rust/hole, left rear door rust, roof hail, tailgate small dents, rust spots near tailgate, no first aid kit/fire extinguisher, left mirror hole in housing, windshield chips/cracked, poor battery, minor exterior damage.>, As is, where is</p>	304,724 km	\$2,197	1C6RR7FP3DS578976
7,111.00 9-009	<p>Van 2012 CHEVROLET Express 1500 Cargo AWD 5.3L, V8, gas auto A/C, tilt, cruise, AM/FM/CD 161,921 km player, rear auxiliary heater, power windows/locks, keyless entry-2 fobs, 3 keys shelving, cargo barrier, map box, ladder rack condition unknown, white, TOW ONLY –</p> <p>This vehicle has a VERY UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Body Integrity Inspection and a Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in "As is, where is" condition., 161,921 km, ,</p> <p>KNOWN PROBLEMS and OBSERVATIONS: Front/rear rotors severely rusted need to be replaced, TPMS message on, left front parking light lens broken, left side lower mirror broken, rear right quarter panel rusted.</p> <p>Hood paint poor/chips, front bumper chips, rear bumper dents/rust, right rear fender rusted, rocker panels rust/dents, right side doors scrape/scratches, 1 hole in roof sealed, left front seat vinyl cracked/cushion sagging, left front signal lens broken no first aid kit/fire extinguisher, windshield chips, poor battery, minor exterior damage.>, As is, where is</p>	161,921 km	\$6,332	1GCSHAF47C1129515

Item #	Description	Kms	Min Price	Serial Number
REGINA, SaskBuilds and Procurement, SaskSurplus Sales Lot, 500 McLeod Street - Miscellaneous				
Contact SaskSurplus 306-787-2062 or 306-798-3306, sasksurplus@gov.sk.ca				
6,587.00	9-137	Trailer 2021 Continental Cargo V-Series Enclosed, 2" ball receiver, 4-flat plug-in comes with replacement, GVW 1,356 kg/2990 lb., outside measurements 15.5' l x 6.5'w x 8' h, inside measurements 11.5' l x 6.25' w x 6.5'h, 2 keys RV plug on outside on left side, inside 3-12v plug-ins, 3 storage cabinets in front inside, has a side door, rear fold out ramp door, tires Rainier ST205/75R15, spare tire Arisun ST205-75R15, has fire extinguisher, all lights <i>operational green</i> As is where is		\$5,700 5NUVH213MN095845
2.75	* 4-122	Disposable Emergency Stretcher, Weave canvas, black. Excellent		\$1
*MT	9-127	Extension Cords, Lot of 2 Powerfist Both yellow, 1-50 ft long, 1-25 ft long with triple outlet. Excellent		\$5
6.75	9-128	Folding Chair, Lot of 2 For Living, polyurethane foam Padded, black, 1 head rest ripped, other head rest has scratch, both worn Good		\$5
*MT	9-129	Generator, Firman, W2000i, gas 1600 watts, 200 starting watts, pull start, 1-20A 120V plug in, 1-30A 120V plug in, USB port, black, <i>operational</i> Excellent		\$200
33.00	9-130	Rubber Matts, Lot of 2 Premlene Sheet, rubber 72" x 40", diamond plate design Good		\$5
38.40	9-131	RV Extension Cord, Mighty Cord 3 prong, 25ft, 30A, red ends, black cord, with adapter from 15-30-RV-A to 15A 125VAC Excellent		\$30
10.10	9-132	Scissor Jacks, Lot of 2 Powerfist, metal Blue, 2 ton, lift range 4 5/8 to 16 1/8 Excellent		\$10
21.99	9-133	Space Heater, Comfort Zone Electric, 1500W, black, 3 settings, <i>operational</i> Excellent		\$20
5.51	9-134	Spiral Anchor, Lot of 2 Braber Equipment, metal 15", with ring, sliver Excellent		\$5
61.60	9-138	Tire, P265/70R17, Goodyear Wrangler HP, M+S Manufacture date week 22, year 2008. Good		\$50
*MT	* 6-102	Tires, Set of 3 LT265/70R17, Sumitomo Encounter AT, Snowflake, Load Range E Manufacture date, week 16, year 2024. Good		\$300
168.00	9-139	Tires, Set of 4 225/65R17, Firestone Weathergrip, Snowflake Manufacture date week 27, year 2020. Poor		\$60

	Item #	Description	Kms	Min Price	Serial Number
*MT	9-140	Tires, Set of 4 P265/70R17, Goodyear Wrangler ST, M+S Manufacture date week 24, year 2008. Good		\$180	
No Bid	9-135	Vacuum, Bissell AeroSwift Compact Corded, grey/black, with floor attachment, operational Good		\$10	
60.00	9-136	Work Bench, Mastercraft, metal 48"w x 22"d x 36"h, top shelf height 59", blue, with self-healing cutting mat, hanging Titan LED light operational, 1 drawer, with top shelf. Excellent		\$50	
11.00	9-101	Cabinet, wood Dark brown, 2 doors with lock and key, adjustable feet, 36.5" w x 19" d x 29.5" h, some scratches. Fair		\$1	
No Bid	9-102	Cabinet, wood Dark brown, 2 drawers with lock and key, missing adjustable feet, 36.5" w x 18" d x 27" h, some scratches. Fair		\$1	
11.11	9-103	Cabinet, wood Dark brown, 2 drawers with lock no key, adjustable feet, 36.5" w x 19" d x 29.5" h, some scratches. Fair		\$1	
No Bid	9-104	Cabinet, wood Dark brown, 2 drawers with lock no key, adjustable feet, 36.5" w x 19" d x 29.5" h, some scratches. Fair		\$1	
12.00	9-105	Cabinet, wood Dark brown, 2 sliding doors, 1 shelf, no lock, adjustable feet, 37" w x 19" d x 29" h, some scratches. Fair		\$1	
No Bid	9-106	Cabinet, wood Maroon, 2 drawers with lock and key, adjustable feet, 36" w x 24" d x 29.5" h, some scratches. Fair		\$1	
4.51 * 4-130		Chair, Swivel, cloth Black, 5 caster, adjustable height, no arms. Fair		\$1	
5.51 * 4-132		Chair, Swivel, cloth Blue, 5 caster, adjustable height and arms. Fair		\$1	
5.51 * 4-133		Chair, Swivel, cloth Grey, 5 caster, adjustable height, no arms. Fair		\$1	
50.31 * 4-136		Chairs, Lot of 3 Swivel, mesh back Black, 5 caster, adjustable height, arms worn, seats soiled. Poor		\$1	

	Item #	Description	Kms	Min Price	Serial Number
70.00	9-107	Credenza, wood Dark brown, 2 sliding doors, 2 drawers with lock no key, adjustable feet, 71" w x 16" d x 29" h, some scratches. Fair		\$1	
No Bid	9-108	Credenza, wood Light brown, 4 drawers with lock and key, 2 doors, 72" w x 19" d x 29.5" h, has some scratches. Fair		\$1	
11.11	9-109	Credenza, wood Light brown, 4 drawers, 2 doors with lock and key, 2 pull-out writing shelf, brass feet covers, 60" w x 21" d x 29.5" h, some scratches. Fair		\$1	
2.50 *	4-138	Desk, L-Shape Pepperdust, 72" w x 36" d x 29" h, return, 42" w x 19" d x 29" h, pedestal 18" w x 24.5" d x 26.5" h on wheels, locks, no key, keyboard tray mount underneath, screws included. Poor		\$1	
20.00	9-110	Desk, L-shape, wood Dark brown, 4 drawers with lock and keys, no hardware, missing adjustable feet, main 71.5" w x 36" d x 28.75" h, return side 84" w x 20" d x 28.75" h, dings and scratches. Fair		\$1	
20.00	9-111	Desk, L-shape, wood Dark brown, 6 drawers with lock with key, adjustable feet, no hardware, main 72" w x 35.5" d x 29" h, return side 51.5" w x 25.25" d x 29" h, some scratches. Fair		\$1	
17.77	9-112	Desk, L-shape, wood Light brown, 5 drawers no locks, 2 pull-out writing shelf, adjustable feet, keyboard tray pull-out, comes with hardware, main 102" w x 34" d x 30.25" h, return side 84.25" w x 20" d x 30.25" h, has some scratches and water damage. Fair		\$1	
No Bid	9-113	Desk, L-shape, wood Light brown, 5 drawers with lock and 2 keys, adjustable feet, comes with hardware, main 66.5" w x 35.5" d x 29.5" h, return side 43.5" w x 20.5" d x 28" h, comes with monitor riser with pull-out tray, some scratches and water damage, missing one adjustable foot. Fair		\$1	
No Bid	9-114	Desk, L-shape, wood Light brown, 5 drawers with lock and 2 keys, adjustable feet, no hardware, main 66.5" w x 35.5" d x 29.5" h, return side 43.5" w x 20.5" d x 28" h, comes with monitor riser with pull-out tray, some scratches and water damage. Fair		\$1	
No Bid	9-115	Desk, U-shape, wood Dark brown, 1 drawer, adjustable feet, has hardware, main 108" w x 20" w, left return, 72.25" w x 32.5" d, right return 120" w x 20.5" w x 29.5" h, some scratches, surface laminate lifting, back has cracked. Fair		\$1	
No Bid	9-116	Desk, wood Light brown, 3 drawers with lock and no key, adjustable feet, 67" w x 36" d x 29.5" h, some scratches and water damage. Fair		\$1	
No Bid	9-117	Desk, wood Light brown, 6 drawers with lock and no keys, adjustable feet, 72" w x 19" d x 29.5" h, some scratches. Fair		\$1	

	Item #	Description	Kms	Min Price	Serial Number
	No Bid 9-118	Desk, wood Light brown, 6 drawers with locks and key, adjustable feet, 72" w x 19" d x 29.5" h, has some scratches, one lock has key broken inside the lock. Fair		\$1	
3.35	9-119	Desk, wood Light brown, adjustable feet, 36.25" w x 20" d x 26.25" h, some scratches and minor water damage. Fair		\$1	
25.00	9-120	Desk, wood Light brown, adjustable feet, 36.25" w x 20" d x 26.25" h, some scratches and water damage. Fair		\$1	
3.33	9-121	Desk, wood Light brown, adjustable feet, 36.25" w x 20" d x 26.25" h, some scratches and water damage. Fair		\$1	
11.11	9-122	Desk with Hutch, wood Both dark brown, 4 doors drawers with lock and 2 keys, adjustable feet, desk 72" w x 19" d x 29.5" h, 6 hutch 69" w x 14.5" d x 39" h, both have minor water damage and scratches. Fair		\$1	
	No Bid 9-123	Desk with Hutch, wood Both dark brown, 6 drawers with lock no key, adjustable feet, desk 72" w x 19" d x 29" h, hutch 69" w x 14.5" d x 39" h, 4 doors with lock with key, some scratches. Fair		\$1	
	No Bid 9-124	Desk with Hutch, wood Both dark brown, 6 drawers with no locks, 72" w x 20" d x 29.5" h, hutch 69.25" w x 14.5" d x 39" h, some scratches. Fair		\$1	
6.75	9-125	Table, wood, round Dark brown, 60" diameter x 29" h, scratches, water damage. Fair		\$1	
7.77	9-126	Table, wood, round Light brown, with brass feet covers, 42" diameter x 30.5" h, some scratches. Fair		\$1	

Item #	Description	Kms	Min Price	Serial Number
LLOYDMINISTER, Highways, 3603 44th Street				
Contact Mark Eisenkirch 306-526-9103, Mark.eisenkirch@gov.sk.ca				
2,800.00 * 8-503	Sander, 2006, Hi Way E2500 slide in Good		\$2,500	125083
MAKWA LAKE PROVINCIAL PARK, Parks, Culture & Sport, 39 Golf Course Rd				
Contact Barry Rogers 306-837-2141, barry.rogers@gov.sk.ca				
5,757.55 9-538	Riding Mower 2007 Grasshopper 721 DT, 5816728 2WD 21 hp 719 cc Kubota, diesel wheel base: 51.5 inches, tire size 20x10, 3 keys Buffalo turbine blower attachment, brown/white, , 962.20 hrs, , KNOWN PROBLEMS: Non-operational, engine runs but keeps blowing engine belts, needs battery, minor exterior damage.>, As is, where is	962.20 hrs	\$800	5816728
1,280.00 9-536	Riding Mower 2003 Kubota ZG 23, 13418 2WD 23 hp, 90 degree V Twin, gas 54 inch mower, 735.1 hrs tire size 23 X10.50 – 12, one key , red, , 735.1 hrs, , KNOWN PROBLEMS: Non-operational, electrical issue - can't start but engine was running good prior to electrical issue. Needs a battery, minor exterior damage.>, As is, where is	735.1 hrs	\$400	13418
1,580.00 9-537	Riding Mower 2012 Toro MX6080, 74873 2WD 24 hp, Kawasaki 726 cc, gas Zero turn with 50 320 hrs inch deck, tire size 22 x 10.00-10 NHS, one key , red, , 320 hrs, , KNOWN PROBLEMS: Non-operational, deck is too big for mower, blows belts in longer/thick grass, engine runs good, needs battery, minor exterior damage.>, As is, where is	320 hrs	\$1,000	312000904
MEADOW LAKE PROVINCIAL PARK, Parks, Culture and Sport, Meadow Lake Provincial Park - Highway 224 - Call for Directions				
Contact Heath Harpham 306-839-7323, heath.harpham@gov.sk.ca or Reg Bayko 306-240-4513, reg.bayko@gov.sk.ca				
*WD 9-540	Cement Mixer, used, Braber Equipment, 3 point hitch Unsure if operational in current condition. Poor		\$25	COS080362
4,659.00 9-541	Tree Spade Trailer 1974 Unknown make GX270 Honda 9.0HP, gas pull-type, tire size 12-16.5LT, clevis hitch, was working when last used, unknown if operational, poor condition It is unknown if this trailer has ever been registered through SGI and, as such, it might not have had a license plate affixed to it. SGI may have to generate and supply a new VIN number to this trailer, so contact with SGI could be necessary if you want to plate this trailer and have it legal to drive on roadways. , yellow, , , KNOWN PROBLEMS: This trailer has been sitting for several years, As is, where is		\$100	

Item #	Description	Kms	Min Price	Serial Number
MEADOW LAKE PROVINCIAL PARK, Parks, Culture and Sport, Meadow Lake Provincial Park - Call for Directions				
Contact Heath Harpham 306-839-7323, heath.harpham@gov.sk.ca				
1,451.00	9-553	Truck 2015 Dodge Ram 3500 4x4, crew cab, 8' box 5.7L, V8, gas auto air, cruise, tilt, AM/FM, GVW 5125.6 kg, tire size LT275/70R18E, hitch receiver, one key headache rack, beacon, white, TOW ONLY, NO SGI Inspection. It is unknown if any repairs or safety concerns exist (if any). Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs if required. , 435389 km, , KNOWN PROBLEMS: Has been parked for one year, no battery, it will not start or run and the engine will not turn over, the motor is locked up, unknown mechanical issues, minor exterior damage.>, As is, where is	435389 km	\$1,000 3C63R3GT9FG592692
2,601.00				
2,601.00	9-542	Truck 2008 Ford F350 Super Duty 4X4, extended cab, flat deck 5.4L V8, gas auto air, cruise, tilt, AM/FM, single axle, 1 set of keys rear hitch receiver, GVW 4536kg, tire size LT275/70R18E, white, TOW ONLY, NO SGI Inspection. It is unknown if any repairs or safety concerns exist (if any). Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs if required. , 282,989.2 km, , KNOWN PROBLEMS: This truck is a TOW ONLY vehicle. It will require an SGI Safety inspection to be completed before it can be driven, vehicle's history unknown, it has been parked for four years, missing its battery, boosted on November 18th and started relatively easy, test drove for 10 minutes and the transmission works and shifted in and out of 4x4 successfully, strong exhaust smell, possible exhaust leak, was reported that it may stall after running for a while and be difficult to restart, poor interior, poor wipers, poor tires, minor exterior damage.>, As is, where is	282,989.2 k	\$2,500 1FDSX35508EB05982
2,121.57				
2,121.57	9-552	Truck 2004 Ford F450 RWD, super cab, flat deck, utility body 6.0L V8, diesel auto air, cruise, tilt, AM/FM, GVW 4989.5 kg, dual rear tires, tire size LT225/70R19.5, 1 key 3 ball hitch, white, TOW ONLY, NO SGI Inspection. It is unknown if any repairs or safety concerns exist (if any). Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs if required. , 257220.6 km, , KNOWN PROBLEMS: Unknown mechanical issues, does not run, originally parked due to bad fuel pump, rusty exterior, poor battery, minor exterior damage.>, As is, where is	257220.6 kr	\$1,000 1FDXX46P64EC66942
MOOSE JAW, Highways, 1 km South of Moose Jaw on Hwy. #2				
Contact Al Froehlich 306-694-3775, allan.froehlich@gov.sk.ca or Tara Watson 306-694-3773, tara.watson@gov.sk.ca				
777.77	9-535	Hydraulic Hose Crimper , Eaton ET1000 weatherhead Comes with 3 boxes of assorted sizes of dies, unknown if operational. Fair		\$50

Item #	Description	Kms	Min Price	Serial Number
MOOSE JAW, Highways, JCT 39/1, NW-33-16-25-W2 - Call for Directions				
Contact Curtis Richardson 306-533-0562, curtis.richardson@gov.sk.ca or Mike Dudley 306-630-4246, michael.dudley@gov.sk.ca				
No Bid 9-547	Bridge Girder, Precast prestressed concrete bridge girder 12m x 48" w x 22" h approximate weight: 12800kg, these girders are salvaged from bridges that have been replaced. IMPORTANT NOTE: The bridge girders SHALL NOT be used for any structural means, the are deemed in "Salvage", "Disposed" and in "Non-Structural" condition, buyer MUST sign an <u>agreement not to use for any structural purposes. Beyond Repair</u>		\$1	
No Bid 9-548	Bridge Girder, Lot of 6 Precast prestressed concrete bridge girder 15m length x 48" w x 24" h, approximate weight: 18200kg, these girders are salvaged from bridges that have been replaced. IMPORTANT NOTE: The bridge girders SHALL NOT be used for any structural means, the are deemed in "Salvage", "Disposed" and in "Non-Structural" condition, buyer MUST sign an agreement not to use for any structural purposes. Beyond Repair		\$1	
No Bid 9-549	Bridge Girder, Lot of 6 Precast prestressed concrete bridge girder 15m length x 48" w x 24" h, approximate weight: 18200kg, these girders are salvaged from bridges that have been replaced. IMPORTANT NOTE: The bridge girders SHALL NOT be used for any structural means, the are deemed in "Salvage", "Disposed" and in "Non-Structural" condition, buyer MUST sign an agreement not to use for any structural purposes. Beyond Repair		\$1	
No Bid 9-550	Bridge Girder, Lot of 5 Precast prestressed concrete bridge girder 9m length x 48" w x 22" h, approximate weight: 9500kg, these girders are salvaged from bridges that have been replaced. IMPORTANT NOTE: The bridge girders SHALL NOT be used for any structural means, the are deemed in "Salvage", "Disposed" and in "Non-Structural" condition, buyer MUST sign an agreement not to use for any structural purposes. Beyond Repair		\$1	
No Bid 9-551	Bridge Girder, Lot of 5 Precast prestressed concrete bridge girder 9m length x 48" w x 22" h, approximate weight: 9500kg, these girders are salvaged from bridges that have been replaced. IMPORTANT NOTE: The bridge girders SHALL NOT be used for any structural means, the are deemed in "Salvage", "Disposed" and in "Non-Structural" condition, buyer MUST sign an agreement not to use for any structural purposes. Beyond Repair		\$1	

Item #	Description	Kms	Min Price	Serial Number
OUTLOOK, Agriculture, 410 Saskatchewan Ave W				
Contact Ben Lalonde 306-867-6469, ben.lalonde@gov.sk.ca or Outlook Front Desk 306-867-5500, stacey.stutters@gov.sk.ca				
No Bid 9-527	GPS Base Radio, Pacific Crest PDL 4335 430-450Mhz radio for GPS system, significant wear, stored in a cool dry place for many years, no cables included, unknown if operational. Poor		\$5	8091658
Leveling Rods, Lot of 3				
No Bid 9-528	aluminum Total height 5m, each set has 4 pieces that clip together with carrying case, one case is blue nylon, the other two are brown leather or vinyl, rods have not been used for decades, stored in a cool dry place, noticeable wear is present, calibration <u>will be likely be required. Fair</u>		\$30	
54.23 9-529	Optical Automatic Level, Sokkisha B2C, Auto Level For surveying, not used in decades, comes with carrying case, stored in a cool dry place, calibration required. Magnification: 32x Eff. OBJ. Aperture: 40mm, shortest foc. Dist. 1.4m Stadia Mult. Const.: 100 add. Const.: +0.151m. Fair		\$50	105114
65.00 9-530	Optical Tilting Level, Geotec, L-21D For surveying, has not been used in decades, in carrying case, stored in a cool dry place, calibration required. Magnification: 32x Eff. OBJ. Aperture: 45mm, shortest Foc. Dist. 1.9m Stadia Mult. Const.: 100 add. Const.: 0. Fair		\$50	516286
102.25 9-531	Robotic Total Station, Lot of 2 1999 Topcon AP-L1A Autotracking Comes with TDS Ranger 1 Data Controller, 360 prism, batteries, radios, 2 carrying cases and instruction manuals, some wear present on TDS Ranger Controller. Prism, carrying case and AP-L1A still in good condition, has not been used for over a decade, stored in a cool dry place, unknown if still fully operational, still useful as spare parts. <u>Fair</u>		\$100	AP-L1A Total Station: LT0913, TDS
18.25 9-532	Trimble Geoexplorer, 2008 series Handheld, operational but battery does not hold charge for long, new rechargeable battery required, internal memory has been wiped. Poor		\$5	
Tripods, Lot of 3				
No Bid 9-533	wood For surveying, one Duratech, two Leica, one Leica tripod has a telescoping antenna pole, stored in a cool dry place, all tripod clamps are somewhat loose, noticeable wear present, tightening and calibration <u>will likely be required. Fair</u>		\$75	
10.75 9-534	VFD Converter, Grundfos Redi-Flo 2 BTI/ MP-1 In case, includes manual, stored in a cool dry place for many years, submersible pump not included, unknown if any other components are missing, appears to be in good shape, unknown if operational. Fair		\$5	
PRINCE ALBERT, Corrections, Policing and Public Safety, 3021 1st Ave W				
Contact: Tonya Granberg 306-953-3005, tonya.granberg@gov.sk.ca or Nola Boechler, nola.boechler@gov.sk.ca				
No Bid * 8-520	Blanket, Lot of 2 light material, unknown material No tag. blue Good		\$1	
No Bid * 8-521	Coffee Filter Basket, Lot of 18 plastic brown Poor		\$1	

Item #	Description	Kms	Min Price	Serial Number
No Bid * 8-522	Coffee Pots , Lot of 21 plastic With metal bottom. Poor		\$1	
PRINCE ALBERT, Environment, 201 - 1061 Central Ave				
Contact Emelyn Feliciano 306-953-3233, emelyn.feliciano2@gov.sk.ca or Mary Jane Mackie, maryjane.mackie@gov.sk.ca				
15.00 9-501	Chair, ergonomic, swivel, tilter Adjustable, black mesh 5 casters, both arm rest are worn. Fair		\$1	
No Bid 9-502	Desk Lamp, metal Black and green, operational. Good		\$1	
No Bid 9-503	Desktop Document Holder, DAC, metal Black, 9" x 13". Fair		\$1	
No Bid 9-504	Digital Cameras, Lot of 3 Canon LCD screen is broken, operational, silver, no memory card, internal memory wiped. Fair		\$1	
1.00 9-505	File Sorter Racks, Lot of 2 metal Black and gray; 7 compartments 9" x 14", 4 layers, legal size. Good		\$1	
No Bid 9-506	Headphones, Lot of 4 wired Black, unknown if operational. Poor		\$1	
3.75 9-507	Hole Punches, metal 3 holes, black. Fair		\$1	
No Bid 9-508	Keyboard Trays, Lot of 8 metal; wood Ergonomic adjustable keyboard platform, black. Fair		\$1	
3.00 9-509	Power strip, Belkin White, operational. Fair		\$1	
No Bid 9-510	RCA Conference Speaker Phone, circular Black, with cable & adapter, operational. Fair		\$1	
1.00 9-511	Wrist Rests, Lot of 3 foam 2 ft long, black. Good		\$1	
PRINCE ALBERT, Saskatchewan Public Safety Agency, 47 - 12th St				
Contact: Justin Pearce 306-953-3492, justin.pearce@gov.sk.ca				
2.00 * 6-532	File Cabinet, metal, lateral Grey, 4 drawer, drawers open and close properly and smoothly, 18" w x 28"d x 51" h. Good		\$1	
No Bid * 6-533	Projector, Kodak Carousel 4200 Black, comes with a corded remote and a power cord, unknown if operational. Good		\$1	SERM: 10-20-20
PRINCE ALBERT, Saskatchewan Public Safety Agency, 2120 Central Ave				
Contact: Suzanne Goota 306-941-7217, suzanne.goota2@gov.sk.ca				
No Bid * 7-512	File Cabinet, metal, lateral 18"w x 28"d x 51" h, doors open properly, no lock. Fair		\$1	
No Bid * 7-513	File Cabinet, metal, lateral 18"w x 28"d x 51" h, doors open properly, no lock. Fair		\$1	

Item #	Description	Kms	Min Price	Serial Number
No Bid * 7-514	File Cabinet, metal, lateral 18"w x 28"d x 51" h, locks, no key, doors open properly. Fair		\$1	
No Bid * 7-515	File Cabinet, metal, lateral 18"w x 28"d x 51" h, locks, no key, doors open properly. Fair		\$1	
REGINA, Legislative Assembly Service, 515 Henderson Drive				
Contact: Kadence McMillen 306-787-0337, kmcmillen@legassembly.sk.ca or Karen Plumb 306-787-8167, kplumb@legassembly.sk.ca				
No Bid * 8-501	Uninterruptable Power Supply with Batteries and Power Modules, Lot of 11 APC Symmetra 1 APC Symmetra LX UPS, SYAF16KRMT, 7 APC Symmetra LX Battery Module, SYBT5, 2 APC Symmetra LX Power Module, SYPM4KP, 1 APC Symmetra LX Power Module, SYPM4KPQ. UPS: 19"w x 27"d x 33" h, (shipping 42 x 24 x 40) 500lbs, each battery is 18 kg, 4 batteries in box, 3 loose, unknown what condition batteries are in, no power cord as it has to be direct wired into building power. Sold as is. UPS: QD1037260148, in-box batteries: 5D2007T60139, 5D2018T65313, 5D2018T65320, 5D2007T60123, loose batteries: 5D2005T15219, 5D2007T60147, 5D2007T60138, SYPM4KP, power modules: QD1513380215, AD2033110087, SYPM4KPQ power module: AQ2106210005, operational. Fair		\$5,000	
REGINA, Saskatchewan. Liquor & Gaming Authority, 12252 Ewing Ave				
Contact: Al Kentz or Todd Leurer, DCMaintenance@slga.com				
3,500.00 9-545	Reach Truck Raymond 740 R35TT electric mast approx. 8.5 ft in height, 1 key charger included - Vulcan Micro Smart, no guarantees, warranties, returns, or refunds are provided, the seller assumes no responsibility for the condition, performance, or any issues after purchase, the buyer is solely responsible for the complete removal and pickup of the machine from the property, the seller will provide minimal loading assistance, but the buyer will be responsible for laydown and any other related tasks, any damage to the premises or lot during removal will be the buyer's responsibility, the buyer assumes full responsibility for all aspects of removal, including any associated tasks, IT IS RECOMMENDED THAT YOU SET-UP A TIME TO VIEW MACHINES BEFORE BIDDING/AUCTION CLOSE TO ENSURE YOU ARE ABLE TO PROPERLY REMOVE THEM FROM PROPERTY. Please contact Al to arrange viewing if interested, , , 25527 key hrs, 11229 total d, Known Recent Repairs: serviced twice annually, KNOWN PROBLEMS: As is, where is	25527 key h	\$500	740-11-CB22834

Item #	Description	Kms	Min Price	Serial Number
2,500.00 9-546	Reach Truck Raymond 20R30TT electric mast approx. 8.5 ft in height, 2 keys charger included - GNB - SCR 100, no guarantees, warranties, returns, or refunds are provided, the seller assumes no responsibility for the condition, performance, or any issues after purchase, the buyer is solely responsible for the complete removal and pickup of the machine from the property, the seller will provide minimal loading assistance, but the buyer will be responsible for laydown and any other related tasks, any damage to the premises or lot during removal will be the buyer's responsibility, the buyer assumes full responsibility for all aspects of removal, including any associated tasks, IT IS RECOMMENDED THAT YOU SET-UP A TIME TO VIEW MACHINES BEFORE BIDDING/AUCTION CLOSE TO ENSURE YOU ARE ABLE TO PROPERLY REMOVE THEM FROM PROPERTY. Please contact AI to arrange viewing if interested, , , 35 hrs, Known Recent Repairs: serviced twice annually, KNOWN PROBLEMS: functionality unknown , As is, where is	35 hrs	\$100 020.87.26357	
2,249.00 9-543	Reach Truck Raymond 752 R45TT electric mast height - approx 14 ft, 2 keys charger included - #215CS32103, no guarantees, warranties, returns, or refunds are provided, the seller assumes no responsibility for the condition, performance, or any issues after purchase, the buyer is solely responsible for the complete removal and pickup of the machine from the property, the seller will provide minimal loading assistance, but the buyer will be responsible for laydown and any other related tasks, any damage to the premises or lot during removal will be the buyer's responsibility, the buyer assumes full responsibility for all aspects of removal, including any associated tasks, IT IS RECOMMENDED THAT YOU SET-UP A TIME TO VIEW MACHINES BEFORE BIDDING/AUCTION CLOSE TO ENSURE YOU ARE ABLE TO PROPERLY REMOVE THEM FROM PROPERTY. Please contact AI to arrange viewing if interested, , , 17380 key hrs, 19485 total d, Known Recent Repairs: serviced twice annually, KNOWN PROBLEMS: Batteries are operational but approximately 5 years old, As is, where is	17380 key h	\$1,000 752-15-AD49007	
2,269.00 9-544	Reach Truck Raymond 752 R45TT electric mast height - approx 14 ft, 2 keys charger included - #215CS32100, no guarantees, warranties, returns, or refunds are provided, the seller assumes no responsibility for the condition, performance, or any issues after purchase, the buyer is solely responsible for the complete removal and pickup of the machine from the property, the seller will provide minimal loading assistance, but the buyer will be responsible for laydown and any other related tasks, any damage to the premises or lot during removal will be the buyer's responsibility, the buyer assumes full responsibility for all aspects of removal, including any associated tasks, IT IS RECOMMENDED THAT YOU SET-UP A TIME TO VIEW MACHINES BEFORE BIDDING/AUCTION CLOSE TO ENSURE YOU ARE ABLE TO PROPERLY REMOVE THEM FROM PROPERTY. Please contact AI to arrange viewing if interested, , , 16088 key hrs, 17050 total d, Known Recent Repairs: serviced twice annually, KNOWN PROBLEMS: Batteries are operational but approximately 5 years old, As is, where is	16088 key h	\$1,000 752-15-AD49012	

Item #	Description	Kms	Min Price	Serial Number
SASKATOON, Highways, 126 105th St E				
Contact Richard Leibel 306-933-5262, Richard.Leibel@gov.sk.ca or Shaun.Bowditch@gov.sk.ca				
2,800.00	9-539 Gravel Truck 2001 Volvo WG64F Tandem Volvo VED12C, 345 horse power, 6 cylinder, diesel standard Super 10 10 speed, tandem axle, interlocking differential, tire size 11R22.5, AM/FM/cassette 2000 Tenco TC116HD RH wing in poor condition, serial# 16587, yellow, TOW ONLY, NO SGI Inspection. It is unknown if any repairs or safety concerns exist (if any). Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs if required. , 552,716 km, Known Recent Repairs:; KNOWN PROBLEMS: Motor leaks and burns oil, transmission is leaking and corroded, hydraulic pump shaft broken, engine fan shroud broken, radiator damaged and leaking, air to air leaking, right rear fender rotted, frame worn and thin, cross chain is running on frame, tarp bearings broken and bracket bent, rear differential leaking, stop engine warning light is on, no hydraulics as control box has been removed, tires removed off second axel, axel chained up. right hand wing and mount attached, interior in fair condition, minor exterior damage.>, As is, where is	552,716 km	\$2,500	4V5JC8GF91N309572
SASKATOON, Saskatchewan Research Council, Bay 2D 820 51st St E				
Contact Aamir Bakhsh 306-370-8011, Aamir.Bakhsh@src.sk.ca or Gina Zimmer 306-250-9690, gina.zimmer@src.sk.ca				
No Bid	* 8-540 Pipe Fittings, grooved 5 pallets, never used or installed. New- Unused		\$500	
SASKATOON, Saskatchewan Research Council, 820 51st St E				
Contact Roger Dauvin 306-385-4035, roger.dauvin@src.sk.ca or purchasing@src.sk.ca				
No Bid	9-512 Dehydrator, Hungry Giant, HGF-320ML Operational, put into use 2020 (RFQ 1920-011 ; 256532). Good		\$15,000	HGF320ML-CAN1601-001
SASKATOON, Trade and Export Development, 219 Robin Cres				
Contact Hiren Khemani 306-787-8712, hiren.khemani@gov.sk.ca or Joan.Lewandoski, joan.lewandoski@gov.sk.ca				
28.75	9-513 Book Shelf, metal 5 shelves, beige, 37.5"w x 17.5"d x 72"h. Good		\$15	
12.56	9-514 Cabinet, lateral, metal 3 drawers, no keys, beige, 36"w x 18"d x 40.5"h. Good		\$10	
22.75	9-515 Cabinet, lateral, metal 3 drawers, no keys, beige, 36"w x 19"d x 40.5"h. Good		\$10	
10.88	9-516 Cabinet, lateral, metal 4 drawers, no keys, grey, 36"w x 18.5"d x 54"h. Good		\$10	

Item #	Description	Kms	Min Price	Serial Number
11.16 9-517	Cabinet, lateral, metal 5 drawers, includes keys, beige, 36"w x19"d x 67"h. Good		\$10	
13.17 9-518	Cabinet, lateral, metal 5 drawers, no keys, beige, 36"w x 18"d x 65"h. Good		\$10	
25.00 9-519	Desk, L-Shape, wood One side 72"w x 36"d x 29"h, other side 42"w x 26"d x 29"h, pepperdust. Good		\$25	
34.75 9-520	Desk, L-Shape, wood One side 72"w x 36"d x 29"h, other side, 42"w x 26"d x 29"h, pepperdust. Good		\$25	
10.50 9-521	Pedestal, lateral, metal 3 drawers, no keys, black, 15"w x 18"d x 28"h. Good		\$9	
YORKTON, Highways, 245 York Rd E				
Contact Randy Potter 306-621-4791, randy.potter@gov.sk.ca				
75.00 9-522	Sign Posts, wood, spruce or fir, used Mix of 4" x 4" and 4" x 6" x 8' to 12' approximately, mix of treated and untreated, old and broken, approximate weight of lift is 6500 lbs, must bring deck over trailer for assistance with loading, if deck over trailer cannot be provided loading is responsibility of buyer. Ministry staff will not load any trailer deemed unsafe to load. Trailers with fenders will not be loaded by Ministry staff. Please note lifts are now smaller to make handling safer 50-60 posts per lift Fair		\$1	
107.97 9-523	Sign Posts, wood, spruce or fir, used Mix of 4" x 4" and 4" x 6" x 8' to 12' approximately, mix of treated and untreated, old and broken, approximate weight of lift is 6500 lbs, must bring deck over trailer for assistance with loading, if deck over trailer cannot be provided loading is responsibility of buyer. Ministry staff will not load any trailer deemed unsafe to load. Trailers with fenders will not be loaded by Ministry staff. Please note lifts are now smaller to make handling safer 50-60 posts per lift Fair		\$1	
137.27 9-524	Sign Posts, wood, spruce or fir, used Mix of 4" x 4" and 4" x 6" x 8' to 12' approximately, mix of treated and untreated, old and broken, approximate weight of lift is 6500 lbs, must bring deck over trailer for assistance with loading, if deck over trailer cannot be provided loading is responsibility of buyer. Ministry staff will not load any trailer deemed unsafe to load. Trailers with fenders will not be loaded by Ministry staff. Please note lifts are now smaller to make handling safer 50-60 posts per lift Fair		\$1	

Item #	Description	Kms	Min Price	Serial Number
127.97 9-525	Sign Posts, wood, spruce or fir, used Mix of 4" x 4" and 4" x 6" x 8' to 12' approximately, mix of treated and untreated, old and broken, approximate weight of lift is 6500 lbs, must bring deck over trailer for assistance with loading, if deck over trailer cannot be provided loading is responsibility of buyer. Ministry staff will not load any trailer deemed unsafe to load. Trailers with fenders will not be loaded by Ministry staff. Please note lifts are now smaller to make handling safer 50-60 posts per lift Fair		\$1	
161.00 9-526	Tires, Lot of 3 LT 245/75R17 121/118 M+S Radial Used, Firestone Destination. Good		\$1	