

COVID-19 Update

To support safe SaskSurplus Sale operations during the COVID-19 pandemic, new measures have been introduced for clients to follow. These include online-only viewings of sale items, a pre-pickup screening checklist, and SaskSurplus Sales - Pick-up Guidelines.

The safety of SaskSurplus clients and employees is our top priority, and we thank you for your cooperation with these new measures. For general Government of Saskatchewan information related to COVID-19, please visit saskatchewan.ca

Every effort has been made to accurately describe items and their condition; however additional problems may exist, items may not be complete or exactly as described. Bidders are deemed to have reviewed the Terms and Conditions on bid forms and relied entirely on their own inspection and evaluation prior to bidding. Vehicles and equipment are sold "AS IS, WHERE IS", there is no implied or express warranty.

Visit www.SaskSurplus.ca for pictures and link to download Bid Form.

- Items identified with * have been on a previous sale and will be listed first on www.SaskSurplus.ca web site.
- Central Services, SaskSurplus reserves right to have unadvertised minimum selling prices on items.

It is the Bidder's responsibility to review the terms and conditions of sale on the Offer to Purchase, Bid Form.

Bid Forms are available from www.SaskSurplus.ca or from the SaskSurplus Sales Lot, 500 McLeod Street, Regina, SK.

Bid Forms can be submitted in the following ways:

- by deposit in the bid box at the SaskSurplus Sales Lot.
- by fax to (306)787-2092; by phone (306)787-2062 or (306)787-2238
- by email to sasksurplus@gov.sk.ca
- or by mail, addressed to: Ministry of Central Services, SaskSurplus, 500 McLeod Street, Regina, SK S4N 4Y1.
(If mailing your bid, please allow sufficient time for bid to be received.)
- Bids received after close date and time cannot be accepted.

MT = (Ministry Transfer) This means that the item has been claimed by another ministry and automatically transferred.

WD = (Withdrawn) This can happen if the item was requested to be removed by the seller,
or if bid prices did not meet the seller's minimum selling price. In this case, the item may be carried forward to a future sale.

Item #	Description	Kms	Serial Number	Ministry	Ministry /	Disposal
REGINA, SaskBuilds and Procurement, SaskSurplus Sales Lot, 500 McLeod Street - Vehicles						
Due to COVID-19, ON-LINE VIEWING ONLY. NO ON-SITE VIEWING. Contact SaskSurplus (306) 787-2062 or (306) 798-3306.						
1,389.89 1-032	Car 2008 CHEVROLET Impala LS FWD, 4 door 3.5L V6 Gas Auto power locks, mirrors, windows, trunk release, and driver's seat; a/c, tilt, cruise, AM/FM/CD, keyless entry (2 keys/2 fobs) , Grey, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: front wheel alignment out, left outer tire rod, windshield cracked, front bumper broken, all doors/trunk lid rusted, battery poor, minor exterior damage.>, As is, Where is	295,297 Kms	2G1WB58K7813537 86	CVA	316364	2103-805 TOW ONLY, 109-3
2,389.89 * X-028	Car 2013 CHEVROLET Impala LS 4 door 3.6L V6 gas auto air, tilt, cruise, AM/FM/CD player, PL, PM, PW, power driver seat, power trunk release , Grey , TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: rear links, both rear valve stems leaking, grille broken, hood chips/dents/scratches, both bumpers chips/scratches, left front fenders scratches, driver door rust at bottom, roof scratches/rust spots, trunk lid scratches, windshield chips, driver seat worn, parking lot dents & scratches>, As is, Where is	277,953 Kms	2G1WA5E35D12566 93	CVA	800058	2004-026 TOW ONLY, 122-7
3,059.00 1-033	Car 2013 CHEVROLET Impala LS V6 FWD, 4 door 3.6L V6 Gas Auto power locks, windows, mirrors, trunk release, and driver's seat; a/c, tilt, cruise, AM/FM/CD, keyless entry (2 keys/2 fobs) , Grey, Passed SGI Inspection., RR flat tire repaired, PROBLEMS: front bumper cracked, rust on LR fender at gas cap, small rust spots on roof and left doors, right rocker panel moulding bent, battery poor, minor exterior damage.>, As is, Where is	252,734 Kms	2G1WA5E35D11724 40	CVA	317172	2103-804 PASSED SGI, 109-2

2,903.42	1-034	Car 2007 CHRYSLER Sebring Touring FWD, 4 door 2.7L V6 Gas Auto power windows, locks, heated mirrors, driver's seat, and trunk release; a/c, tilt, cruise, AM/FM/CD, 2 key fobs , Blue, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: front and rear struts leaking, hood paint bubbling, driver's door/hood/rear bumper/left mirror paint poor, passenger's door rust spots, LF fender scuffed, headliner peeling, battery poor, minor exterior damage.>, As is, Where is	152,825 Kms	1C3LC56R77N63472 3	CVA	145458 TOW ONLY, 109-7	2103-809
2,559.00	1-035	Car 2007 CHRYSLER Sebring Touring FWD, 4 door 2.7L V6 Gas Auto power locks, heated mirrors, windows, and trunk release; a/c, tilt, cruise, AM/FM/CD, keyless entry (2 key fobs) , Silver, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: LF strut leaking, front rotors badly rusted, left lower balljoint, front and rear wheel alignment out, TPMS light on, windshield cracked, rear fenders/left doors rusted, rear toe link/knuckle bushings, undercarriage very rusty, hood/driver's door paint poor, driver's head lamp fogged out, left license lamp out, gas cap door loose, battery poor, minor exterior damage.>, As is, Where is	204,965 Kms	1C3LC56R87N63469 6	CVA	156281 TOW ONLY, 107-6	2103-814

2,159.00	1-036	Car 2008 CHRYSLER Sebring Touring FWD, 4 door 2.7L V6 Gas Auto power locks, heated mirrors, and windows; a/c, tilt, cruise, AM/FM/CD, keyless entry (2 key fobs) , Beige, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , Catalyst System Efficiency P0420, PROBLEMS: check engine light on, rear struts pulsation, rear pads and rotors, passenger door rusted, bumpers/front fenders badly chipped/scratched, hood paint bubbling, driver side mirror paint chipping, battery poor, minor exterior damage.>, As is, Where is	238,948	1C3LC56R28N23053	CVA	142281	2103-789
			Kms	6			TOW ONLY, 106-5
4,110.37	1-037	Car 2012 DODGE Avenger SE FWD, 4 door 2.4L L4 Gas Auto power locks, windows, mirrors, and trunk release; a/c, tilt, cruise, AM/FM/CD, keyless entry (2 keys/2 fobs) , Copperhead, Passed SGI Inspection., rear pads and rotors, engine oil, PROBLEMS: hood paint bubbling, hail damage on roof, left visor clip broken, battery poor, minor exterior damage.>, As is, Where is	199,884	1C3CDZAB0CN2136	CVA	158493	2103-808
			Kms	31			PASSED SGI, 109-6
3,859.00	1-038	SUV 2009 DODGE Durango 4x4, 5 passenger 5.7L V8 Gas Auto power windows, locks, mirrors, and driver's seat; a/c, tilt, cruise, rear HVAC, keyless entry (2 key fobs) driving lights, front tow hooks, roof rails, mud flaps, cargo barrier, plywood floor cargo area, hitch, trailer wiring, electric trailer brake, White, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , TPMS light, PROBLEMS: front wheel alignment out, windshield cracked, driver window switch inoperable, LF/LR/RF fenders rusted, doors/roof/tailgate rusted, holes in rear seat carpet, holes in head liner, 2 sealed holes in roof, battery poor, minor exterior damage.>, As is, Where is	184,794	1D8HB48TX9F71777	CVA	434826	2103-775
			Kms	7	STEL	297297	TOW ONLY, 109-1

3,553.00	1-040	SUV 2009 SATURN Vue (Green Line Hybrid) FWD, 5 passenger 2.4L L4 Gas-Mild Hybrid Electric Auto power locks, windows, and mirrors; a/c, tilt, cruise, AM/FM/CD, keyless entry (2 keys/2 fobs) tire sealant + compressor kit, cargo management system - including net, 4 cargo tie-down adaptors/hooks, and cargo cover, White, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: front and rear rotors and pads, battery poor, minor exterior damage.>, As is, Where is	139,346 8	3GSCL93Z19S62666	CVA	403584	2103-782
2,719.50	1-041	Truck 2012 CHEVROLET Colorado 4x4, EXT Cab Gas Auto air, cruise, tilt tool box, White, TOW ONLY, No SGI Inspection. It is unknown if any repairs or safety concerns exist (if any). Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs if required. , Wiring was repaired in 2018, PROBLEMS: Transmission problems- issues shifting in low speeds occasionally, highway speed work well. Other issues- issues with battery (needs replacement), odometer and air conditioner stopped working recently. Vehicle had floor mats screwed into the floor which caused some wiring issues. Vehicle in poor condition, there may be additional unknown issues>, As is, Where is	229,702	1GCJTCFE6C812628	Parks	TOW ONLY, ROW UNKNOWN	2007-286

8,690.00	1-043	Truck 2012 CHEVROLET Silverado 2500HD 4x4, EXT Cab, 8' box 6.0L V8 Gas Auto power locks, mirrors, and windows on all doors; a/c, tilt, cruise, AM/FM/CD, keyless entry (2 fobs) Brand FX topper with roof rack, side and rear doors (condition unknown), 2-tiered pullout mounted in box, front tow hooks, side steps, hitch, trailer wiring, OEM trailer brake, White, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: rear pads and rotors, both inner tie rods/Pitman arms, front wheel alignment out, windshield cracked, all fenders rusted, driver's seat torn, front bumper missing lower trim piece, wiper blades, middle seat mounting loop cut off, 2 holes in RR floor pan, battery poor, minor exterior damage>, As is, Where is	207,724	1GC2KVCG8CZ2086	CVA	437563	2103-772
			Kms	22		STEL	227567
							TOW ONLY, 123-2
8,690.00	1-044	Truck 2012 CHEVROLET Silverado 2500HD 4x4, EXT Cab, 8' box, has a back seat 6.0L V8 Gas Auto power windows, mirrors, and locks; a/c, tilt, cruise, AM/FM/CD Range Rider box topper with roof rack (condition unknown), plywood on floor of box, side steps, mud flaps, front tow hooks, hitch, trailer wiring, OEM trailer brake, White, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: rear pads and rotors, rear shocks, windshield cracked, RF fender rusted, steering wheel wobbles, washer line cracked, beacon on rack broken, driver's and passenger's seats stained, holes in RR floor pan, battery poor, minor exterior damage>, As is, Where is	216,168	1GC2KVCGXCZ2087	CVA	437647	2103-771
			Kms	35		STEL	227563
							TOW ONLY, 123-3

7,600.00	1-045	Truck 2012 CHEVROLET Silverado 2500HD 4x4, Ext Cab, has a back seat, 8' box 6.0L V8 Gas Auto power locks, mirrors, and windows; a/c, tilt, cruise, AM/FM/CD, keyless entry (2 fobs) Brand FX topper (condition unknown), 2-level slideout, roof rack with beacon, swing-out doors on sides, single door at rear, front tow hooks, side steps, mud flaps, hitch, trailer wiring, OEM trailer brake, White, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: engine misfire, drive belts, front wheel alignment, no tailgate, fenders rusted/paint flaking, front bumper missing lower valance/chrome peeling, hood hail damage, passenger windows won't roll down from driver's door switch, driver's seat ripped/worn, hole in RR floor board, has no rear seat, rear center top seat mount loop is cut off - cannot mount seat, battery poor, minor exterior damage.>, As is, Where is	217,765	1GC2KVCG6CZ2064	CVA	437423	2103-768
			Kms	16	STEL	227579	TOW ONLY, 122-2
7,290.00	1-046	Truck 2012 CHEVROLET Silverado 2500HD 4x4, EXT Cab, has a back seat, 8' box 6.0L V8 Gas Auto power locks, mirrors, and windows; cruise, a/c, tilt, AM/FM/CD, keyless entry (2 keys/2 fobs) side steps, hitch, trailer wiring, OEM trailer brake, White, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , Check Engine Light/ TPMS light, PROBLEMS: rear pads and rotors, RF axle seal, both lower ball joints, front and rear shocks, park brake doesn't hold in reverse, LF fender badly rusted, LR fender/right fenders rust spots, driver's seat worn with cushion and frame visible, plate light assembly, 4 holes drilled/small crack in box, battery poor, minor exterior damage>, As is, Where is	201,117	1GC2KVCGXCZ2096	CVA	437555	2102-674
			Kms	91	STEL	227568	TOW ONLY, 121-7

8,600.00	1-047	Truck 2012 CHEVROLET Silverado 2500HD 4x4, Ext Cab, has a backseat, 8' box 6.0L V8 Gas Auto power windows, locks, and mirrors; AM/FM/CD, a/c, tilt, cruise, keyless entry (3 keys/2 fobs/2 topper keys) front tow hooks, side steps, mud flaps, hitch, trailer wiring, OEM trailer brakes, FX brand topper with roof rack (condition unknown), beacon, roll out, side doors & 1 rear door, White, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: front/rear pads and rear rotors, front wheel alignment out, windshield cracked, rear bumper bent/dented, passenger door pins, front/rear fenders rusted at box rail, front bumper chrome peeling, driver's seat worn/ripped, battery poor, minor exterior damage.>, As is, Where is	192,221 Kms	1GC2KVCG0CZ2089 68	CVA STEL	437670 227558	2103-734
5,680.00	1-048	Truck 2012 DODGE Ram 2500 4x4, Crew Cab, has a back seat 5.7L V8 Gas Auto power mirrors, windows, and locks; a/c, tilt, cruise, AM/FM/CD, keyless entry (2 key fobs) grille inserts, front tow hooks, side steps, hitch, trailer wiring, White, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: manifold leaks, parking brake cable, rear rotors, steering shock & shaft, right upper balljoint, TPMS light on, air dam tied up, windshield cracked, LR fender/tailgate dented, rear bumper bent/dented, tailgate rusted, driver's seat worn down to frame, 3rd brake light, plate light, front of box bent, paint dull, holes drilled in front bumper, 1 sealed hole in roof, battery poor, minor exterior damage.>, As is, Where is	270,787 Kms	3C6TD5CT0CG1893 11	CVA	438033 107-4	2103-812

7,305.00	1-049	Truck 2012 DODGE Ram 2500 4x4, Crew Cab, has a back seat, 6'5" box, 2 Viper remote fobs (condition unknown) 6.7L L6 Diesel Auto power windows, locks, and mirrors; a/c, tilt, cruise, aftermarket AM/FM, keyless entry (2 key fobs - 1 does not work) front tow hooks, side steps, mud flaps, hitch, trailer lights, trailer brake, headache rack with beacon (condition unknown), Byers tool box, light mounted on front bumper, winter front grille (condition unknown), White, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: check engine light on/engine misfire, steering shocks, all 4 ball joints, front and rear wheel alignment, drag link, pit arm, windshield cracked, front tires poor, tailgate will not open, front fenders badly rusted, bumpers/tailgate rust spots, driver's seat cushion worn, holes in dash, front storage containers broken with holes drilled, 3 sealed holes in roof, battery poor, minor exterior damage.>, As is, Where is	283,595	3C6UD5CL7CG1852	CVA	438124	2103-807
			Kms	13		A12005	TOW ONLY, 109-5
6,758.61	1-050	Truck 2012 DODGE Ram 3500 4x4, Crew Cab, has a back seat, 8' box 6.7L L6 Diesel Auto power windows, locks, and heated mirrors; a/c, tilt, cruise, AM/FM/CD, keyless entry (2 keys/2 fobs) grille inserts, front tow hooks, side steps, hitch, trailer wiring, electric trailer brake, headache rack with beacon (condition unknown), rubber mat in box, White, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: check engine light on/engine misfire, right lower ball joint, pittman, drag link, bumpers rusted/bent/dented, tailgate dented/bent/missing moulding, right fenders/RF door dented, LF fender rusted, windshield cracked, passenger's seat worn (frame visible), washer nozzle, all seats soiled, battery poor, minor exterior damage.>, As is, Where is	337,125	3C63D3GL5CG1865	CVA	437761	2103-783
			Kms	02		A12003	TOW ONLY, 104-4

1,859.00	1-052	Truck 2006 FORD F150 4x4, Supercab, has a back seat, 6'7" box 5.4L V8 Gas Auto a/c, tilt, cruise hitch, trailer wiring, Green, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: exhaust manifold tick, left park brake sticking, RR shock, tires poor, windshield cracked, no plate lights, front fenders rusted through, bumpers/rear fenders rusted, bumpers dented, driver's seat worn, LF side marker, missing wheel wrench, battery poor, minor exterior damage.>, As is, Where is	292,272	1FTPX14586NB4001	CVA	438796	2103-813
			Kms	0			TOW ONLY, 107-5
3,802.23	1-053	Truck 2008 FORD F150 4x4, Supercrew, has a back seat, 5'7" box 5.4L V8 Gas Auto power windows, mirrors, and locks; a/c, tilt, cruise, AM/FM/CD/MP3, keyless entry (2 keys/2 fobs) front tow hooks, grille inserts, side steps, mud flaps, hitch trailer wiring, electric trailer brake, Grey, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: front wheel alignment out, parking brake sticky, front fenders rusted, both cab corners rusted, front of box bent (touching back of cab), rust around gas cap door, hole in driver's side mirror housing, 1 sealed hole in roof, wheel wrench loose under back seat, battery poor, minor exterior damage.>, As is, Where is	224,995	1FTPW14V98FC266	CVA	433661	2103-786
			Kms	84			TOW ONLY, 106-2

8,261.00	1-054	Truck 2013 FORD F250 S/D 4x4, Supercab, has a back seat, 8' box 6.7L V8 Diesel Auto power front windows, mirrors, and locks; a/c, tilt, cruise, keyless entry (3 key fobs) non-OEM driving lights, towhooks, side steps, hitch, trailer wiring, OEM trailer brakes, trailer tow mirrors, White, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: exhaust leak, front wheel alignment, steering shock, front pads, drag link, bumpers/doors/roof/tailgate/cab corners rusted, LR fender/hood dented, fenders/tailgate paint flaking, holes in front hump/dash pad, plate light assembly, driver's mirror housing broken, winter front on grille may be loose, 2 sealed holes in roof, spare tire loose in box (may be incompatible with vehicle), jack missing, battery poor, minor exterior damage.>, As is, Where is	309,789	1FT7X2BT6DEA2815	CVA	430066	2103-806
			Kms	0			TOW ONLY, 109-4
8,361.00	1-055	Truck 2013 FORD F250 SD 4x4, Crew Cab, has a back seat, 6'10" box 6.2L V8 Gas Auto power windows, locks, and heated mirrors; a/c, tilt, cruise, AM/FM/CD, keyless entry (2 key fobs), 1 tool box key grille inserts, front tow hooks, side steps, mud flaps, headache rack with beacon (condition unknown), tool box behind cab (condition unknown) hitch, trailer wiring, OEM trailer brake, trailer tow mirrors, , Blue, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: parking brake not holding, front wheel alignment out, RR fender rusted, RR park brake shoes worn out, rear bumper dented, driver's seat & passenger rear seat worn, RR seat belt retractor, holes in front hump, 2 sealed holes in roof, battery poor, minor exterior damage.>, As is, Where is	285,720	1FT7W2B64DEA281	CVA	430009	2103-811
			Kms	44			TOW ONLY, 107-3

4,739.99	1-056	Truck 2013 FORD F350 S/D 4x4, Crew Cab, 6'10" box with power lift gate (rusted, condition unknown) 6.7L V8 Diesel Auto power windows, locks, and heated mirrors; a/c, tilt, cruise, AM/FM/CD/MP3, keyless entry (2 keys/2 fobs) grille inserts, front tow hooks, side steps, mud flaps, hitch, trailer wiring, OEM trailer brake, headache rack, trailer tow mirrors inside box (dented), White, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: coolant leaking, front shocks & pads, track bar ball joint, steering shock, right lower outer tie rod, left leaf spring, windshield cracked, tail pipe bolts broken, grille broken, both rear seatbelts don't retract, right backup light out, right windshield washer nozzle missing, RF seat belt buckle broken, front bumper rusted with holes drilled, rear fenders/all doors/roof/box rusted, driver's seat worn, holes in front hump, spare tire missing, battery poor, minor exterior damage.>, As is, Where is	401,233	1FT8W3BT6DEA254	CVA	430264	2103-784
			Kms	41		A13009	TOW ONLY, 104-5
8,500.00 *	11-031	Truck 2000 FORD F550 RWD, dual wheels, service body, Auto Crane 3203 PRX (condition of crane unknown) 7.3L V8 Diesel Manual air, tilt, cruise, AM/FM grille inserts, side steps, front tow hooks, trailer towing mirrors, electric trailer brake, 2 beacons, White, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: lots of rust on body, broken grille, rust on bumpers, lights and indicators, battery poor, minor cosmetic damage.>, As is, Where is	319,048	1FDAF56F3YED0205	CVA	515320	2102-642
			Kms	0		A00008	TOW ONLY, 92-1

3,210.00	1-058	Truck 2005 GMC Sierra 2500HD 4x4, Ext Cab, has a back seat, 6'6" box 6.0L V8 Gas Auto dual zone a/c, cruise, tilt, AM/FM spare tire is loose in box, may not be compatible with vehicle, Grey, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: oil leaks, transmission lines leaking, oil cooler lines leaking, hydroboost leaking, engine light does not self-check, no heat, pitman and idler loose, manifold bolts broken, missing rear bumper, missing tailgate, front fenders rusted, RF quarter panel rusted, left rocker panel rusted, rust holes in box, RR fender dented/moulding loose, both box rails dented, front door pins, hole in rear seat floor board, missing spare tire/tools, battery poor, minor exterior damage.>, As is, Where is	226,871	1GTHK29UX5E3129	CVA	437905	2103-788
			Kms	17			TOW ONLY, 106-4
8,390.00	1-059	Van 2012 CHEVROLET Express 1500 AWD, Cargo Van 5.3L V8 Gas Auto power locks and front windows; a/c, tilt, cruise, AM/FM/CD, rear aux. heat, keyless entry (2 fobs) hitch, trailer wiring, electric trailer brake, mud flaps, crash barrier, fiber floor, shelves, White, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , TPMS light, both upper/right lower balljoints, park brake/rear pads & rotors, PROBLEMS: A/F leaks, heater not working, left outer tire rod, wheel alignment out, windshield washer not working, tires poor, hood/rear bumper/LR fender/left rocker panel/RR door dented, LF fender/tailgate paint peeling, rear bumper bent, light switch, driver's seat torn, side door outside handle, LF marker, passenger's side mirror and housing broken, RR door hard to open, 2 sealed holes in roof, battery poor, minor exterior damage.>, As is, Where is	189,780	1GCSHAF45C11304	CVA	410217	2102-640
			Kms	84		227533	2012-537
					STEL		TOW ONLY, 122-3

8,390.00	1-060	Van 2012 CHEVROLET Express 1500 AWD, Cargo Van 5.3L V8 Gas Auto power windows and locks; a/c, tilt, cruise, rear aux. heat, AM/FM/CD, keyless entry (2 fobs) map box, cargo barrier, shelving, wood floor, hitch, trailer wiring, electric trailer brake, White, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , TPMS light, change oil light, PROBLEMS: engine oil leak, transmission pan leaking, park brake doesn't hold, left outer tie rod, LF wheel bearing, left park brake cable, front bumper/RR door/tailgate rusted, rear bumper/tailgate dented, front tires poor, driver's seat worn, 2 sealed holes in roof, battery poor, minor exterior damage>, As is, Where is	179,262	1GCSHAF41C11329	CVA	410571	2102-652
			Kms	27	STEL	227520	2011-514 TOW ONLY, 122-4
10,183.00	1-061	Van 2012 CHEVROLET Express 3500 RWD, Cargo Van 6.0L V8 Gas Auto power front windows and locks; a/c, tilt, cruise, AM/FM/CD, keyless entry (3 keys/2 fobs) Warwick ladder with beacon (condition unknown), Warwick inspection certificate and manual behind passenger's seat, mud flaps, cargo barrier, plywood floor, shelves/ladder for rear of unit, HD rear bumper, generator compartment, pintel hook, trailer wiring, electric trailer brake, bag with tent, White, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: parking brake not working, pitman/idler arms loose, inner tie rods loose, hood paint peeling, RF fender/RR door/tailgate dented, left mirror broken, driver's seat worn/torn, LF marker light bulb, spare tire missing, battery poor, minor exterior damage.>, As is, Where is	127,834	1GCGTTCG6C11285	CVA	410241	2103-760
			Kms	14	STEL	627587	TOW ONLY, 107-1

6,780.00	1-062	Van 2007 CHEVROLET Express 3500 Cargo EXT RWD, 155" wheel base, cargo van 6.0L V8 Gas Auto power locks, a/c, tilt, cruise, AM/FM, rear HVAC HD rear bumper, fabric & metal cargo barrier, shelving, work table, wood floor, pintel hook, trailer wiring, electric trailer brake, mud flaps, map box, White, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: hydro boost leaking, power steering pressure hose leaking, brake pads and rotors poor, left lower ball joint, right inner tie rod, no tail lights, RR door won't open from outside, front bumper rusted, right rocker panel dented, 4 sealed holes in roof, hood/RR door/RR fender paint poor, no low beams, no high mount, no cluster lamps, no front or rear markers, driver's seat torn, battery poor, minor exterior damage.>, As is, Where is	119,665	41	1GCHG39U4712484	CVA	416776	2103-733
						STEL	276965	TOW ONLY, 103-2
3,059.00	1-063	Van 2009 DODGE Grand Caravan 2WD, Cargo Van 3.3L V6 Gas Auto power locks, mirrors, and front windows; a/c, tilt, cruise, AM/FM/CD, keyless entry (2 fobs) map box, computer stand, cargo barrier, steel floor, shelving, roof rack with beacon (condition unknown), White, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , TPMS light, PROBLEMS: oil leak, intake gasket leak, transmission cooler line leak, rear rotors rusted, motor mounts torn, sway bar links loose, front pads and rotors low, windshield cracked, front bumper cracked, RF fender/doors/tailgate rusted, tailgate dented, hail damage on hood and roof, no rear wiper spray, drivers door missing trim, driver's seat worn, rear wiper torn, 3 sealed holes in roof, battery poor, minor exterior damage>, As is, Where is	154,947			CVA	172767	2102-643
					2D4HN11E69R6833	STEL	297224	2012-539
					95			TOW ONLY, 121-6

4,059.00	1-064	Van 2009 DODGE Grand Caravan FWD, Cargo Van 3.3L V6 Gas Auto power locks, mirrors, and front windows; a/c, tilt, cruise, AM/FM/CD, keyless entry (2 fobs) remote start (condition unknown), map box, computer stand, cargo barrier, steel floor, beacon (condition unknown), White, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , Check Engine Light/ TPMS light, PROBLEMS: rear pads and rotors, front cradle mount damage, rust on LR fender/bottom of LR door, roof has rust spots, rear bumper dented, hood paint bubbling and hail damage, tailgate glass scratched, 2 holes sealed in roof, battery poor, minor exterior damage>, As is, Where is	82,647	Kms	2D4HN11E99R6176	STEL	CVA	171645	2102-627
					48			297215	2012-540
									TOW ONLY, 121-3
2,759.00	1-065	Van 2009 DODGE Grand Caravan SE 2WD, 7 Passenger 3.3L V6 Gas Auto power windows and locks, air, cruise, tilt, rear heat & air , White, TOW ONLY, No SGI Inspection. It is unknown if any repairs or safety concerns exist (if any). Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs if required. , , PROBLEMS: Rust spots, dent on top of passenger sliding door, hood peeling, front drivers headlight plastic damaged, no middle seat, dent on hood drivers side, tires in poor condition, there may be additional unknown issues>, As is, Where is	198,700	Kms	2D8HN44E49R6834	PCS	Parks	Van #2	2011-532
					41				TOW ONLY, ROW UNKNOWN

3,911.00	1-066	Van 2013 DODGE Grand Caravan SE FWD, 7 passenger, Stow-N-Go (3rd seat only), 2 bench seats 3.6L V6 Gas Auto power windows, heated mirrors, and locks; a/c, tilt, cruise, AM/FM/CD, rear HVAC, keyless entry (2 key fobs) , Blue, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: rear pads and rotors, RF side marker, hood paint bubbling, 2nd bench seat will not fold into floor, battery poor, minor exterior damage.>, As is, Where is	280,950	2C4RDGBG5DR6365	CVA	173815	2103-787
			Kms	22			TOW ONLY, 106-3
2,059.00	1-067	Van 2008 FORD Econoline E350 S/D EXT RWD, 11 passenger, cargo barrier behind last seat 5.4L V8 Gas Auto power locks, mirrors, and front windows; a/c, tilt, cruise, rear HVAC, AM/FM/CD hitch, trailer wiring, grille inserts, beacon (condition unknown), White, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: exhaust manifolds gaskets leaking, front rotors, windshield cracked, wheel bearings, doors rusted/cracked at bottom, hood badly dented, RF door/both bumpers/left fenders dented, tailgate dented/does not open, shifter loose, both front and side door pins, sway bar bushings, drag link, driver's seat/passenger's seat torn, interior badly soiled, grille chrome peeling, trim pieces missing on doors, weather stripping on front doors, RF mud flap, roof rust along drip moulding, 3 sealed holes in roof, battery poor, minor exterior damage.>, As is, Where is	240,030	1FBSS31L18DB4873	CVA	424259	2103-780
			Kms	1			A08014 TOW ONLY, 103-3

6,180.00	1-068	Van 2008 GMC Savana 1500 AWD 5.3L V8 Gas Auto power locks, a/c, tilt, cruise, AM/FM, rear aux. heat mud flaps, hitch, trailer wiring, electric trailer brake, computer stand, map box, cargo barrier, shelving, plywood floor, roof rack with beacon (condition unknown) , White, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: oil leak, power steering leak, RF lower balljoint loose, rear u-joint on front drive shaft loose, missing tailpipe, muffler rusted, driver's side manifold broken, rear bumper/fenders/rocker panels rusted, rear bumper/right fenders/right doors/tailgate dented, no highmount, no plate light, right corner marker, RF signal light is tie wrapped in, driver's door inside lower paint missing, wiper blades, passenger's seat armrest broken, driver's seat worn, 3 sealed holes in roof, battery poor, minor exterior damage>, As is, Where is	184,715	1GTFH15498120888	CVA	417139	2103-769
			Kms	7	STEL	287112	TOW ONLY, 122-7
6,780.00	1-069	Van 2008 GMC Savana 1500 AWD 5.3L V8 Gas Auto power locks, a/c, tilt, cruise, AM/FM, rear aux. heat hitch, trailer wiring, electric trailer brake, map box, computer stand, cargo barrier, shelving, plywood floor, White, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , TPMS light, PROBLEMS: front and rear rotors, front wheel alignment out, bumpers rusted, bumpers/rear fenders/driver's door dented, tailgate cracked on left side, mud flaps missing, 3rd brake light, driver's seat torn, left visor broken, battery poor, minor exterior damage>, As is, Where is	147,267	1GTFH15428121050	CVA	417147	2102-654
			Kms	0	STEL	287111	2011-517 TOW ONLY, 122-5

6,180.00	1-070	Van 2008 GMC Savana 1500 AWD 5.3L V8 Gas Auto power locks, a/c, tilt, cruise, AM/FM, rear aux. heat hitch, trailer wiring, electric trailer brake, map box, computer stand, cargo barrier, shelving, plywood floor, roof rack with beacon (condition unknown), White, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , PROBLEMS: exhaust leak on start up, left outer tie rod, RR valve stem, left manifold, windshield cracked, bumpers/right rocker panel rusted, a/c belt, tire light, front bumper dented, front tires cupped, hood/passenger's door paint poor, driver's seat torn, driver's side mirror cracked, wiper blades, 3rd brake light, wheel wrench/jack missing, 3 sealed holes in roof, hole in LF headlight bezel, holes in RF floorboard, battery poor, minor exterior damage>, As is, Where is	211,673	1GTFH15428120925	CVA	417154	2102-655
			Kms	1	STEL	287109	2011-516
							TOW ONLY, 122-6
6,180.00	1-071	Van 2008 GMC Savana 1500 AWD, 135" Wheelbase 5.3L V8 Gas Auto power locks, a/c, tilt, cruise, AM/FM, rear aux. heat map box, cargo barrier, plywood floor, shelving, hitch, trailer wiring, electric trailer brake, roof rack with beacon (condition unknown), computer stand, White, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , TPMS light, PROBLEMS: front bumper/RR fender/rocker panels/roof rusted, rear bumper/RR fender dented, LR door won't open, rocker panels/tailgate paint poor, both headlights out, driver's seat worn and cushion visible, 4 sealed holes in roof, battery poor, minor exterior damage>, As is, Where is	220,544	1GTFH15418121063	CVA	417220	2103-773
			Kms	4	STEL	287110	TOW ONLY, 121-5

6,780.00	1-072	Van 2008 GMC Savana 1500 AWD, Cargo Van 5.3L V8 Gas Auto a/c, tilt, cruise, aux heater, AM/FM map box, computer stand, cargo barrier, plywood floor, shelving, hitch, trailer wiring, electric trailer brake, White, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: power steering leak, RF upper ball joint loose, LF axle, windshield cracked, a/c belt cracked, tires poor, highmount brake light out, rear mudflaps missing, driver's seat worn, instrument panel torn open, driver door weatherstripping missing, right mirror damaged, 2 holes sealed in roof, battery poor, minor exterior damage>, As is, Where is	189,004	1GTFH15428120801	CVA	417253	2012-542
			Kms	8	STEL	287123	TOW ONLY, 121-2
6,978.00	1-073	Van 2003 GMC Savana 3500 RWD, Cargo Van 6.0L V8 Gas Auto a/c, tilt, cruise, AM/FM Warwick Ladder with maintenance inspection (condition unknown), map box with manual, cargo barrier, shelving, plywood floor, HD rear bumper, ladder on rear door, pintel hook, trailer wiring, electric trailer brake, computer stand, bag with tent, White, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: RR brake line bent at caliper, idler arm loose, a/c not working, driver's seat worn to metal frame, RR fender rust, hood/right doors dented, needs wiper blades, hole drilled in front bumper, 2 sealed holes in roof, spare tire in cargo area (may be incompatible with vehicle), battery poor, minor exterior damage.>, As is, Where is	84,674	1GTHG35U5311912	CVA	416065	2103-761
			Kms	94	STEL	636566	TOW ONLY, 107-2

REGINA, SaskBuilds and Procurement, SaskSurplus Sales Lot, 500 McLeod Street - Miscellaneous Items and Equipment.

Due to COVID-19, ON-LINE VIEWING ONLY. NO ON-SITE VIEWING. Contact SaskSurplus (306) 787-2062 or (306) 798-3306.

No Bid	1-117	Cargo Bed SD model, rollout, approx. 34" W, 67.5 " L, bolted to plywood Top plywood 79"L, 48"W, 1 1/2" D. Bottom plywood 80"L, 48"W, 3/4" D. , , , , , Good	433232 CVA	SS3274	2103-725
No Bid	* 12-112	Letterpress Printer and Metal Type Cabinet Showcard Machine Company letterpress, "Futura" font metal type Cabinet size: 24" wide, 49" tall, 17½" deep, several weights and sizes of "Futura" font metal type. Unknown if operational. , , , , , Fair	Parks	4 ss3980	2101-591
1.10	* 12-140	Light Fixtures Metal Wall mount lighting fixtures, various sizes, light baffles, 1 pallet, condition unknown , , , , , Fair	SaskSur plus	X-V1151	2102-690
No Bid	* 12-114	Photographic Enlarger Stand Besler 45MCRX Enlarger chassis has a triangular reinforced truss with twin girder frame which permits the enlarger to produce prints greater than 16"x20" on the baseboard from 35mm film. , , , , , Good	Parks	5	2101-591
No Bid	* 8-105	Tire Artic Claw Winter TKI M+S 205/60R/16 , , , , , Excellent	CVA		2006-206
25.61	1-119	Tire Continental Contipro Contact 97H. M+S 225/55R/17. Manufacture date- week 39, year 2012 , , , , , Fair	CVA	SS3267	2103-751
No Bid	1-137	Tire Firestone FR 710. M+S 215/65R/16. Manufacture date - week 07, year 2016 , , , , , Good	CVA	SS3133	2103-767
31.00	1-120	Tire Firestone FR710. M+S 225/60R/16, Manufacture date- week 07, year 2012 , , , , , Fair	CVA	SS3610	2103-751
31.00	1-148	Tire Goodyear Integrity M+S 225/60R/16. Manufacture date - week 9, year 2013 , , , , , Fair	CVA	X-V626	2103-799
40.61	1-121	Tire Goodyear Integrity M+S P225/60R/16 . Manufacture date- week 08, year 2013 , , , , , Good	CVA	SS3606	2103-751
No Bid	1-125	Tire Sailun Ice Blazer. Snow flake, M+S 195/60R/15. Maufature date - week 26, year 2014 , , , , , Fair	CVA	SS3270	2103-752
*MT	1-122	Tire Sumitomo HTR Enhance LX2. M+S 225/60R/17, Manufacture date-week 23, year 2019 , , , , , Good	CVA	SS3609	2103-751

45.61	1-126	Tire Wild Country XTX. Premium all Terrain. Snow flake, M+S LT245/75R/16. Manufacture date - week 41, year 2015 , , , , , Good	CVA	SS3266	2103-752
No Bid	1-123	Tire Winter Claw Extreme Grip. M+S 225/60R/16, Manufacture date-week 24, year 2014 , , , , , Good	CVA	SS3608	2103-751
No Bid	1-127	Tire Winter Claw Extreme Grip. Snow flake, M+S 195/60R/15. Manufacture date-week 18, year 2014 , , , , , Fair	CVA	SS3268	2103-752
*MT	1-128	Tire and Rim Bridgestone Vsteel R1B 265. M+S LT245/75R/16. Manufacture date - week 20, year 2015. Rim rusty , , , , , Good	CVA	SS3271	2103-752
*MT	1-138	Tires Set of 4 Artic Claw Winter TXI. M+S 225/60R/17. Manufacture date - week 29, year 2015 , , , , , Fair	CVA	SS3135	2103-767
162.33	1-157	Tires Set of 4 Artic Claw Winter XSI. M+S 215/70R/16. Manufacture date - week 21, year 2015 , , , , , Good	CVA	SS3143	2103-817
428.85	1-131	Tires Set of 4 BF Goodrich All Terrain T/A Ko2. Snow Flake. M+S LT225/75R/16. Manufacture date - week 30, year 2018, white lettering , , , , , Good	CVA	SS3278	2103-763
*MT	1-129	Tires Set of 2 BF Goodrich, Rugged Trail T/A. M+S LT245/70R/17. Manufacture date - week 41, year 2015 , , , , , Fair	CVA	SS3272	2103-752
191.28	1-158	Tires Set of 4 Firestone All Season. M+S 215/65R/16. Manufacture date - week 37, year 2017 , , , , , Fair	CVA	SS3146	2103-817
*MT	1-132	Tires Set of 4 Firestone All Season. M+S 225/65R/16. Manufacture date - week 31, year 2019 , , , , , Good	CVA	SS3276	2103-763
132.12	1-143	Tires Set of 4 Firestone FR 690. M+S P215/65R/16. Manufacture date - week 04, year 2009 , , , , , Fair	CVA	SS3139	2103-799
203.71	1-144	Tires Set of 4 Firestone FR 710. M+S 215/60R/16. Manufacture date - week 03, year 2017 , , , , , Good	CVA	SS3142	2103-799
211.12	1-139	Tires Set of 4 Firestone FR 710. M+S 215/65R/16. Manufacture date - week 46, year 2015 , , , , , Good	CVA	SS3136	2103-767
47.57	1-130	Tires Set of 2 Firestone FR710. M+S 205/60R/16. Manufacture date-week 44, year 2016. , , , , , Fair	CVA	SS3269	2103-752

	216.71	1-133	Tires Set of 4 Firestone FR710. M+S 215/65R/16. Manufacture date - week 23, year 2016 , , , , , Good	CVA	SS3279	2103-763
*MT		1-159	Tires Set of 4 Firestone FR710. M+S 225/60R/16. Manufacture date - week 43, year 2016 , , , , , Good	CVA	SS3145	2103-817
	375.51	1-134	Tires Set of 5 General Grabber HTS P245/70R/17. Manufacture date - week 31, year 2015 , , , , , Good	CVA	SS3277	2103-763
	77.33	1-140	Tires Set of 2 Goodyear Integrity. M+S 225/60R/16. Manufacture date - week 13, year 2013 , , , , , Good	CVA	SS3134	2103-767
	144.14	1-160	Tires Set of 4 Matrix Tour R/S Multimile 225/60R/16. Manufacture date - week 11, year 2014 , , , , , Fair	CVA	SS3148	2103-817
	96.00	1-124	Tires Set of 3 Matrix Tour RS Multi Mile. M+S 225/60R/16, Manufacture date-week 10, year 2013 , , , , , Fair	CVA	SS3137	2103-751
*MT		1-145	Tires Set of 4 Michelin Latitude Tour P225/65R/17. Manufacture date - week 09, year 2015 , , , , , Good	CVA	SS3138	2103-799
	150.00	1-161	Tires Set of 4 Sumitomo HTR Enhance L/X. M+S 215/60R/16. Manufacture date - week 41, year 2016 , , , , , Fair	CVA	SS3144	2103-817
	213.82	1-146	Tires Set of 4 Sumitomo HTR Enhance L/X. M+S 215/65R/16. Manufacture date - week 26, year 2017 , , , , , Good	CVA	SS3141	2103-799
	223.82	1-162	Tires Set of 4 Sumitomo HTR Enhance L/X. M+S 225/55R/17. Manufacture date - week 04, year 2019 , , , , , Good	CVA	SS3147	2103-817
	No Bid	1-141	Tires Set of 3 Sumitomo HTR Enhance L/X. M+S 225/60R/16. Manufacture date - week 03, year 2017 , , , , , Good	CVA	SS3132	2103-767
	214.32	1-135	Tires Set of 4 Sumitomo HTR Enhance LX. M+S 215/60R/16. Manufacture date - week 03, year 2019. , , , , , Good	CVA	SS3280	2103-763
*MT		1-136	Tires Set of 4 Sumitomo HTR Enhance LX2. M+S 225/60R/17. Manufacture date - week 23, year 2019 , , , , , Good	CVA	SS3275	2103-763
*MT		1-142	Tires Set of 2 Winter Claw Extreme Grip MX. M+S 215/60R/17. Manufacture date - week 33, year 2014 , , , , , Fair	CVA	SS3131	2103-767
	35.25 *	12-133	Tires Set of 2 Winter Claw, Extreme Grip MX, Snow Flake, M+S 215/60R/17 Manufacture date - week 21, year 2014 , , , , , Poor	CVA	SS3594	2102-675
*MT		1-147	Tires Set of 4 Yokohama Geolandar GO33 215/70R/16. Manufacture date - week 45, year 2018 , , , , , Good	CVA	SS3140	2103-799

228.61	* 8-102	Truck Topper Raider Make high mount brake light, possible fit to a 2011 Dodge Ram, approx. 67"x79", black in color , , , , , Fair	437290	SaskSurplus	2005-106
No Bid	1-118	Truck Topper Raider, commercial grade, aluminum construction, white in color approx. 71" wide, 84 long. Minor hail damage, handle loose. Door on left, 2 doors on right side. , , , , , Good	433232, Key for Tailgate only.	CVA SS3273	2103-725
7.50	1-112	Warning Triangle Kit Grote 3 weighted triangles in each kit , , , , , Fair		CVA SS3604	2102-682
7.50	1-113	Warning Triangle Kit Grote 3 weighted triangles in each kit. , , , , , Fair		CVA SS3602	2102-682
*MT	1-114	Warning Triangle Kit Grote, Model 71422 3 weighted triangles in each kit. , , , , , Fair		CVA SS3603	2102-682
7.50	1-115	Warning Triangle Kit James King + Co, Model 1005 3 weighted triangles in each kit, storage box broken . , , , , , Fair		CVA SS3600	2102-682
7.50	1-116	Warning Triangle Kit James King + Co, Model 1005 3 weighted triangles in each kit, storage box broken. , , , , , Fair		CVA SS3601	2102-682
10.52	1-163	Book Case wood adjustable shelving, 2 sliding doors, 42"w x 16.5"d x 43.75"h , , , , , Fair		LRWS X-V622	2103-779
5.10	1-111	Desk metal, 2 drawers on right side of desk 45"W X 24"D, particle board with arborite top, corner broken, no lock, black, rectangular shape. , , , , , Fair		CVA SS3605	2102-682
*MT	1-164	File Cabinet metal 3 drawer lateral, beige 36"w x 18"d x 41"h , , , , , Fair		LRWS X-V623	2103-779
21.25	1-101	Filing Cabinet metal, beige lateral, 4 drawer, includes keys, 36" wide x 53.5" tall x 19" deep , , , , , Fair		TED SS3999 CDP30678	2010-481
125.00	1-102	Filing Cabinet Lot of 2 metal, beige lateral, 5 drawer, includes key, drawers open bottom up, 36" wide x 65.5" tall x 18" deep , , , , , Fair		TED SS3998 CDP30679	2010-481

200.00	1-103	Plotter Ricoh, Aficio, W2400 number-w2400 on wheels, hard drive removed, unsure if operational , , , , , Fair	Model Manufacture date-NA Large plotter	3271200148	SBP ITD	SS3990	2102-681
200.00	1-150	Plotter-Scanner Large Plotter/Scanner on wheels, no hard drive, unsure if operational. Hewlett-Packard DesignJet T1100 MFP, Model number-Q6713A, Manufacture date-NA , , , , , Fair		DK7C12F04Z	SBP ITD	SS3192	2103-737
3.00	1-152	Printer Hewlett-Packard Color LaserJet CP4025DN Model number-CC490A 2011 Large Printer on pallet, no hard drive, unsure if operational. , , , , , Fair	Manufacture date Dec 7th	JPBCCD6033	SBP ITD	X-V616	2103-777
3.00	1-153	Printer Hewlett-Packard Color LaserJet CP4025DN Model number-CC490A 1st 2013 Large Printer on pallet, no hard drive, no bottom paper tray #3, unsure if operational. , , , , , Fair	Manufacture date April	JPDCF40071	SBP ITD	X-V619	2103-777
3.00	1-154	Printer Hewlett-Packard Color LaserJet CP4025DN Model number-CC490A 26th 2012 Large Printer on pallet, no hard drive, no bottom paper tray #3, unsure if operational. , , , , , Fair	Manufacture date April	JPBCD4T0DD	SBP ITD	X-V618	2103-777
1.00	1-155	Printer Hewlett-Packard Color LaserJet M575 MFP Model number-CD645A 2nd 2014 Large Printer on pallet, no hard drive, no bottom paper tray #3, unsure if operational. , , , , , Fair	Manufacture date April	MXDCG41174	SBP ITD	X-V617	2103-777
1.00	1-104	Printer Hewlett-Packard LaserJet 9050DN Model number-Q3723A 29th 2011 Large printer on pallet, no hard drive, unsure if operational , , , , , Fair	Manufacture date July	JPRCC7X01Q	SBP ITD	SS3994	2102-681

17.00	1-106	Printer Hewlett-Packard, Color LaserJet, 4005DN Model number-CB504A Manufacture date Dec 10th 2008 Large printer on pallet, no hard drive, unsure if operational , , , , , Fair	JP4LD16427	SBP ITD	SS3992	2102-681
17.00	1-107	Printer Hewlett-Packard, Color LaserJet, 4700DN Model number-Q7493A Manufacture date Feb 20th 2008 Large printer on pallet, no hard drive, unsure if operational , , , , , Fair	JP4LB31082	SBP ITD	SS3995	2102-681
17.00	1-105	Printer Hewlett-Packard, Color LaserJet, CP4005DN Model number-CB504A Manufacture date Aug 20th 2009 Large printer on pallet, no hard drive, unsure if operational , , , , , Fair	JP8RD21891	SBP ITD	SS3991	2102-681
1.00	1-109	Printer Hewlett-Packard, LaserJet, 9050DN Model number-Q37238 Manufacture date Dec 21st 2007 Large printer on pallet, no hard drive, unsure if operational , , , , , Fair	JPRL7DN02C	SBP ITD	SS3993	2102-681
1.00	1-108	Printer Hewlett-Packard, LaserJet, 9050N Model number-Q3722A Manufacture date June 18th 2008 Large printer on wheels, no hard drive, unsure if operational , , , , , Fair	JPRL86K00C	SBP ITD	SS3996	2102-681
200.00	1-156	Plotter-Scanner Large Scanner on wheels, drive removed, unsure if operational. Hewlett-Packard HD 4530 Scanner Model number-CQ654A Manufacture date NA , , , , , Fair	DK0310B025	SBP ITD	X-V620	2103-801
23.45	1-151	Scanner Large Scanner on wheels, no hard drive, unsure if operational. Contex Plus HD3650 Scanner, Model number- KH67E, Manufacture date unknown , , , , , Fair	KH67E08017X	SBP ITD	SS3191	2103-737

23.45	1-110	Surveyor Vidar, Surveyor, 600E Plus Model number-GT67D Manufacture date-NA Large surveyor on wheels, no hard drive, unsure if operational , , , , Fair	GT67D7B059Z	SBP ITD	SS3997	2102-681
2.25	1-165	Table metal metal legs, wood grain top, 54"w x 27"d x 30"h , , , , , Good		LRWS	X-V625	2103-779
2.25	1-166	Table metal metal legs, wood grain top, 60"w x 30"d x 29"h , , , , , Good		LRWS	X-V624	2103-779
6.00	1-167	Table Lot of 2 pepperdust 60"w x 30"d x 30.5"h black metal legs , , , , , Good		LRWS	X-V621	2103-779
68.00	1-149	Table Pepperdust 180"L x 47"W (at widest) boardroom table , , , , , Good		LRWS	SS4000	2010-496

BIG RIVER, Environment, Compliance and Field Services, CALL FOR DIRECTIONS

Due to COVID-19, ON-LINE VIEWING ONLY. Contact Frazer Parsons 306-479-7309 or 1-800-567-4224, Frazer.Parsons@gov.sk.ca

*MT	* 11-555	Utility Trailer 1955 tilt deck, 4' wide x 8' long, 2" hitch, deck rotten, tires dry rotted and flat, lights unknown , , , , , Broken Repairable	AT2001	ENV	2	2006-216
------------	----------	---	--------	-----	---	----------

ESTEVAN, Environment, CFS, #128-1302 3rd Street

Due to COVID-19, ON-LINE VIEWING ONLY. NO ON-SITE VIEWING. Contact: Chad Shapley 306-637-4601, chad.shapley@gov.sk.ca

No Bid	* 12-695	Automatic Stapler Swingline Optima 45 Stapler Not functional , , , , , Beyond Repair		48209 ENV	122344	2012-571
No Bid	* 12-698	Camera Pentax Zoom60-X not functional , , , , , Beyond Repair		1775110 ENV	122321	2012-571
1.50	* 12-699	Digital Camera Kodak EasyShare ZD710 functional older model with case , , , , , Good	KCXHG73213663	ENV	122331	2012-571
No Bid	* 12-700	GPS Garmin GPSmap 60, Garmin GPS Screen will not turn on , , , , , Beyond Repair		37805768 ENV	122213	2012-571
1.00	* 12-706	Telescope Bausch & Lomb The Discoverer, 60mm telescope Old. Unable to focus , , , , , Beyond Repair	N/A	ENV	122204	2012-571
No Bid	* 12-707	Voice Recorder Sony Handheld Voice Recorder Not functional , , , , , Beyond Repair		1443553 ENV	122315	2012-571

HUDSON BAY, Environment, 501 Prince Street.

Due to COVID-19, ON-LINE VIEWING ONLY. NO ON-SITE VIEWING. Contact Shelley Kraft Schnell 306-865-4400, shelly.kraftschnell@gov.sk.ca

10.00	* X-558	Map Colour Topographical 62m-Yorkton, topographical 1974, located in Hudson Bay , , , , , New - Unused		ENV	39 62M	2004-010
10.00	* X-557	Map Colour Topographical 62n-Duck Mountain, topographical 1972, located in Hudson Bay , , , , , New - Unused		ENV	38 62N	2004-010
10.00	* X-534	Map Colour Topographical 63-d11-Porcupine Plain, topographical 1993, located in Hudson Bay , , , , , New - Unused		ENV	15 63D11	2004-010
10.00	* X-535	Map Colour Topographical 63d12-Bjorkdale, topographical 1993, located in Hudson Bay , , , , , New - Unused		ENV	16 63D12	2004-010

10.00 * X-536	Map Colour Topographical 63d13-Crooked River, topographical 1993, located in Hudson Bay , , , , , New - Unused	ENV	17 63D13	2004-010
10.00 * X-537	Map Colour Topographical 63d14-Mistatim, topographical 1993, located in Hudson Bay , , , , , New - Unused	ENV	18 63D14	2004-010
10.00 * X-524	Map Colour Topographical 63-d1-Swan Plain, topographical 1993, located in Hudson Bay , , , , , New - Unused	ENV	5 63D1	2004-010
10.00 * X-525	Map Colour Topographical 63-d2-Endeavour, topographical 1993, located in Hudson Bay , , , , , New - Unused	ENV	6 63D2	2004-010
10.00 * X-526	Map Colour Topographical 63-d3-Lintlaw, topographical 1993, located in Hudson Bay , , , , , New - Unused	ENV	7 63D3	2004-010
10.00 * X-529	Map Colour Topographical 63-d6-Klogei Lake, topographical 1993, located in Hudson Bay , , , , , New - Unused	ENV	10 63D6	2004-010
10.00 * X-531	Map Colour Topographical 63-d8-McBride Lake, topographical 1976, located in Hudson Bay , , , , , New - Unused	ENV	12 63D8	2004-010
10.00 * X-532	Map Colour Topographical 63-d9-Pepaw River, topographical 1993, located in Hudson Bay , , , , , New - Unused	ENV	13 63D9	2004-010
10.00 * X-542	Map Colour Topographical 63e3-Connell Creek, topographical 1984, located in Hudson Bay , , , , , New - Unused	ENV	23 63E/3	2004-010
10.00 * X-543	Map Colour Topographical 63e4-Arborfield, topographical 1993, located in Hudson Bay , , , , , New - Unused	ENV	24 63E/4	2004-010
10.00 * X-544	Map Colour Topographical 63e5-Carrot River, topographical 1993, located in Hudson Bay , , , , , New - Unused	ENV	25 63E/5	2004-010
10.00 * X-563	Map Colour Topographical 63m16-Norquay, topographical 1993, located in Hudson Bay , , , , , New - Unused	ENV	44 63M16	2004-010
10.00 * X-556	Map Colour Topographical 73a-Melfort, topographical 1976, located in Hudson Bay , , , , , New - Unused	ENV	37 73A	2004-010

LA RONGE, SaskBuilds and Procurement, Northern Property Management, Box 487, 1328 La Ronge Ave.

Due to COVID-19, ON-LINE VIEWING ONLY. NO ON-SITE VIEWING. Contact Cory Kirkham 306-425-4296, email: cory.kirkham@gov.sk.ca

4,199.99	1-611	Truck 1989 FORD F600 Bucket Truck RWD, regular cab, dual rear wheels, service body - bucket lift (condition of manlift unknown) V8 Gas Auto unknown options , White, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: Not road worthy - Out of Service condition, might only be salvageable for parts. Oil leaking onto exhaust pipe/engine & trans wet, power steering gear leaking, rear wheel cylinders severely leaking, front brake rotors severely rusted, fuel filter nearly rusted out, service body rusting out, clearance lights, signal lights, park lights, interior light, windshield washer, horn, battery weak, minor exterior damage.>, As is, Where is	126,090	1FDNF60H2KVA418	CVA	801556	2009-449
			Kms	26			TOW ONLY, Off-site - CVA owned

MAPLE CREEK, Parks, Culture & Sport, Cypress Hills Interprovincial Park

Due to COVID-19, ON-LINE VIEWING ONLY. NO ON-SITE VIEWING. Contact: Paul Rumancik 306-662-5414, paul.rumancik@gov.sk.ca

6.00	* 12-603	Air Conditioner - Window BTU, used , , , , , Fair	Electrohome, Model A601A00	6000	84319758??	Parks	12	2010-500
6.00	* 12-604	Air Conditioner - Window BTU, used , , , , , Fair	Electrohome, Model A601A00	6000	8431975950	Parks	13	2010-500
6.00	* 12-605	Air Conditioner - Window BTU, used , , , , , Fair	Electrohome, Model A601A00	6000	8431975953	Parks	14	2010-500
10.00	* 12-608	Blower Unit Unknown brand , Poor	blower unit for furnace, used , , , ,			Parks	8	2010-500
1.00	* 12-611	Educational Display how moisture in clouds turns into rain , , , , , Good	Water cycle Interactive display that shows			Parks	69	2010-500
No Bid	* 12-612	Electric Motor , , New - Unused	Century Pump Motor A.O. Smith, Part:7-360335-01-OJ, Cat #: E370, 3phase, 7.5 hp, 1760 rpm, 230V, 21A, 60Hz , ,		BY03	Parks	36	2010-500
No Bid	* 12-616	Flat top Commercial Electric Flat top Repairable	white , , , , , Broken			Parks	23	2010-500

10.00	* 12-617	Furnace Intertherm 75,000 BTUH, natural gas, Model MGH-075AC, Date Code 81JY23 L-01, used , , , , , Poor		Parks	9	2010-500
No Bid	* 12-623	Lawn Mower Jacobsen Textron commercial, 123V, 4 hp, 2 cycle, missing gas cap, SERM-SK 6900 , , , , , Poor		Parks	20	2010-500
No Bid	* 12-624	Lawn Mower Jacobsen Textron commercial, 123V, 4 hp, 2 cycle, SERM-SK 7280 , , , , , Poor		Parks	21	2010-500
No Bid	* 12-625	Lawn Mower Jacobsen Textron commercial, 123V, 4hp, 2 cycle, missing pin on handle , , , , , Poor	32017 10660	Parks	19	2010-500
15.00	* 12-634	Radial Arm Saw Delta, Model LR30211 230V, 9.6A, 60 Hz, 2 hp, Delta No. 438-02-314-206 , , , , , Poor	97L95906	Parks	18	2010-500
10.00	* 12-636	Sink Freestanding cast iron 22"w x 18"d x 10.5"h, 8" between faucet holes, porcelain finish, white , , , , , Good		Parks	64	2010-500
25.25	* 12-653	Wall Art Star map 3.6m x 1.5m, star constellations, plugs in for star effect , , , , , Good		Parks	68	2010-500
No Bid	* 12-657	Water Pump Baldor Cat No. WCM3710T, 3 phase, 7.5 hp, 230V, 22.2 A, 1760 rpm, 60 Hz , , , , , Fair	F199	Parks	31	2010-500
No Bid	* 12-658	Water Pump Franklin Electric Model 1403041418 1/3 hp, 3450 rpm, 115V, 7.5 A, 60 Hz , , , , , Poor		Parks	30	2010-500
No Bid	* 12-660	Water Pump J Class Model K56P2N101 3 hp, 3450 rpm , , , , , Poor	2D06	Parks	26	2010-500
No Bid	* 12-661	Water Pump - Pool Jacuzzi Canada, Magnetek 7-187895-20 1/2 hp, 3450 rpm , , , , , Fair	E44549	Parks	27	2010-500
No Bid	* 12-662	Water Pump - Pool Jacuzzi Canada, Pump model 3VLB-1208-LQ 3450 rpm , , , , , Poor	BY09-11	Parks	29	2010-500
No Bid	* 12-615	File Cabinet Metal 36"w x 18"d x 54"h, 4 drawer, horizontal , , , , Fair		Parks	51	2010-500
6.00	* 12-628	Office Cabinet Metal 42"w x 14"d x 35"h, chrome legs, sliding metal door, no shelves , , , , , Fair		Parks	60	2010-500
72.00	* 12-637	Storage Cabinet Metal 36"w x 18"d x 65"h, double doors, shelves inside , , , , , Fair		Parks	50	2010-500
No Bid	* 12-638	Table Metal 60"w x 30"d x 27"h, chrome legs, beige, arborite top, brown wood grain , , , , , Fair		Parks	42	2010-500

No Bid	* 12-639	Table Metal 60"w x 30"d x 27"h, chrome legs, beige, arborite top, brown wood grain , , , , , Fair	Parks	43	2010-500
No Bid	* 12-640	Table Metal 60"w x 30"d x 27"h, chrome legs, beige, arborite top, brown wood grain , , , , , Fair	Parks	44	2010-500
No Bid	* 12-641	Table Metal 60"w x 30"d x 27"h, chrome legs, beige, arborite top, brown wood grain , , , , , Fair	Parks	45	2010-500
No Bid	* 12-642	Table Metal 60"w x 30"d x 27"h, chrome legs, grey, arborite top, grey solid , , , , , Fair	Parks	47	2010-500
No Bid	* 12-643	Table Metal 60"w x 30"d x 29"h, chrome legs, grey, arborite top, grey solid , , , , , Fair	Parks	48	2010-500
No Bid	* 12-644	Table Metal 60"w x 30"d x 29"h, double pedestal legs, arborite top, light brown solid , , , , , Fair	Parks	49	2010-500
No Bid	* 12-645	Table Oak slatted 36"w x 42"d x 27"h, possible drying table, adjustable angle top , , , , , Broken Repairable	Parks	62	2010-500
No Bid	* 12-646	Table Round 48" diameter x 32"h, single chrome leg, arborite top, grey , , , , , Fair	Parks	63	2010-500
31.50	* 12-647	Table - folding Banquet Style - foldable legs 30"w x 72"d x 29"h, arborite top, brown wood grain , , , , , Fair	Parks	52	2010-500
31.50	* 12-648	Table - folding Banquet Style - foldable legs 30"w x 72"d x 29"h, arborite top, brown wood grain , , , , , Fair	Parks	53	2010-500
31.50	* 12-649	Table - folding Banquet Style - foldable legs 30"w x 72"d x 29"h, arborite top, brown wood grain , , , , , Fair	Parks	54	2010-500
31.50	* 12-650	Table - folding Banquet Style - foldable legs 30"w x 72"d x 29"h, arborite top, brown wood grain , , , , , Fair	Parks	55	2010-500
MEADOW LAKE PROVINCIAL PARK, Parks Culture and Sport, Meadow Lake Provincial Park					
Due to COVID-19, ON-LINE VIEWING ONLY. Contact Ernie Schwartz 306-236-7680, 306-240-5055, email: ernie.schwartz@gov.sk.ca					
5,795.00	1-605	Tractor Deutz D6806A FWA Diesel Cab, Green, , , body exterior/paint/interior in poor condition, motor/transmission/brakes/battery/exhaust/lights condition unknown>, As is, Where is		4,239 hours	75663680 Parks PCS 2012-543

129.99	1-607	Truck 1998 DODGE Ram 1500 2WD, Club Cab V8 Gas Auto air, tilt, cruise , White, TOW ONLY, No SGI Inspection. It is unknown if any repairs or safety concerns exist (if any). Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs if required. , , PROBLEMS: Sitting for approx 4 years without being started or used. Some body damage and rust. Body exterior poor, tires poor, interior poor, paint poor, windshield glass poor>, As is, Where is	219,433	3B7HC12Y3WG1894	Parks	TOW	2012-547
			Kms	27	PCS	ONLY, Off-Site	
439.99	1-608	Truck 2001 DODGE Ram 1500 4x4, Quad Cab V8 Gas Auto air, tilt, cruise tool box, White, TOW ONLY, No SGI Inspection. It is unknown if any repairs or safety concerns exist (if any). Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs if required. , , PROBLEMS: Sitting for approx 4 years without being started or used. Parked for mechanical issues. Body exterior poor, tires poor, interior poor, other unknown conditions>, As is, Where is	260,233	1B7HF13Z01J58953	Parks	TOW	2012-546
			Kms	3	PCS	ONLY, Off-Site	
439.99	1-606	Truck 1998 DODGE Ram 2500 RWD V8 Gas Auto air, tilt, cruise , White, TOW ONLY, No SGI Inspection. It is unknown if any repairs or safety concerns exist (if any). Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs if required. , , PROBLEMS: Right rear tail light broken, small chips on windshield, some body damage and rust. Sitting for approx 4 years without being started or used. Body exterior poor, tires poor, interior poor, paint poor>, As is, Where is	339,957	3B7KC26Z9WM240	Parks	TOW	2012-545
			Kms	753	PCS	ONLY, Off-Site	

MOOSE JAW, Highways & Infrastructure, 1 km south of Moose Jaw on Highway #2

Due to COVID-19, ON-LINE VIEWING ONLY. NO ON-SITE VIEWING. Contact: Al Froehlich 306-694-3775, allan.froehlich@gov.sk.ca

14,275.00	1-610	Grader 1994 Champion 740A RWD Cummins L10, Inline 6, Diesel Synchronesh A/C , Yellow, , air conditioning repair last fall, Multiple engine and transmission leaks, mouse smell in cab, rear tires worn out, multiple lights out, turn signals, light bar, left door glass cracked, some rust on exterior, horn doesn't work, needs batteries.>, As is, Where is	12,495 hours	24259 HI	C94981	2103-759
210.00	1-539	Plow 2006, Henderson 2 way plow, Model 12X42XIS , , , , , Fair	functional	RSP04696	HI	M-3637 2101-597
521.00	1-540	Plow 2010, Henke 1 way plow, Model 39-52-12 IS ECT used , , , , , Fair	lightly	14168 HI	M-4167	2101-598
369.00	1-541	Power Tools Hilti DX 450, TE 24 cart and accessories go with , , , , Fair		HI	1	2101-602
NORTH BATTLEFORD, Environment, Compliance and Field Services, 1600-1192 102nd Street						
Due to COVID-19, ON-LINE VIEWING ONLY. NO ON-SITE VIEWING. Contact: Karen Howard 306-446-7416, karen.howard@gov.sk.ca						
1,602.00	1-537	Snowmobile 1998 Polaris 340 Indy Lite Deluxe Model No. 0983431 Standard Differential Fan Twin EC34-2PM02A LWH 105" x 42.5" x 45", displacement 339cc / 2 cylinders, gas Rear of seat and top of hood storage, handwarmers., Green, , , Has not been used at all in quite a few years. Not operational, may be repairable., As is, Where is	1,779 miles	3372722 ENV	1120	2101-595
PRINCE ALBERT, Corrections & Policing, Pine Grove Prism Industries, 1700 7th ave NE.						
Due to COVID-19, ON-LINE VIEWING ONLY. NO ON-SITE VIEWING. Contact Mark Halcro 306-953-3144, mark.halcro@gov.sk.ca						
22.00	* 12-568	Cabinet ivory, wooden 62" wide, 25" deep, 80" high , , , , , Fair		CP	52 P.A.	2101-587
No Bid	* 12-573	Desks Lot of 4 very old, wooden 36" wide, 24" deep, 30" high , , , , , Fair		CP	26 P.A.	2101-587
No Bid	* 12-530	Fanny Packs and Duffel Bags Lot of 34 canvas cut fabric only, no hardware, 20 canvas fanny packs, 14 canvas medium duffel bags , , , , , Good		CP	73 P.A.	2101-580

No Bid	* 12-533	Headbands Lot of 22 poly cotton lycra rib knit fabric lulu lemon knockoff headbands , , , , , Fair	N/A	CP	10 P.A.	2101-580
No Bid	* 12-537	Mobile Cabinets Lot of 2 wood grain laminate 20" w, 18" d, 29" h , , , , , Fair		CP	22 P.A.	2101-580
5.00	* 12-584	Sewing Machine Tables Lot of 2 wood, shelf underneath 23.5" wide, 48" deep, 30" high , , , , , Fair		CP	58 P.A.	2101-587
3.00	* 12-549	Sherpa Lining Lot of 2 fabric ivory and black, approx. 5m each , , , , , Good	N/A	CP	65 P.A.	2101-580
No Bid	* 12-550	Shorts Rompers Lot of 12 printed and plain t-shirt knit assorted colours, sizes 10-16 , , , , , Good		CP	67 P.A.	2101-580
5.51	* 12-551	Single Size Quilt and Pillow Case flannelette and broadcloth baseball print , , , , , Good		CP	71 P.A.	2101-580
No Bid	* 12-589	Wheeled Bin off-white, rounded edges, 4 wheels has 1 end section that is damaged, as seen in pictures , , , , , Fair		CP	43 P.A.	2101-587
No Bid	* 12-590	Wheeled Bin painted wood 28" wide, 74" deep, 25" high , , , , , Good		CP	32 P.A.	2101-587

REGINA, Corrections & Policing, 4040 East, 9th Avenue North

Due to COVID-19, ON-LINE VIEWING ONLY. Contact Brad Cossette 306-924-9965, 306-313-8446, email: bradley.cossette@gov.sk.ca

2,117.00	1-609	Dump Truck 1991 White-GMC Volvo Heavy Vehicle 2WD Cummins L10, Diesel Manual hydraulic hook ups, tandem axle belly blade, dual tires, Yellow, TOW ONLY, No SGI Inspection. It is unknown if any repairs or safety concerns exist (if any). Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs if required. , New Batteries, some rust holes repaired., PROBLEMS: This was an old Highways truck that was used for spreading salt causing a great deal of rusting. It did run but has been parked for quite some time now.>, As is, Where is	37,316 hours	4V2JCBMD2MR811	CP	TOW ONLY, Off-Site	2011-512
----------	-------	---	--------------	----------------	----	--------------------	----------

REGINA, Highways, Financial Services, 1660 Park St.

Due to COVID-19, ON-LINE VIEWING ONLY. NO ON-SITE VIEWING. Contact: Karen Lappa 306-787-3176, karen.lappa@gov.sk.ca, or Judy Adams 306-787-4796, judy.adams@gov.sk.ca

2.00	1-542	Book Case	Brown wood	42"h x 42"w x 12"d , , , , ,	Good	HI	269 1660	2101-607
							Park St, Reg	CD#31870d
2.25	1-543	Book Case	Brown wood	42"h x 42"w x 12"d , , , , ,	Good	HI	270 1660	2101-607
							Park St, Reg	CD#31870e
2.76	1-544	Book Case	Brown wood	43"h x 42"w x 12"d , , , , ,	Good	HI	271 1660	2101-607
							Park St, Reg	CD#31870f
17.00	1-545	Book Case	Brown wood	51"h x 51"w x 12"d , , , , ,	Good	HI	268 1660	2101-607
							Park St, Reg	CD#31870c
2.50	1-546	Book Case	Brown wood	60"h x 51"w x 12"d , , , , ,	Good	HI	267 1660	2101-607
							Park St, Reg	CD#31870b
2.50	1-547	Book Case	Brown wood	72"h x 32"w x 12"d , , , , ,	Good	HI	266 1660	2101-607
							Park St, Reg	CD#31870a
46.00	1-548	Book Case with Cupboard	Brown Executive Style wood	92"h x 32"w x 12"d , , , , ,	Good	HI	264 1660	2101-607
							Park St, Reg	CD#31871
46.00	1-549	Book Case with Cupboard	Brown Executive Style wood	92"h x 32"w x 12"d , , , , ,	Good	HI	265 1660	2101-607
							Park St, Reg	CD#31871
4.50	1-550	Chair	Side Chair	Solid oak, armless , , , , ,	Fair	HI	224 1660	2101-607
							Park St, Reg	CD#31924
3.97	1-551	Coffee Table	Executive Style Brown Wood	48"d x 18"w x 15"h , , , , ,	Good	HI	381 1660	2101-607
							Park St, Reg	CD#31901

6.27	1-552	End Table Lot of 2 Executive Style Brown Wood 18"h x 25"w , , , , , Fair	HI	379 1660	2101-607 Park St, Reg CD#31901
No Bid	1-594	Microwave Brown 12"h x 21"w x 16"d, operability unknown , , , , Fair	HI	395 1660	2101-607 Park St, Reg CD#31923
53.50	1-553	Filing Cabinet Executive Style Brown Wood 2 drawer 28"h x 36"w x 19"d , , , , , Good	HI	51 1660	2101-607 Park St, Reg CD#31849
53.50	1-554	Filing Cabinet Executive Style Brown Wood 2 drawer 28"h x 36"w x 19"d , , , , , Good	HI	52 1660	2101-607 Park St, Reg CD#31849
31.00	1-555	Filing Cabinet Metal, 4 drawer, lateral 52"h x 36"w x 20"d , , , , , Good	HI	416 1660	2101-607 Park St, Reg CD#31856b
19.50	1-556	Filing Cabinet Metal, 4 drawer, lateral 52"h x 36"w x 20"d , , , , , Good	HI	417 1660	2101-607 Park St, Reg CD#31856b
20.25	1-557	Filing Cabinet Metal, 4 drawer, lateral 52"h x 36"w x 20"d , , , , , Good	HI	418 1660	2101-607 Park St, Reg CD#31856b
20.25	1-558	Filing Cabinet Metal, 4 drawer, lateral 52"h x 36"w x 20"d , , , , , Good	HI	419 1660	2101-607 Park St, Reg CD#31856b
20.25	1-559	Filing Cabinet Metal, 4 drawer, lateral 52"h x 36"w x 20"d , , , , , Good	HI	420 1660	2101-607 Park St, Reg CD#31856b
20.25	1-560	Filing Cabinet Metal, 4 drawer, lateral 52"h x 36"w x 20"d , , , , , Good	HI	421 1660	2101-607 Park St, Reg CD#31856b

20.25	1-561	Filing Cabinet Good	Metal, 4 drawer, lateral	52"h x 36"w x 20"d , , , , ,	HI	422 1660	2101-607 Park St, Reg CD#31856b
20.25	1-562	Filing Cabinet Good	Metal, 4 drawer, lateral	52"h x 36"w x 20"d , , , , ,	HI	423 1660	2101-607 Park St, Reg CD#31856b
20.25	1-563	Filing Cabinet Good	Metal, 4 drawer, lateral	52"h x 36"w x 20"d , , , , ,	HI	424 1660	2101-607 Park St, Reg CD#31856b
25.00	1-564	Filing Cabinet Good	Metal, 4 drawer, lateral	52"h x 36"w x 20"d , , , , ,	HI	425 1660	2101-607 Park St, Reg CD#31856b
25.00	1-565	Filing Cabinet Good	Metal, 4 drawer, lateral	52"h x 36"w x 20"d , , , , ,	HI	426 1660	2101-607 Park St, Reg CD#31856b
20.25	1-566	Filing Cabinet Good	Metal, 4 drawer, lateral	52"h x 36"w x 20"d , , , , ,	HI	427 1660	2101-607 Park St, Reg CD#31856b
20.25	1-567	Filing Cabinet Good	Metal, 4 drawer, lateral	53"h x 36"w x 18"d , , , , ,	HI	311 1660	2101-607 Park St, Reg CD#31856b
20.00	1-568	Filing Cabinet ,, Good	Metal, 4 drawer, vertical	51"h x 18"w x 28"d , , ,	HI	313 1660	2101-607 Park St, Reg CD#31880
10.51	1-569	Filing Cabinet ,, Good	Metal, 4 drawer, vertical	51"h x 18"w x 28"d , , ,	HI	314 1660	2101-607 Park St, Reg CD#31880
10.51	1-570	Filing Cabinet ,, Good	Metal, 4 drawer, vertical	51"h x 18"w x 28"d , , ,	HI	315 1660	2101-607 Park St, Reg CD#31880

10.51	1-571	Filing Cabinet , , Good	Metal, 4 drawer, vertical	51"h x 18"w x 28"d , , ,	HI	316 1660	2101-607 Park St, Reg CD#31880
10.51	1-572	Filing Cabinet , , Good	Metal, 4 drawer, vertical	51"h x 18"w x 28"d , , ,	HI	317 1660	2101-607 Park St, Reg CD#31880
4.25	1-573	Filing Cabinet , , Good	Metal, 4 drawer, vertical	51"h x 18"w x 28"d , , ,	HI	318 1660	2101-607 Park St, Reg CD#31880
3.75	1-574	Filing Cabinet , , Good	Metal, 4 drawer, vertical	51"h x 18"w x 28"d , , ,	HI	428 1660	2101-607 Park St, Reg CD#31880
4.00	1-575	Filing Cabinet , , Good	Metal, 4 drawer, vertical	51"h x 18"w x 28"d , , ,	HI	429 1660	2101-607 Park St, Reg CD#31880
20.50	1-576	Filing Cabinet , , Good	Metal, 4 drawer, vertical	51"h x 18"w x 28"d , , ,	HI	430 1660	2101-607 Park St, Reg CD#31880
20.50	1-577	Filing Cabinet , , Good	Metal, 4 drawer, vertical	51"h x 18"w x 28"d , , ,	HI	431 1660	2101-607 Park St, Reg CD#31880
20.50	1-578	Filing Cabinet , , Good	Metal, 4 drawer, vertical	51"h x 18"w x 28"d , , ,	HI	432 1660	2101-607 Park St, Reg CD#31880
20.50	1-579	Filing Cabinet , , Good	Metal, 4 drawer, vertical	51"h x 18"w x 28"d , , ,	HI	433 1660	2101-607 Park St, Reg CD#31880
20.50	1-580	Filing Cabinet , , Good	Metal, 4 drawer, vertical	51"h x 18"w x 28"d , , ,	HI	434 1660	2101-607 Park St, Reg CD#31880

20.50	1-581	Filing Cabinet , , Good	Metal, 4 drawer, vertical	51"h x 18"w x 28"d , , ,	HI	436 1660	2101-607 Park St, Reg CD#31880
20.50	1-582	Filing Cabinet , , Good	Metal, 4 drawer, vertical	51"h x 18"w x 28"d , , ,	HI	437 1660	2101-607 Park St, Reg CD#31880
20.50	1-583	Filing Cabinet , , Good	Metal, 4 drawer, vertical	51"h x 18"w x 28"d , , ,	HI	438 1660	2101-607 Park St, Reg CD#31880
20.50	1-584	Filing Cabinet , , Good	Metal, 4 drawer, vertical	51"h x 18"w x 28"d , , ,	HI	439 1660	2101-607 Park St, Reg CD#31880
4.25	1-585	Filing Cabinet , , Good	Metal, 4 drawer, vertical	51"h x 18"w x 28"d , , ,	HI	440 1660	2101-607 Park St, Reg CD#31880
65.00	1-586	Filing Cabinet Good	Metal, 5 drawer, lateral	65"h x 36"w x 18"d , , , , ,	HI	308 1660	2101-607 Park St, Reg CD#31856c
65.00	1-587	Filing Cabinet Good	Metal, 5 drawer, lateral	65"h x 36"w x 18"d , , , , ,	HI	309 1660	2101-607 Park St, Reg CD#31856c
*MT	1-588	Hutch	Pepperdust wood	42"h x 24"w , , , , , Excellent	HI	254 1660	2101-607 Park St, Reg CD#31867
No Bid	1-589	Hutch	Pepperdust wood	42"h x 42"w , , , , , Excellent	HI	240 1660	2101-607 Park St, Reg CD#31867
No Bid	1-590	Hutch	Pepperdust wood	42"h x 42"w , , , , , Excellent	HI	244 1660	2101-607 Park St, Reg CD#31867

No Bid	1-591	Hutch	Pepperdust wood	42"h x 42"w , , , , ,	Excellent	HI	245 1660	2101-607
							Park St, Reg	CD#31867
*MT	1-592	Hutch	Pepperdust wood	42"h x 42"w , , , , ,	Excellent	HI	247 1660	2101-607
							Park St, Reg	CD#31867
*MT	1-593	Hutch	Pepperdust wood	42"h x 42"w , , , , ,	Excellent	HI	248 1660	2101-607
							Park St, Reg	CD#31867
3.75	1-595	Table	Brown, round, wood, office	42" diameter , , , , ,	Good	HI	334 1660	2101-607
							Park St, Reg	CD#31878
3.50	1-596	Table	Brown, round, wood, office	42" diameter , , , , ,	Good	HI	335 1660	2101-607
							Park St, Reg	CD#31878
3.25	1-597	Table	Brown, round, wood, office	42" diameter , , , , ,	Good	HI	336 1660	2101-607
							Park St, Reg	CD#31878
7.50	1-598	Table	Executive style, brown, wood, office	46" diameter , , , , ,	Good	HI	333 1660	2101-607
							Park St, Reg	CD#31921
7.50	1-599	Table	Executive style, brown, wood, office	46" diameter , , , , ,	Good	HI	392 1660	2101-607
							Park St, Reg	CD#31921
1.25	1-600	Table	Metal, brown, rectangular	54"d x 30"w x 29.5"h , , , , ,	Fair	HI	387 1660	2101-607
							Park St, Reg	CD#31898
5.00	1-601	Table	Metal, brown, rectangular	60"d x 30"w x 29.5"h , , , , ,	Fair	HI	385 1660	2101-607
							Park St, Reg	CD#31898

5.00	1-602	Table Metal, brown, rectangular 60"d x 30"w x 29.5"h , , , , , Fair	HI	386 1660	2101-607 Park St, Reg CD#31898
------	-------	--	----	----------	--------------------------------------

REGINA, Energy and Resources, 201 Dewdney Ave E.

Due to COVID-19, ON-LINE VIEWING ONLY. Contact Richard Wood 306-787-2621, richard.wood@gov.sk.ca

1.28	* X-603	Satellite System satellite dish, modern charger, 2 single coaxial cables and 1 satellite finder, small coaxial cable. , , , , , Poor	ER	40	2004-079
------	---------	--	----	----	----------

REGINA, Immigration and Career Training, 1000-2103 11th Ave.

Due to COVID-19, ON-LINE VIEWING ONLY. NO ON-SITE VIEWING. Contact Tristyn Firth at 306-787-8716, tristyn.firth@gov.sk.ca, or Patrice Naces at 306-787-2830, patrice.naces@gov.sk.ca

*WD	* 11-583	Phone Headset Lot of 2 1. Microsoft, black, comes with cords, unknown if working. 2. GN Netcom, includes cords, unknown if working. , , , , , Fair	ICT	2	2010-486
------------	----------	--	-----	---	----------

REGINA, Parks, Culture, and Sport, 1660 Park St.

Due to COVID-19, ON-LINE VIEWING ONLY. NO ON-SITE VIEWING. Contact: Marlon Janzen 306-787-9548, Marlon.Janzen@gov.sk.ca, or Ray Poulin 306-787-2801, ray.poulin@gov.sk.ca

162.99	1-501	Boat Outboard Motor Evinrude, Sportwin 10 hp, has been in storage approx. 20 years and hasn't been run during that time. 24" wide, 44" tall, 12" deep , , , , , Fair	Parks	20	2010-505
--------	-------	--	-------	----	----------

162.99	1-502	Boat Outboard Motor Johnson, Sea 10 10 hp, has been in storage approx. 20 years and hasn't been run during that time. 22" wide, 44" tall, 14" deep , , , , , Fair	Parks	21	2010-505
--------	-------	---	-------	----	----------

50.00	1-503	Camp Cook Stove metal Approx. 1940s vintage camp stove, 29" wide, 21" deep, 15" tall, box of mostly new stove pipes for chimney , , , , , Fair	Parks	18	2010-505
-------	-------	--	-------	----	----------

128.88	1-504	Combination Disk & Belt Sander Powerking, 5010 10" disk and 4½" wide belt, no motor, otherwise working , , , , , Fair	Parks	12	2010-505
--------	-------	--	-------	----	----------

105.00	1-505	Dust Collector Vacuum King, KC-2108 24" wide, 12" deep, 44" tall , , , , , Good	Parks	15	2010-505
--------	-------	--	-------	----	----------

27.55	1-506	Gas Engine 3 hp Briggs & Statton, small Has been in storage approx. 20 years and hasn't been run during that time. , , , , , Fair	Parks	27	2010-505
223.00	1-507	Jointer Rockwell Beaver, 48-600 40" wide, 24" deep, 38" tall , , , , , Fair	Parks	14	2010-505
221.00	1-508	Lathe Rockwell Beaver, 3400 Table is 48"x12". Comes with 30" tall stand. , , , , , Good	Parks	13	2010-505
10.00	1-509	Light Table Herring Graphic, Model 3545 H, adjustable Top glass is cracked, otherwise in good working order , , , , , Broken Repairable	Parks	17	2010-505
250.00	1-510	Matrix Screener Custom built unit. 1/4 hp Boston Gear electric motor Used on Paleo and Archeology digs to screen sand and gravel for fossils. Was in running order, but has not been used for several years. Screen is 36" wide by 18" diameter, whole unit is 43" wide, 39" deep, 48" tall. , , , , , Fair	Parks	26	2010-505
No Bid	1-511	Movie Projector Hortson 16mm theatre movie projector & power supply 28" wide, 60" tall, 20" deep. Was in good working order when removed from theatre. Has been in storage for approx. 20 years. , , , , , Good	Parks	7	2010-505
1,013.00	1-512	Multi-tool Woodworking Machine Shopsmith Mark V Machine includes 6" belt sander, disk sander table saw, lathe, drill press , , , , , Good	Parks	16	2010-505
1.25	1-513	Opaque Projector Artograph 3D Prosketch, 30-2R Used to project an image of a drawing or object onto canvas or wall for tracing. , , , , , Fair	Parks	8	2010-505
262.50	1-514	Storage Cabinets Lot of 8 metal, made by Electrical Manufacturing Co. Ltd. 29½" wide, 89½" tall, 20½" deep, fixed shelves, pull out counters , , , , , Good	Parks	1	2010-505
501.00	1-515	Table Saw Rockwell, 34-450 Fence length = 83", requires 3 phase power , , , , , Good	Parks	11	2010-505

75.00	1-516	Vacuum Former Made by Canadian Technical School Equipment and supply, Model 1324 Requires 220 plug in. 77" wide, 54" tall, 36" deep. , , , , Fair	Parks	10	2010-505
-------	-------	---	-------	----	----------

REGINA, SaskBuilds and Procurement, Property Management, 1660 Park Street.

Due to COVID-19, ON-LINE VIEWING ONLY. Contact Rhonda Gelowicz 306-552-8049, or at rhonda.gelowicz@gov.sk.ca

500.00	* 8-716	Shrink Wrap Machine 1998 Wulftec International Model WRT-150 Machine works normally, all functions worked, the top cover button is missing from panel, the rotation motor is likely soon to be replaced as it has carbon dust and grease markings on the back end, motor is quiet and doesn't draw extra amperage- this could mean motor needs service, reflector will need to be fastened properly NOTE: • Specialized equipment - successful bidder will have to dismantle and unbolt the device from the concrete. A lifting kit is required to take the wrappers down. This can be purchased directly through Wulftec. , , , , Fair	9708-1-0703	SBP Prop Man	CS20-02	2010-488
--------	---------	--	-------------	--------------------	---------	----------

700.00	* 8-717	Shrink Wrap Machine 2002 Wulftec International Model WRT-150 All functions work properly, photo eye is weak and needs replacement auto height sensor switch works but needs replacing soon NOTE: • Specialized equipment - successful bidder will have to dismantle and unbolt the device from the concrete. A lifting kit is required to take the wrappers down. This can be purchased directly through Wulftec , , , , Fair	0200-5525	SBP Prop Man	CS20-01	2010-488
--------	---------	---	-----------	--------------------	---------	----------

SASKATOON, Environment, Compliance and Field Services, 102-112 Research Drive

Due to COVID-19, ON-LINE VIEWING ONLY. NO ON-SITE VIEWING. Contact: Michael Paschke 306-933-6240, FieldOffice.Saskatoon@gov.sk.ca

111.11	1-531	Air Compressor Milton Lyn, Leland Electric motor 3/4 hp, 110V, two tanks , , , , Fair	5565L5037	ENV	CFS-5.1, 5.2, 5.3, 5.4	2012-567
--------	-------	---	-----------	-----	---------------------------	----------

2,199.50	1-532	ATV 1995 Yamaha Big Bear 350 4x4, winch, sat for several years, not running, flat tires , , , , , Fair	A222142	ENV	CFS-1.1, 1.2, 1.3	2012-567
476.00	1-533	Ice Fishing Shack OSB Wood 6' L, 81.5"W (4'w bottom) flat screen TV, wood stove , , , , , Fair		ENV	CFS-4.1, 4.2, 4.3	2012-567
12.00	1-534	Lawn Mower Roof model 522110 sat for several years , , , , , Fair	138553	ENV	CFS-6.1, 6.2, 6.3, 6.4	2012-567
30.00	1-535	Tool Boxes Lot of 2 Payload tool boxes for truck box 63.5" long, 11" wide on top, latches work, no keys , , , , , Fair		ENV	CFS-3.1, 3.2	2012-567
216.00	1-536	Truck Box Ramps Loadpro 4' wide, 77" long , , , , , Fair		ENV	CFS-2.1, 2.2	2012-567
SASKATOON, Environment, Fish, Wildlife and Lands, 126-105 St. East						
Due to COVID-19, ON-LINE VIEWING ONLY. NO ON-SITE VIEWING. Contact: Gord Sedgewick 306-229-4230, Gord.Sedgewick@gov.sk.ca, or Jennifer Merkowsky 306-933-7943, Jennifer.Merkowsky@gov.sk.ca						
57.50	1-517	Belly Boat inflatable for angling , , , , , Good		ENV	FWL-14	2011-533
89.91	1-518	Boat Trailer 1965 Boat Utility Trailer for 12-14' car topper boats, loaded upside down Homemade, boat trailer tires minimal condition , , , , , Poor	TGK248-Licence Plate # VIN-	ENV	FWL-9	2011-533
35.00	1-519	Chain Saw Homelite Chain Saw Model # XL-12 50003, wooden carrying case with extra chain included , , , , , Fair	VIN#-12670028	ENV	FWL-3	2011-533
42.00	1-520	Lead Line Lot of 2 Nylon-covered lead line originally used for gill nets Several hundred meters or several hundred kg by weight of product , , , , , Good		ENV	FWL-7	2011-533
15.00	1-521	Net Leader Approximately 50' in length x 5' height Cotton, originally used as leader with trapnets for live capture of fish , , , , , Good		ENV	FWL-4	2011-533
15.00	1-522	Net Leader Approximately 50' in length x 5' height Nylon, originally used as leader with trapnets for live capture of fish , , , , , Good		ENV	FWL-5	2011-533
55.00	1-523	Net Leader Approximately 150' ? in length x 5'-6' height, includes net tub Originally used as leader with trapnets for live capture of fish , , , , , Good		ENV	FWL-11	2011-533

55.00	1-524	Net Leader	Approximately 150' in length x 5'-6' height, includes net tub Originally used as leader with trapnets for live capture of fish , , , , , Good		ENV	FWL-10	2011-533
20.00	1-525	Nuts and Bolts	Wooden box, nuts and bolts all one size, includes 2 crescent wrenches & 3 ratchet tools Contents heavy , , , , , Good		ENV	FWL-12	2011-533
2,965.00	1-526	Quad	1996 Honda 400 Gas system leak, no battery, running condition but not used for years, tires need inflating , , , , , Good	VIN#- 478TE2021TA10441 8	ENV	FWL-2	2011-533
15.00	1-527	Rope	100' Nylon Rope, 1.5" diameter Yellow coil of rope , , , , , Good		ENV	FWL-6	2011-533
1,622.00	1-528	Snowmobile	1991 Yamaha Enticer 2 cylinder, reverse, Model CS-806, no battery, running condition but not used for years , , , , , Fair	VIN#-89X-000500	ENV	FWL-1	2011-533
28.35	1-529	Snowshoes	Lot of 2 Wooden 1 pair, foot strap assembly incomplete , , , , , Good		ENV	FWL-13	2011-533
45.00	1-530	Weights for Gill Nets	Lead, 1 bag plus one tub, approx. 50 kgs 5 cm x 2 cm each , , , , , Good		ENV	FWL-8	2011-533
SASKATOON, Saskatchewan Research Council, 125-15 Innovation Boulevard							
Due to COVID-19, ON-LINE VIEWING ONLY. NO ON-SITE VIEWING. Contact: Roger Dauvin 306-385-4035, roger.dauvin@src.sk.ca							
No Bid	1-603	Cartesian System	XRS XRS Cartesian System (small) with enclosure , , , , , Good	803-5251A	SRC	x	2102-678
4,044.00	1-604	Inverter and 15 Batteries	AIMS Power 6000w 24V to 120/240V Inverter and 15 Batteries Includes all cables and hook-ups; five racks (66"x20"x36") of 3 data safe 4DX-21 batteries (20"x16"x23") , , , , , Good		SRC	1	2102-692
STONY RAPIDS, Environment, Stony Rapids Fire Base							
Due to COVID-19, ON-LINE VIEWING ONLY. NO ON-SITE VIEWING. Contact: Steven Asselstine 306-439-2062, steve.asselstine@gov.sk.ca							
700.00	* 12-504	ATV	2001 Polaris 325 four stroke, 2x4 , does not run, problem unknown, snowblade and storage box included. SOLD AS IS , , , , , Broken Repairable	4xacd32a11a36067 8	ENV	1	2009-398

No Bid	* 12-505	Boat Motor 2002 Evinrude 75hp DI motor runs, currently has lower unit disassembled, needs injectors, forward gears, prop shaft, minor damage to lower unit exterior, includes oil container. SOLD AS IS , , , , , Broken Repairable	4983925 ENV	3	2009-398
299.99	* 12-506	Trailer 1999 Homebuilt Trailer single axle. 14x8. deck and axle needs replacement, spare tire and jack Included, tire size ST205/75/R15, items on deck of trailer sold separate. SOLD AS IS , , , , , Broken Repairable	SK401018377	ENV	2 2009-398
WADENA, Environment, Compliance & Field Services, 1 Mile North of Wadena					
Due to COVID-19, ON-LINE VIEWING ONLY. NO ON-SITE VIEWING. Contact: Dale Achtymichuk 306-338-8184, dale.achtymichuk@gov.sk.ca, or Scott Harvey 306-338-8174, scott.harvey@gov.sk.ca					
988.00	1-538	Snowmobile 1998 Polaris Tran Sport, Model 0980143. 6545 miles, Not used in the last 5 years, fan cooled twin cylinder engine, 432 cc engine displacement, oil injection, has reverse , , , , , Poor	3370081	ENV	W1 2102-669
WEYAKWIN, Saskatchewan Public Safety Agency, Weyakwin Response Area, #1 Weyakwin Drive					
Due to COVID-19, ON-LINE VIEWING ONLY. NO ON-SITE VIEWING. Contact: Dave Young 306-663-5620, dave.young@gov.sk.ca					
No Bid	* 12-665	Barbeque Coleman G52204 , , , , , Beyond Repair	G522041002000737	SPSA	6 2011-521
No Bid	* 12-666	Counter Top Oven Kitchen Aid Model KC0223QG , , , , , Broken Repairable	WF42403069	SPSA	5 2011-521
No Bid	* 12-677	Deep Freeze Gibson white, 61" W X 27 1/2" D X 34" H , , , , , Beyond Repair		SPSA	1 2011-523
No Bid	* 12-678	Dishwasher Maytag Model MDB6650AWB 24", black , , , , , Broken Repairable	27907300ZU	SPSA	2 2011-523
No Bid	* 12-679	Dryer Maytag 28", propane-powered , , , , , Beyond Repair		SPSA	5 2011-523
40.00	* 12-671	Generator United Power, GG1300 max output 1300 W , , , , , Broken Repairable	9030344	SPSA	3 2011-522
5.00	* 12-681	Ladders Lot of 2 Lite Products Inc. 6', aluminium - type 2 , , , , , Beyond Repair		SPSA	4 2011-523

No Bid	* 12-674	Orbital Sander	Black & Decker	electric , , , , ,	Beyond Repair		SPSA	6	2011-522
No Bid	* 12-682	Parts Cleaner	Metal	30" X 20" , , , , ,	Beyond Repair		SPSA	3	2011-523
No Bid	* 12-676	Propane Stove	Enterprise	30", white , , , , ,	Beyond Repair		SPSA	5	2011-522
No Bid	* 12-683	Propane/Electric Mini Fridge	Dometic	21 1/2" , , , , ,	Broken Repairable		SPSA	5	2011-524
No Bid	* 12-684	Propane/Electric Mini Fridge	Dometic - Freedom	21 1/2", broken door , , , , ,	Beyond Repair		SPSA	3	2011-524
No Bid	* 12-685	Propane/Electric Mini Fridge	Dometic - RM2410	21 1/2" , , , , ,	Broken Repairable		SPSA	4	2011-524
No Bid	* 12-670	Water Cooler	Greenway	Model GWD200W-1 , , , , ,	Broken Repairable	O103053011016	SPSA	4	2011-521

WHITE SPRUCE - ORCADIA, Central Services, Property Management, 12.2 km NW of Yorkton

Due to COVID-19, ON-LINE VIEWING ONLY. Contact Mark Bigoraj 306-786-5871, mark.bigoraj2@gov.sk.ca, or Val Yaholnitsky 306-786-5747, or at val.yaholnitsky@gov.sk.ca

No Bid	* 12-732	Trailer 7 Make is unknown 3 Bedroom, Trailer is 45 feet X 20 feet outside measurements and 10 feet X 6 feet porch, this is a double wide trailer, no wheels or hitch is on the unit, trailer consists of wood frame structure and the roof is metal panels, exterior windows are single glazed and aluminum framed, exterior doors are wood, interior floors consist of vinyl tile and the walls are wood paneling and plywood, ceilings are finished with plywood also and spline ceiling tiles, all finishes are dated and worn, appliances and furnace date back to 1962 and have not been operational for years, the floor tiles in the pantry/kitchen contain asbestos along with the tar sealant on the roof systems, asbestos report is available. Prior to successful bidder pickup, all furniture and appliances, shown in pictures, will be removed; furnace to remain. Water and sewer disconnected under unit. All bolting to wooded frame will be completed and trailer ready for pickup. Pickup to be May 1st or earlier, if agreed upon by facility operator. , , , , , Poor	Unknown	SBP	0870-39	2009-416
--------	----------	---	---------	-----	---------	----------

5.00 * 12-733	<p>Trailer 9 Make is unknown 3 Bedroom, Trailer is 45 feet X 20 feet outside measurements and 10 feet X 6 feet porch, this is a double wide trailer, no wheels or hitch is on the unit, trailer consists of wood frame structure and the roof is metal panels, exterior windows are single glazed and aluminum framed, exterior doors are wood, interior floors consist of vinyl tile and the walls are wood paneling and plywood, ceilings are finished with plywood also and spline ceiling tiles, all finishes are dated and worn, appliances and furnace date back to 1962 and have not been operational for years, the floor tiles in the pantry/kitchen contain asbestos along with the tar sealant on the roof systems, asbestos report is available. Prior to successful bidder pickup, all furniture and appliances, shown in pictures, will be removed; furnace to remain. Water and sewer disconnected under unit. All bolting to wooded frame will be completed and trailer ready for pickup. Pickup to be May 1st or earlier, if agreed upon by facility operator. , , , , , Poor</p>	Unknown	SBP	0870-40	2009-417
---------------	--	---------	-----	---------	----------

No Bid	* 12-734	<p>Trailer 11 Make is unknown 3 Bedroom, Trailer is 45 ft X 20 ft outside measurements and 10 ft X 6 ft porch, this is a double wide trailer, no wheels or hitch is on the unit, trailer consists of wood frame structure and the roof is metal panels, exterior windows are single glazed and aluminum framed, exterior doors are wood, interior floors consist of vinyl tile and the walls are wood paneling and plywood, ceilings are finished with plywood also and spline ceiling tiles, all finishes are dated and worn, appliances and furnace date back to 1962 and have not been operational for years, the floor tiles in the pantry/kitchen contain asbestos along with the tar sealant on the roof systems, asbestos report is available, trailer has a range. Prior to successful bidder pickup, all furniture and appliances, shown in pictures, will be removed; furnace to remain. Water and sewer disconnected under unit. All bolting to wooded frame will be completed and trailer ready for pickup. Pickup to be May 1st or earlier, if agreed upon by facility operator. , , , , , Poor</p>	Unknown	SBP	0870-40	2009-439
--------	----------	--	---------	-----	---------	----------

475.00 * 12-735	Trailer 12 Make is unknown 3 Bedroom, Trailer is 45 ft X 20 ft outside measurements and 10 ft X 6 ft porch, this is a double wide trailer, no wheels or hitch is on the unit, trailer consists of wood frame structure and the roof is metal panels, exterior windows are single glazed and aluminum framed, exterior doors are wood, interior floors consist of vinyl tile and the walls are wood paneling and plywood, ceilings are finished with plywood also and spline ceiling tiles, all finishes are dated and worn, appliances and furnace date back to 1962 and have not been operational for years, the floor tiles in the pantry/kitchen contain asbestos along with the tar sealant on the roof systems, asbestos report is available. Prior to successful bidder pickup, all furniture and appliances, shown in pictures, will be removed; furnace to remain. Water and sewer disconnected under unit. All bolting to wooded frame will be completed and trailer ready for pickup. Pickup to be May 1st or earlier, if agreed upon by facility operator. , , , , , Poor	Unknown	SBP	0870-41	2009-440
-----------------	--	---------	-----	---------	----------

WHITE SPRUCE - ORCADIA, Central Services, Property Management, NE-35-TP26-R5-W2ND.

Due to COVID-19, ON-LINE VIEWING ONLY. Contact Mark Bigoraj 306-786-5871, mark.bigoraj2@gov.sk.ca

No Bid	* 11-537	Cart wooden , , , , , Poor		CS Prop 4 Man	2006-199
No Bid	* 11-503	Plug dividers 1 & 2 Lot of 24 10 foot lengths Operational , , , , , Poor		CS Prop 52 Man	2006-197
No Bid	* 11-526	Projector THE FIVE "o" EIGHTY EIGHT Operational , , , , , Poor		CS Prop 31 Man	2006-198
No Bid	* 11-535	Bench wooden -12' , , , , , Poor		CS Prop 2 Man	2006-199
1.00	* 11-515	Cart Blane & Brothers Operational , , , , , Poor		CS Prop 26 Man	2006-198
5.00	* 11-540	Chairs Set of 4 metal, fabric, stackable , , , , , Poor		CS Prop 10 Man	2006-199

5.00 *	11-541	Chairs Set of 3 metal, fabric, stackable , , , , ,	Poor	CS Prop 12	2006-199
No Bid	* 11-542	Chairs Set of 4 metal, plastic, stackable , , , , ,	Poor	CS Prop 11	2006-199
1.00 *	11-543	Chairs Set of 8 metal, plastic, stackable , , , , ,	Poor	CS Prop 13	2006-199
No Bid	* 11-544	Chairs Set of 3 metal, plastic, stackable , , , , ,	Poor	CS Prop 14	2006-199
No Bid	* 11-548	Computer Chair plastic, fabric Missing arm rest , , , , ,	Poor	CS Prop 7	2006-199
No Bid	* 11-549	Computer Chair Year Unknown , Model Unknown , , , , ,	Poor	CS Prop 5	2006-199
No Bid	* 11-550	Computer Chair Year Unknown , Model Unknown , , , , ,	Poor	CS Prop 6	2006-199
No Bid	* 11-551	Computer Chair Year Unknown , Model Unknown , , , , ,	Poor	CS Prop 18	2006-199
No Bid	* 11-552	Desk Year Unknown , Model Unknown , , , , ,	Poor	CS Prop 19	2006-199
5.51 *	11-517	Lamps Lot of 5 Year Unknown , Model Unknown Operational , , , , ,	Poor	CS Prop 25	2006-198
No Bid	* 11-518	Lamps Lot of 2 Year Unknown , Model Unknown Operational , , , , ,	Poor	CS Prop 24	2006-198
5.51 *	11-519	Lamps Lot of 5 Year Unknown , Model Unknown Operational , , , , ,	Poor	CS Prop 23	2006-198
5.51 *	11-520	Lamps Lot of 5 Year Unknown , Model Unknown Operational , , , , ,	Poor	CS Prop 22	2006-198
No Bid	* 11-521	Lights Lot of 4 Year Unknown , Model Unknown Operational - 4 foot fluorescent lights , , , , ,	Poor	CS Prop 27	2006-198
1.00 *	11-524	Organizer Year Unknown , Model Unknown Operational , , , , ,	Poor	CS Prop 30	2006-198
No Bid	* 11-511	Table set 5 60" X 30" Operational , , , , ,	Poor	CS Prop 45	2006-197

No Bid	* 11-506	Table set 6	47.5" X 29.2"	Operational , , , , ,	Poor	CS Prop	46	2006-197
						Man		
No Bid	* 11-508	Table set 7	48" round	Operational , , , , ,	Poor	CS Prop	47	2006-197
						Man		
No Bid	* 11-507	Table set 8	47.5" X 29.2"	Operational , , , , ,	Poor	CS Prop	48	2006-197
						Man		
No Bid	* 11-509	Table set 9	48" X 30"	Operational , , , , ,	Poor	CS Prop	49	2006-197
						Man		
YORKTON, Highways, Fleet Services, 245 York Road East.								
Due to COVID-19, ON-LINE VIEWING ONLY. NO ON-SITE VIEWING. Contact Brian Perih 306-786-1651, brian.perih@gov.sk.ca								
No Bid	* 12-509	FORD AM/FM Radio	2019 Ford, Model Ford RU-9493P-B	part		130388 HI	1	2009-401
		number HC3T-18K810-AK , , , , ,		New - Unused				