

SALE SUMMARY LIST

PLEASE NOTE: Every effort has been made to accurately describe items and their condition; however, additional problems may exist, items may not be complete or exactly as described. Bidders are deemed to have reviewed the Terms and Conditions on bid forms and relied entirely on their own inspection and evaluation prior to bidding. Vehicles and equipment are sold "AS IS, WHERE IS", there is no implied or express warranty.

Visit www.SaskSurplus.ca for pictures and link to download Bid Form.

- Items identified with * have been on a previous sale and will be listed first on www.SaskSurplus.ca web site.
- SaskBuilds and Procurement, SaskSurplus, reserves right to have unadvertised minimum selling prices on items.

It is the Bidder's responsibility to review the terms and conditions of sale on the Offer to Purchase, Bid Form.

Bid Forms are available in each item slide at the left-hand side at the bottom where it says "Bid Form", from www.SaskSurplus.ca or from the SaskSurplus Sales Lot, 500 McLeod Street, Regina, SK.

Bid Forms can be submitted in the following ways:

- by deposit in the bid box at the SaskSurplus Sales Lot,
- by fax to 306-787-2092; by phone 306-787-2062 or 306-798-3300,
- by email to sasksurplus@gov.sk.ca, or
- by mail, addressed to: Ministry of SaskBuilds and Procurement, SaskSurplus, 500 McLeod Street, Regina, SK S4N 4Y1.

(If mailing your bid, please allow sufficient time for bid to be received.)

- Bids received after close date and time cannot be accepted.

MT = (Ministry Transfer) This means that the item has been claimed by another ministry and automatically transferred to the ministry.

WD = (Withdrawn) This can happen if the item was requested to be removed by the seller.

No Bid = Items that did not receive any bids are normally carried forward to the next sale or may be withdrawn.

Item #	Description	Kms	Min Price	Serial Number
REGINA, SaskBuilds and Procurement, SaskSurplus Sales Lot, 500 McLeod Street - Vehicles				
Contact SaskSurplus 306-787-2062 or 306-798-3306, sasksurplus@gov.sk.ca				
1,230.00 * 9-001	Car 2007 CHEVROLET Impala FWD 3.5L, V6, gas auto A/C, tilt, cruise, AM/FM/CD player, power mirrors/locks/windows/trunk release/left front seat, keyless entry-2 fobs, 2 keys, grey, TOW ONLY – This vehicle has a VERY UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Body Integrity Inspection and a Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in "As is, where is" condition., 252,275 km, , KNOWN PROBLEMS and OBSERVATIONS: Both rockers' panels rusted out. Grille chrome poor, hood scratches/chips, both bumpers cracked/road rash, rear bumper paint poor/scratches, left front fender scratches/road rash, left rear fender rust, right front fender rust, rocker panels rusted out, left side doors rust at bottom, left front door loose at hinge or pins, right front doors paint chips, right rear door paint chips/rust inside bottom, roof rust/scratches, trunk lid rust/scratches, no first aid kit/fire extinguisher, windshield chips, missing 4-wheel covers, poor battery, minor exterior damage.> , As is, where is	252,275 km	\$1,229	2G1WB58K979408397
1,674.00 10-010	Car 2008 CHEVROLET Impala LS FWD 3.5L, V6, gas auto A/C, tilt, cruise, AM/FM/CD player, power mirrors/locks/windows/left front seat/trunk release, keyless entry-2 keys, 2 fobs , grey, TOW ONLY – This vehicle has a VERY UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Body Integrity Inspection and a Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in "As is, where is" condition., 183,874 km, , KNOWN PROBLEMS and OBSERVATIONS: Alignment needed, both rocker panels, plate light. Grille missing badge, hood road rash/scratches/paint cracked, front bumper scratches/cracked/dented, rear bumper scratches, left front fender rust/scratches, right side fenders scratches/rust, both rocker panels rusted, left side doors rusted inside bottom, trunk lid rusted/dents/scratches, no first aid kit/fire extinguisher, windshield chips, poor battery, minor exterior damage.> , As is, where is	183,874 km	\$1,585	2G1WB58K681359644

Item #	Description	Kms	Min Price	Serial Number
3,178.08 10-011	<p>Car 2013 CHEVROLET Impala LS FWD 3.6L, V6, gas auto A/C, tilt, cruise, AM/FM/CD player, power mirrors/locks/windows/left front seat/trunk release, keyless entry-1 fob, 2 keys , white, TOW ONLY –</p> <p>This vehicle has a VERY UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Body Integrity Inspection and a Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in “As is, where is” condition., 239,667 km, ,</p> <p>KNOWN PROBLEMS and OBSERVATIONS: Engine has no power, transmission shifts hard, steering rack leaking, power steering pump leaking, rear struts, alignment needed, rocker panels.</p> <p>Grille lower broken, hood rust/chips, right rear fender light scratches, rocker panels rusted (PMVI), left side doors both rusted inside bottom, roof rusted, no first aid kit/fire extinguisher, windshield small chips, poor battery, minor exterior damage.>, As is, where is</p>	239,667 km	\$1,725	2G1WA5E30D1168909
1,549.00 10-012	<p>Car 2013 CHEVROLET Impala LS FWD 3.6L, V6, gas auto A/C, tilt, cruise, AM/FM/CD player, power locks/windows/mirrors/left front seat/trunk release, keyless entry-2 fobs, 2 keys , grey, TOW ONLY –</p> <p>This vehicle has a VERY UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Body Integrity Inspection and a Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in “As is, where is” condition., 180,049 km, ,</p> <p>KNOWN PROBLEMS and OBSERVATIONS: Power steering rack leaking, both boots not attached, left rear caliper, park brake sticking, both rear door inside handles and windshields switches disconnected, right head light assembly, both rocker panels rusted out.</p> <p>Hood small dent, rear bumper scratches/dent, left rear fender scratches, right rear fender scratches/dent, both rocker panels rusted out, left front door rust, left rear door rust inside bottom, right front door rust/chips/scratches, right rear door chips/scratches, missing molding on inside of left and right rear doors, rear door locks and windows do not work, rear doors don’t open from inside, roof rust/scratches, trunk lid slight dents, no first aid kit/fire extinguishers, windshield chips, left and right mirrors housing broke, right head light fogged, poor battery, minor exterior damage.>, As is, where is</p>	180,049 km	\$1,122	2G1WA5E38D1253402

Item #	Description	Kms	Min Price	Serial Number
8,620.00 10-001	<p>Car 2017 CHEVROLET Malibu Hybrid FWD 1.8L, inline 4, gas auto A/C, tilt cruise, AM/FM, power mirrors/locks/windows/left front seat, keyless entry-2 key fobs , silver, This vehicle has a PASSED SGI Inspection. This vehicle can be driven off premises with an SGI Permit or a registered, active license plate attached. Purchaser assumes full responsibility for repairs. This vehicle is sold in "As is, where is" condition., 185,661 km, , KNOWN PROBLEMS and OBSERVATIONS:</p> <p>Needs exhaust heat exchanger, heater hose leaking, both bumpers' scratches, left side fenders scratches, both dog legs road rash, both rocker panels road rash/very rusty, spare tire/wheel wrench/jack replaced by sealant and compressor kit, kit may not be complete, no first aid kit/fire extinguishers, windshield chips, left front seat stained, left rear seat stained, rear seat release cables are hanging loose in trunk, poor battery, minor exterior damage.>, As</p>	185,661 km	\$7,345	1G1ZJ5SU3HF220087
2,178.08 10-002	<p>Car 2014 CHEVROLET Malibu LS FWD 2.5L, inline 4, gas auto A/C, tilt, cruise, AM/FM/CD player, power mirrors/locks/windows, both front seats partial power, keyless entry-2 key fobs km , grey, TOW ONLY –</p> <p>This vehicle has a VERY UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Body Integrity Inspection and a Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in "As is, where is" condition., 234,955 km, , KNOWN PROBLEMS and OBSERVATIONS: Left front wheel bearing noise, stone chips in windshield, right rocker panel damaged, left rear rocker damage. Hood chips/scratches, both bumpers' chips/scratches, right front fender scratches/road rash/dented, right rear fender scratches/dents, right dog leg damaged, both rocker panels damaged, right side doors road rash/chips/scratches, roof rust above windshield, small rust spots, trunk lid scratches, no first aid kit/fire extinguisher, windshield chips, right front seat stained, rear seat stained, poor battery, minor exterior damage.>, As is, where is</p>	234,955 km	\$785	1G11A5SL7EF204071

Item #	Description	Kms	Min Price	Serial Number
1,726.00 10-013	<p>SUV 2015 CHEVROLET Equinox 4WD 2.4L, inline 4, gas auto A/C, tilt, cruise, AM/FM/Bluetooth, power locks/windows/mirrors, keyless entry-2 key fobs , white, TOW ONLY –</p> <p>This vehicle has a VERY UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Body Integrity Inspection and a Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in "As is, where is" condition., 240,175 km, ,</p> <p>KNOWN PROBLEMS and OBSERVATIONS: Rear shocks, TPMS sensor, both rear rockers rusted through.</p> <p>Grille broken, hood road rash/scratches, left side fenders road rash/rust, right side fenders scratches/road rash/rust, rocker panels rusted through, left front door rust inside lower/chips, left rear door chips, right rear door stained, roof stain/dents, tailgate rusted/dents/glass scratched, no first aid kit/fire extinguisher, windshield chips, poor batty,</p>	240,175 km	\$1,325	2GNFLEEK2F6317181
3,965.00 10-022	<p>SUV 2014 CHEVROLET Equinox LS 4WD 2.4L, inline 4, gas auto A/C, tilt, cruise, AM/FM, power mirrors/locks/windows/left front seat, keyless entry-2 key fobs 5 passenger, grey, TOW ONLY km –</p> <p>This vehicle has an UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in "As is, where is" condition., 294,939 km, ,</p> <p>KNOWN PROBLEMS and OBSERVATIONS: Drive belt, radiator support mounts missing, alignment needed.</p> <p>Hood chips/dents, both bumpers' chips/scratches, left side fender road rash, right rear fender rust, all door rust inside bottom, right front door window trim dents, roof scratches, tailgate rust/glass scratched, no first aid kit/fire extinguisher, windshield chips, headlights fogged, poor battery, minor exterior damage.>, As is, where is</p>	294,939 km	\$1,258	2GNFLEEK8E6234000

Item #	Description	Kms	Min Price	Serial Number
1,598.00 10-003	<p>SUV 2015 CHEVROLET Equinox LS AWD 2.4L, inline 4, gas auto A/C, tilt, cruise, AM/FM, power 241,898 mirrors/windows/locks/left front seat, keyless entry-2 key fobs 5 passengers, white, TOW km ONLY –</p> <p>This vehicle has a VERY UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Body Integrity Inspection and a Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in "As is, where is" condition., 241,898 km, ,</p> <p>KNOWN PROBLEMS and OBSERVATIONS: Drive belt frayed, right lower ball joint, headlights foggy, both rocker panels rusted.</p> <p>Hood road rash, both bumpers' chips/scratches, left side fenders road rash, left front fender lower molding loose, right front fender chips, rear right fender road rash, both rocker panels rusted, left front door rust inside bottom, left rear door chips, right front door rust inside bottom, roof small chips, tailgate rusted/paint poor, no first aid kit/fire extinguisher, windshield chips, poor battery, minor exterior damage.>, As is, where is</p>		\$1,322	2GNFLEEK3F6316105
1,793.00 10-004	<p>SUV 2015 CHEVROLET Equinox LS AWD 2.4L, inline 4, gas auto A/C, tilt, cruise, AM/FM, power 284,393 locks/windows/left front seat, keyless entry-2 key fobs 5 passengers, white, TOW ONLY – km</p> <p>This vehicle has an UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in "As is, where is" condition., 284,393 km, ,</p> <p>KNOWN PROBLEMS and OBSERVATIONS: Known problems and observations are listed below.</p> <p>Left rear lateral arm, alignment needed.</p> <p>Grille lower broke, hood road rash, rear bumper chips/dents/scratches/broke, left front fender road rash, left rear fender road rash/rust, right rear fender road rash, both dog legs rusted, both rocker panels rusted, left side doors rust inside bottom/road rash, right front door rust inside bottom, right rear door road rash, tailgate rust/glass scratched, no first aid kit/fire extinguisher, windshield chips, poor battery, minor exterior damage.>, As is, where is</p>		\$1,156	2GNFLEEK5F6315473

Item #	Description	Kms	Min Price	Serial Number
5,641.50 10-005	<p>SUV 2014 CHEVROLET Tahoe 4WD 5.3L, V8, gas auto A/C, tilt, cruise, AM/FM/CD player, rear HVAC, power mirrors/locks/windows/front seat, keyless entry-1 fob, 3 keys front tow hooks, side steps, mud flaps, hitch, trailer wiring, 5 passengers, white, TOW ONLY –</p> <p>This vehicle has an UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in "As is, where is" condition., 320,456 km, , KNOWN PROBLEMS and OBSERVATIONS: left outer tie rod, front tires, alignment needed, right-low beam, washer nozzle, passenger mirror.</p> <p>Hood road rash/scratches, both bumpers' chips/scratches, left side fenders rusted, right side fenders rust, left rear door chips, roof small rust spot, 9 holes sealed in roof, tailgate glass scratched, no first aid kit/fire extinguisher, windshield chips, right mirror housing and glass broke, left front seat cushion sagging/soiled, holes in head liner, hole drilled in dash, B-pillar trim modified, poor battery, minor exterior damage.>, As is, where is</p>	320,456 km	\$5,562	1GNSK2E06ER184653
1,024.00 10-023	<p>SUV 2008 FORD Escape Hybrid 4WD 2.3L, inline 4, gas auto A/C, tilt, cruise, AM/FM/CD player, power mirrors/locks/windows/left front seat, keyless entry-2 key fobs grille inserts, driving lights, 110V plug-in in rear bumper, 5 passenger, white, TOW ONLY –</p> <p>This vehicle has a VERY UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Body Integrity Inspection and a Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in "As is, where is" condition., 269,624 km, , KNOWN PROBLEMS and OBSERVATIONS: TPMS light on, exhaust leak/damaged, left inner and outer tie rod play, left front hub bearing loose, 4 tires low/damaged tread/failed, spare tire loose, loose front-end components/hub, rear wiper torn, rocker panels damaged, sun visors loose both sides, middle seat belt non operational.</p> <p>Hood road rash/rust, both bumpers chips, left front fender chips, left rear fender rusted, right rear fender rust/road rash, both rocker panels damaged, left side doors rusted at bottom/chips, right side doors rusted inside bottom, roof chips, tailgate rusted, no first aid kit/fire extinguisher, windshield chips, left front cushion sagging, rear seat stained, poor battery, minor exterior damage.>, As is, where is</p>	269,624 km	\$845	1FMCU59H78KE17926

Item #	Description	Kms	Min Price	Serial Number
1,670.00 10-015	<p>SUV 2008 JEEP Commander Sport 4WD 3.7L, V6, gas auto A/C, tilt, cruise, AM/FM/CD player, power heated mirrors, power locks/windows/left front seat, keyless entry-2 key fobs roof rails, hitch, trailer wiring, driving lights, 7 passenger, white, TOW ONLY –</p> <p>This vehicle has a VERY UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Body Integrity Inspection and a Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in "As is, where is" condition., 197,370 km, ,</p> <p>KNOWN PROBLEMS and OBSERVATIONS: Both lower ball joints, front drive shaft, anti-freeze low, wheel alignment-parts required, needs oil change, tires noisy, air bag light on, both rear side impact rails damaged, head lights foggy, both rocker panels rusted out.</p> <p>Both bumpers' chips/scratches, left front fender chips/rusted, left rear fender chips, right front fender rusted, all dog legs rusted, rocker panels rusted through, left side doors road rash/rusted, right front door rusted, roof rust near windshield, tailgate rusted, no first aid kit/fire extinguisher, windshield chips, roof rails weathered, poor battery, minor exterior damage.>, As is, where is</p>	197,370 km	\$1,555	1J8HG48KX8C226660
4,276.60 10-028	<p>Truck 2014 CHEVROLET Silverado 1500 4WD, crew cab, 5'9" box 4.3L, V8, gas auto A/C, tilt, cruise, AM/FM, power mirrors/locks/windows, keyless entry-2 fobs, 2 keys front wigwags, front tow hooks, side steps, mud flaps, hitch, trailer wiring, OEM trailer brakes, headache rack with beacons and wigwags, has a back seat, grille inserts, blue, TOW ONLY –</p> <p>This vehicle has an UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in "As is, where is" condition., 308,418 km, ,</p> <p>KNOWN PROBLEMS and OBSERVATIONS: Potential transmission slipping and main seal leaking, left inner tie rod, alignment, inside of box scratches, hood road rash/scratches, left front fender road rash/dents, left rear fender rust/scratches/dents, right front fender road rash/scratches, right rear fender road rash/rust/dents, rocker panels road rash, left doors scratches/road rash, right front door rust/chips, right rear door paint flaking/chips, roof dented, tailgate scratches/small dents, no first aid kit/fire extinguisher, windshield chips, seat worn/small hole, poor battery, minor exterior damage.>, As is, where is</p>	308,418 km	\$4,156	3GCUKPEH5EG378675

Item #	Description	Kms	Min Price	Serial Number
3,876.60 * 9-014	<p>Truck 2015 CHEVROLET Silverado 1500 4WD, crew cab, 6'6" box 4.36L, V6, gas auto A/C, tilt, 355,907 cruise, AM/FM, power mirrors/locks/windows, keyless entry-2 fobs, 2 keys grille inserts, front km tow hooks, side steps (paint poor), mudflaps, hitch, trailer wiring, OEM trailer brake, white, TOW ONLY –</p> <p>This vehicle has an UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in "As is, where is" condition., 355,907 km, , KNOWN PROBLEMS and OBSERVATIONS: Left lower ball joint loose and right lower ball joint loose, sway bar bushing loose, exhaust manifold leak-broken bolts, exhaust flex pipe damaged, service trailer brake system-light on-harness cut/removed, windshield cracked, front bumper valance push in/damaged, both plate lights non-operational, left lower marker bulb non-operational. Head lights fogged, hood road rash, front bumper road rash, rear bumper road rash/dents, left side fenders road rash/rust/dents, right front fender road rash, right rear fender rust/road rash, left front door rust, left rear door paint poor/dents, right front door rust/road rash, right rear door paint poor/road rash, roof paint chips, tailgate will not open/road rash/dents, no first aid kit/fire extinguisher, windshield cracked/chipped, front lower valance bent, A-pillar paint poor, holes drilled in box rails, paint in box poor, poor battery, minor exterior damage.>, As is, where is</p>	355,907	\$3,721	3GCUKPEH6FG369632
3,210.98 10-016	<p>Truck 2009 CHEVROLET Silverado 2500 HD 4WD, extended cab, 8' box 6.0L, V8, gas auto A/C, 251,871 tilt, cruise, AM/FM, 2 keys grille inserts, tow hooks, side steps, mud flaps, hitch, trailer wiring, km electric trailer brake, headache rack, has back seat, red, TOW ONLY –</p> <p>This vehicle has a VERY UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Body Integrity Inspection and a Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in "As is, where is" condition., 251,871 km, , KNOWN PROBLEMS and OBSERVATIONS: Check engine light on code P0449 EVAP vent solenoid, left lower ball joint, TPMS both rear sensors, battery 48/850, floor rusted out, box rusted through, fenders rusted through. Hood scratches/road rash/dents, both bumpers' bent/scratches/chrome peeling, rear bumper dented, left front fender rusted scratched, left rear fender badly dented/rusted, right front fender rusted, right rear fender holes/scratches/dents, left side doors rusted/chips/dents/scratches, right side doors chips/scratches/rust, roof rusted/chips, tailgate rusted/dented/bent/scratched, no first aid kit/fire extinguisher, windshield chips, right front seat recline lever off, front of box bent, driver door handle broken on the inside, poor battery, minor exterior damage.>, As is, where is</p>	251,871	\$2,150	1GCHK49K59E150002

Item #	Description	Kms	Min Price	Serial Number
2,178.60 10-017	<p>Truck 2013 DODGE Ram 1500 4WD, quad cab, 6'6" box 4.7L, V8, gas auto A/C, tilt, cruise, AM/FM, heated power mirrors, power locks/windows, keyless entry-2 key fobs, 1 key grille inserts, front tow hooks, mud flaps, trailer wiring, headache rack, beacon on roof, has back seat, silver, TOW ONLY –</p> <p>This vehicle has a VERY UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Body Integrity Inspection and a Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in "As is, where is" condition., 359,234 km, ,</p> <p>KNOWN PROBLEMS and OBSERVATIONS: Lower ball joints left and right loose, exhaust manifold shield not secure/loose/hanging, front sway bar bushing play, front rotors rusted out inside, rear pads low 2mm-pads/rotors, TPMS sensor, front wipers streaky, park brake doesn't hold, both rocker panels rusted through, note right running board removed.</p> <p>Hood hail, front bumper dented, left rear fender rust/scratches/dents, right rear fender road rash/scratches/rust, both rocker panels rusted through, left front door dents/scratches, roof molding taped down, tailgate dents/rust/scratches, no first aid kit/fire extinguisher, windshield chips, sidestep loose in box, poor battery, minor exterior damage.>, As is, where is</p>	359,234 km	\$1,899	1C6RR7FP5DS578977
5,290.00 10-029	<p>Truck 2014 DODGE Ram 1500 4WD, crew cab, 5'6" box 5.7L, V8, gas auto A/C, tilt, cruise, AM/FM, power heated side mirrors/locks/windows, keyless entry-2 fobs, 1 key front tow hooks, grille inserts, side steps, hitch, trailer wiring, OEM trailer brakes, has a back seat, white, TOW ONLY –</p> <p>This vehicle has an UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in "As is, where is" condition., 239,290km, ,</p> <p>KNOWN PROBLEMS and OBSERVATIONS: Both front fenders rust holes, LT park brake not releasing, right reverse light, missing middle rear seatbelt buckle, both rear doors missing trim, both b pillars trim modified, headliner ripped, grille road rash, hood paint poor, front bumper rusted/scratched, rear bumper chips, left front fender badly rusted, left rear fender small rust spots, right front fender badly rusted, right rear fender rusted, both rocker panel rusted, left front door rusted at bottom, right rear door rusted at edge, roof small rust spots, tailgate dents/rust, no first aid kit/fire extinguisher, windshield chips, poor battery, minor exterior damage.>, As is, where is</p>	239,290km	\$4,982	1C6RR7KT8ES178920

Item #	Description	Kms	Min Price	Serial Number
3,582.00 10-018	<p>Truck 2012 DODGE/RAM 1500 4WD, quad cab, 6'4" box 4.7L, V8, gas auto A/C, tilt, cruise, AM/FM/CD player, power heated mirrors, power windows/locks, keyless entry-2 fobs, 2 keys km front tow hooks, grille inserts, side steps, mud flaps, hitch, trailer wiring, has back seat, blue, TOW ONLY –</p> <p>This vehicle has a VERY UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Body Integrity Inspection and a Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in "As is, where is" condition., 250,198 km, ,</p> <p>KNOWN PROBLEMS and OBSERVATIONS: Rear pads/rotors, alignment needed, park brake not holding, rocker panels. Grille road rash, hood scratches/chips, front bumper road rash, rear bumper rusted/ scraped, left front fender rusted scratches, left rear fender dent/scratches, right side fenders rust/scratches, both rocker panels rusted, left side doors rusted/scratched, right side doors dents, roof rust/dents, five holes sealed, tailgate rusted, wheel wrench missing, no first aid kit/fire extinguisher, windshield chips, left front seat worn/sagging, both cab corners rusted, interior soiled, bad odor, poor battery, minor exterior damage.>, As is, where is</p>	250,198	\$2,170	1C6RD7FP6CS218405
3,278.08 10-024	<p>Truck 2013 DODGE/RAM 1500 4WD, extended cab, 6'3" box 4.7L, V8, gas auto A/C, tilt, cruise, AM/FM, power heated mirrors, power windows/locks/left front seat, keyless entry-2 km key fobs, 2 other keys front tow hooks, side steps, mud flaps, hitch, trailer wiring, OEM trailer brakes, Bakflip Fold tonneau cover, sliding rear cab window, has a back seat, white, TOW ONLY –</p> <p>This vehicle has a VERY UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Body Integrity Inspection and a Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in "As is, where is" condition., 276,397 km, ,</p> <p>KNOWN PROBLEMS and OBSERVATIONS: Front sway bar bushing loose, rear sway bar bushing loose, front rotors rusted out, brake lines rusted in sections, 4 tires low tread, both rocker panels, both fenders, sun visor clip broken. Hood paint bubbling, left side fender rusted, right front fender scratches/rusted, right rear fender dents/rusted, both rocker panels rusted, left side doors dent/rusted, right side doors chips/rusted, no first aid kit/fire extinguisher, windshield chips, left front seat worn/ sagging, left sun visor broken, tonneau cover will not open, poor battery, minor exterior damage.>, As is, where is</p>	276,397	\$1,999	1C6RR7GP1DS556067

Item #	Description	Kms	Min Price	Serial Number
2,844.00 10-006	<p>Truck 2013 DODGE/RAM 1500 4WD, quad cab, 5'6" box 4.7L, V8, gas auto A/C, tilt, cruise, AM/FM, power heated mirrors, power locks/windows, keyless entry-2 fob keys, 2 tonneau keys, 1 fob will not unlock doors grille inserts, side steps, hitch, trailer wiring, Roll-N-Lock soft tonneau-lock and latch non-operational, has back seat, white, TOW ONLY –</p> <p>This vehicle has a VERY UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Body Integrity Inspection and a Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in "As is, where is" condition., 269,644 km, ,</p> <p>KNOWN PROBLEMS and OBSERVATIONS: Both rocker panels. Hood paint cracking, left front fender rust, left rear fender road rash, right rear fender road rash/rust, both rocker panels rusted, 6 holes sealed in roof, tailgate rusted, no first aid kit/fire extinguisher, windshield chips, right front wheel flare broken, moisture in right front headlight, both cab corners rusted, tonneau lock and latch non-operational, poor battery, minor exterior damage.>, As is, where is</p>	269,644 km	\$2,235	1C6RR7FPXDS555226
2,676.60 10-019	<p>Truck 2014 DODGE/RAM 2500 4WD, crew cab, 6'4" box 5.7L, V8, gas auto A/C, tilt, cruise, AM/FM, power heated mirrors, power locks/windows, keyless entry-2 key fobs front tow hooks, side steps, mud flaps, hitch, trailer wiring, OEM trailer brake, box liner headache rack, has back seat, white, TOW ONLY –</p> <p>This vehicle has a VERY UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Body Integrity Inspection and a Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in "As is, where is" condition., 246,312 km, ,</p> <p>KNOWN PROBLEMS and OBSERVATIONS: Check engine light on codes: P0113 intake air sensor, P0562 low voltage, P0870 OD hydraulic pressure test, P0933 hydraulic pressure sensor range/performance, front and rear crank seals leaking, left upper and lower ball joint, rear U joint on rear drive shaft seized, front sway bar links, left front wheel joint, left front wheel bearing, wheel joints seized, drive belt, wiper blades, both front fenders rusted out, rear middle seat belt. Transmission flaring when accelerating from a stop, fluid full of metal need transmission, hood scratches/chips, both bumpers' bent/rusted/scratches, left front fender rusted through, left rear fender dent/scratches, right front fender rusted through, right rear fender dents/scratches, both rocker panels road rash/rust, left rear door dents, roof rust spots/scratches, 2 holes in roof sealed, tailgate chips/molding loose/dents, no first aid kit/fire extinguisher, windshield chips, missing front valance, front of box bent, side steps chrome peeling, holes in box rails, headliner holes, B-pillar inside trim modified, holes drilled in dash, poor battery, minor exterior damage.>, As is, where is</p>	246,312 km	\$900	3C6TR5CT4EG193026

Item #	Description	Kms	Min Price	Serial Number
No Bid 10-007	<p>Truck 2014 DODGE/RAM 2500 4WD, crew cab, 6'4" box 5.7L, V8, gas auto A/C, tilt, cruise, AM/FM, power heated mirrors, power locks/windows, keyless entry-1 key fob front tow hooks, grille inserts, mud flaps, side steps, hitch, trailer wiring, trailer wiring, OEM trailer brakes, has back seat, brown, TOW ONLY –</p> <p>This vehicle has an UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in "As is, where is" condition., 271,195 km, , KNOWN PROBLEMS and OBSERVATIONS: Check engine light on codes (P0456 EVAP small leaks, P0463 fuel level sensor, V0159 lost com. parking, V1403 fuel level), all four ball joints, U-joints, manifold leaks, gas gauge non operational.</p> <p>Hood stone bruises/chips/scratches, front bumper rust spots, rear bumper rust/paint poor, left side fenders road rash/scratches/dents, right side fenders rust/scratches/dents, rocker panels road rash/rust, left side doors dents/scratches, right front door chips/scratches, right rear door rust/chips/scratches, roof chips/rust/scratches, tailgate rust/dent/scratches/guard bent, no first aid kit/fire extinguisher, windshield chips, inside box scratched, vehicle has bush scratches, poor battery, minor exterior damage.> , As is, where is</p>	271,195 km	\$6,580	3C6TR5CT4EG21211

Item #	Description	Kms	Min Price	Serial Number
3,276.60 10-025	<p>Truck 2015 DODGE/RAM 2500 4WD, crew cab, 6'3" box 5.7L, V8, gas auto A/C, tilt, cruise, 229,953 aftermarket AM/FM/CD player, power heated mirrors, power locks/ windows, keyless entry-1 km key fob, 1 other key front tow hooks, grille inserts, side steps, mud flaps, hitch, trailer wiring, OEM trailer brakes, has back seat, white, TOW ONLY –</p> <p>This vehicle has a VERY UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Body Integrity Inspection and a Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in "As is, where is" condition., 229,953 km, ,</p> <p>KNOWN PROBLEMS and OBSERVATIONS: Check engine light on codes: (C003A right rear speed, B0028:13 right seat deployment, B0020:13 left seat, P0734 gear ratio 4x4, P0869 line pressure high), TPMS on, ABS on, misfire, transmission not working, 4WD not working, all 4 ball joints, front shocks, exhaust manifold leaks, alignment needed, foggy head lamps, right brake light, right rear signal, no plate light, no washer, right rear door, front fenders, driver seat ripped.</p> <p>Transmission fluid full of metal, bad solenoid, hood road rash/dents/scratches, front bumper scratched, rear bumper rusted/dented, right front fender rust/scratches/flap loose, rocker panels road rash, left side doors dents, right rear door missing inside trim/rusted-hole, roof small rust spots, two holes in roof sealed, tailgate bent/rust/scratched, missing spare tire/wheel wrench, jack loose under back seat, no first aid kit/fire extinguisher, windshield chips, left front seat worn cushion/ripped, left front seat back worn frame visible, holes in floor of box, inside of box bent/scratched, holes in head liner, inside trim on B-pillar modified, holes drilled in box rails, holes above doors in roof frame, behind right front seat door on floor storage loose, front console modified, missing jump seat, poor battery, minor exterior damage.>, As is, where is</p>	229,953	\$2,600	3C6TR5CT0FG544760

Item #	Description	Kms	Min Price	Serial Number
No Bid * 9-016	<p>Truck 2015 DODGE/RAM 2500 4WD, crew cab, 6'5" box 5.7L, V8, gas auto A/C, tilt, cruise, AM/FM, power heated mirrors, power locks/windows, keyless entry-1 key fob front tow hooks, grille inserts, mud flaps, sidestep, hitch, trailer wiring, OEM trailer brake, headache rack with beacon, front and rear wig wags-operational, has back seat, white, TOW ONLY – This vehicle has an UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in "As is, where is" condition., 291,726 km, , KNOWN PROBLEMS and OBSERVATIONS: Right headlight has water and loose. Hood chips, both bumpers chips/scratches, left rear fender paint worn/road rash/chips/dents/rust, right rear fender dents/scratches, both rocker panels road rash, roof black sealant on roof, one hole sealed antenna, tailgate hard to open/chips/dents/molding loose, spare tire loose in box may not be compatible with vehicle, no first aid kit/fire extinguisher, windshield chips, small holes in left front seat, front of box bent, box rusted badly/ scratched, beacon does not work, poor battery, minor exterior damage.> , As is, where is</p>	291,726 km	\$8,767	3C6TR5CT7FG592353
No Bid * 9-017	<p>Truck 2016 DODGE/RAM 2500 4WD, crew cab, 6'5" box 5.7L, V8, gas auto A/C, tilt, cruise, AM/FM, power heated mirrors, power locks/windows, keyless entry-2 key fobs front tow hooks, grille inserts, side steps, mud flaps, hitch, trailer wiring, OEM trailer brake, box liner, headache rack, wigwags front and rear, has back seat, white, TOW ONLY – This vehicle has an UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in "As is, where is" condition., 297,316 km, , KNOWN PROBLEMS and OBSERVATIONS: TPMS light on, left headlight assembly full of water. Hood hail, front bumper scratches/chips, rear bumper dents/scratches/rust, left rear fender dents/scratches/road rash, right rear fender dents/road rash, both rocker panels road rash, left front door dents, left rear door scratches, right front door scratch, roof hail, tailgate dents/rust/bent/chips/molding loose, spare on rear left , wheel wrench/jack loose under back seat, no first aid kit/fire extinguisher, windshield chips, back seat soiled, left front floor mat worn, front of box bent, left cab corner dents, left rear seat floor storage lid broke, missing left rear wheel hub cap, left front headlights moisture, wigwags non-operational, poor battery, minor exterior damage.>, As is, where is</p>	297,316 km	\$7,791	3C6TR5CT4GG118572

Item #	Description	Kms	Min Price	Serial Number
9,657.00 * 9-021	<p>Truck 2017 DODGE/RAM 2500 4WD, crew cab, 8' box 5.7L, V8, gas auto A/C, tilt, cruise, AM/FM, power heated tow mirrors, power locks/windows, keyless entry-2 key fobs side steps, mud flaps, hitch, trailer wiring, OEM trailer brake, headache rack, has back seat, white, TOW ONLY –</p> <p>This vehicle has an UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in "As is, where is" condition., 313,884 km, , KNOWN PROBLEMS and OBSERVATIONS: Left upper and lower ball joints have play, right upper ball joint play, left and right outer tie rod play, front shock for drag link leaked out, steering shocks, left rear axle seal leak, E-brake doesn't hold, driver switch door lock/unlock switch intermittent works, 4x4 intermittent, note drive door weather strip coming off.</p> <p>Grille loose, hood chips/dents, front bumper modified cross/chips, rear bumper dents, left rear fender road rash/dents, right rear fender road rash/dents/rust, left front door chips/weather strip, left rear door dents/chips, 3 holes in roof sealed, tailgate chips/scratches/dents, no first aid kit/fire extinguisher, windshield chips, hole in right rear seat head rest, center lower dash modified, no hub caps, poor battery, minor exterior damage.>, As is, where is</p>	313,884 km	\$9,120	3C6TR5HT9HG636154
No Bid 10-031	<p>Truck 2016 DODGE/RAM Ram 2500 4WD, crew cab, 6'3" box 5.7L, V8, gas auto A/C, tilt, cruise, AM/FM, power heated mirrors/locks/windows, keyless entry, 1 key fob grille inserts, front tow hooks, side steps, mud flaps, hitch, trailer wiring, OEM trailer brakes, has a back seat, white, TOW ONLY –</p> <p>This vehicle has an UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in "As is, where is" condition., 218,390 km, , KNOWN PROBLEMS and OBSERVATIONS: Both upper ball joints, right lower ball joint, alignment, right rear window non-operational, holes drilled in box rails, trim on inside b pillars modified, holes in headliner, hole drilled in roof above doors, holes drilled in dash, multiple holes in floor pan in front of rear seat, right front headlight has moisture, no jump seat, front console modified, hood chips, both bumpers road rash/rust/dents, left rear fender road rash, right rear fender road rash dents, both rocker panels road rash/rusted, right front door dents/scratches, right rear door will not roll down from left front door, roof scratches, 5 holes in roof sealed, tailgate dents/molding loose, no first aid kit/fire extinguisher, left front seat worn, padding visible, poor battery, minor exterior damage.>, As is, where is</p>	218,390 km	\$9,875	3C6TR5CT2GG118585

	Item #	Description	Kms	Min Price	Serial Number
No Bid	10-026	<p>Truck 2019 FORD F150 4WD, supercrew, 6'5" box 5.0L V8, gas auto A/C, tilt, cruise, AM/FM, 420,852 power heated mirrors, power locks/windows, keyless entry-1 key fob, 1 key for topper front km tow hooks, side steps, hitch, trailer wiring, OEM trailer brake, ARE topper, has a back seat, white, TOW ONLY –</p> <p>This vehicle has an UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in "As is, where is" condition., 420,852 km, , KNOWN PROBLEMS and OBSERVATIONS: Drive belt, left inner tie rod, left outer tie rod, front and rear pads/rotors, alignment needed, windshield, missing mud flaps, wiper blades, washer switch, plate light. Transmission chatters and surges, mobile for short trips, diagnosed with internal transmission issues, need replacement transmission, grille broken, hood chips/road rash, rear bumper dented, left side fenders road rash, right rear fender road rash, right front door chips, tailgate corner bent, unknown if wheel wrench is under the back seat, no first aid kit/fire extinguisher, windshield cracked, left mirror housing broken, topper tailgate or lock non operational, poor battery, minor exterior damage.>, As is, where is</p>		\$8,770	1FTFW1E5XKKE71275
5,497.00	10-020	<p>Truck 2013 FORD F250 SD 4WD, crew cab, 6'10" box 6.2L V8, gas auto A/C, tilt, cruise, 177,697 AM/FM/CD player, power heated tow mirrors, power windows/locks, keyless entry-2 key km fobs front tow hooks, grille inserts, side steps poor condition, hitch, trailer wiring, OEM trailer brake, box liner, headache rack, has back seat, red, TOW ONLY –</p> <p>This vehicle has a VERY UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Body Integrity Inspection and a Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in "As is, where is" condition., 177,697 km, , KNOWN PROBLEMS and OBSERVATIONS: TPMS light on, rear shocks leaking, right front shock broken. Grille holes drilled, hood dents/scratches, front bumper chips, rear bumper rusted/dents/ pad screwed down and broken, left front fender chips, left rear fender scratches/dents/ chips, right rear fender dents/chips/scratches, both rocker panels rusted, left front door chips, left rear door dents/chips, left front and rear doors weather strip loose, right rear door rust inside/bottom weather strip loose, six holes in roof sealed, tailgate badly damaged and missing molding, no first aid kit/fire extinguisher, windshield chips, left mirror housing cracked, left front seat worn/ripping, right front seat hole, left side step bent, front valance loose, left and right cab corners rusting, missing rear mud flaps, holes in front center floor mat, holes drilled in dash, missing front cup holder, poor battery, minor exterior damage.>, As is, where is</p>		\$2,200	1FT7W2B62DEA28143

Item #	Description	Kms	Min Price	Serial Number
No Bid 10-027	<p>Truck 2016 FORD F250 SD 4WD, crew cab, 6'5" box 6.7L, V8, diesel auto A/C, tilt, cruise, after market AM/FM radio, power heated mirrors, power locks/windows, keyless entry-2 key fobs front tow hooks, side steps, mud flaps, hitch, trailer wiring, OEM trailer brake, headache rack, box liner, wig wags front and rear, has a back seat, white, TOW ONLY –</p> <p>This vehicle has an UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in "As is, where is" condition., 313,317 km, , KNOWN PROBLEMS and OBSERVATIONS:</p> <p>Engine codes: P2464E exhaust gas (B154), P24C7 part matter sensor, P2463 soot accumulation(B1), P246F exhaust gas (B154), pit man arm, right outer tie rod, rear pads/rotors, 4WD not working, driver seat ripped.</p> <p>Multiple codes, 4WD problems, power lock problems, steering and brake issues, spare tire key for winch missing, signs of coolant between transmission and engine, both bumpers rusted/dented/scratched, left front fender road rash, left rear fender rust/dents/road rash, right side fenders road rash/rust/dents, left rocker panel rusted, left side doors rusted/chips/dents, right side doors rusted/chips/dents/road rash, roof rusting/chips, tailgate poor/rusted/dented, no first aid kit/fire extinguisher, windshield chips, both mirror housing broken, left seat badly worn/cushion visible/holes, right seat worn/torn, left cab corner rusted, trim loose inside left front door, interior soiled, holes in front bump mat, switch for wig wags hanging, poor battery, minor exterior damage.>, As is, where is</p>	313,317 km	\$8,956	1FT7W2BT0GEB63809
No Bid * 9-019	<p>Truck 2017 FORD F250 SD 4WD, crew cab, 6'10" box 6.2L, V8, gas auto A/C, tilt, cruise, aftermarket AM/FM radio, power heated trailer tow mirrors, power locks/windows, keyless entry-2 key fobs front tow hooks, side steps, mud flaps, hitch, trailer wiring, OEM trailer brake, box liner, headache rack, has back seat, white, TOW ONLY –</p> <p>This vehicle has an UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in "As is, where is" condition., 334,118 km, , KNOWN PROBLEMS and OBSERVATIONS:</p> <p>Exhaust manifold, front shocks, left outer tie rod, alignment needed, rear brake line not secured.</p> <p>Grille holes drilled, hood dents/stone chips, front bumper chips, rear bumper rusted/holes drilled, left front fender chips, left rear fender scratch, right rear fender small dents, left front door dents, tailgate chips/small dents, no first aid kit/fire extinguishers, windshield chips, left front seat sagging, holes drilled in box rails, front valance broken, poor battery, minor exterior damage.>, As is, where is</p>	334,118 km	\$14,920	1FT7W2B60HEE88021

Item #	Description	Kms	Min Price	Serial Number
8,975.30 * 8-011	<p>Truck 2018 FORD F250 SD 4WD, crew cab, 6'10" box 6.2L, v8, gas auto A/C, tilt, cruise, after market AM/FM, power heated trailer tow mirrors, power windows/locks, keyless entry-2 key fobs front tow hooks, side steps, mud flaps, hitch, trailer wiring, OEM trailer brakes, box liner, headache rack with beacon and wigwags, has back seat, grey, TOW ONLY –</p> <p>This vehicle has an UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Mechanical Safety Inspection to be licensed.</p> <p>Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in "As is, where is" condition., 318,842 km, , KNOWN PROBLEMS and OBSERVATIONS:</p> <p>Left tire worn out, front pads/rotors 3mm, wipers streaky, note hood ajar lights stay on.</p> <p>Grille broken, hood chips/scratches, both bumpers' scratches/chips/rust spots, all fenders scratches/chips, left side doors chips/scratches, right side doors parking lot dent, 1 tape covering hole in roof, tailgate dent/scratches/chips, spare tire loose in box may not be compatible with vehicle, no first aid kit/fire extinguisher, windshield chips left front seat sagging, broken wig wag on grille, exhaust noisy, back up assist not working, poor battery, minor exterior damage.>, As is, where is</p>	318,842 km	\$7,720	1FT7W2B69JEB32639
5,333.00 10-008	<p>Truck 2016 GMC Sierra 1500 4WD, crew cab, 6'6" box 5.3L, V8, gas auto A/C, tilt, cruise, AM/FM, power mirrors/locks/windows, keyless entry-2 fobs, 2 keys front tow hooks, side steps, mud flaps, hitch, trailer wiring, OEM trailer brake, has a back seat, white, TOW ONLY –</p> <p>This vehicle has an UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Mechanical Safety Inspection to be licensed.</p> <p>Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in "As is, where is" condition., 310,998 km, , KNOWN PROBLEMS and OBSERVATIONS:</p> <p>Both lower ball joints, right outer tie rod end, rear parking brake cables.</p> <p>Hood hail, front bumper dents, rear bumper bent, left front fender chips, right rear fender dents, left side doors chips/dents/paint poor, right side doors rust along bottom inside and out, rear right door paint poor, roof hail, no first aid kit/fire extinguisher, windshield chips, paint poor on both A pillars, hole in right front floor mat, inside of box scratched, left corner of cab dented, poor battery, minor exterior damage.>, As is, where is</p>	310,998 km	\$2,540	3GTU2LEC0GG192560

Item #	Description	Kms	Min Price	Serial Number
1,535.00 10-021	<p>Van 2009 DODGE Grand Caravan SE FWD 3.3L, V6, gas auto A/C, tilt, cruise, AM/FM/CD player, rear HVAC, power mirrors/locks/front windows, keyless entry-2 key fobs 7 passenger, km brown, TOW ONLY –</p> <p>This vehicle has a VERY UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Body Integrity Inspection and a Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in "As is, where is" condition., 203,835 km, ,</p> <p>KNOWN PROBLEMS and OBSERVATIONS: Front links, rockers, alignment needed. Hood paint bubbling/faded, front bumper chips/scratches/cover loose, rear bumper broke/scratches, left and right-side fenders rusted, dog legs rusted, rocker panels rusted PMVI, left front door rusted, tailgate rusted, tailgate does not latch, no first aid kit/fire extinguisher, windshield chips, 3rd row seat carpet covers remover, poor battery, does not hold a charge, minor exterior damage.>, As is, where is</p>	203,835	\$890	2D8HN44E89R685323
1,746.00 10-009	<p>Van 2013 DODGE Grand Caravan SE FWD 3.6L, V6, gas auto A/C, tilt, cruise, AM/FM/CD player, rear HVAC, power heated mirrors, power windows/locks, rear vent windows, keyless entry-2 key fobs 7 passenger, Stow-N-Go 3rd row seat only, silver, TOW ONLY –</p> <p>This vehicle has a VERY UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Body Integrity Inspection and a Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in "As is, where is" condition., 244,546 km, ,</p> <p>KNOWN PROBLEMS and OBSERVATIONS: TPMS, right outer tie rod, front and rear pads/rotors, alignment needed, wiper blades, washer nozzle, rocker panels. Hood paint bubbling/chips/dents, both bumpers' chips/scratches, left front fender chips/scratches, left rear fender rusted/dented, right front fender dent, right rear fender rust, both dog legs rusted, both rocker panels rusted, roof rust above windshield/small rust spots, tailgate glass scratched/dent, no first aid kit/fire extinguisher, windshield chips, moisture in left front seal beam, right rear tail light lens broken, poor battery, minor exterior damage.>, As is, where is</p>	244,546 km	\$1,350	2C4RDGBG2DR634131

Item #	Description	Kms	Min Price	Serial Number
REGINA, SaskBuilds and Procurement, SaskSurplus Sales Lot, 500 McLeod Street - Miscellaneous				
Contact SaskSurplus 306-787-2062 or 306-798-3306, sasksurplus@gov.sk.ca				
No Bid 10-107	Tires, Lot of 2 225/60R16, Goodyear Integrity, M+S Manufacture date, week 23, year 2008. Fair		\$20	
38.40 10-109	Tires, Lot of 3 225/65R17, Winter Quest Duration, Snowflake, M+S Manufacture date, week 27, year 2017. Fair		\$20	
67.50 10-110	Tires, Lot of 2 LT245/75R16, Sumitomo Encounter AT, Load range E, Snowflake Manufacture date week 19, year 2017. Fair		\$40	
43.60 10-106	Tires, Lot of 2 225/60R16, Firestone FR710, M+S Manufacture date week 44, year 2016. Fair		\$40	
68.58 10-102	Tires, Lot of 3 225/65R17, Firestone WeatherGrip, Snowflake, M+S Manufacture date week 30, year 2020. Fair		\$60	
72.10 10-108	Tires, Lot of 4 225/60R16, Winter Claw Extreme Grip MX, Snowflake Manufacture date week 14, year 2013, one tire has a patch. Good		\$40	
*MT 10-101	Tires, Lot of 4 215/60R16, Firestone All-Season, M+S Manufacture date, week 46, year 2021 Fair		\$100	
No Bid 10-103	Tires, Lot of 4 225/65R17, Firestone Weathergrip, Snowflake, M+S Manufacture date week 31, year 2020. Fair		\$100	
131.58 10-104	Tires, Lot of 4 P225/65R17, Michelin Energy Saver, M+S Manufacture date week 38, year 2019 Fair		\$100	
100.00 10-105	Tires, Lot of 4 P235/70R16, Firestone All-Season, M+S Manufacture date week 50, year 2021. Fair		\$100	
32.00 * 9-135	Vacuum, Bissell AreoSwift Compact Corded, grey/black, with floor attachment, operational Good		\$10	
45.00 * 9-102	Cabinet, wood Dark brown, 2 drawers with lock and key, missing adjustable feet, 36.5" w x 18" d x 27" h, some scratches. Fair		\$1	

Item #	Description	Kms	Min Price	Serial Number
10.00 * 9-104	Cabinet, wood Dark brown, 2 drawers with lock no key, adjustable feet, 36.5" w x 19" d x 29.5" h, some scratches. Fair		\$1	
10.00 * 9-106	Cabinet, wood Maroon, 2 drawers with lock and key, adjustable feet, 36" w x 24" d x 29.5" h, some scratches. Fair		\$1	
15.00 * 9-108	Credenza, wood Light brown, 4 drawers with lock and key, 2 doors, 72" w x 19" d x 29.5" h, has some scratches. Fair		\$1	
No Bid * 9-113	Desk, L-shape, wood Light brown, 5 drawers with lock and 2 keys, adjustable feet, comes with hardware, main 66.5" w x 35.5" d x 29.5" h, return side 43.5" w x 20.5" d x 28" h, comes with monitor riser with pull-out tray, some scratches and water damage, missing one adjustable foot. Fair		\$1	
No Bid * 9-114	Desk, L-shape, wood Light brown, 5 drawers with lock and 2 keys, adjustable feet, no hardware, main 66.5" w x 35.5" d x 29.5" h, return side 43.5" w x 20.5" d x 28" h, comes with monitor riser with pull-out tray, some scratches and water damage. Fair		\$1	
No Bid * 9-115	Desk, U-shape, wood Dark brown, 1 drawer, adjustable feet, has hardware, main 108" w x 20" h, left return, 72.25" w x 32.5" d, right return 120" w x 20.5" w x 29.5" h, some scratches, surface laminate lifting, back has cracked. Fair		\$1	
12.00 * 9-116	Desk, wood Light brown, 3 drawers with lock and no key, adjustable feet, 67" w x 36" d x 29.5" h, some scratches and water damage. Fair		\$1	
12.00 * 9-117	Desk, wood Light brown, 6 drawers with lock and no keys, adjustable feet, 72" w x 19" d x 29.5" h, some scratches. Fair		\$1	
12.00 * 9-118	Desk, wood Light brown, 6 drawers with locks and key, adjustable feet, 72" w x 19" d x 29.5" h, has some scratches, one lock has key broken inside the lock. Fair		\$1	
21.00 * 9-123	Desk with Hutch, wood Both dark brown, 6 drawers with lock no key, adjustable feet, desk 72" w x 19" d x 29" h, hutch 69" w x 14.5" d x 39" h, 4 doors with lock with key, some scratches. Fair		\$1	
60.00 * 9-124	Desk with Hutch, wood Both dark brown, 6 drawers with no locks, 72" w x 20" d x 29.5" h, hutch 69.25" w x 14.5" d x 39" h, some scratches. Fair		\$1	

Item #	Description	Kms	Min Price	Serial Number
CHRISTOPHER LAKE, Corrections, Policing, and Public Safety, 379 Main Street				
Contact: Charlene Berard 306-982-6250, charlene.berard@gov.sk.ca				
3,200.00 10-501	Snowmobile 2011 SKI-DOO Grand Touring 550 553.4 cc, two-stroke, gas visor cord plug in, hand warmers, 2 keys, primer and choke spare belt, black, , 12313.6 km, , UNKNOWN PROBLEMS: Battery not included, was used the 2025 snowmobile season, burned more oil than usual, several scratches and wear on machine, windshield is intact but crack on inside windshield mount on left side, seat has wear on both sides towards bottom, missing left mirror, original track, lights and brakes operational, minor exterior damage.>, As is, where is	12313.6 km	\$500	2BPSELBA0BV000372
CONDIE NATURE REFUGE, Corrections, Policing, and Public Safety, NW-32-18-20-W2 Call for Directions				
Contact: James Jensen 306-787-2080, james.jensen@gov.sk.ca or James Mcleod 306-725-8244, james.mcleod@gov.sk.ca				
1,701.51 10-507	Motorcycle,1983 Honda dual purpose, XL250R 249cc, 1 cylinder, gasstandard, 6 speed 1 key red 7,070 kmKNOWN PROBLEMS: Difficult to start, 1 mirror broken, has not had a SGI Inspection, poor battery, minor exterior damage.> As is, where is	7,070 km	\$1	JH2MD0305DM103342
MEADOW LAKE PROVINCIAL PARK, Parks, Culture and Sport, Meadow Lake Provincial Park - Highway 224 - Call for Directions				
Contact Heath Harpham 306-839-7323, heath.harpham@gov.sk.ca or Reg Bayko 306-240-4513, reg.bayko@gov.sk.ca				
4,300.00 10-502	Trencher Backhoe unknown year Case DH4 4WD diesel non-operational, tires in poor shape, 2544.2 tire size 12.5L-15, 1 key , yellow, , 2544.2 hours, , UNKNOWN PROBLEMS: leaking diesel injector hours pump, poor battery,minor exterior damage.>, As is, where is	2544.2 hours	\$500	1187559
1,201.00 10-506	Truck 2001 GMC Sierra 1500 RWD, extended cab, 6 foot box 4.8L V8, gas auto Air/cruise/tilt, 195,477 AM/FM radio, GVW 2812kg, tire size P255/70R16, hitch receiver, one key , white, TOW ONLY, km NO SGI Inspection. It is unknown if any repairs or safety concerns exist (if any). Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs if required. , 195,477 km, , UNKNOWN PROBLEMS: Vehicle starts with a boost and runs but has a rough idle and wants to stall, unknown reasons, poor paint, poor interior, poor wipers, poor battery, minor exterior damage.>, As is, where is	195,477 km	\$1,000	2GTEC19V911313779

Item #	Description	Kms	Min Price	Serial Number
MOOSE JAW, Highways, 1km south of Moose Jaw on Hwy #2				
Contact Ben Dueck 306-694-3773, ben.dueck@gov.sk.ca or Tara Watson 306-694-3773, tara.watson@gov.sk.ca				
301.00 10-503	Message Board , 2004, Vermac, VM-4815L non-operational, rims rusty, good tires, batteries fair, pintle hitch it is unknown if this trailer has ever been registered through SGI and, as such, it might not have had a license plate affixed to it. SGI may have to generate and supply a new VIN number to this trailer, so contact with SGI could be necessary if you want to plate this trailer and have it legal to drive on roadways. Beyond Repair		\$1	04-05731
MOOSE JAW, Highways, JCT 39/1, NW-33-16-25-W2 - Call for Directions				
Contact Curtis Richardson 306-533-0562, curtis.richardson@gov.sk.ca or Mike Dudley 306-630-4246, michael.dudley@gov.sk.ca				
6.00 * 9-547	Bridge Girder, Precast prestressed concrete bridge girder 12m x 48" w x 22" h approximate weight: 12800kg, these girders are salvaged from bridges that have been replaced. IMPORTANT NOTE: The bridge girders SHALL NOT be used for any structural means, the are deemed in "Salvage", "Disposed" and in "Non-Structural" condition, buyer MUST sign an agreement not to use for any structural purposes. Beyond Repair		\$1	
46.00 * 9-548	Bridge Girder, Lot of 6 Precast prestressed concrete bridge girder 15m length x 48" w x 24" h, approximate eight: 18200kg, these girders are salvaged from bridges that have been replaced. IMPORTANT NOTE: The bridge girders SHALL NOT be used for any structural means, the are deemed in "Salvage", "Disposed" and in "Non-Structural" condition, buyer MUST sign an agreement not to use for any structural purposes. Beyond Repair		\$1	

Item #	Description	Kms	Min Price	Serial Number
46.00 * 9-549	Bridge Girder, Lot of 6 Precast prestressed concrete bridge girder 15m length x 48" w x 24" h, approximate weight: 18200kg, these girders are salvaged from bridges that have been replaced. IMPORTANT NOTE: The bridge girders SHALL NOT be used for any structural means, the are deemed in "Salvage", "Disposed" and in "Non-Structural" condition, buyer MUST sign an agreement not to use for any structural purposes. Beyond Repair		\$1	
21.00 * 9-550	Bridge Girder, Lot of 5 Precast prestressed concrete bridge girder 9m length x 48" w x 22" h, approximate weight: 9500kg, these girders are salvaged from bridges that have been replaced. IMPORTANT NOTE: The bridge girders SHALL NOT be used for any structural means, the are deemed in "Salvage", "Disposed" and in "Non-Structural" condition, buyer MUST sign an agreement not to use for any structural purposes. Beyond Repair		\$1	
21.00 * 9-551	Bridge Girder, Lot of 5 Precast prestressed concrete bridge girder 9m length x 48" w x 22" h, approximate weight: 9500kg, these girders are salvaged from bridges that have been replaced. IMPORTANT NOTE: The bridge girders SHALL NOT be used for any structural means, the are deemed in "Salvage", "Disposed" and in "Non-Structural" condition, buyer MUST sign an agreement not to use for any structural purposes. Beyond Repair		\$1	

OUTLOOK, Agriculture, 410 Saskatchewan Ave W

 Contact Ben Lalonde 306-867-6469, ben.lalonde@gov.sk.ca or Outlook Front Desk 306-867-5500, stacey.stutters@gov.sk.ca

No Bid * 9-527	GPS Base Radio, Pacific Crest PDL 4335 430-450Mhz radio for GPS system, significant wear, stored in a cool dry place for many years, no cables included, unknown if operational. Poor	\$5	8,091,658
No Bid * 9-528	Leveling Rods, Lot of 3 aluminum Total height 5m, each set has 4 pieces that clip together with carrying case, one case is blue nylon, the other two are brown leather or vinyl, rods have not been used for decades, stored in a cool dry place, noticeable wear is present, calibration <u>will be likely be required. Fair</u>	\$30	
No Bid * 9-533	Tripods, Lot of 3 wood For surveying, one Duratech, two Leica, one Leica tripod has a telescoping antenna pole, stored in a cool dry place, all tripod clamps are somewhat loose, noticeable wear present, tightening and calibration will likely be required. Fair	\$75	

PRINCE ALBERT, Corrections, Policing and Public Safety, 3021 1st Ave W

 Contact: Tonya Granberg 306-953-3005, tonya.granberg@gov.sk.ca or Nola Boechler, nola.boechler@gov.sk.ca

No Bid * 8-520	Blanket, Lot of 2 light material, unknown material No tag. blue Good	\$1
No Bid * 8-521	Coffee Filter Basket, Lot of 18 plastic brown Poor	\$1
No Bid * 8-522	Coffee Pots, Lot of 21 plastic With metal bottom. Poor	\$1

Item #	Description	Kms	Min Price	Serial Number
PRINCE ALBERT, Environment, 201 - 1061 Central Ave				
Contact Emelyn Feliciano 306-953-3233, emelyn.feliciano2@gov.sk.ca or Mary Jane Mackie, maryjane.mackie@gov.sk.ca				
1.25 * 9-502	Desk Lamp, metal Black and green, operational. Good		\$1	
1.25 * 9-503	Desktop Document Holder, DAC, metal Black, 9" x 13". Fair		\$1	
10.00 * 9-504	Digital Cameras, Lot of 3 Canon LCD screen is broken, operational, silver, no memory card, internal memory wiped. Fair		\$1	
No Bid * 9-506	Headphones, Lot of 4 wired Black, unknown if operational. Poor		\$1	
No Bid * 9-508	Keyboard Trays, Lot of 8 metal, wood Ergonomic adjustable keyboard platform, black. Fair		\$1	
No Bid * 9-510	RCA Conference Speaker Phone, circular Black, with cable & adapter, operational. Fair		\$1	
REGINA, Legislative Assembly Service, 515 Henderson Drive				
Contact: Kadence McMillen 306-787-0337, kmcmillen@legassembly.sk.ca or Karen Plumb 306-787-8167, kplumb@legassembly.sk.ca				
No Bid * 8-501	Uninterruptable Power Supply with Batteries and Power Modules, Lot of 11 APC Symmetra 1 APC Symmetra LX UPS, SYAF16KRMT, 7 APC Symmetra LX Battery Module, SYBT5, 2 APC Symmetra LX Power Module, SYPM4KP, 1 APC Symmetra LX Power Module, SYPM4KPQ. UPS: 19" w x 27" d x 33" h, (shipping 42 x 24 x 40) 500lbs, each battery is 18 kg, 4 batteries in box, 3 loose, unknown what condition batteries are in, no power cord as it has to be direct wired into building power. Sold as is. UPS: QD1037260148, in-box batteries: 5D2007T60139, 5D2018T65313, 5D2018T65320, 5D2007T60123, loose batteries: 5D2005T15219, 5D2007T60147, 5D2007T60138, SYPM4KP, power modules: QD1513380215, AD2033110087, SYPM4KPQ power module: AQ2106210005, operational. Fair		\$5,000	
REGINA, SaskBuilds & Procurement, *Online Viewing Only*, 1920 Rose Street				
Contact: Christina Rodman 306-787-9255, christina.rodman@gov.sk.ca or 306-787-9231, controlroom@gov.sk.ca				
51.00 10-508	Server Racks, metal 23.5" w x 37.5" d x 81.5" h, good shape, four wheels, with a front single door only, front door has a lock but no key. *Online Viewing Only* Good		\$50	
No Bid 10-509	Server Racks, Lot of 2 metal 31" w x 40" d x 80" h, good shape, four wheels, with front double doors and rear single door, one rack is missing the side panel, front and back doors have locks but no key. *Online Viewing Only* Good		\$50	

Item #	Description	Kms	Min Price	Serial Number	
SASKATOON, Highways, 126 105th St E					
Contact Richard Leibel 306-933-5262, Richard.Leibel@gov.sk.ca or Shaun.Bowditch@gov.sk.ca					
2,501.00	9-539	Gravel Truck 2001 Volvo WG64F Tandem Volvo VED12C, 345 horse power, 6 cylinder, diesel standard Super 10 10 speed, tandem axle, interlocking differential, tire size 11R22.5, AM/FM/cassette 2000 Tenco TC116HD RH wing in poor condition, serial# 16587, yellow, TOW ONLY, NO SGI Inspection. It is unknown if any repairs or safety concerns exist (if any). Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs if required. , 552,716 km, Known Recent Repairs:; KNOWN PROBLEMS: Motor leaks and burns oil, transmission is leaking and corroded, hydraulic pump shaft broken, engine fan shroud broken, radiator damaged and leaking, air to air leaking, right rear fender rotted, frame worn and thin, cross chain is running on frame, tarp bearings broken and bracket bent, rear differential leaking, stop engine warning light is on, no hydraulics as control box has been removed, tires removed off second axel, axel chained up. right hand wing and mount attached, interior in fair condition, minor exterior damage.>, As is, where is	552,716 km	\$2,500	4V5JC8GF91N309572
SASKATOON, Saskatchewan Research Council, Bay 2D 820 51st St E					
Contact Aamir Bakhsh 306-370-8011, Aamir.Bakhsh@src.sk.ca or Gina Zimmer 306-250-9690, gina.zimmer@src.sk.ca					
No Bid	* 8-540	Pipe Fittings, grooved 5 pallets, never used or installed. New- Unused		\$500	
SASKATOON, Saskatchewan Research Council, 820 51st St E					
Contact Roger Dauvin 306-385-4035, roger.dauvin@src.sk.ca or purchasing@src.sk.ca					
No Bid	* 9-512	Dehydrator, Hungry Giant, HGF-320ML Operational, put into use 2020 (RFQ 1920-011 ; 256532). Good		\$15,000	HGF320ML-CAN1601-001