

SALE SUMMARY LIST

PLEASE NOTE: Every effort has been made to accurately describe items and their condition; however, additional problems may exist, items may not be complete or exactly as described. Bidders are deemed to have reviewed the Terms and Conditions on bid forms and relied entirely on their own inspection and evaluation prior to bidding. Vehicles and equipment are sold "AS IS, WHERE IS", there is no implied or express warranty.

Visit www.SaskSurplus.ca for pictures and link to download Bid Form.

- Items identified with * have been on a previous sale and will be listed first on www.SaskSurplus.ca web site.
- SaskBuilds and Procurement, SaskSurplus, reserves right to have unadvertised minimum selling prices on items.

It is the Bidder's responsibility to review the terms and conditions of sale on the Offer to Purchase, Bid Form.

Bid Forms are available from www.SaskSurplus.ca or from the SaskSurplus Sales Lot, 500 McLeod Street, Regina, SK.

Bid Forms can be submitted in the following ways:

- by deposit in the bid box at the SaskSurplus Sales Lot,
- by fax to 306-787-2092; by phone 306-787-2062 or 306-798-3300,
- by email to sasksurplus@gov.sk.ca, or
- by mail, addressed to: Ministry of SaskBuilds and Procurement, SaskSurplus, 500 McLeod Street, Regina, SK S4N 4Y1.

(If mailing your bid, please allow sufficient time for bid to be received.)

- Bids received after close date and time cannot be accepted.

MT = (Ministry Transfer) This means that the item has been claimed by another ministry and automatically transferred to the ministry.

WD = (Withdrawn) This can happen if the item was requested to be removed by the seller.

No Bid = Items that did not receive any bids are normally carried forward to the next sale or may be withdrawn.

Item #	Description	Kms	Min Price	Serial Number
--------	-------------	-----	-----------	---------------

Item #	Description	Kms	Min Price	Serial Number	
REGINA, SaskBuilds and Procurement, SaskSurplus Sales Lot, 500 McLeod Street - Vehicles					
Contact SaskSurplus 306-787-2062 or 306-798-3306, sasksurplus@gov.sk.ca					
2,688.88	11-010	Car 2008 CHEVROLET Impala FWD 3.5L, V6, gas auto A/C, tilt, cruise, AM/FM/CD player, power mirrors/locks/windows/left front seat, power trunk release, keyless entry-2 fobs, 2 keys , grey, TOW ONLY – This vehicle has an UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in “As is, where is” condition., 205,507 km, , KNOWN PROBLEMS and OBSERVATIONS: Right CV joint, LESA front control arm bushing, alignment needed, foggy head lamps, rockers. Hood dented/road rash/scratches, front bumper cracked, rear bumper scratches, left front fender scratches/road rash, left rear fender chips, right front fender road rash, right rear fender dent, both rocker panels rust/road rash, left side doors rust/dents/scratches/road rash, right rear door missing trim piece, tailgate rust/scratches, no first aid kit/fire extinguisher, windshield chips, left head light fogged, poor battery, minor exterior damage.>, As is, where is	205,507 km	\$1,961	2G1WB58K581359442
501.00	11-011	Car 2008 CHEVROLET Impala LS FWD 3.5L, V6, gas auto A/C, tilt, cruise, AM/FM/CD player, power mirrors/locks/windows/left front seat, keyless entry 2 fobs, 2 keys , grey, TOW ONLY – This vehicle has a VERY UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Body Integrity Inspection and a Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in “As is, where is” condition., 321,391 km, , KNOWN PROBLEMS and OBSERVATIONS: Front sway bar broken, both lower ball joints, TPMS light on, rear pads/rotors, park brake not fully releasing, left fronts signal bulb, wiper blades, headlight assembly foggy, right front door binds on fender, both rocker panels rusted out. Hood chips/scratches, both bumpers’ chips/scratches, left front fender rust/chips/ scratches, right front fender chips, right rear fender rusted, both rocker panels rusted out, left side doors rust, right front door rust/binds/chips, right rear door rust, tailgate rust/scratches, no first aid kit/fire extinguisher, windshield chips, left front seat sagging, head lights fogged, missing left rear wheel cover, poor battery, minor exterior damage.>, As is, where is	321,391 km	\$387	2G1WB58K681358168

Item #	Description	Kms	Min Price	Serial Number
1,100.00 11-014	<p>Car 2011 DODGE Avenger SXT FWD 2.4L, inline 4, gas auto A/C, tilt, cruise, AM/FM/CD player, power mirrors/locks/windows, keyless entry 2 fobs , white, TOW ONLY –</p> <p>This vehicle has a VERY UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Body Integrity Inspection and a Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in “As is, where is” condition., 267,681 km, , KNOWN PROBLEMS and OBSERVATIONS: Front and rear pads/rotors, both wiper blades, foggy head lamps, rocker panels, both visor clips.</p> <p>Hood chips/hail/scratches, front bumper chips, left front fender scratches, right rear fender rust, both dog legs rusted, both rocker panels rusted, all doors rust/road rash, roof paint faded/rust/hail, trunk lid hail/rust, no first aid kit/fire extinguisher, windshield chips, headlights faded, visor clips, poor battery, minor exterior damage.>, As is, where is</p>	267,681 km	\$654	1B3BD4FB5BN507433
1,510.00 * 10-022	<p>SUV 2014 CHEVROLET Equinox LS 4WD 2.4L, inline 4, gas auto A/C, tilt, cruise, AM/FM, power mirrors/locks/windows/left front seat, keyless entry-2 key fobs 5 passenger, grey, TOW ONLY –</p> <p>This vehicle has an UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in “As is, where is” condition., 294,939 km, , KNOWN PROBLEMS and OBSERVATIONS: Drive belt, radiator support mounts missing, alignment needed.</p> <p>Hood chips/dents, both bumpers’ chips/scratches, left side fender road rash, right rear fender rust, all door rust inside bottom, right front door window trim dents, roof scratches, tailgate rust/glass scratched, no first aid kit/fire extinguisher, windshield chips, headlights fogged, poor battery, minor exterior damage.>, As is, where is</p>	294,939 km	\$1,258	2GNFLEEK8E6234000

Item #	Description	Kms	Min Price	Serial Number
3,088.88 11-009	<p>SUV 2014 CHEVROLET Equinox LS AWD 2.4L, inline 4, gas auto A/C, tilt, cruise, AM/FM, power mirrors/locks/windows, keyless entry-2 key fobs , grey, TOW ONLY –</p> <p>This vehicle has an UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in “As is, where is” condition., 265,777 km, , KNOWN PROBLEMS and OBSERVATIONS: Exhaust manifold, exhaust leak, front links, alignment needed, front fenders. Hood chips/scratches/dents, both bumpers’ chips/scratches/hitch cover loose, left front fender rust, left rear fender road rash/over spray, right side fenders road rash/rust/chips, left front door chips, left rear door chips/scratches/rust, right front door dents/chips/ scratches, right rear door chips/scratches, roof chips/scratches, tailgate rust/paint poor/glass scratched, no first aid kit/fire extinguisher, windshield chips, poor battery, minor exterior damage.>, As is, where is</p>	265,777 km	\$1,689	2GNFLEEK7E6235204
1,800.00 11-001	<p>SUV 2015 CHEVROLET Equinox LS AWD 2.4L, inline 4, gas auto A/C, tilt, cruise, AM/FM, power mirrors/locks/windows/left front seat, keyless entry-2 key fobs 5 passenger, white, TOW ONLY –</p> <p>This vehicle has a VERY UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Body Integrity Inspection and a Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in “As is, where is” condition., 261,022 km, , KNOWN PROBLEMS and OBSERVATIONS: Front lower arm bushing torn/damaged, right lower ball joint boot torn apart, E-brake pedal missing cover, both rocker panels rust holes/ rear right. Grille broke, hood chips, both bumpers’ chips/scratches, left front fender rust/chips, right side fenders road rash, both rocker panels rusted, right side doors road rash, roof dents, tailgate rusted/glass scratched, no first aid kit/fire extinguisher, windshield chips, scratches right roof rail above doors, washer fluid cap missing, poor battery, minor exterior damage.>, As is, where is</p>	261,022 km	\$848	2GNFLEEK0F6318278

Item #	Description	Kms	Min Price	Serial Number
5,995.00 11-008	<p>SUV 2014 CHEVROLET Tahoe LTZ 4WD 5.3L, V8, gas auto Front and rear AC/heat, tilt, cruise, AM/FM/CD player, power front seats/windows/locks, keyless entry-1 fob, 1 key front tow hooks, grille inserts, side steps, hitch, trailer wiring, mud flaps, white, TOW ONLY – This vehicle has an UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in “As is, where is” condition., 283,559 km, , KNOWN PROBLEMS and OBSERVATIONS: Left upper ball joint, all pads/rotors, alignment needed, both rear door/window locks. Hood chips/rust, both bumpers’ chips/scratches, left front fender chips, left rear fender road rash, right side fenders road rash/rust, right front door trim around mirror broken, right rear door does not open from inside, missing rear door pop-up locks, roof chips/small rust spots/scratches, 8 holes in roof - sealed, tape on spoiler, no first aid/fire extinguisher, windshield chips, hole drilled in dash, head liner, rear storage area, missing molding in cargo area, molding loose on rear seat, left head rest ripped, no jump seat, poor battery, minor exterior damage.> , As is, where is</p>	283,559 km	\$5,156	1GNSK2E07ER183365
7,000.00 11-002	<p>SUV 2017 DODGE Durango 4WD 5.7L, V8, gas auto A/C, tilt, cruise, AM/FM, rear A/C and heat, power heated mirrors, power locks/windows/ left front seat, keyless entry-2 key fobs driving lights, hitch, trailer wiring, 5 passenger, steel wheel on rear right, white, TOW ONLY – This vehicle has an UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in “As is, where is” condition., 161,068 km, , KNOWN PROBLEMS and OBSERVATIONS: transmission axle noise, alignment, left fog light. Hood paint peeling/dents, left rear door road rash/rust at bottom, right front door small rust-inside front, one hole in roof sealed, tailgate chips/glass scratched/door gasket ripped, no first aid kit/fire extinguisher, windshield chips, right rear seat trim loose, holes in head liner, inside trim on B pillar modified, holes drilled in both rear door around window frames inside, holes drilled in rear door panels, holes drilled in console, both rear door missing pop up locks, poor battery, minor exterior damage.> , As is, where is</p>	161,068 km	\$6,158	1C4SDJFT0HC651272

Item #	Description	Kms	Min Price	Serial Number
No Bid 11-003	<p>Truck 2018 CHEVROLET Silverado 1500 4WD, crew cab, 6'7" box 5.3L, V8, gas auto A/C, tilt, cruise, AM/FM, power mirrors/locks/windows/left front seat, keyless entry-2 fobs, 2 keys side steps, front tow hooks, mud flaps, hitch, trailer wiring, OEM trailer brakes, toolbox behind cab no key, has back seat, grey, TOW ONLY –</p> <p>This vehicle has an UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in "As is, where is" condition., 308,303 km, , KNOWN PROBLEMS and OBSERVATIONS: Front struts leak, rear shocks leaking, exhaust flex pipe separating, left upper ball joint, both plate bulbs non-operational, high mount bulb non-operational. Front bumper bent/road rash, right front fender dents/scratches, right rear fender scratches/road rash, right side doors scratches, roof badly dented, tailgate scratches/hard to open, no first aid kit/fire extinguisher, windshield chips, left front seat worn/sagging, front valance loose, left A pillar dented/road rash, right side step bent, poor battery, minor exterior damage.>, As is, where is</p>	308,303 km	\$7,269	3GCUKNEC7JG107040
6,899.50 11-004	<p>Truck 2006 CHEVROLET Silverado 2500 HD 4WD, extended cab, 6'7" box 6.0L, V8, gas auto A/C dual zone, tilt, cruise, AM/FM, 3 keys front tow hooks, side steps, mud flaps, hitch, trailer wiring, has a back seat, white, TOW ONLY –</p> <p>This vehicle has an UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in "As is, where is" condition., 247,349 km, , KNOWN PROBLEMS and OBSERVATIONS: Left exhaust manifold leaking and broken bolt, left front axle stub seized in front differential-cannot fix, left front axle seal leaking without opening front differential, right park brake not releasing all the way, right wiper blade.</p> <p>Hood road rash/dents, rear bumper holes drilled, left rear fender cents/chips/road rash, right road rash/dents, both rocker panels paint worn, left/right rear door dents, no first aid kits/fire extinguishers, windshield chips, left front seat worn/ripped, both box rails dented, front of box bent, floor of box dent, poor battery, minor exterior damage.>, As is, where is</p>	247,349 km	\$3,856	1GCHK29U56E274613

Item #	Description	Kms	Min Price	Serial Number
6,000.00 * 10-007	<p>Truck 2014 DODGE/RAM 2500 4WD, crew cab, 6'4" box 5.7L, V8, gas auto A/C, tilt, cruise, AM/FM, power heated mirrors, power locks/windows, keyless entry-1 key fob front tow hooks, grille inserts, mud flaps, side steps, hitch, trailer wiring, trailer wiring, OEM trailer brakes, has back seat, brown, TOW ONLY –</p> <p>This vehicle has an UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in "As is, where is" condition., 271,195 km, , KNOWN PROBLEMS and OBSERVATIONS: Check engine light on codes (P0456 EVAP small leaks, P0463 fuel level sensor, V0159 lost com. parking, V1403 fuel level), all four ball joints, U-joints, manifold leaks, gas gauge non operational.</p> <p>Hood stone bruises/chips/scratches, front bumper rust spots, rear bumper rust/paint poor, left side fenders road rash/scratches/dents, right side fenders rust/scratches/dents, rocker panels road rash/rust, left side doors dents/scratches, right front door chips/scratches, right rear door rust/chips/scratches, roof chips/rust/scratches, tailgate rust/dent/scratches/guard bent, no first aid kit/fire extinguisher, windshield chips, inside box scratched, vehicle has bush scratches, poor battery, minor exterior damage.> , As is, where is</p>	271,195 km	\$4,732	3C6TR5CT4EG212111
6,001.00 * 9-016	<p>Truck 2015 DODGE/RAM 2500 4WD, crew cab, 6'5" box 5.7L, V8, gas auto A/C, tilt, cruise, AM/FM, power heated mirrors, power locks/windows, keyless entry-1 key fob front tow hooks, grille inserts, mud flaps, sidestep, hitch, trailer wiring, OEM trailer brake, headache rack with beacon, front and rear wig wags-operational, has back seat, white, TOW ONLY –</p> <p>This vehicle has an UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in "As is, where is" condition., 291,726 km, , KNOWN PROBLEMS and OBSERVATIONS: Right headlight has water and loose.</p> <p>Hood chips, both bumpers chips/scratches, left rear fender paint worn/road rash/chips/dents/rust, right rear fender dents/scratches, both rocker panels road rash, roof black sealant on roof, one hole sealed antenna, tailgate hard to open/chips/dents/molding loose, spare tire loose in box may not be compatible with vehicle, no first aid kit/fire extinguisher, windshield chips, small holes in left front seat, front of box bent, box rusted badly/ scratched, beacon does not work, poor battery, minor exterior damage.> , As is, where is</p>	291,726 km	\$5,717	3C6TR5CT7FG592353

Item #	Description	Kms	Min Price	Serial Number
5,501.99 * 9-017	<p>Truck 2016 DODGE/RAM 2500 4WD, crew cab, 6'5" box 5.7L, V8, gas auto A/C, tilt, cruise, AM/FM, power heated mirrors, power locks/windows, keyless entry-2 key fobs front tow hooks, grille inserts, side steps, mud flaps, hitch, trailer wiring, OEM trailer brake, box liner, headache rack, wigwags front and rear, has back seat, white, TOW ONLY –</p> <p>This vehicle has an UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in “As is, where is” condition., 297,316 km, , KNOWN PROBLEMS and OBSERVATIONS: TPMS light on, left headlight assembly full of water.</p> <p>Hood hail, front bumper scratches/chips, rear bumper dents/scratches/rust, left rear fender dents/scratches/road rash, right rear fender dents/road rash, both rocker panels road rash, left front door dents, left rear door scratches, right front door scratch, roof hail, tailgate dents/rust/bent/chips/molding loose, spare on rear left , wheel wrench/jack loose under back seat, no first aid kit/fire extinguisher, windshield chips, back seat soiled, left front floor mat worn, front of box bent, left cab corner dents, left rear seat floor storage lid broke, missing left rear wheel hub cap, left front headlights moisture, wigwags non-operational, poor battery, minor exterior damage.>, As is, where is</p>	297,316 km	\$5,291	3C6TR5CT4GG118572
4,487.15 11-013	<p>Truck 2013 DODGE/RAM 1500 SLT 4WD, quad cab, 6'3" box 4.8L, V8, gas auto A/C, tilt, cruise, AM/FM, power heated mirrors, power locks/windows/left front seat, keyless entry-2 key fobs, 1 key for toolbox front tow hooks, mud flaps, hitch, trailer wiring, OEM trailer brakes, Challenger Gull wing toolbox-lid does not stay open, has back seat, white, TOW ONLY –</p> <p>This vehicle has an UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in “As is, where is” condition., 219,390 km, , KNOWN PROBLEMS and OBSERVATIONS: Both lower ball joints, rear links, left front hubs, front fenders.</p> <p>Hood paint peeling/chips, left side fenders badly rusted/chips, right side fenders rusted, both rocker panels rusted, left side doors chips/dents, tailgate will not open/rusted/dented, wheel wrench/jack loose under back seat, no first aid kit/fire extinguisher, windshield chips, left front seat worn/ripped, left side step in box, poor battery, minor exterior damage.>, As is, where is</p>	219,390 km	\$3,987	1C6RR7GP1DS558868

Item #	Description	Kms	Min Price	Serial Number
No Bid * 10-026	<p>Truck 2019 FORD F150 4WD, supercrew, 6'5" box 5.0L, V8, gas auto A/C, tilt, cruise, AM/FM, power heated mirrors, power locks/windows, keyless entry-1 key fob, 1 key for topper front tow hooks, side steps, hitch, trailer wiring, OEM trailer brake, ARE topper, has a back seat, white, TOW ONLY –</p> <p>This vehicle has an UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in "As is, where is" condition., 420,852 km, , KNOWN PROBLEMS and OBSERVATIONS: Drive belt, left inner tie rod, left outer tie rod, front and rear pads/rotors, alignment needed, windshield, missing mud flaps, wiper blades, washer switch, plate light. Transmission chatters and surges, mobile for short trips, diagnosed with internal transmission issues, need replacement transmission, grille broken, hood chips/road rash, rear bumper dented, left side fenders road rash, right rear fender road rash, right front door chips, tailgate corner bent, unknown if wheel wrench is under the back seat, no first aid kit/fire extinguisher, windshield cracked, left mirror housing broken, topper tailgate or lock non operational, poor battery, minor exterior damage.>, As is, where is</p>	420,852 km	\$8,270	1FTFW1E5XKKE71275
7,161.33 * 10-027	<p>Truck 2016 FORD F250 SD 4WD, crew cab, 6'5" box 6.7L, V8, diesel auto A/C, tilt, cruise, after market AM/FM radio, power heated mirrors, power locks/windows, keyless entry-2 key fobs front tow hooks, side steps, mud flaps, hitch, trailer wiring, OEM trailer brake, headache rack, box liner, wig wags front and rear, has a back seat, white, TOW ONLY –</p> <p>This vehicle has an UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in "As is, where is" condition., 313,317 km, , KNOWN PROBLEMS and OBSERVATIONS: Engine codes: P2464E exhaust gas (B154), P24C7 part matter sensor, P2463 soot accumulation(B1), P246F exhaust gas (B154), pit man arm, right outer tie rod, rear pads/rotors, 4WD not working, driver seat ripped. Multiple codes, 4WD problems, power lock problems, steering and brake issues, spare tire key for winch missing, signs of coolant between transmission and engine, both bumpers rusted/dented/scratched, left front fender road rash, left rear fender rust/dents/road rash, right side fenders road rash/rust/dents, left rocker panel rusted, left side doors rusted/chips/dents, right side doors rusted/chips/dents/road rash, roof rusting/chips, tailgate poor/rusted/dented, no first aid kit/fire extinguisher, windshield chips, both mirror housing broken, left seat badly worn/cushion visible/holes, right seat worn/torn, left cab corner rusted, trim loose inside left front door, interior soiled, holes in front bump mat, switch for wig wags hanging, poor battery, minor exterior damage.>, As is, where is</p>	313,317 km	\$4,956	1FT7W2BT0GEB63809

Item #	Description	Kms	Min Price	Serial Number
No Bid * 9-019	<p>Truck 2017 FORD F250 SD 4WD, crew cab, 6'10" box 6.2L, V8, gas auto A/C, tilt, cruise, aftermarket AM/FM radio, power heated trailer tow mirrors, power locks/windows, keyless entry-2 key fobs front tow hooks, side steps, mud flaps, hitch, trailer wiring, OEM trailer brake, box liner, headache rack, has back seat, white, TOW ONLY –</p> <p>This vehicle has an UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in "As is, where is" condition., 334,118 km, , KNOWN PROBLEMS and OBSERVATIONS: Exhaust manifold, front shocks, left outer tie rod, alignment needed, rear brake line not secured.</p> <p>Grille holes drilled, hood dents/stone chips, front bumper chips, rear bumper rusted/holes drilled, left front fender chips, left rear fender scratch, right rear fender small dents, left front door dents, tailgate chips/small dents, no first aid kit/fire extinguishers, windshield chips, left front seat sagging, holes drilled in box rails, front valance broken, poor battery, minor exterior damage.>, As is, where is</p>	334,118 km	\$9,920	1FT7W2B60HEE88021
9,080.70 11-018	<p>Van 2006 CHEVROLET Express 3500 Cargo RWD, 14' x 7'6" Unicell Cube 7'h 6.0L, V8, gas auto A/C, tilt, cruise, AM/FM, 3 keys rollup rear door, HD step, 6' x 12" grated step at rear, van body mirrors, dual rear wheels, white, TOW ONLY –</p> <p>This vehicle has an UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in "As is, where is" condition., 33,214 km, , KNOWN PROBLEMS and OBSERVATIONS: Engine light on, misfiring, oil cooler lines, power steering pump, exhaust leak from left exhaust manifold gasket, windshield wiper wash broken off, left front wipers not clearing windshield.</p> <p>Hood paint poor/dents, left front fender rusted, both rocker panels rusted, left front door rust/chips, roof poor paint/large dent, spare tire loose in back may not be compatible with vehicle, no wheel wrench/jack/first aid kit/fire extinguishers, windshield chips/scratches, left front seat badly worn, right cab corner rusted, cube scratches at left rear corners, sealant loose on both rear corners, rollup door scratches, front of cube road rash, molding loose on right side, poor battery, minor exterior damage.>, As is, where is</p>	33,214 km	\$7,369	1GBJG31U761253858

Item #	Description	Kms	Min Price	Serial Number
1,200.00 11-015	<p>Van 2012 DODGE Grand Caravan SE FWD 3.6L, V6, gas auto A/C, tilt, cruise, AM/FM/CD player, power mirrors/windows/locks, keyless entry-2 fobs, 1 key 7 passenger, Stow-N-Go 3rd row seat only, copper head, TOW ONLY –</p> <p>This vehicle has a VERY UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Body Integrity Inspection and a Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in “As is, where is” condition., 224,408 km, , KNOWN PROBLEMS and OBSERVATIONS: Check engine light on codes: P0152, 02B251, P1129 closed loop, P2098 fuel trim, tires cupped, both rocker panels rusted through. Grille upper right broke, hood scratches/chips/paint peeling, front bumper chips, rear bumper holes, left front fender scratches, left rear fender rust/scratches, right front fender dent/road rash, right rear fender rust/scratches/road rash, both dog legs rust, both rocker panels rusted through, left front door road rash, left rear door dent/rust/road rash, roof rust at front edge, tailgate glass scratched, no first aid kit/fire extinguisher, poor battery, minor exterior damage.>, As is, where is</p>	224,408	\$962	2C4RDGBG7CR272148

Item #	Description	Kms	Min Price	Serial Number
REGINA, SaskBuilds and Procurement, SaskSurplus Sales Lot, 500 McLeod Street - Miscellaneous				
Contact SaskSurplus 306-787-2062 or 306-798-3306, sasksurplus@gov.sk.ca				
25.00 * 10-107	Tires, Lot of 2 225/60R16, Goodyear Integrity, M+S Manufacture date, week 23, year 2008. Fair		\$20	
109.00 * 10-103	Tires, Lot of 4 225/65R17, Firestone Weathergrip, Snowflake, M+S Manufacture date week 31, year 2020. Fair		\$100	
No Bid * 9-113	Desk, L-shape, wood Light brown, 5 drawers with lock and 2 keys, adjustable feet, comes with hardware, main 66.5"w x 35.5" d x 29.5" h, return side 43.5"w x 20.5"d x 28" h, comes with monitor riser with pull-out tray, some scratches and water damage, missing one adjustable foot. Fair		\$1	
No Bid * 9-114	Desk, L-shape, wood Light brown, 5 drawers with lock and 2 keys, adjustable feet, no hardware, main 66.5"w x 35.5" d x 29.5" h, return side 43.5"w x 20.5"d x 28" h, comes with monitor riser with pull-out tray, some scratches and water damage. Fair		\$1	
No Bid * 9-115	Desk, U-shape, wood Dark brown, 1 drawer, adjustable feet, has hardware, main 108" w x 20" w, left return, 72.25" w x 32.5" d, right return 120" w x 20.5" w x 29.5" h, some scratches, surface laminate lifting, back has cracked. Fair		\$1	
20.00 11-101	Printer, Hewlett-Packard LaserJet Enterprise 600, M602X Operational (powers on, no noises, no further testing), some scratches, wiped/reset, no power cord. Fair		\$1	CNCCF2N01V
20.00 11-102	Printer, Hewlett-Packard LaserJet Enterprise 600, M602X, floor model Operational (powers on, no noises, no further testing) on wheels, some scratches, wiped/reset, no power cord. Fair		\$1	CNBCD941G9
25.00 11-103	Printer, Hewlett-Packard LaserJet Enterprise, M605X Operational (powers on, no noises, no further testing), some scratches, wiped/reset, no power cord. Fair		\$1	CNDCJ8L0CY
18.29 11-104	Printer, Hewlett-Packard LaserJet Enterprise, M605X Operational (powers on, no noises, no further testing), some scratches, wiped/reset, no power cord. Fair		\$1	CNDCJB21NS
150.00 11-105	Printer, Hewlett-Packard LaserJet Enterprise, M605X Operational (powers on, no noises, no further testing), some scratches, wiped/reset, no power cord. Fair		\$1	CNDCJDC141
150.00 11-106	Printer, Hewlett-Packard LaserJet Enterprise, M605X Operational (powers on, no noises, no further testing), some scratches, wiped/reset, no power cord. Fair		\$1	CNDCJDC14B

Item #	Description	Kms	Min Price	Serial Number
27.00 11-107	Printer, Hewlett-Packard LaserJet Enterprise, M605X Operational (powers on, no noises, no further testing), some scratches, wiped/reset, no power cord. Fair		\$1	CNDCK1R007
55.00 11-108	Printer, Hewlett-Packard LaserJet Enterprise, M608X Operational (powers on, no noises, no further testing), some scratches, wiped/reset, no power cord. Fair		\$1	CNBCK651SS
55.00 11-109	Printer, Hewlett-Packard LaserJet Enterprise, M608X Operational (powers on, no noises, no further testing), some scratches, wiped/reset, no power cord. Fair		\$1	CNBCK651T5
55.00 11-110	Printer, Hewlett-Packard LaserJet Enterprise, M608X Operational (powers on, no noises, no further testing), some scratches, wiped/reset, no power cord. Fair		\$1	CNBCLBS1T8
49.00 11-111	Printer, Hewlett-Packard LaserJet Enterprise, M608X Operational (powers on, no noises, no further testing), some scratches, wiped/reset, no power cord. Fair		\$1	CNBCM3N12Z
51.00 11-112	Printer, Hewlett-Packard LaserJet Enterprise, M608X Operational (powers on, no noises, no further testing), some scratches, wiped/reset, no power cord. Fair		\$1	CNBCMBX2F4
101.00 11-113	Printer, Hewlett-Packard LaserJet Pro, M479FDN, Color MFP Operational (powers on, no noises, no further testing), some scratches, wiped/reset, no power cord. Fair		\$1	CNCRP2L4QR
56.56 11-114	Printer, Hewlett-Packard LaserJet, M527F MFP Operational (powers on, no noises, no further testing), some scratches, wiped/reset, no power cord. Fair		\$1	MXBCHBTOVG
20.00 11-115	Printer, Hewlett-Packard LaserJet, P4015X Operational (powers on, no noises, no further testing), some scratches, wiped/reset, no power cord. Fair		\$1	CNDY839624
20.00 11-116	Printer, Hewlett-Packard LaserJet, P4015X Operational (powers on, no noises, no further testing), some scratches, wiped/reset, no power cord. Fair		\$1	JPDF272697
49.00 11-117	Printer, Lexmark International Inc, XC4140, floor model Operational (powers on, no noises, no further testing) on a cart with wheels, some scratches, wiped/reset, no power cord. Fair		\$1	7528744011TV2
50.00 11-118	Printer, Lexmark International Inc, XM1145 Operational (powers on, no noises, no further testing), some scratches, wiped/reset, no power cord. Fair		\$1	70156PHH1447T

Item #	Description	Kms	Min Price	Serial Number
LA RONGE, Environment, 800 Poirier St				
Contact Mark Duffy 306-425-7595, mark.duffy@gov.sk.ca				
2,413.00	11-530 ATV,2008 Arctic Cat 366 4X4366cc, 1 cylinder, gasstandard 1 key1434 kmKNOWN PROBLEMS: Has a new carb but needs a tune up to get running. As is, where is	1434 km	\$1	RFB08ATV28K6T4931
377.00	11-526 Outboard Motor, Suzuki 2.2 hp With internal fuel tank, was operational when placed into storage. Fair		\$1	
711.00	11-527 Outboard Motor, Suzuki 30 hp 2 stroke With oil tank, was operational when put into storage. Fair		\$1	03003-461880
433.33	11-528 Outboard Motor, Suzuki 4 hp With internal fuel tank, was operational when put into storage. Fair		\$1	
LA RONGE, Saskatchewan Public Safety Agency, Hangar 2 Athabasca Airways Rd				
Contact Mike Towill 306-425-4585, mike.towill@gov.sk.ca or JD Faubert 306-425-4587, jeandenis.faubert@gov.sk.ca				
645.56	11-553 Air Condition Servicing Units, Lot of 2 Mother boards are no good, parts only, non-operational. Beyond Repair		\$1	
6,500.00	11-554 Engine Stands, Lot of 2 CL215 These stands are not certified and will be sold as scrap. Poor		\$100	
1,366.60	11-555 Golf Cart, Battery powered golf cart with solar charging panel, batteries are dead. Fair		\$200	
600.00	11-556 Hydraulic Jacks, Lot of 4 For low wing aircraft. Fair		\$100	
1,250.00	11-557 Starter Tester, Aircraft D/C, testing clutch, operational when removed from service. Fair		\$100	
1,250.00	11-558 Tester, Aircraft D/C, generator test unit, operational when removed from service. Fair		\$100	
211.11	11-559 Welder, Acklands, Tungsten, arc AC/DC, operational when removed from service. Fair		\$100	
750.00	11-560 Welder, Syncrowave 351, Millerwelder AC/DC welding power source, works intermittently, problem unknown. Fair		\$100	

Item #	Description	Kms	Min Price	Serial Number
MEADOW LAKE, Environment, 311 6th St E				
Contact Chad Doherty 306-240-9989, chad.doherty@gov.sk.ca				
2,145.00	11-531 Snowmobile 2008 Polaris 550 Touring 550cc, 1 cylinder, gas 1 key, , , 4123.6 km, , KNOWN PROBLEMS: Tune up needed, poor battery, has never been registered with SGI, minor exterior damage.>, As is, where is	4123.6 km	\$1	S1NT5B558C358579
2,100.00	11-529 Snowmobile 2007 Yamaha Venture Lite 1 cylinder, gas 1 key, , , unknown km, , KNOWN PROBLEMS: Tune up needed, was operational when last used several years ago, dead battery, km has never been registered with SGI minor exterior damage.>, As is, where is	unknown	\$1	JYE86J0077A000998
MEADOW LAKE PROVINCIAL PARK, Parks Culture and Sport, Highway 224				
Contact Heath Harpham 306-839-7323, heath.harpham@gov.sk.ca				
889.00	11-552 Snowmobile year unknown Ski Doo Alpine gas single ski, electric start, 1 key , orange, , 3,508 km, , KNOWN PROBLEMS: will run but may be hard to start, poor windscreen, poor paint, poor body, poor battery.>, As is, where is	3,508 km	\$400	2583282B
OUTLOOK, Agriculture, 410 Saskatchewan Ave W				
Contact Ben Lalonde 306-867-6469, ben.lalonde@gov.sk.ca or Outlook Front Desk 306-867-5500, stacey.stutters@gov.sk.ca				
No Bid	11-509 GPS Base Radio, Pacific Crest PDL 4335 GPS 430-450Mhz radio for GPS system, significant wear, unknown if still operational, stored in a cool dry place for many years, no cables included. Poor		\$5	8,091,658
10.00	11-510 Leveling Rod, 1 set of 5m, aluminum, unknown brand, brown leather or vinyl case Total height 5m, set has 4 pieces that clip together, carrying case included case is blue nylon, case is brown leather or vinyl, rods have not been used for decades, stored in a cool dry place, noticeable wear present. calibration likely required. Fair		\$10	
No Bid	11-511 Leveling Rod, 1 set of 5m, aluminum, unknown brand, brown leather or vinyl case Total height 5m, set has 4 pieces that clip together, carrying case included case is blue nylon, case is brown leather or vinyl, rods have not been used for decades, stored in a cool dry place, noticeable wear present. calibration likely required. Fair		\$10	
No Bid	11-512 Leveling Rod, 1 set of 5m, aluminum, unknown brand, brown leather or vinyl case Total height 5m, set has 4 pieces that clip together, carrying case included case is blue nylon, case is brown leather or vinyl, rods have not been used for decades, stored in a cool dry place, noticeable wear present, calibration likely required. Fair		\$10	
No Bid	11-513 Surveying Tripod, Duratech, wood, flat head Stored in a cool dry place, clamps are somewhat loose, one leg is partially detached from the hinge (needs a new screw), noticeable wear present, tightening and calibration likely required. Fair		\$20	

Item #	Description	Kms	Min Price	Serial Number
30.00 11-514	Surveying Tripod, Leica, wood, flat head Stored in a cool dry place, clamps are somewhat loose, noticeable wear present, tightening and calibration likely required. Fair		\$25	
No Bid 11-515	Surveying Tripod, Leica, wood, telescoping antenna pole Stored in a cool dry place, clamps are somewhat loose, noticeable wear present, tightening and calibration likely required. Fair		\$30	
PRINCE ALBERT, Community Safety, 1827 - 1 Ave W				
Contact Richard LaClaire, richard.laclaire@gov.sk.ca or Graham Topoorowski, graham.toporowski@gov.sk.ca				
1.00 11-506	Oven, Moffat, MCB757DM2WW 30 inch range, self cleaning, oven door hinges broken, door not attached, stove top elements work but are in poor condition, operational. Broken Repairable		\$1	TS508812P
PRINCE ALBERT, Community Safety, 3021 1st Ave W				
Contact Tonya Granberg, tonya.granberg@gov.sk.ca or Nola Boechler, nola.boechler@gov.sk.ca				
No Bid 11-507	Cups, Lot of 12 ceramic White. Fair		\$1	
No Bid 11-508	Napkin Holders, Lot of 9 Stainless steel. Poor		\$1	
PRINCE ALBERT, Environment, 301 Red Wing Drive				
Contact Kory Bertrand 306-941-8675, kory.bertrand@gov.sk.ca, Chance Prestie 306-420-4306, chance.prestie@gov.sk.ca, Doug Gullickson, doug.gullickson@gov.sk.ca or				
360.00 11-517	Generator, Honda EB 2200 2200 watt, 120 volt output, pulls over but needs a tune up. Fair		\$1	
480.00 11-518	Generator, Honda EB 5000x 5000 watt, 120/240 volt output, pulls over but needs a tune up, has modified exhaust that can be removed. Fair		\$1	
770.00 11-519	Outboard Motor, Honda 15 hp, longshaft outboard motor, operational, slow leak from bottom end. Good		\$1	BAAS-1801168
450.00 11-520	Outboard Motor, Johnson 25 hp, long shaft, black, unknown if operational. Fair		\$1	G04171118
400.00 11-521	Outboard Motor, Johnson 25 hp, long shaft, white, unknown if operational. Fair		\$1	R 08620767
456.78 11-523	Trailer, 1975 Homebuilt utility, 10'1 x 5' single axle, wooden sided, wiring for lights, lights are non-operational, 2" receiver, used for snowmobile, could be used for hauling other equipment As is, where is		\$1	SASK90577000393

Item #	Description	Kms	Min Price	Serial Number
678.90 11-524	Trailer,1971 utility, 9'7"l x 7'w single axle trailer for quad, expanded metal sides, wiring for lights, lights are non-operational, 2" receiver As is, where is		\$1	NW11971
1,580.00 11-525	Trailer,1985 tandem axle, 15'9"l x 6'4" w wooden deck with fold down ramps, wooden sides and front, 2 5/16 receiver, wiring for lights, lights are non-operational, brakes are present, unknown if functional, two flat tires As is, where is		\$1	2LSF2T7F6FP000037
125.25 11-522	Trolling Motor, Minn Kota Vector Electric, 55 lbs of thrust, operational. Fair		\$1	
REGINA, Health, 3475 Albert St				
Contact: Steve Fairbairn 306-530-7703, steve.fairbairn@health.gov.sk.ca or Vicki Buchanan 306-787-8308, vicki.buchanan@health.gov.sk.ca				
No Bid 11-546	Truck-Mount Cold Fogger, 2003 Maxi Pro 145 Ultra-low volume aerosol generator designed for mosquito and fly control applications, 18 HP Briggs & Stratton gasoline engine with electric start, single Dyna-Fog Multi-Mist nozzle, engineered to produce 90% of droplets below 20 microns, output control available with a gear pump or FMI piston pumping system, constructed with welded steel and powder-coat finishes for corrosion resistance. Unit has been flushed with isopropyl alcohol and washed after each use but the tanks that hold the pesticide cannot be cleaned. **Please see the attached Deltagard SC Insecticide PDF below for handling instructions and proper Personal protective equipment (PPE) requirements. The successful bidder must sign a disclaimer attached below in acknowledgement of the potential hazards, and PPE requirements before payment will be accepted. *Online viewing only - serious inquires may request an appointment for viewing on-site Excellent		\$2,000	293
No Bid 11-547	Truck-Mount Cold Fogger, 2003 Maxi Pro 145 Ultra-low volume aerosol generator designed for mosquito and fly control applications, 18 HP Briggs & Stratton gasoline engine with electric start, single Dyna-Fog Multi-Mist nozzle, engineered to produce 90% of droplets below 20 microns, output control available with a gear pump or FMI piston pumping system, constructed with welded steel and powder-coat finishes for corrosion resistance. Unit has been flushed with isopropyl alcohol and washed after each use but the tanks that hold the pesticide cannot be cleaned. **Please see the attached Deltagard SC Insecticide PDF below for handling instructions and proper Personal protective equipment (PPE) requirements. The successful bidder must sign a disclaimer attached below in acknowledgement of the potential hazards, and PPE requirements before payment will be accepted. *Online viewing only - serious inquires may request an appointment for viewing on-site Excellent		\$2,000	292

Item #	Description	Kms	Min Price	Serial Number
No Bid 11-548	Truck-Mount Cold Fogger, 2003 Maxi Pro 145 Ultra-low volume aerosol generator designed for mosquito and fly control applications, 18 HP Briggs & Stratton gasoline engine with electric start, single Dyna-Fog Multi-Mist nozzle, engineered to produce 90% of droplets below 20 microns, output control available with a gear pump or FMI piston pumping system, constructed with welded steel and powder-coat finishes for corrosion resistance. Unit has been flushed with isopropyl alcohol and washed after each use but the tanks that hold the pesticide cannot be cleaned. **Please see the attached Deltagard SC Insecticide PDF below for handling instructions and proper Personal protective equipment (PPE) requirements. The successful bidder must sign a disclaimer attached below in acknowledgement of the potential hazards, and PPE requirements before payment will be accepted. *Online viewing only - serious inquires may request an appointment for viewing on-site Excellent		\$2,000	295
No Bid 11-549	Truck-Mount Cold Fogger, 2003 Maxi Pro 145 Ultra-low volume aerosol generator designed for mosquito and fly control applications, 18 HP Briggs & Stratton gasoline engine with electric start, single Dyna-Fog Multi-Mist nozzle, engineered to produce 90% of droplets below 20 microns, output control available with a gear pump or FMI piston pumping system, constructed with welded steel and powder-coat finishes for corrosion resistance. Unit has been flushed with isopropyl alcohol and washed after each use but the tanks that hold the pesticide cannot be cleaned. **Please see the attached Deltagard SC Insecticide PDF below for handling instructions and proper Personal protective equipment (PPE) requirements. The successful bidder must sign a disclaimer attached below in acknowledgement of the potential hazards, and PPE requirements before payment will be accepted. *Online viewing only - serious inquires may request an appointment for viewing on-site Excellent		\$2,000	294
No Bid 11-550	Truck-Mount Cold Fogger, 2003 Maxi Pro 145 Ultra-low volume aerosol generator designed for mosquito and fly control applications, 18 HP Briggs & Stratton gasoline engine with electric start, single Dyna-Fog Multi-Mist nozzle, engineered to produce 90% of droplets below 20 microns, output control available with a gear pump or FMI piston pumping system, constructed with welded steel and powder-coat finishes for corrosion resistance. Unit has been flushed with isopropyl alcohol and washed after each use but the tanks that hold the pesticide cannot be cleaned. **Please see the attached Deltagard SC Insecticide PDF below for handling instructions and proper Personal protective equipment (PPE) requirements. The successful bidder must sign a disclaimer attached below in acknowledgement of the potential hazards, and PPE requirements before payment will be accepted. *Online viewing only - serious inquires may request an appointment for viewing on-site Excellent		\$2,000	296

Item #	Description	Kms	Min Price	Serial Number
REGINA, Legislative Assembly Service, 515 Henderson Drive				
Contact: Karen Plumb 306-787-8167, kplumb@legassembly.sk.ca				
No Bid * 8-501	Uninterruptable Power Supply with Batteries and Power Modules, Lot of 11 APC Symmetra 1 APC Symmetra LX UPS, SYAF16KRMT, 7 APC Symmetra LX Battery Module, SYBT5, 2 APC Symmetra LX Power Module, SYPM4KP, 1 APC Symmetra LX Power Module, SYPM4KPQ. UPS: 19"w x 27"d x 33"h, (shipping 42 x 24 x 40) 500lbs, each battery is 18 kg, 4 batteries in box, 3 loose, unknown what condition batteries are in, no power cord as it has to be direct wired into building power. Sold as is. UPS: QD1037260148, in-box batteries: 5D2007T60139, 5D2018T65313, 5D2018T65320, 5D2007T60123, loose batteries: 5D2005T15219, 5D2007T60147, 5D2007T60138, SYPM4KP, power modules: QD1513380215, AD2033110087, SYPM4KPQ power module: AQ2106210005, operational. Fair		\$1,000	
REGINA, Saskatchewan Liquor and Gaming Authority, 1702 Park St				
Contact Shola Babarinde 306-787-5864, sbabarinde@slga.com or Tyrone Smith 306-787-1934, tsmith1@slga.com				
No Bid 11-533	Cabinet , wood, lateral Brown, 2 drawers, few scratches, 20" w x 36" l x 29" h. Fair		\$15	
No Bid 11-534	Cabinet , wood, lateral Brown, few scratches with tape residue, 20" w x 37" d x 29" h. Fair		\$15	
32.00 11-535	Chair, mesh Black, adjustable. Good		\$5	
No Bid 11-536	Desk, wood, lateral Brown, few scratches, 21.5" w x 72" d x 30" h Fair		\$25	
No Bid 11-537	Desk, wood, lateral Brown, few scratches, 36" w x 72" d x 30 h. Fair		\$25	
32.00 11-538	File Cabinet, metal, lateral Beige, 4 drawer, 1 shelf with key, 36" w x 19.4" d x 66" h, top panel only engages lock on one side. Fair		\$10	
32.00 11-539	File Cabinet, metal, lateral Black, 3 drawer, 1 shelf, no key, 36" w x 19.5" d x 53" h. Good		\$10	
No Bid 11-540	File Cabinet, wood, lateral Brown, 3 drawers with keys, 20" w x 30" d x 44" h Good		\$10	
5.25 11-541	Table, wood Brown, rectangular, few scratches, 19.5" w x 29" d x 20" h. Fair		\$5	
25.83 11-542	Table, wood Brown, steel legs, rectangular, 30" w x 60" d x 28" h. Fair		\$10	

Item #	Description	Kms	Min Price	Serial Number
25.22 11-543	Table, wood Brown, steel legs, rectangular, 36" w x 72" d x 29" h. Good		\$10	
26.66 11-544	Table, wood Brown, steel legs, rectangular, 36" w x 72" d x 29" h. Fair		\$10	
5.00 11-545	Table, wood White, steel legs, 23.5" w x 20" d x 28.5" h. Poor		\$1	
REGINA, SaskBuilds and Procurement, 110 Henderson Drive				
Contact Matthew Frison 306-787-7030, matthew.frison@gov.sk.ca				
1,111.00 11-503	Forklift Clark TM20 electric max capacity 1587.6 Kg, 1 key comes with charger, green, , unknown hrs, , KNOWN PROBLEMS and OBSERVATIONS: Non-operational, battery needs replacement, will not charge, tires heavily worn, seat is torn, lights and horn unknown if operational, minor exterior damage.>, As is, where is	unknown hrs	\$1	TM 247-0443-9058FB
250.00 11-502	Pallet Jack Crown 60PE electric max capacity 2721.6 Kg, 2 keys comes with charger, grey, , 2,517 hours, , KNOWN PROBLEMS and OBSERVATIONS: Non-operational, battery needs replacement, will not charge, tires heavily worn, unknown if horn is operational, minor exterior damage.>, As is, where is	2,517 hours	\$1	W-48224
REGINA, SaskBuilds & Procurement, *Online Viewing Only*, 1920 Rose Street				
Contact: Christina Rodman 306-787-9255, christina.rodman@gov.sk.ca or 306-787-9231, controlroom@gov.sk.ca				
52.01 * 10-508	Server Racks, metal 23.5"w x 37.5" d x 81.5"h, good shape, four wheels, with a front single door only, front door has a lock but no key. *Online Viewing Only* Good		\$25	
ROWAN'S RAVINE PROVINCIAL PARK, Community Safety, Highway 220				
Contact Kaleb MacCrimmon 306-725-5200, kaleb.maccrimmon@gov.sk.ca				
1,278.00 11-532	Snowmobile 2001 Polaris Sport Touring 550cc, 2 stroke, gas, direct inject oil mixture belt driven, clutch 2 up - rear seat, 1 key available to view on February 8, 2026 between 12:00PM and 3:00PM at the Rowan's Ravine Provincial Park maintenance yard, , , 8,741 km, , KNOWN PROBLEMS: Initial start is difficult, poor brakes, poor battery, minor exterior damage.>, As is, where is	8,741 km	\$1	4XAST5BS31C134648
SASKATOON, Saskatchewan Research Council, Bay 2D 820 51st St E				
Contact Aamir Bakhsh 306-370-8011, Aamir.Bakhsh@src.sk.ca or Gina Zimmer 306-250-9690, gina.zimmer@src.sk.ca				
No Bid * 8-540	Pipe Fittings, grooved 5 pallets, never used or installed. New- Unused		\$500	

Item #	Description	Kms	Min Price	Serial Number
SASKATOON, Saskatchewan Research Council, 820 51st St E				
Contact Roger Dauvin 306-385-4035, roger.dauvin@src.sk.ca or purchasing@src.sk.ca				
No Bid * 9-512	Dehydrator, Hungry Giant, HGF-320ML Operational, put into use 2020 (RFQ 1920-011 ; 256532). Good		\$15,000	HGF320ML-CAN1601-001
SASKATOON, Western Canada Lottery Corporation, 1914 1st Ave North				
Contact: David Tutka 306-933-6926 or 306-230-0905 , tutkad@sk-wclc.com				
2,525.25 11-501	Van 2019 Dodge Grand Caravan SE 2WD 3.6L, V6, gas auto Air/tilt/cruise, AM/FM/CD player, power windows/locks/seat, 2 key fobs 6 speed, cargo barrier, GVW 2,745 kg, wheel base 3078mm, tire size 225/65R17, 4 ply, 2nd row seating stowed, white, TOW ONLY, NO SGI Inspection. It is unknown if any repairs or safety concerns exist (if any). Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs if required. , 332,130 km, Known Recent Repairs: new front tires, KNOWN PROBLEMS: Missing 3rd row seats, dead battery, minor exterior damage.>, As is, where is	332,130 km	\$1	2C4RDGBG9KR734336
SOUTHEND, Community Safety, 15 College Dr				
Contact: Casey Howey 306-758-6254, casey.howey@gov.sk.ca				
51.45 11-504	Depth Finder, Lowrance Elite - 4x With transducer, speedo cable unit. (1 attachment), operational. Good		\$1	104,761,844
51.45 11-505	Depth Finder, Lowrance Elite - 5x With mount, power cord and transducer. (1 attachment), operational. Good		\$1	103,385,625
WEYBURN, Community Safety, 100D 18th Street				
Contact Lindsey Leko 306-891-9106, Lindsey.Leko@gov.sk.ca				
2,165.60 11-516	Snowmobile 1999 Polaris Indy Trail Touring 2 stroke, gas , blue, , km unknown, Known Recent Repairs: carb has been serviced over the past two years, KNOWN PROBLEMS: Unknown if operational, machine has not been used for 2 years, As is, where is	km unknown	\$100	4XAET4ESSOXC069026