

SALE SUMMARY LIST

PLEASE NOTE: Every effort has been made to accurately describe items and their condition; however, additional problems may exist, items may not be complete or exactly as described. Bidders are deemed to have reviewed the Terms and Conditions on bid forms and relied entirely on their own inspection and evaluation prior to bidding. Vehicles and equipment are sold "AS IS, WHERE IS", there is no implied or express warranty.

Visit www.SaskSurplus.ca for pictures and link to download Bid Form.

- Items identified with * have been on a previous sale and will be listed first on www.SaskSurplus.ca web site.
- SaskBuilds and Procurement, SaskSurplus, reserves right to have unadvertised minimum selling prices on items.

It is the Bidder's responsibility to review the terms and conditions of sale on the Offer to Purchase, Bid Form.

Bid Forms are available from www.SaskSurplus.ca or from the SaskSurplus Sales Lot, 500 McLeod Street, Regina, SK.

Bid Forms can be submitted in the following ways:

- by deposit in the bid box at the SaskSurplus Sales Lot,
- by fax to 306-787-2092; by phone 306-787-2062 or 306-798-3300,
- by email to sasksurplus@gov.sk.ca, or
- by mail, addressed to: Ministry of SaskBuilds and Procurement, SaskSurplus, 500 McLeod Street, Regina, SK S4N 4Y1.

(If mailing your bid, please allow sufficient time for bid to be received.)

- Bids received after close date and time cannot be accepted.

MT = (Ministry Transfer) This means that the item has been claimed by another ministry and automatically transferred to the ministry.

WD = (Withdrawn) This can happen if the item was requested to be removed by the seller.

No Bid = Items that did not receive any bids are normally carried forward to the next sale or may be withdrawn.

Bid Price	Item #	Description	Kms	Min Price	Serial Number
REGINA, SaskBuilds and Procurement, SaskSurplus Sales Lot, 500 McLeod Street - Vehicles					
Contact SaskSurplus 306-787-2062 or 306-798-3306, sasksurplus@gov.sk.ca					
\$1,081.00	12-001	<p>Car 2013 CHEVROLET Impala LS FWD 3.6L, V6, gas auto A/C, tilt, cruise, AM/FM/CD player, power mirrors/locks/windows/left front seat/trunk release, keyless entry-1 fob, 1 key , white, km TOW ONLY –</p> <p>This vehicle has a VERY UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Body Integrity Inspection and a Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in “As is, where is” condition., 251,915 km, , KNOWN PROBLEMS and OBSERVATIONS: Right outer tie rod, right front hub bearing, front and rear pads/rotors, all four tires, alignment needed, driver lock switch, driver door pins, rocker panels. Note: transaxle noise.</p> <p>Note: Misfire at idle, cam shaft/rocker arms are rust/pitted and damaged. Hood chips/scratches, front bumper broken, rear bumper scratches/clear coat peeling, left rear fender rusted, right front fender paint cracked, right rear fender rusted, right rocker panel rusted, left side doors rusted, roof rusted, trunk lid scratches, no first aid kit/fire extinguishers, no first aid kit/fire extinguisher, windshield chips, left front seat worn/ripped, left head light fogged, full size tire and rim in trunk may not be compatible with vehicle, poor battery, minor exterior damage.> , As is, where is</p>	251,915	\$481	2G1WA5E38D1248426
\$5,432.10	12-002	<p>SUV 2014 CHEVROLET Tahoe LTZ 4WD 5.3L, V8, gas auto A/C, tilt, cruise, AM/FM/CD player, power mirrors/locks/windows/front seats, rear HVAC, keyless entry-1 fob, 1 key front tow hooks, hitch, trailer wiring, 5 passenger, white, TOW ONLY –</p> <p>This vehicle has an UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in “As is, where is” condition., 253,707 km, , KNOWN PROBLEMS and OBSERVATIONS: Both outer tie rods, alignment needed, both rear doors missing locks, both rear windows switches.</p> <p>Hood road rash, both bumpers’ chips/scratches, left side fenders chips, right side fenders rust/chips, left rocker panel door sill paint off, left side doors chips, rear right door panel ripped, both rear door locks deactivated, no pop-up locks on rear doors, roof dents, 10 holes in roof sealed, tailgate chips/scratches/glue on spoiler, wheel wrench missing, no first aid kit/fire extinguisher, windshield chips, left front seat back hole, holes drilled in dash, holes drilled in rear cargo area, trim on inside B pillar modified, holes in head liner, missing trim in rear cargo area, both interior quarter trim modified, some trim on all seats loose or missing, missing center console, poor battery, minor exterior damage.> , As is, where is</p>	253,707	\$3,868	1GNSK2E05ER181047

Bid Price	Item #	Description	Kms	Min Price	Serial Number
\$1,426.00	12-003	<p>SUV 2008 Jeep Commander Sport 4WD 3.7L, V6, gas auto A/C, tilt, cruise, AM/FM/CD player, power heated mirrors, power locks/windows/left front seat, 2 key fobs 5 passenger, driving lights, hitch, trailer wiring, green, TOW ONLY –</p> <p>This vehicle has a VERY UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Body Integrity Inspection and a Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in “As is, where is” condition., 198,026 km, , KNOWN PROBLEMS and OBSERVATIONS: Left lower ball joint loose, outer tie rod boot missing cotter pins, front/rear rotors rusted out and pads, left inner tie rod boot not attached, front lower control arm bushing damaged, rockers rusted through, steering wheel not straight, rear differential vent broken, park brake does not hold, door switch doesn’t unlock, rear doors, both rear doors don’t open-locks jammed, brake rotors very rusty, minor leaks starting. Hood dents/chips/scratches, front bumper chips/scratches, rear bumper chips/scratches/missing 2 sensors, left front fender chips/road rash/rust, left rear fender road rash, right front fender chips/rust/road rash, right rear fender road rash, both dog legs road rash/rusted, both rocker panels rusted/large holes, left front door road rash, left rear door road rash/molding loose, right side doors road rash/chips, roof rusted, roof rails weathered, tailgate scratches, no OEM spare, full size tire and rim loose in rear may not be compatible with vehicle, no first aid kit/fire extinguishers, windshield chips, poor battery, minor exterior damage.>, As is, where is</p>	198,026 km	\$755	1J8HG48K08C225162

Bid Price	Item #	Description	Kms	Min Price	Serial Number
\$6,473.00	12-005	<p>Truck 2009 CHEVROLET Silverado 2500 HD 4WD, extended cab, 8' box 6.0L, V8, gas auto A/C, tilt, cruise, AM/FM/CD player, power mirrors/locks/windows, 2 keys front tow hooks, mud flaps, side steps, hitch with pintle insert, trailer wiring, electric trailer brake, Brand FX slide-in, ladder rack with beacon, no back seat, white, TOW ONLY –</p> <p>This vehicle has a VERY UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Body Integrity Inspection and a Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in “As is, where is” condition., 196,518 km, , KNOWN PROBLEMS and OBSERVATIONS: Rear brake rotors excessively rusty, left low beam headlight out, both headlight lens fogged, both front fenders have rust holes, rear seats and seat belts missing.</p> <p>Grille broke, front bumper rust, left front fender badly rusted, left rear fender rusted, right front fender badly rusted, right rear fender rusted, left side doors scratches/rusted, right rear door rusted, roof rust spots, one hole in roof sealed, jack missing, no first aid kit/fire extinguisher, windshield chips, left mirror housing broke, left front seat worn/ripped/ sagging, tire low pressure light on, both headlights fogged, holes drilled and bolts cut in rear seat area, one hanger for rear seat cut off, Brand FX slide-in roll out does not work, rear door gasket hanging, rusted at rear door, holes drilled in dash, no back seat or belts, poor battery, minor exterior damage.>, As is, where is</p>	196,518 km	\$6,473	1GCHK49K79E134643
\$4,990.00	12-004	<p>Truck 2017 CHEVROLET Silverado 1500 4WD, crew cab, 6'6" box 5.3L, V8, gas auto A/C, tilt, cruise, AM/FM, power mirrors/locks/windows, keyless entry-2 fobs, 2 keys, 1 toolbox key Brute Gull Wing toolbox 1 key-dented, mud flaps, side steps, front tow hooks, hitch, trailer wiring, OEM trailer brakes, box liner headache rack, beacon, wig wags on rack and grille, has a back seat, white, TOW ONLY –</p> <p>This vehicle has an UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in “As is, where is” condition., 346,987 km, , KNOWN PROBLEMS and OBSERVATIONS: Left lower ball joint loose, left CV axle boot blown, service air bag light on.</p> <p>Hood chips, front bumper road rash, rear bumper dents, left side fenders chips/road rash, right front fender chips, right rear fender road rash/rust, left side doors road rash, roof chips, tailgate chips/dents/scratches, no first aid kit/fire extinguisher, windshield chips, seats are soiled, left front seat worn/sagging, poor battery, minor exterior damage.>, As is, where is</p>	346,987 km	\$4,989	1GCUKNEC3HF133839

Bid Price	Item #	Description	Kms	Min Price	Serial Number
\$6,015.00 *	11-003	<p>Truck 2018 CHEVROLET Silverado 1500 4WD, crew cab, 6'7" box 5.3L, V8, gas auto A/C, tilt, cruise, AM/FM, power mirrors/locks/windows/left front seat, keyless entry-2 fobs, 2 keys side steps, front tow hooks, mud flaps, hitch, trailer wiring, OEM trailer brakes, toolbox behind cab no key, has back seat, grey, TOW ONLY –</p> <p>This vehicle has an UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in “As is, where is” condition., 308,303 km, , KNOWN PROBLEMS and OBSERVATIONS: Front struts leak, rear shocks leaking, exhaust flex pipe separating, left upper ball joint, both plate bulbs non-operational, high mount bulb non-operational. Front bumper bent/road rash, right front fender dents/scratches, right rear fender scratches/road rash, right side doors scratches, roof badly dented, tailgate scratches/hard to open, no first aid kit/fire extinguisher, windshield chips, left front seat worn/sagging, front valance loose, left A pillar dented/road rash, right side step bent, poor battery, minor exterior damage.>, As is, where is</p>	308,303 km	\$5,295	3GCUKNEC7JG107040
\$2,676.60	12-016	<p>Truck 2012 DODGE/RAM 1500 4WD, crew cab, 6'5" box 5.7L, V8, gas auto A/C, tilt, cruise, AM/FM/CD player, power heated mirrors, power locks/windows, keyless entry-2 key fobs, 1 key grille inserts, front tow hooks, side steps, mud flaps, hitch, trailer wiring, roof rack brackets-no cross bar, has a back seat, black, TOW ONLY –</p> <p>This vehicle has an UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in “As is, where is” condition., 337,655 km, , KNOWN PROBLEMS and OBSERVATIONS: Both front axles, left lower ball joint, left outer tie rod, rear sway bar bushing, right hub and bearings, alignment needed, 3rd brake light. Hood chips/scratches/dents, front bumper rusted, rear bumper rusted/bent, left front fender scratches, right front fender scratches/chips, left rear fender scratches/rust, right rear fender rusted/scratches/road rash, both rocker panels road rash, left front door rust, right rear door rust, roof rusted, two holes in roof sealed, tailgate dents/scratches, no first aid kit/fire extinguishers, windshield chips, right mirror housing cracked/broke, left front seat worn/sagging, left front seat back worn, right cab corner rust, holes drilled in box rails, missing lower section of jump seat, poor battery, minor exterior damage.>, As is, where is</p>	337,655 km	\$2,516	1C6RD7KT3CS224679

Bid Price	Item #	Description	Kms	Min Price	Serial Number
\$3,131.60	12-006	<p>Truck 2014 DODGE/RAM 2500 4WD, crew cab, 6'5" box 5.7L, V8, gas auto A/C, tilt, cruise, Am/FM, power windows/locks/mirrors, keyless entry-2 key fobs tow hooks, grille inserts, mud flaps, side steps, hitch, trailer wiring, OEM trailer brakes, "Buyers" Gullwing toolbox-no keys, spare tire on truck, has back seat, red, TOW ONLY –</p> <p>This vehicle has an UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in "As is, where is" condition., 268,464 km, , KNOWN PROBLEMS and OBSERVATIONS: Cannot start vehicle to check items on list, all four ball joints, rear tires, rear windows inoperable, no road test, oil over filled, windshield cracked, washers leaking. Engine seized, failed timing chain caused seized engine, grille loose, hood chips/scratches/dents, front bumper rust/bent, rear bumper dents/bent, all fenders chips/scratches/road rash, rocker panels road rash, all doors chips/scratches, roof dents/chips/scratches, tailgate scratches/chips, a rim and tire in box unknown condition (tire not on rim loose in box), wheel wrench/jack loose in toolbox, no first aid kit/fire extinguisher, windshield cracked, right mirror housing broke, interior badly soiled, poor battery, minor exterior damage.>, As is, where is</p>	268,464	\$1,480	3C6TR5CT5EG202283
\$4,688.88 *	11-013	<p>Truck 2013 DODGE/RAM 1500 SLT 4WD, quad cab, 6'3" box 4.8L, V8, gas auto A/C, tilt, cruise, AM/FM, power heated mirrors, power locks/windows/left front seat, keyless entry-2 key fobs, 1 key for toolbox front tow hooks, mud flaps, hitch, trailer wiring, OEM trailer brakes, Challenger Gull wing toolbox-lid does not stay open, has back seat, white, TOW ONLY –</p> <p>This vehicle has an UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in "As is, where is" condition., 219,390 km, , KNOWN PROBLEMS and OBSERVATIONS: Both lower ball joints, rear links, left front hubs, front fenders. Hood paint peeling/chips, left side fenders badly rusted/chips, right side fenders rusted, both rocker panels rusted, left side doors chips/dents, tailgate will not open/rusted/dented, wheel wrench/jack loose under back seat, no first aid kit/fire extinguisher, windshield chips, left front seat worn/ripped, left side step in box, poor battery, minor exterior damage.>, As is, where is</p>	219,390	\$2,987	1C6RR7GP1DS558868

Bid Price	Item #	Description	Kms	Min Price	Serial Number
\$18,550.00	12-007	<p>Truck 2012 DODGE/RAM 5500 SLT 4WD, crew cab, service body 6.7L, inline 6, diesel auto A/C, tilt, cruise, AM/FM/CD player, power heated trailer tow mirrors, power windows/locks, keyless entry-2 fobs, 3 keys front tow hooks, side steps, mud flaps, pintle hook, trailer wiring, dual rear wheels, BrandX service body 6 compartments-2 beacons, 5 keys, 2 additional storage boxes attached to service body, Altec aerial device model AT237 condition unknown, has a back seat loose in cab, white, TOW ONLY –</p> <p>This vehicle has an UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in “As is, where is” condition., 220,567 km, , KNOWN PROBLEMS and OBSERVATIONS: Engine light on Code P0101 mass air flow sensor A circuit P2 BAC-not exceedance deactivated EGR, all upper and lower ball joints loose in front end, rear seats and belts missing (rear seat is loose in cab needs to be mounted)-condition unknown.</p> <p>Grille broken, hood dents/chips/small rust spots, front bumper rust, both rocker panels rusted, left front door rust spots, left rear door rust spots/rust at bottom, left door sill worn/rusted, right rear door small rust spots, roof rust spots/dents, no wheel wrench/jack/first aid kit/fire extinguisher, windshield chips, poor battery, minor exterior damage.>, As is, where is</p>	220,567 km	\$12,388	3C7WDNEL4CG174686
\$7,890.12	12-017	<p>Truck 2015 FORD F150 4WD, supercrew, 5'7" box 3.5L, V6, gas auto A/C, tilt, cruise, AM/FM/CD player, fog lights, power locks/windows/mirrors, keyless entry-2 key fobs, keypad on left front door side steps, mud flaps, front tow hooks, hitch, trailer wiring, box liner, has back seat, red, TOW ONLY –</p> <p>This vehicle has an UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in “As is, where is” condition., 288,810 km, , KNOWN PROBLEMS and OBSERVATIONS: Rear rotors, passenger window does not roll down.</p> <p>Grille left side broken(hole)/chrome peeling, hood chips/scratches, left side fenders scratches/road rash/dents, right side scratches/road rash, left side doors dents/scratches, roof dents/chips, tailgate scratches/chips/dents, no first aid kit/fire extinguisher, windshield chips, front seats soiled, left front seat sagging, both cab corners scratches, poor battery,</p>	288,810 km	\$5,189	1FTEW1E87FFB49682

Bid Price	Item #	Description	Kms	Min Price	Serial Number
No Bid *	10-026	<p>Truck 2019 FORD F150 4WD, supercrew, 6'5" box 5.0L, V8, gas auto A/C, tilt, cruise, AM/FM, power heated mirrors, power locks/windows, keyless entry-1 key fob, 1 key for topper front tow hooks, side steps, hitch, trailer wiring, OEM trailer brake, ARE topper, has a back seat, white, TOW ONLY –</p> <p>This vehicle has an UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in “As is, where is” condition., 420,852 km, , KNOWN PROBLEMS and OBSERVATIONS: Drive belt, left inner tie rod, left outer tie rod, front and rear pads/rotors, alignment needed, windshield, missing mud flaps, wiper blades, washer switch, plate light.</p> <p>Transmission chatters and surges, mobile for short trips, diagnosed with internal transmission issues, need replacement transmission, grille broken, hood chips/road rash, rear bumper dented, left side fenders road rash, right rear fender road rash, right front door chips, tailgate corner bent, unknown if wheel wrench is under the back seat, no first aid kit/fire extinguisher, windshield cracked, left mirror housing broken, topper tailgate or lock non operational, poor battery, minor exterior damage.>, As is, where is</p>	420,852 km	\$5,995	1FTFW1E5XKKE71275
\$7,230.00 *	9-019	<p>Truck 2017 FORD F250 SD 4WD, crew cab, 6'10" box 6.2L, V8, gas auto A/C, tilt, cruise, aftermarket AM/FM radio, power heated trailer tow mirrors, power locks/windows, keyless entry-2 key fobs front tow hooks, side steps, mud flaps, hitch, trailer wiring, OEM trailer brake, box liner, headache rack, has back seat, white, TOW ONLY –</p> <p>This vehicle has an UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in “As is, where is” condition., 334,118 km, , KNOWN PROBLEMS and OBSERVATIONS: Exhaust manifold, front shocks, left outer tie rod, alignment needed, rear brake line not secured.</p> <p>Grille holes drilled, hood dents/stone chips, front bumper chips, rear bumper rusted/holes drilled, left front fender chips, left rear fender scratch, right rear fender small dents, left front door dents, tailgate chips/small dents, no first aid kit/fire extinguishers, windshield chips, left front seat sagging, holes drilled in box rails, front valance broken, poor battery, minor exterior damage.>, As is, where is</p>	334,118 km	\$4,986	1FT7W2B60HEE88021

Bid Price	Item #	Description	Kms	Min Price	Serial Number
\$5,497.00	12-020	Truck 2017 FORD F250 Super Duty 4WD, crew cab, 6'10" box 6.2L, V8, gas auto A/C, tilt, cruise, AM/FM, power heated trailer tow mirrors, keyless entry-1 key fob front tow hooks, mud flaps, side steps/right side step in box, box liner, has a back seat, grey, TOW ONLY – This vehicle has a VERY UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Body Integrity Inspection and a Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in "As is, where is" condition., 192,979 km, , KNOWN PROBLEMS and OBSERVATIONS: Check engine lights on codes: P0430/ P068A/ P06E9, TPMS light on, left and right upper ball joints loose, right lower and upper ball joints loose, exhaust manifold, exhaust hanger broken in rear, exhaust not secure, Drag link loose, left outer tie rod and right outer loose, windshield cracked, rear tailgate damaged /does not open, front bumper damaged, right mirror damaged, right taillight damaged, plate lamp inoperative, no spare tire, left front door damaged, note: CEL on, left running board removed, missing left front and rear door lock buttons.	192,979 km	\$3,915	1FT7W2B69HEE88034
\$25,821.11	12-008	Truck 2012 FORD F550 RWD, extended cab, service body 6.8L, V10, gas auto A/C, tilt, cruise, AM/FM/CD player, 2 keys, 1 other key Warwick (telelift) aerial device and ladder rack with beacon, FX brand service body-6 compartments, power inverter, HD rear bumper with pintle hook, trailer wiring, OEM trailer brakes, dual rear wheels, generator, batteries, back seat loose in cab, white, TOW ONLY – This vehicle has an UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in "As is, where is" condition., 68,146 km, , KNOWN PROBLEMS and OBSERVATIONS: 1 clearance light out, battery will not hold a charge. Hood hail(dents)/scratches, front bumper pitted, holes drilled in both rear doors inside panels, roof dents, wheel wrench/jack loose in cab, no first aid kit/fire extinguisher, windshield chips, poor battery, minor exterior damage.>, As is, where is	68,146 km	\$25,816	1FD0X5HY7CEB01610

Bid Price	Item #	Description	Kms	Min Price	Serial Number
*MT	12-019	<p>Truck 2008 GMC Sierra 3500 4WD, crew cab, 8' box 6.0L V8, gas auto A/C, tilt, cruise, AM/FM/CD player, power locks, 2 keys aftermarket goose neck hitch, front two hooks, grille inserts, mud flaps, side steps, hitch, trailer wiring, headache rack, box liner, has back seat, red, TOW ONLY –</p> <p>This vehicle has an UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in “As is, where is” condition., 209,591 km, , KNOWN PROBLEMS and OBSERVATIONS: Power steering pump leaking, both sides exhaust manifold gasket leaking, park brake assembly not releasing, front and rear wheel alignment, clunk front, left front axle seal, gasket at rear of transmission, right side high mount stop lamp is out. Grille chrome peeling, hood chips/scratches/dents, rear bumper dents/pad screwed down, left side fenders road rash/scratches/dents, right front fender road rash/scratches, right rear fender road rash/dents/rust/scratches, both rocker panels paint worn on door sills/road rash, left side doors road rash/scratches/dent, right side doors rash/scratches/chips, roof</p>	209,591 km	\$3,958	1GTHK33K78F219350
\$6,477.00	12-018	<p>Truck 2009 GMC Sierra 4WD, crew cab, 8' box 6.0L V8, gas auto A/C, tilt, cruise, AM/FM, power locks, 2 keys left tow hook, missing right tow hook, side steps, mud flaps, hitch, trailer wiring, electric trailer brake, headache rack, rails on side box, box liner, wheel flares, new seat covers on back seat, has back seat, grey, TOW ONLY –</p> <p>This vehicle has an UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in “As is, where is” condition., 206,048 km, , KNOWN PROBLEMS and OBSERVATIONS: Drive shaft steady bearing torn/needs to be replaced, noise from drive line, transfer case metal in fluid. Needs transfer case noise, oil full of fillings, oil pan gasket, two rear side bearing cap bolts, reseal for engine oil leak, grille holes drilled, hood chips/dents/scratches, both bumpers' dents, left front fender chips/dents, right side fenders chips/scratches/dents, left side doors chips/scratches/dents, right side doors scratches/chips, roof scratches, one hole in roof sealed, tailgate chips/scratches/dents, no first aid kit/fire extinguisher, windshield chips, poor battery, minor exterior damage.>, As is, where is</p>	206,048 km	\$3,987	1GTHK73K69F160879

Bid Price	Item #	Description	Kms	Min Price	Serial Number
\$5,337.00	12-009	<p>Truck 2016 GMC Sierra 1500 4WD, crew cab, 6'5" box 5.3L, V8, gas auto A/C, tilt, cruise, AM/FM, power mirrors/locks/windows, keyless entry-2 fobs, 2 keys, 1 tonneau key front tow hooks, side steps, mud flaps, hitch, trailer wiring, OEM trailer brakes, Roll-N-Lock tonneau cover, has back seat, white, TOW ONLY –</p> <p>This vehicle has a VERY UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Body Integrity Inspection and a Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in “As is, where is” condition., 249,000 km, , KNOWN PROBLEMS and OBSERVATIONS: Both front hub and bearings, alignment needed, plate light, windshield, rocker panels.</p> <p>Left front fender dent/scratch, both rocker panels rust, left front door rust, right front door rust, right rear door chips/paint poor/peeling/rust, roof rusted, five holes sealed in roof, tailgate will not open, no first aid kit/fire extinguisher, windshield chips, left front mirror glass chipped, dome light trim missing, poor battery, minor exterior damage.>, As is, where is</p>	249,000	\$822	3GTU2LEC1GG192566
\$11,758.00	12-010	<p>Truck 2008 GMC Sierra 2500 HD 4WD, extended cab, utility body 6.0L, V8, gas auto A/C, tilt, cruise, AM/FM, power locks, remote start-keyless entry-1 fob/control, 2 keys front tow hooks, side steps, HD rear bumper, pintle hook, trailer wiring, mud flaps, Brand FX utility body 6 compartments, 2 additional boxes on top no keys, no back seat, white, TOW ONLY –</p> <p>This vehicle has an UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in “As is, where is” condition., 141,102 km, , KNOWN PROBLEMS and OBSERVATIONS: Engine light on, pitman arm loose, both headlight lens cloudy, rear seats and seat belts missing.</p> <p>Hood chips/paint poor, front bumper rust/scratches/cover dented/scratches, right front fender rust, left side doors road rash/dents, right side doors chips, roof chips/rust spots, hole in roof 2 sealed, 1 spare in holder, another spare loose in box may not be compatible with vehicle, no first aid kit/fire extinguisher, windshield chips, head lights foggy, holes drilled in dash, poor battery, minor exterior damage>, As is, where is</p>	141,102	\$10,737	1GTHK29K78E209974

Bid Price	Item #	Description	Kms	Min Price	Serial Number
\$4,708.00	12-011	<p>Van 2012 CHEVROLET Express 1500 Cargo AWD 5.3L, V8, gas auto A/C, tilt, cruise, AM/FM/CD player, rear heat, power locks/windows, keyless entry-1 fob, 3 keys hitch, trailer wiring, electric trailer brake, computer stand, map box-no keys, ladder rack, cargo barrier, shelving, wood floor, "Electron" metal rack(boxed), white, TOW ONLY –</p> <p>This vehicle has a VERY UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Body Integrity Inspection and a Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in "As is, where is" condition., 177,382 km, , KNOWN PROBLEMS and OBSERVATIONS: Left front CV axle inner boot torn, right front CV axle outer boot torn, front brake pads at 2mm, front rotors rusty, battery will not hold a charge, left low beam light out, windshield cracked, rust hole in right rear door, left rear corner molding broken.</p> <p>Hood paint poor, front bumper pitted/scratched, rear bumper rusted/dents/cover loose, left front fender paint poor, left rear fender rusted/chips/dents, right front fender scratch, right rear fender rust, right dog leg rusted/dents, both rocker panels rusted, right side doors rusted/chips, roof small rust spots, tailgate rusted/hole in rear right/chips, no first aid kit/fire extinguisher, windshield cracked, left front seat worn sagging, left quarter panel molding broke, poor battery, minor exterior damage.>, As is, where is</p>	177,382 km	\$2,708	1GCSHAF41C1130272
\$4,708.00	12-012	<p>Van 2012 CHEVROLET Express 1500 Cargo AWD 5.3L, V8, gas auto A/C, tilt, cruise, AM/FM/CD player, rear heat, power locks/windows, 1 key map box, computer stand, cargo barrier, shelves, ladder rack with beacon, step attachment to hitch, plywood floor with carpet, mud flaps, , white, TOW ONLY –</p> <p>This vehicle has a VERY UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Body Integrity Inspection and a Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in "As is, where is" condition., 187,112 km, , KNOWN PROBLEMS and OBSERVATIONS: Right upper ball joint loose, parking brake not working, left headlight not working, battery will not hold a charge, left side rocker panel rusted through, driver door catching/binding, driver seat torn.</p> <p>Grille broke, hood chips/paint flaking, front bumper road rash, rear bumper rusted, left side fenders rust/scratches, right rear fender rusted, right dog leg rusted, both rocker panels rusted, left front door binding, right front door paint flaking, roof chips/rust, tailgate paint flaking/rust/chips, wheel wrench/jack loose on shelf, no first aid kit/fire extinguisher, windshield chips, left front seat badly worn, poor battery, minor exterior damage.>, As is, where is</p>	187,112 km	\$2,688	1GCSHAF4XC1129217

Bid Price	Item #	Description	Kms	Min Price	Serial Number
No Bid	12-013	<p>Van 2012 CHEVROLET Express 3500 Cargo RWD 6.0L, V8, gas auto A/C, tilt, cruise, AM/FM/CD player, power windows/locks, keyless entry-1 fob, 2 keys cargo barrier, computer stand, shelving, ladder for aerial device, converter, generator, HD rear bumper with pintle hook, 2 generator battery compartments-may have batteries, Warwick ladder aerial device with beacons and ladder, ladder strapped to Warwick ladder, electric trailer brake, white, TOW ONLY –</p> <p>This vehicle has a VERY UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Body Integrity Inspection and a Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in “As is, where is” condition., 160,355 km, , KNOWN PROBLEMS and OBSERVATIONS: Transmission leaks onto mounts, both front upper ball joints loose, rear brake rotors rusty, battery will not hold a charge, park brake not working, wiper blades, drive side mirror glass cracked.</p> <p>Hood chips/dents/scratches, left front fender scratches/dents/paint poor, left rear fender road rash/ rust, right rear fender rusted/scratches, right dog leg rusted, both rocker panels rusted, left front door chips, tailgate chips/rust/left door binds on blot, spare tire missing, no first aid kit/fire extinguisher, windshield chips, left mirror glass cracked, left front seat holes/sagging, front valance broke, poor battery, minor exterior damage.>, As is, where is</p>	160,355 km	\$10,193	1GCZGTCG6C1129789
\$1,556.00	12-014	<p>Van 2009 DODGE Grand Caravan SE FWD 3.3L, V6, gas auto A/C, tilt, cruise, AM/FM/CD player, rear HVAC, power mirrors/locks/front windows, keyless entry-3 key fobs 5 passenger, Stow-N-Go 3rd row only, blue, TOW ONLY –</p> <p>This vehicle has a VERY UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Body Integrity Inspection and a Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in “As is, where is” condition., 170,256 km, , KNOWN PROBLEMS and OBSERVATIONS: Front struts, rear pads/rotors, alignment needed, both rear fenders, left front fender, rocker panels.</p> <p>Needs new recirc door in heater box and new blend door actuator in rear heater box, hood scratches/chips/dents, both bumpers’ chips/scratches, left side fenders rusted, right front fender rusted/missing molding, right rear fender rusted, both dog legs rusted, both rocker panels rusted, left side doors dents/scratches, tailgate scratches including glass, wheel wrench missing, no first aid kit/fire extinguisher, windshield chips, trim broke on rear 3rd row seat, trim broke rear cargo area broken molding, gas filler door dose not close, holes in headliner, missing all rear HVAC vents/rear doom light, missing center seat, poor battery, minor exterior damage.>, As is, where is</p>	170,256 km	\$556	2D8HN44E79R641524

Bid Price	Item #	Description	Kms	Min Price	Serial Number
\$2,522.00	12-015	<p>Van 2013 DODGE Grand Caravan SE FWD 3.6L, V6, gas auto A/C, tilt, cruise, AM/FM/CD player, power heated mirrors, power locks/windows/rear vent windows, keyless entry-2 key fobs 3rd row seat Stow-N-Go only, 7 passenger, silver, TOW ONLY –</p> <p>This vehicle has a VERY UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Body Integrity Inspection and a Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in “As is, where is” condition., 140,783 km, , KNOWN PROBLEMS and OBSERVATIONS: Both front hubs-bearings noise, front pads/rotors, alignment needed, windshield, rear wiper blade, floor, rocker panels.</p> <p>Hood paint peeling, both bumpers’ chips/scratches, left side fenders rusted, right rear fender rusted/scratches, left dog leg rusted, left side doors rust at bottom, right front door chip/dent, roof dents, tailgate rusted, no first aid kit/fire extinguisher, windshield large stone bruise, poor battery, minor exterior damage.>, As is, where is</p>	140,783	\$961	2C4RDGBG4DR634132

Bid Price	Item #	Description	Kms	Min Price	Serial Number
REGINA, SaskBuilds and Procurement, SaskSurplus Sales Lot, 500 McLeod Street - Miscellaneous					
Contact SaskSurplus 306-787-2062 or 306-798-3306, sasksurplus@gov.sk.ca					
\$8.00	12-101	Tie Down Strap, Erickson Ratcheting, metal hooks, 2"w x 27' long, yellow, maximum load 10,000 lbs., maximum working load 3,300 lbs., stained. Fair		\$5	
No Bid	12-102	Tire, 225/65R17, Goodyear Nordic Winter, Snowflake Manufacture date, week 36, year 2019. Good		\$25	
\$387.00	12-103	Tires, Set of 5 265/65R18, Michelin Primacy LTX, Mud And Snow Manufacture date, week 23, year 2025. Excellent		\$275	
*MT	12-104	Tow Strap, Grip brand 2"w x 20' long, green, maximum weight 10,000 lbs. Good		\$5	
\$50.00	* 9-113	Desk, L-shape, wood Light brown, 5 drawers with lock and 2 keys, adjustable feet, comes with hardware, main 66.5"w x 35.5" d x 29.5" h, return side 43.5"w x 20.5"d x 28" h, comes with monitor riser with pull-out tray, some scratches and water damage, missing one adjustable foot. Fair		\$1	
\$50.00	* 9-114	Desk, L-shape, wood Light brown, 5 drawers with lock and 2 keys, adjustable feet, no hardware, main 66.5"w x 35.5" d x 29.5" h, return side 43.5"w x 20.5"d x 28" h, comes with monitor riser with pull-out tray, some scratches and water damage. Fair		\$1	
\$11.00	* 9-115	Desk, U-shape, wood Dark brown, 1 drawer, adjustable feet, has hardware, main 108" w x 20" w, left return, 72.25" w x 32.5" d, right return 120" w x 20.5" w x 29.5" h, some scratches, surface laminate lifting, back has cracked. Fair		\$1	

Bid Price	Item #	Description	Kms	Min Price	Serial Number
HUMBOLDT, Agriculture, 2414 Westwood Dr					
Contact Leona Messmer 306-682-6701, leona.messmer@gov.sk.ca or Terry Bauer 306-682-6708, terry.bauer@gov.sk.ca					
No Bid	12-517	Bulletin Board, Lot of 4 cork with metal edge trim 4' w x 1" d x 3' h. Good		\$1	
No Bid	12-518	Bulletin Board, cork with metal edge trim 4'w x 4'h. Good		\$1	
No Bid	12-519	Chair, leather Seatback, 21"w x 19" d x 30" h, adjustable height, 5 star base with castors.		\$1	
No Bid	12-520	Whiteboard, 4' w x 6'h. Good		\$1	
HUMBOLDT, Community Safety, Unit 2, 2420 Westwood Dr					
Contact: Kyle Hanson 306-682-6729 or 306-513-8596, kyle.hanson@gov.sk.ca					
\$2,020.00	12-552	Snowmobile 2001 Ski-Doo Touring 500 Rotax 500F, 2-stroke, gas Heated visor plug, 136" track, electric start and reverse, handwarmers, 1 key Cargo rack and bag, 2-up seat, black, , 8,563 km, , KNOWN PROBLEMS: Starts and runs fine but after running for a period of time, will not start again after being shut off, pull start recoil cord will occasionally stick and not retract, it has rarely been used in past 3 years.>, As is, where is	8,563 km	\$500	2BPS185231v000782
KINDERSLEY, Agriculture, Unit 1120 608 12th Ave E					
Contact Anne Sim 306-460-5513, anne.sim@gov.sk.ca					
\$5.00	12-514	Chair, Blue, 5 castors, adjustable arms and adjustable height. Good		\$1	
\$10.00	12-515	File Cabinets, Lot of 2 metal, lateral 28"w x 18"d x 51"h, 4 drawer, light beige, lock and key. Good		\$1	
\$5.00	12-516	File Cabinets, Lot of 2 metal, lateral 36"w x 18"d x 41"h, 3 drawer, light beige, lock and key Good		\$1	
LA RONGE, Saskatchewan Public Safety Agency, Hangar 2 Athabasca Airways Rd					
Contact Mike Towill 306-425-4585, mike.towill@gov.sk.ca or JD Faubert 306-425-4587, jeandenis.faubert@gov.sk.ca					
\$125.00 *	11-560	Welder, Syncrowave 351, Millerwelder AC/DC welding power source, works intermittently, problem unknown. Fair		\$100	
MOOSE JAW, Agriculture, 45 Thatcher Dr. E					
Contact Colby Elford 306-694-3938, colby.elford@gov.sk.ca					
\$40.00	12-513	Projector, 2008 Benq MP612c Operational. Good		\$1	

Bid Price	Item #	Description	Kms	Min Price	Serial Number
NORTH BATTLEFORD, Agriculture, A131 1192 - 102 St					
Contact Melissa Welford 306-446-7964, melissa.welford3@gov.sk.ca or Jenny Ruazol 306-446-7962, jenny.ruazol@gov.sk.ca					
\$55.50	12-531	Chairs, Lot of 20 Stained, grey, cloth, chrome legs with black arm rests. Fair		\$1	
\$107.04	12-532	Table, Lot of 8 One has a loose leg, dusty rose with chrome legs, 54" w x 27" d x 29" h Good		\$1	
NORTH BATTLEFORD, Community Safety, 502 - 114th St					
Contact: Robbie Gaetz 306-446-7419, robbie.gaetz@gov.sk.ca or Ryan Green 306-446-7428, ryan.green@gov.sk.ca					
\$2,447.00	12-553	ATV 2008 Arctic Cat 500 ATV 4X4 493cc, 4-stroke, single-cylinder, gas manual Hand warmers, 1550 miles		\$1	4UF08ATV28T212908
OUTLOOK, Agriculture, 410 Saskatchewan Ave W					
Contact Ben Lalonde 306-867-6469, ben.lalonde@gov.sk.ca or Outlook Front Desk 306-867-5500, stacey.stutters@gov.sk.ca					
No Bid *	11-509	GPS Base Radio, Pacific Crest PDL 4335 GPS 430-450Mhz radio for GPS system, significant wear, unknown if still operational, stored in a cool dry place for many years, no cables included. Poor		\$5	8,091,658
No Bid *	11-511	Leveling Rod, 1 set of 5m, aluminum, unknown brand, brown leather or vinyl case Total height 5m, set has 4 pieces that clip together, carrying case included case is blue nylon, case is brown leather or vinyl, rods have not been used for decades, stored in a cool dry place, noticeable wear present. calibration likely required. Fair		\$10	
No Bid *	11-512	Leveling Rod, 1 set of 5m, aluminum, unknown brand, brown leather or vinyl case Total height 5m, set has 4 pieces that clip together, carrying case included case is blue nylon, case is brown leather or vinyl, rods have not been used for decades, stored in a cool dry place, noticeable wear present. calibration likely required. Fair		\$10	
No Bid *	11-513	Surveying Tripod, Duratech, wood, flat head Stored in a cool dry place, clamps are somewhat loose, one leg is partially detached from the hinge (needs a new screw), noticeable wear present, tightening and calibration likely required. Fair		\$20	
No Bid *	11-515	Surveying Tripod, Leica, wood, telescoping antenna pole Stored in a cool dry place, clamps are somewhat loose, noticeable wear present, tightening and calibration likely required. Fair		\$30	
OUTLOOK, Agriculture, 410 Saskatchewan Ave W					
Contact Stacey Sutters, stacey.stutters@gov.sk.ca or Tammie Wood, tammie.wood@gov.sk.ca					
No Bid	12-533	Chairs, Lot of 7 metal, fabric Blue, grey, 11" w x 24" d x 31" h. Fair		\$1	
No Bid	12-534	Chairs, Lot of 7 metal, fabric Brown, 22" w x 25" d x 31" h. Fair		\$1	
No Bid	12-535	Chair, metal, fabric Brown, 23" w x 24" d x 30" h. Fair		\$1	
No Bid	12-536	Desk Hutch, wood Pepperdust, 72"w x 18"d x 41"h. Good		\$1	

Bid Price	Item #	Description	Kms	Min Price	Serial Number
\$20.00	12-537	File Cabinets, Lot of 3 metal, lateral Tan, 3 drawers, 36" w x 18" d x 40" h, no keys Good		\$1	
No Bid	12-538	File Cabinet, metal, vertical Black, 4 drawers, 18" w x 26.5" d x 52" h, no key Good		\$1	
No Bid	12-539	Shredder, plastic Black, 15" w x 17.5" d x 28" h Good		\$1	
PRINCE ALBERT, Community Safety, 3021 1st Ave W					
Contact Tonya Granberg , tonya.granberg@gov.sk.ca or Nola Boechler, nola.boechler@gov.sk.ca					
No Bid *	11-507	Cups, Lot of 12 ceramic White. Fair		\$1	
No Bid *	11-508	Napkin Holders, Lot of 9 Stainless steel. Poor		\$1	
PRINCE ALBERT, Saskatchewan Public Safety Agency, Hwy. 2 N. Nisbet Depot					
Contact Kevin Frey 306-953-3423, kevin.frey2@gov.sk.ca or Scott Ackerman 306-953-3422, scott.ackerman@gov.sk.ca					
\$59.59	12-501	Air Compressor, CH Campbell Hausfeld - WL 650903AJ CH - 150psi, 22 gal - oil-free , operational, has a leak and not maintaining pressure. Broken Repairable		\$10	
\$257.00	12-502	Gas Welder, Oxy-acetylene torch 1 oxygen and 1 acetylene cylinder, hoses and torch on hand-truck, was operational when last used, has not been used in 10-15 years. Fair		\$100	
\$210.00	12-503	Insulation, Lot of 4 Johns Manville Batt and roll in packaging, fiberglass R20- 6"x15"x47". New- Unused		\$100	
\$50.00	12-504	Pressure Washer, STIHL - RE 129 - PLUS Operational but leaking. Broken Repairable		\$10	
REGINA, Agriculture, 125 - 3085 Albert St					
Contact Keira Derkson 306-787-9719, keira.derkson2@gov.sk.ca or Tammie Wood, 306-787-8034, tammie.wood@gov.sk.ca					
\$33.33	12-521	File Cabinet, metal, lateral Tan, 3 drawer, 36" w x 18" d x 39.25" h, no keys Good		\$1	
\$33.33	12-522	File Cabinet, metal, lateral Tan, 3 drawer, 36" w x 18" d x 40.5" h, no keys Good		\$1	
\$33.33	12-523	File Cabinet, metal, lateral Tan, 3 drawer, 36" w x 19.3" d x 41" h, no keys Good		\$1	
\$33.33	12-524	File Cabinet, metal, lateral Tan, 4 drawer, 18" w x 28" d x 51" h, no keys Good		\$1	
\$33.33	12-525	File Cabinet, metal, lateral Tan, 4 drawer, 36" w x 18" d x 52.3" h, no keys Good		\$1	
\$33.33	12-526	File Cabinet, metal, lateral Tan, 4 drawer, 36" w x 18" d, 51.2" h, no keys Good		\$1	
No Bid	12-527	File Cabinet, metal, vertical Black, 4 drawer, 18" w x 28" d x 51" h, no keys Good		\$1	

Bid Price	Item #	Description	Kms	Min Price	Serial Number
No Bid	12-528	File Cabinet, metal, vertical Tan, 4 drawer, 18" w x 28" d x 51" h, no keys Good		\$1	
No Bid	12-529	File Cabinet, metal, vertical Tan, 4 drawer, 18" w x 28" d x 51" h, no keys Good		\$1	
\$62.99	12-530	File Cabinet, metal, vertical Tan, 4 drawer, 18.3" w x 28.5" d x 52" h, no keys Good		\$1	
REGINA, Agriculture, 226 - 3085 Albert St					
Contact Avishek Paul 306-787-5130, avishek.paul@gov.sk.ca					
\$30.00	12-505	Printer Cartridge, 53A, Q7553A, HP LaserJet M2727 mfp . P2014. P2015. New- Unused		\$1	
\$101.00	12-506	Printer Cartridge, Lot of 4 78A, black, CE278A, HP LaserJet Pro P1566, P1606. New- Unused		\$1	
\$30.00	12-507	Printer Toner, Toshiba, T-FC34U-C, cyan, e-STUDIO287CS/287CSL/347CS/347CSL/407CS. New- Unused		\$1	
\$35.00	12-508	Printer Toner, Lot of 2 Toshiba, T-FC34U-K, black, e-STUDIO287CS/287CSL/347CS/347CSL/407CS. New- Unused		\$1	
\$30.00	12-509	Printer Toner, Toshiba, T-FC34U-M, magenta violet, e-STUDIO287CS/287CSL/347CS/347CSL/407CS. New- Unused		\$1	
\$30.00	12-510	Printer Toner, Toshiba, T-FC34U-Y, yellow, e-STUDIO287CS/287CSL/347CS/347CSL/407CS. New- Unused		\$1	
REGINA, Health, 3475 Albert St					
Contact: Steve Fairbairn 306-530-7703, steve.fairbairn@health.gov.sk.ca or Vicki Buchanan 306-787-8308, vicki.buchanan@health.gov.sk.ca					
No Bid *	11-546	Truck-Mount Cold Fogger, 2003 Maxi Pro 145 Ultra-low volume aerosol generator designed for mosquito and fly control applications, 18 HP Briggs & Stratton gasoline engine with electric start, single Dyna-Fog Multi-Mist nozzle, engineered to produce 90% of droplets below 20 microns, output control available with a gear pump or FMI piston pumping system, constructed with welded steel and powder-coat finishes for corrosion resistance. Unit has been flushed with isopropyl alcohol and washed after each use but the tanks that hold the pesticide cannot be cleaned. **Please see the attached Deltagard SC Insecticide PDF below for handling instructions and proper Personal protective equipment (PPE) requirements. The successful bidder must sign a disclaimer attached below in acknowledgement of the potential hazards, and PPE requirements before payment will be accepted. *Online viewing only - serious inquires may request an appointment for viewing on-site Excellent		\$2,000	293

Bid Price	Item #	Description	Kms	Min Price	Serial Number
No Bid *	11-547	Truck-Mount Cold Fogger, 2003 Maxi Pro 145 Ultra-low volume aerosol generator designed for mosquito and fly control applications, 18 HP Briggs & Stratton gasoline engine with electric start, single Dyna-Fog Multi-Mist nozzle, engineered to produce 90% of droplets below 20 microns, output control available with a gear pump or FMI piston pumping system, constructed with welded steel and powder-coat finishes for corrosion resistance. Unit has been flushed with isopropyl alcohol and washed after each use but the tanks that hold the pesticide cannot be cleaned. **Please see the attached Deltagard SC Insecticide PDF below for handling instructions and proper Personal protective equipment (PPE) requirements. The successful bidder must sign a disclaimer attached below in acknowledgement of the potential hazards, and PPE requirements before payment will be accepted. *Online viewing only - serious inquires may request an appointment for viewing on-site Excellent		\$2,000	292
No Bid *	11-548	Truck-Mount Cold Fogger, 2003 Maxi Pro 145 Ultra-low volume aerosol generator designed for mosquito and fly control applications, 18 HP Briggs & Stratton gasoline engine with electric start, single Dyna-Fog Multi-Mist nozzle, engineered to produce 90% of droplets below 20 microns, output control available with a gear pump or FMI piston pumping system, constructed with welded steel and powder-coat finishes for corrosion resistance. Unit has been flushed with isopropyl alcohol and washed after each use but the tanks that hold the pesticide cannot be cleaned. **Please see the attached Deltagard SC Insecticide PDF below for handling instructions and proper Personal protective equipment (PPE) requirements. The successful bidder must sign a disclaimer attached below in acknowledgement of the potential hazards, and PPE requirements before payment will be accepted. *Online viewing only - serious inquires may request an appointment for viewing on-site Excellent		\$2,000	295
No Bid *	11-549	Truck-Mount Cold Fogger, 2003 Maxi Pro 145 Ultra-low volume aerosol generator designed for mosquito and fly control applications, 18 HP Briggs & Stratton gasoline engine with electric start, single Dyna-Fog Multi-Mist nozzle, engineered to produce 90% of droplets below 20 microns, output control available with a gear pump or FMI piston pumping system, constructed with welded steel and powder-coat finishes for corrosion resistance. Unit has been flushed with isopropyl alcohol and washed after each use but the tanks that hold the pesticide cannot be cleaned. **Please see the attached Deltagard SC Insecticide PDF below for handling instructions and proper Personal protective equipment (PPE) requirements. The successful bidder must sign a disclaimer attached below in acknowledgement of the potential hazards, and PPE requirements before payment will be accepted. *Online viewing only - serious inquires may request an appointment for viewing on-site Excellent		\$2,000	294

Bid Price	Item #	Description	Kms	Min Price	Serial Number
No Bid *	11-550	Truck-Mount Cold Fogger, 2003 Maxi Pro 145 Ultra-low volume aerosol generator designed for mosquito and fly control applications, 18 HP Briggs & Stratton gasoline engine with electric start, single Dyna-Fog Multi-Mist nozzle, engineered to produce 90% of droplets below 20 microns, output control available with a gear pump or FMI piston pumping system, constructed with welded steel and powder-coat finishes for corrosion resistance. Unit has been flushed with isopropyl alcohol and washed after each use but the tanks that hold the pesticide cannot be cleaned. **Please see the attached Deltagard SC Insecticide PDF below for handling instructions and proper Personal protective equipment (PPE) requirements. The successful bidder must sign a disclaimer attached below in acknowledgement of the potential hazards, and PPE requirements before payment will be accepted. *Online viewing only - serious inquires may request an appointment for viewing on-site Excellent		\$2,000	296
REGINA, Legislative Assembly Service, 515 Henderson Drive					
Contact: Karen Plumb 306-787-8167, kplumb@legassembly.sk.ca					
No Bid *	8-501	Uninterruptable Power Supply with Batteries and Power Modules, Lot of 11 APC Symmetra 1 APC Symmetra LX UPS, SYAF16KRMT, 7 APC Symmetra LX Battery Module, SYBT5, 2 APC Symmetra LX Power Module, SYPM4KP, 1 APC Symmetra LX Power Module, SYPM4KPQ. UPS: 19" w x 27" d x 33" h, (shipping 42 x 24 x 40) 500lbs, each battery is 18 kg, 4 batteries in box, 3 loose, unknown what condition batteries are in, no power cord as it has to be direct wired into building power. Sold as is. UPS: QD1037260148, in-box batteries: 5D2007T60139, 5D2018T65313, 5D2018T65320, 5D2007T60123, loose batteries: 5D2005T15219, 5D2007T60147, 5D2007T60138, SYPM4KP, power modules: QD1513380215, AD2033110087, SYPM4KPQ power module: AQ2106210005, operational. Fair		\$1,000	
REGINA, Saskatchewan Liquor and Gaming Authority, 1702 Park St					
Contact Shola Babarinde 306-787-5864, sbabarinde@slga.com or Tyrone Smith 306-787-1934, tsmith1@slga.com					
\$15.01 *	11-533	Cabinet, wood, lateral Brown, 2 drawers, few scratches, 20" w x 36" l x 29" h. Fair		\$15	
No Bid *	11-534	Cabinet, wood, lateral Brown, few scratches with tape residue, 20" w x 37" d x 29" h. Fair		\$15	
\$47.00 *	11-536	Desk, wood, lateral Brown, few scratches, 21.5" w x 72" d x 30" h Fair		\$25	
\$47.00 *	11-537	Desk, wood, lateral Brown, few scratches, 36" w x 72" d x 30 h. Fair		\$25	
\$12.00 *	11-540	File Cabinet, wood, lateral Brown, 3 drawers with keys, 20" w x 30" d x 44" h Good		\$10	

Bid Price	Item #	Description	Kms	Min Price	Serial Number
SASKATOON, Innovation Saskatchewan, 1 North Access Road					
Contact: Kyla Ledingham 306-370-4068, kyla.ledingham@innovationsask.ca					
\$3,500.00	12-551	Front Mount Tractor 2005 John Deere 1420 4x2 878cc, 3 cylinder, gas Hydrostatic heat and a/c, 4 counterweights included, 1 key gard cab, PTO (Power Take-Off), no attachments included, tire size front 23x10.5-12 and rear 18x8.5-8, GVW 816.5 kg without mower deck, green, , 3,245.2 hrs, Known Recent Repairs: Oil changes were done at 200 hours, greasing is done monthly, PTO switch was replaced August 30th, 2024, engine was rebuilt in 2019, new air filter cap and new gaskets and hardware were installed on September 9th, 2024, , As is, where is	3,245.2 hrs	\$2,600	TC1420G050098
\$5,557.00	12-550	UTV 2013 John Deere HPX 4x4 617cc, V-twin, gas CVT 1 key enclosed cab, 2 inch ball hitch , GVW 1,383 kg, tire size front: 24X9.5-10 rear: 24X10.5, green, , 3,286.7 hrs, Known Recent Repairs: Oil changes done between 100 and 200 hours, transaxle oil changed roughly every 800 hours, KNOWN PROBLEMS: windshield wiper motor is damaged and does not work, poor battery minor exterior damage > As is where is	3,286.7 hrs	\$3,000	1MOHPXGSADM110552
SASKATOON, SaskBuilds and Procurement, Hangar 17 Wayne Hicks Lane					
Contact Eric Braaten 306-491-8565, eric.braaten2@gov.sk.ca or Tim Sawatzky 306-385-2164, tim.sawatzky@gov.sk.ca					
\$26.88	12-540	Inspection Scope, VideoStik, VSXX-10WW Video based, flexible, picture quality is poor, operational. Fair		\$1	
\$55.00	12-541	Shelving, Lot of 35 metal 27 - 15" x 36" shelves, 8 - 78" vertical supports, two supports have diagonal bracing. Fair		\$1	
\$12.00	12-542	Shelving, Lot of 5 metal 5- 15" x 36" shelves, no vertical supports. Fair		\$1	
\$21.50	12-543	Shelving, Lot of 13 metal 7 - 24" x 36" shelves, 2 - 78" vertical supports (minor bends at the top), 4 - 48" vertical supports, all pieces are in good condition. Fair		\$1	
\$1.00	12-544	Television, Lot of 2 2011 Insignia 32-inch LCD/LED Both are operational, no remote controls. Fair		\$1	J168AJA039541 & J1689JA034529
\$360.00	12-545	Work Seat, EIDOS, metal Has wheels, backrest and seat height are adjustable, operational, has not been used in years. Fair		\$1	

Bid Price	Item #	Description	Kms	Min Price	Serial Number
SASKATOON, Saskatchewan Research Council, 143 - 11 Research Dr					
Contact Roger Dauvin 306-385-4035, roger.dauvin@src.sk.ca					
\$500.00	12-511	Cleanroom, Vention Enclosure with a Guardian air home electric air purification system, plug-in, operational, will be disassembled with instructions for reassembly. Good		\$1	
\$557.00	12-512	Safety Cabinet, Forma Scientific Class II A/B3 biological, plug-in, operational, it will need a HEPA filter. Good		\$1	
SASKATOON, Western Canada Lottery Corp , 1914 1st Ave N					
Contact: David Tutka 306-933-6926 or 306-230-0905, tutkad@sk-wclc.com					
\$6,789.10	12-554	Van 2021 Dodge Promaster City ST RWD 2.4 L, inline 4, gas 9 speed auto air, tilt, cruise control, power windows and locks, remote start, 2 sets of keys GWV 2,447 kg, wheel base 3109mm, tire size P215/55R16 4 ply, white, TOW ONLY, NO SGI Inspection. It is unknown if any repairs or safety concerns exist (if any). Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs if required. , 238,266 km, , KNOWN PROBLEMS: front axle and wheel bearing seized, not drivable, poor battery, minor exterior damage.>, As is, where is	238,266 km	\$1	ZFBHRFCB1M6S89663
TISDALE, Agriculture, 1105 99th St					
Contact Teresa Casavant 306-878-8842, teres.casavant@gov.sk.ca or Kacey Palidwar 306-878-8843, kacey.palidwar@gov.sk.ca					
No Bid	12-546	Hand Sprayer, Green Turf-Care, metal, plastic Operational. Good		\$1	
\$1.00	12-547	Hand Sprayer, Premier Pro, metal, plastic White and blue, operational. Good		\$1	
\$167.20	12-548	Post Hole Auger, Briggs & Stratton, metal 2-man, 206cc 5HP, gas powered, operational. Fair		\$1	
\$11.02	12-549	Powered Forage Probe, metal Gas powered, operational. Good		\$1	