

SALE SUMMARY LIST

PLEASE NOTE: Every effort has been made to accurately describe items and their condition; however, additional problems may exist, items may not be complete or exactly as described. Bidders are deemed to have reviewed the Terms and Conditions on bid forms and relied entirely on their own inspection and evaluation prior to bidding. Vehicles and equipment are sold "AS IS, WHERE IS", there is no implied or express warranty.

Visit www.SaskSurplus.ca for pictures and link to download Bid Form.

- Items identified with * have been on a previous sale and will be listed first on www.SaskSurplus.ca web site.
- SaskBuilds and Procurement, SaskSurplus, reserves right to have unadvertised minimum selling prices on items.

It is the Bidder's responsibility to review the terms and conditions of sale on the Offer to Purchase, Bid Form.

Bid Forms are available from www.SaskSurplus.ca or from the SaskSurplus Sales Lot, 500 McLeod Street, Regina, SK.

Bid Forms can be submitted in the following ways:

- by deposit in the bid box at the SaskSurplus Sales Lot,
- by fax to 306-787-2092; by phone 306-787-2062 or 306-798-3300,
- by email to sasksurplus@gov.sk.ca, or
- by mail, addressed to: Ministry of SaskBuilds and Procurement, SaskSurplus, 500 McLeod Street, Regina, SK S4N 4Y1.

(If mailing your bid, please allow sufficient time for bid to be received.)

- Bids received after close date and time cannot be accepted.

MT = (Ministry Transfer) This means that the item has been claimed by another ministry and automatically transferred to the ministry.

WD = (Withdrawn) This can happen if the item was requested to be removed by the seller.

No Bid = Items that did not receive any bids are normally carried forward to the next sale or may be withdrawn.

Bid Price	Item #	Description	Kms	Min Price	Serial Number
REGINA, SaskBuilds and Procurement, SaskSurplus Sales Lot, 500 McLeod Street - Vehicles					
Contact SaskSurplus 306-787-2062 or 306-798-3306, sasksurplus@gov.sk.ca					
\$4,045.45	2-001	<p>Car 2013 DODGE Avenger SE FWD 2.4L, inline 4, gas auto A/C, tilt, cruise, power windows/locks/ mirrors/trunk release, keyless entry-2 key fobs , white, TOW ONLY –</p> <p>This vehicle has an UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in “As is, where is” condition., 225,445 km, , KNOWN PROBLEMS and OBSERVATIONS: Front links and sway bar bushings, front brake pads and rotors, alignment needed, foggy head lamps, sun visor clip.</p> <p>Hood paint peeling/chips/scratches, both bumpers’ chips/scratches, all fenders’ chips/scratches, both dog legs chips/scratches/surface rust, both rocker panels chips/ surface rust, all doors chips/surface rust, roof paint chips/scratches, trunk lid, paint scratches, no first kit/fire extinguishers, hubcap cracked, poor battery, minor exterior damage.>, As is, where is</p>	225,445 km	\$885	1C3CDZABXDN604500
\$1,608.00 *	1-001	<p>Car 2009 FORD Focus SE FWD 2.0L, inline 4, gas auto A/C, tilt, cruise, AM/FM/CD player, power windows/locks/heated mirrors, keyless entry-2 key, 2 fobs , grey, TOW ONLY –</p> <p>This vehicle has a VERY UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Body Integrity Inspection and a Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in “As is, where is” condition., 135,708 km, , KNOWN PROBLEMS and OBSERVATIONS: All four tires, front pads/rotors, rear shoes, alignment needed, rocker panels.</p> <p>Hood scratches/rear bumper scratches, right rear fender scratches, left dog leg road rash/rust, right dog leg rust, both rocker panels rust, left front door sill molding broke, left rear door road rash/rust/dent, jack missing, no first aid kit/fire extinguisher, windshield small chips, left and right mirrors chrome pitted, poor battery, minor exterior damage.>, As is, where is</p>	135,708 km	\$524	1FAHP35N29W115638

Bid Price	Item #	Description	Kms	Min Price	Serial Number
\$1,809.00 *	1-002	<p>Car 2009 FORD Focus SE FWD 2.0L, inline 4, gas auto A/C, tilt, cruise, AM/FM/CD player, power heated mirrors, power locks/windows, keyless entry-2 keys, 2 fobs , yellow, TOW ONLY –</p> <p>This vehicle has a VERY UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Body Integrity Inspection and a Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in “As is, where is” condition., 118,459 km, , KNOWN PROBLEMS and OBSERVATIONS: Flex pipe, both rocker panels rusted.</p> <p>Hood scratches, left side fenders road rash, right front fender road rash, right rear fender dents, left dog leg road rash, both rocker panels rusted, left rear door scratches/road rash, wheel wrench/jack loose in trunk, windshield small chips, both front mirrors chrome pitted, three-wheel covers lose in trunk, poor battery, minor exterior damage.>, As is, where is</p>	118,459 km	\$521	1FAHP35N49W115639
\$5,654.00 *	1-006	<p>Truck 2012 CHEVROLET Silverado 2500 HD 4WD, extended cab, 8' box 6.0L, V8, gas auto A/C, tilt, cruise, AM/FM/CD player, power mirrors/locks/windows, keyless entry-1 fob, 2 keys front km tow hooks, mud flaps, pintle hook with wiring, OEM trailer brakes, converter-condition unknown, Brand X slide in topper, no key for topper, rollout, ladder rack with beacon condition of items unknown, tailgate laying on pull-out, missing rear seat, white, TOW ONLY –</p> <p>This vehicle has a VERY UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Body Integrity Inspection and a Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in “As is, where is” condition., 144,982 km, , KNOWN PROBLEMS and OBSERVATIONS: Right rear axle seal leaking, both lower ball joints loose, front left brake rotor excessively rusted, parking brake does not work, battery does not hold a charge, rear seats and belts missing, windshield cracked, wiper blades no good, both rocker panels rusted through, hole in left rear door, left front fender has rust holes, license plate assembly missing.</p> <p>Hood chips/dents/scratches, front bumper poor/missing trim-valance ETC, rear bumper pad/rust/not aligned, left and right-side fenders badly rusted. Rocker panels rusted through, left front door road rash/ rust, left rear door dents/rust/scratches, right side doors scratches/dents/chips, roof dents/road rash, one hole in roof sealed, wheel wrench/jack loose in back seat, no first aid kit/fire extinguisher, windshield cracked, left front seat worn/foam visible, hook for rear seat missing, poor battery, minor exterior damage.>, As is, where is</p>	144,982 km	\$5,654	1GC2KVCG1CZ204430

Bid Price	Item #	Description	Kms	Min Price	Serial Number
\$5,604.00 *	1-007	<p>Truck 2012 CHEVROLET Silverado 2500 HD 4WD, extended cab, 8' box 6.0L, V8, gas auto A/C, tilt, cruise, AM/FM/CD player, power mirrors/windows/locks, keyless entry-2 fobs, 3 keys, 1 key for slide in front tow hooks, side steps, hitch, trailer wiring, OEM trailer brakes, BrandFX slide in, ladder rack/beacon, slide in has a cargo bed roll out with side shelves and lighting, has back seat, white, TOW ONLY –</p> <p>This vehicle has a VERY UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Body Integrity Inspection and a Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in “As is, where is” condition., 155,938 km, , KNOWN PROBLEMS and OBSERVATIONS: Engine light on code P0442 EVAP system small leak detected, both outer tie rods, front brakes metal on metal, front rotors severely rusted, loose front wheel, alignment needed, license plate light, rust holes in both front fenders, left rear mud flap broken.</p> <p>Hood road rash/chips, front bumper cracked/chrome peeling, rear bumper dented/pad loose, left and right side fenders badly rusted, all doors road rash/chips/rust, no first aid kit/fire extinguisher, windshield chips, left front seat worn/cover hole/padding visible, right front floor board hole, cargo bed rust/crack at rear - condition fair, missing back seat center hook for rear seat, back rest is missing, poor battery, minor exterior damage.>, As is, where is</p>	155,938 km	\$5,604	1GC2KVCG5CZ203877
\$7,278.08	2-012	<p>Truck 2014 DODGE/RAM 2500 4WD, crew cab, 6'2" box 5.7L, V8, gas auto A/C, tilt, cruise, AM/FM, power locks/windows/mirrors, keyless entry-1 key fob, 1 door key side steps, mud flaps, hitch, trailer wiring, has back seat, white, TOW ONLY –</p> <p>This vehicle has a VERY UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Body Integrity Inspection and a Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in “As is, where is” condition., 192,561 km, , KNOWN PROBLEMS and OBSERVATIONS: Check engine light on – runs rough, oil leak, drive belt, left rear shock leak, exhaust manifold leak, windshield cracked, coolant cover, park brake doesn't hold, battery not secured, rear right door doesn't open(inside), left fender rusted out.</p> <p>Hood paint chips/dents, both bumpers' dents/rust/lower valance missing, left side fenders rusted through/chips, right rear fender rusted, both rocker panels rust, all doors paint chips/scratches, four holes in roof sealed, tailgate sticks/chips/rust, no spare tire, no first aid kit/fire extinguisher, windshield cracked, jump seat missing/center council cut, holes in in floor interior, poor battery, minor exterior damage.>, As is, where is</p>	192,561 km	\$491	3C6TR5CT6EG207668

Bid Price	Item #	Description	Kms	Min Price	Serial Number
\$5,800.00	2-013	<p>Truck 2015 DODGE/RAM 2500 4WD, crew cab, 6'2" box 5.7L, V8, gas auto A/C, tilt, cruise, AM/FM, power locks/windows/mirrors, keyless entry-1 key fob side steps, mud flaps, hitch, trailer wiring, grille inserts, has a back seat, brown, TOW ONLY –</p> <p>This vehicle has an UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in "As is, where is" condition., 255,948 km, , KNOWN PROBLEMS and OBSERVATIONS: Rear sway bar links, left rear axle seal, all four ball joints, left outer tie rod, front pads and rotors, park brake, windshield cracked, high mount brake light, right front mud flap, holes drilled through floor.</p> <p>Note: Rocker panels dented, drive seat torn, B-pillar modified, rear right door molding missing, holes in head liner. Grille holes/logo missing, hood paint chips/scratches, both bumpers' dents/trim loose, all fenders paint chips/scratches/dent, rocker panels dented, left side doors scratches/chips, right rear door will not open from inside, roof scratches/chipped, six holes filled in roof, tailgate dented/scratched/trim broken, has spare tire, wheel wrench/jack missing, no first aid kit/fire extinguisher, windshield cracked, driver seat hole, jump seat missing, center console cut out, poor battery, minor exterior damage.>, As is,</p>	255,948 km	\$3,474	3C6TR5CT0FG674845
\$11,300.00	2-004	<p>Truck 2012 DODGE/RAM 5500 RWD, crew cab, 10'1 x 7'4"w, dump body 6.7L, inline 6, diesel auto A/C, tilt, cruise, AM/FM/CD player, power heated trailer tow mirrors, power windows/locks, keyless entry-1 key fob dump body-2 beacons condition unknown, front tow hooks/side steps, mud flaps, hitch, trailer wiring, trailer brakes, front and rear wig wags-condition unknown, dual wheels, lift gate condition unknown, has a back seat, white, TOW ONLY –</p> <p>This vehicle has an UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in "As is, where is" condition., 279, 357 km, , KNOWN PROBLEMS and OBSERVATIONS: Belt cracking, both upper ball joints have lateral play, rock chips on windshield, windshield wipers not clearing.</p> <p>Hood road rash/scratches, front bumper pitted/scratches/rusted, left front fender road rash, right front fender tar, all doors chips/tar, left front door sill paint worn, roof small rust spots, one hole in roof sealed (antenna), rear of cab covered in tar, right side of dump body damaged-mechanical condition unknown, front of dump body rusted, lift gate rusted-mechanical condition unknown, poor battery, minor exterior damage.>, As is, where is</p>	279, 357 km	\$5,256	3C7WDMEL0CG195173

Bid Price	Item #	Description	Kms	Min Price	Serial Number
\$16,001.01	2-014	<p>Truck 2013 DODGE/RAM 5500 RWD, crew cab, dump body 10' x 7'4" 6.7L, inline 6, turbo diesel auto A/C, tilt, cruise, AM/Fm, power locks/windows/mirrors, keyless entry-1 key fob seat covers, lift gate mechanical condition unknown, mud flaps, side steps, hitch, trailer wiring, beacon, dump body mechanical condition unknown, grille has winter cover, has a back seat, white, TOW ONLY –</p> <p>This vehicle has an UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in "As is, where is" condition., 305,335 km, , KNOWN PROBLEMS and OBSERVATIONS: Both upper ball joints have lateral play and need to be replaced, windshield wipers not cleaning.</p> <p>Hood paint chips/scratches, left and right front fender paint chips/scratches, both rocker panels chips/paint peeling, all doors chips/scratches, roof antenna, tailgate lift rusted, no spare tire/wheel wrench/jack/firs aid kit/fire extinguisher, holes in dash, tar on rear cab, poor</p>	305,335 km	\$5,783	3C7WRMEL1DG524823
\$5,261.67 *	1-010	<p>Truck 2017 FORD F250 4WD, crew cab, 6'10" box 6.2L, V8, gas auto A/C, tilt, cruise, AM/FM, power windows/locks, power heated trailer tow mirrors, keyless entry-2 key fobs hitch, trailer wiring, OEM trailer brakes, side steps, mud flaps, front tow hooks, jump seat loose in back seat, has back seat, white, TOW ONLY –</p> <p>This vehicle has an UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in "As is, where is" condition., 296,857 km, , KNOWN PROBLEMS and OBSERVATIONS: Left outer tie rod, left axle U-joints, engine noise, rear pads/rotors, alignment needed, battery.</p> <p>Grille broke/holes drilled, hood scratches/chips, front bumper scratched/road rash, rear bumper rusted, left rear fender dented, roof scratches, six holes sealed on roof, tailgate will not open/holes drilled, wheel wrench/jack loose under back seat, no first aid kit/fire extinguisher, windshield chips, left front seat sagging, holes drilled in door frame above doors, holes drilled in box rails, four holes in floor of bac seat, vanity mirror cracked, holes in head liner, B-pillar trim modified, holes drilled in dash, rear right window switch, holes drilled in rear right window frame, poor battery, minor exterior damage.> , As is, where is</p>	296,857 km	\$4,841	1FT7W2B69HEB71595

Bid Price	Item #	Description	Kms	Min Price	Serial Number
\$6,250.00	2-006	<p>Truck 2017 FORD F250 SD 4WD, crew cab, 6'10" box 6.2L, V8, gas auto A/C, tilt, cruise, AM/FM power heated trailer mirrors, power locks/windows, keyless entry-2 key fobs front tow hooks, side steps, hitch, trailer wiring, OEM trailer brakes, jump seat loose in vehicle, has a back seat, blue, TOW ONLY –</p> <p>This vehicle has an UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in "As is, where is" condition., 265,321 km, , KNOWN PROBLEMS and OBSERVATIONS: Both outer tie rod, pitman arm, alignment needed, mud flaps, left rear signal and brake, windshield, wiper blades.</p> <p>Grille holes drilled, hood chips/scratches/dents, both bumpers' scratches/chips, all fenders road rash/scratches/dents, all doors road rash/scratches/dents, right rear door will not open from the inside, one hole in roof sealed, scratches, tailgate no handle or trim/dents/scratches, no first aid kit/ fire extinguisher, windshield cracked, left front seat worn/sagging, holes in head liner, B-pillar inside trim modified, multiple holes in rear floor pan, front valance broken, left taillight broken, right side of unit paint stained, right front mud flap missing, holes drilled in rear right door window, frame holes drilled in dash, poor battery, minor exterior damage.>, As is, where is</p>	265,321 km	\$4,956	1FT7W2B66HEB71599
\$8,321.00	2-008	<p>Truck 2017 FORD F250 SD 4WD, crew cab, 6'10" box 6.2L, V8, gas auto A/C, tilt, cruise, AM/FM, power heated trailer tow mirrors, power locks/windows, keyless entry-2 key fobs front tow hooks, side steps, mud flaps, hitch, trailer wiring, OEM trailer brake, loose jump seat inside cab, has back seat, grey, TOW ONLY –</p> <p>This vehicle has an UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in "As is, where is" condition., 244,429 km, , KNOWN PROBLEMS and OBSERVATIONS: Right lower tie rod, alignment need, TPMS light on, 3rd brake right signal, left signal, right front markers, right front passenger window doesn't roll down, a bunch of lights burnt out. Grille holes drilled, hood chips/scratches/dents, front bumper pitted, rear bumper badly rusted, left rear fender scrape/scratches, right front fender scratches, right rear fender scrape/scratches, right side doors scratches, twelve holes in roof sealed, tailgate chips/dents/scratches, missing wheel wrench/jack, no first aid kit/fire extinguisher, windshield chips, left front seat sagging, left and right B pillars modified, holes drilled around right rear inside window frame, holes drilled in dash, front valance broken, holes drilled in rear floor pan, left rear hanger broken, poor battery, minor exterior damage.>, As is, where is</p>	244,429 km	\$4,991	1FT7W2B68HEE22817

Bid Price	Item #	Description	Kms	Min Price	Serial Number
\$5,077.00	2-009	<p>Van 2012 CHEVROLET Express 1500 Cargo AWD 5.3L, V8, gas auto A/C, tilt, cruise, AM/FM/CD player, power windows front/locks, 1 key cargo barrier, hitch, trailer wiring, white, TOW ONLY –</p> <p>This vehicle has a VERY UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Body Integrity Inspection and a Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in “As is, where is” condition., 201,130 km, , KNOWN PROBLEMS and OBSERVATIONS: Front differential broken, cross member below is torn/cracked, drivers door cracked above exterior handle, left rear fender rusted through behind wheel, right rear fender rusted through before and after tire. Hood chips/paint peeling, left rear fender rusted/dents/scratches, right rear fender rusted/scratches, both dog legs rusted, both rocker panels rusted, left front door cracked/rusted, left door sill rusted, right side doors rusted/scratches, roof rust spots, one hole in roof sealed, tailgate rusted/scratches/dents, no first aid kit/fire extinguisher, windshield chips, left front seat sagging/worn, housing broken on rear heater fan, both visors broken, poor battery, minor exterior damage.> , As is, where is</p>	201,130 km	\$652	1GCSHAF42C1129910
\$10,477.00 *	12-013	<p>Van 2012 CHEVROLET Express 3500 Cargo RWD 6.0L, V8, gas auto A/C, tilt, cruise, AM/FM/CD player, power windows/locks, keyless entry-1 fob, 2 keys cargo barrier, computer stand, shelving, ladder for aerial device, converter, generator, HD rear bumper with pintle hook, 2 generator battery compartments-may have batteries, Warwick ladder aerial device with beacons and ladder, ladder strapped to Warwick ladder, electric trailer brake, white, TOW ONLY –</p> <p>This vehicle has a VERY UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Body Integrity Inspection and a Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in “As is, where is” condition., 160,355 km, , KNOWN PROBLEMS and OBSERVATIONS: Transmission leaks onto mounts, both front upper ball joints loose, rear brake rotors rusty, battery will not hold a charge, park brake not working, wiper blades, drive side mirror glass cracked.</p> <p>Hood chips/dents/scratches, left front fender scratches/dents/paint poor, left rear fender road rash/ rust, right rear fender rusted/scratches, right dog leg rusted, both rocker panels rusted, left front door chips, tailgate chips/rust/left door binds on blot, spare tire missing, no first aid kit/fire extinguisher, windshield chips, left mirror glass cracked, left front seat holes/sagging, front valance broke, poor battery, minor exterior damage.> , As is, where is</p>	160,355 km	\$9,693	1GCZGTCG6C1129789

Bid Price	Item #	Description	Kms	Min Price	Serial Number
\$1,000.00	2-010	<p>Van 2009 DODGE Grand Caravan SE FWD 3.3L, V6, gas auto A/C, tilt, cruise, AM/FM/CD player, power mirrors/locks/front windows, keyless entry-2 key fobs 7 passenger, 3rd row seat Stow-N-Go , white, TOW ONLY –</p> <p>This vehicle has a VERY UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Body Integrity Inspection and a Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in “As is, where is” condition., 205,585 km, , KNOWN PROBLEMS and OBSERVATIONS: Left rocker panel rust holes.</p> <p>Hood dents/scratches/paint peeling, front bumper chips/scratches, rear bumper chips/scratches/paint cracked, left rear fender rusted, right rear fender rusted/dents, dog leg rusted, left rocker panel rusted, left front door rusted, left rear door dents/rusted, right side doors rusted, tailgate clear coat peeling, no first aid kit/fire extinguisher, windshield chips, head light fogged, poor battery, minor exterior damage.>, As is, where is</p>	205,585 km	\$459	2D8HN44E69R683442
\$2,956.00	2-011	<p>Van 2016 DODGE Grand Caravan SE FWD 3.6L, V6, gas auto A/C, tilt, cruise, AM/FM/CD player, rear HVAC, power heated mirrors/windows/rear vent windows/locks, keyless entry-1 key fob 7 passenger, Stow-N-Go 3rd seat only, roof rack, silver, TOW ONLY –</p> <p>This vehicle has an UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in “As is, where is” condition., 212,714 km, , KNOWN PROBLEMS and OBSERVATIONS: left outer tie rod, steering rack is stiff in the morning, rear bumper, rear tires, alignment needed, parking brake broken, windshield.</p> <p>Grille broke, hood chips/scratches, front bumper scratches, rear bumper broken, left side fenders scratches, right front fender road rash, right rear fender scratches, left front door rusted, left rear door road rash, right rear door scratches, tailgate scratches, no first aid kit/fire extinguisher, windshield cracked, interior badly soiled, poor battery, minor exterior damage.>, As is, where is</p>	212,714 km	\$1,098	2C4RDGBG2GR331712

Bid Price	Item #	Description	Kms	Min Price	Serial Number
\$2,815.65	2-015	<p>Van 2008 GMC Savana 1500 AWD 5.3L, V8, gas auto A/C, tilt, cruise, AM/FM, manual seat/windows, power locks, keyless entry-2 key fobs, 3 keys, remote start trailer wiring, hitch, km mud flaps, partition behind driver seat, shelving in the back with fiber floor, grille mesh cover, white, TOW ONLY –</p> <p>This vehicle has a VERY UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Body Integrity Inspection and a Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in “As is, where is” condition., 235,009 km, , KNOWN PROBLEMS and OBSERVATIONS: Left front axle seals, right lower ball joint, rear pads and rotors, alignment needed, air bag light on, driver door pin, driver seat ripped, both rocker panels.</p> <p>Hood paint chips, rear bumper dents, left and right front fender chips/paint peeling, both rocker panels rusted holes, all doors paint peeling/dents, roof scratches/rust spots, three holes in roof sealed, has spare tire/wheel wrench/jack, no first aid kit/fire extinguisher, drive seat hole/stained, poor battery, minor exterior damage.> , As is, where is</p>	235,009	\$451	1GTFH154881209450

Bid Price	Item #	Description	Kms	Min Price	Serial Number
REGINA, SaskBuilds and Procurement, SaskSurplus Sales Lot, 500 McLeod Street - Miscellaneous					
Contact SaskSurplus 306-787-2062 or 306-798-3306, sasksurplus@gov.sk.ca					
\$20.00 *	1-140	Booster Cables, light duty 10-11 feet in length. Good		\$1	
\$2.00	2-101	Booster Cables, Motomaster 10 foot light duty, yellow & black cables, 8 gauge. Excellent		\$1	
\$26.40 *	12-102	Tire, 225/65R17, Goodyear Nordic Winter, Snowflake Manufacture date, week 36, year 2019. Good		\$25	CN1493K00M
\$323.00 *	1-133	Tires, Set of 4 255/60R18, Goodyear Eagle Enforcer, M+S Manufacture date, week 28, year 2024. Excellent		\$300	
\$101.00	2-104	Tires, Set of 4 225/65R16, Winter Claw Extreme Grip, Snowflake Manufacture date, week 34, year 2014. Good		\$25	
No Bid	2-102	Tires, Set of 4 225/65R17, Firestone Winter Force, Snowflake, M+S Manufacture date, week 45, year 2021. Fair		\$120	
\$183.83	2-103	Tires, Set of 4 225/65R17, Sumitomo HTR Enhance LX2, M+S Manufacture date, week 27, year 2019. Good		\$160	
\$25.01 *	1-144	Tool Box, Brute Commercial Class 5'10" long, 2 supporting legs, has a tray, 2 keys, lid hard to close, side mount, damaged, removed from a 2015 Ram 2500. Fair		\$25	

Bid Price	Item #	Description	Kms	Min Price	Serial Number
ASSINIBOIA, Community Safety, 401 1st Ave West					
Contact Layne Pederson 306-530-6703, layne.pederson4@gov.sk.ca					
No Bid	2-595	Film Projector, Viewlex Unknown if operational, unable to plug in due to damaged cord, comes with case, and film projector. Broken Repairable		\$1	
ECHO VALLEY PROVINCIAL PARK, Parks Culture and Sports, Echo Valley Provincial Park - Call for Directions					
Contact Shelley MacLean 306-332-3215, shelley.maclean@gov.sk.ca					
\$959.00 *	11-007	Van 2009 DODGE Grand Caravan FWD 3.3L, V6, gas auto A/C, tilt, cruise, AM/FM/CD player, rear HVAC, power mirrors/front windows/locks, keyless entry-2 key fobs Stow-N-Go 3rd row only, 7 passenger, silver, TOW ONLY – This vehicle has a VERY UNSAFE SGI VIN status. A TOW ONLY Disclaimer must be signed by the purchaser. This vehicle requires a PASSED SGI Body Integrity Inspection and a Mechanical Safety Inspection to be licensed. Purchaser assumes full responsibility for repairs and any required inspections. This vehicle is sold in “As is, where is” condition., 168,040 km, , KNOWN PROBLEMS and OBSERVATIONS: Rear shocks, rear pads and rotors, alignment needed, sun visor clip, rocker panels. Grille broke, hood scratches/paint bubbling/dents, front bumper hole, rear bumper scratches, left front fender scratches, left rear fender rusted/dent, right rear fender rusted, both dog legs rusted, both rocker panels rusted, left front door rust/dents/chips, right front door rust/dents, roof small rust spots, tailgate glass scratched, no first aid kit/fire extinguisher, windshield chips, right mirror heated left is not, poor battery, minor exterior damage.>, As is, where is	168,040 km	\$951	2D8HN44E29R681753
MEADOW LAKE PROVINCIAL PARK, Parks, Culture and Sport, Meadow Lake Provincial Park - Highway 224 - Call for Directions					
Contact Chris Greedus 306-240-7229, christopher.greedus@gov.sk.ca					
No Bid *	1-519	Truck 2005 Dodge Dakota RWD, club cab 3.7L, V6, gas auto air, tilt, cruise, AM/FM/CD GVW 6010 lbs / 2726 kg, tire size P245/70R16, one set of keys, white, TOW ONLY, NO SGI Inspection. It is unknown if any repairs or safety concerns exist (if any). Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs if required. , unknown, , KNOWN PROBLEMS: transmission will only engage the reverse, 1st, and 2nd gears, odometer non-operational - shows error message, no battery, poor tires, poor windshield and wipers, poor mirrors, poor interior, poor exterior, minor exterior damage.>, As is, where is	unknown	\$600	1D7HE22K45S298326

Bid Price	Item #	Description	Kms	Min Price	Serial Number
No Bid *	1-511	Truck 2006 Dodge Dakota 4x4, club cab 3.7L, V6, gas auto air, tilt, cruise, AM/FM/CD, 6 foot box tire size P245/70R16, one set of keys, white, TOW ONLY, NO SGI Inspection. It is unknown if any repairs or safety concerns exist (if any). Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs if required. , 303,864 km, , KNOWN PROBLEMS: no battery, burns oil, rear side window replaced with plexi-glass, rusty exterior, poor tires, poor windshield, poor paint, poor interior, minor exterior damage.> , As is, where is	303,864 km	\$800	1D7HW22K16S626865
OUTLOOK, Agriculture, 410 Saskatchewan Ave W					
Contact Ben Lalonde 306-867-6469, ben.lalonde@gov.sk.ca or Outlook Front Desk 306-867-5500, stacey.stutters@gov.sk.ca					
No Bid *	11-509	GPS Base Radio, Pacific Crest PDL 4335 GPS 430-450Mhz radio for GPS system, significant wear, unknown if still operational, stored in a cool dry place for many years, no cables included. Poor		\$5	8,091,658
No Bid *	11-513	Surveying Tripod, Duratech, wood, flat head Stored in a cool dry place, clamps are somewhat loose, one leg is partially detached from the hinge (needs a new screw), noticeable wear present, tightening and calibration likely required. Fair		\$20	
No Bid *	11-515	Surveying Tripod, Leica, wood, telescoping antenna pole Stored in a cool dry place, clamps are somewhat loose, noticeable wear present, tightening and calibration likely required. Fair		\$30	
OUTLOOK, Agriculture, 410 Saskatchewan Ave W					
Contact Darren Clay 306-867-6733, darren.clay@gov.sk.ca or Stacey Stutters 306-867-5500, stacey.stutters@gov.sk.ca					
\$30.00	2-543	Air Tank, 11 gallon Operational. Fair		\$1	
\$35.00	2-544	Compound Miter Saw, Makita LS1040 10", operational. Fair		\$10	1,021,872
\$327.15	2-545	Generator, Honda EG3500X Unknown if operational. Fair		\$25	EA6-4111109
\$327.15	2-546	Generator, Honda EM3000c Unknown if operational. Fair		\$25	EZGL-1008606
No Bid	2-547	Pipes and Fittings, PVC and ABS Bundle of various lengths and sizes. Good		\$1	
\$5.00	2-548	Plan Holder, MasterFile 4 Engineering Grey, operational, 33 3/4" w x 29" d x 42 1/2" h, no keys. Good		\$1	
\$15.15	2-549	Side Mirrors, Set of 2 2014 Dodge Black, driver and passenger side, operational. Good		\$1	(P)68147863AG, (P)68147862AG
\$315.00	2-550	Soil Samplers, Lot of 2 Concord Truck mounted, 1 operational, 1 non-operational(parts), controllers. Fair		\$1	

Bid Price	Item #	Description	Kms	Min Price	Serial Number
\$35.00	2-551	Tow Hitches, Lot of 2 Pintle and Ball Operational, 2" ball. Fair		\$1	
PIKE LAKE PROVINCIAL PARK, Parks, Culture and Sport, Pike Lake Provincial Park - Call For Directions					
Contact Dwight Martin 306-933-6968 or 306-250-8490, Dwight.martin@gov.sk.ca					
\$557.00	2-606	Golf Cart 1999 Club Car Turf II CarryALL 2WD 1 cylinder, gas CVT Forward and reverse, electric dump box canopy, tire size 18-8x8, 1 set of keys, white, , , , KNOWN PROBLEMS: Engine removed, battery gone, other parts from engine bay may be missing, no roll over protection, one headlight damaged/missing, scratched plastic, brown paint overspray on various parts of vehicle, some of the tires do not hold air, plastic windshield is scratched, minor exterior damage > As is where is		\$10	RG9919-763361
\$2,122.00	2-607	Truck 2009 Chevrolet 2500 HD 4X4, 8' box 6.2L V8, gas auto air, tilt, cruise, power locks/windows/mirrors, AM/FM/CD Tipster box with hoist, GVW 4,173 kg, tire size 245/75R16, hitch receiver, two sets of keys, white, TOW ONLY, NO SGI Inspection. It is unknown if any repairs or safety concerns exist (if any). Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs if required. , 266,753 km, , KNOWN PROBLEMS: Light lenses fogged, large dent in passenger side of box, rusting around wheel wells and fenders, stone chips on hood and sides, front bumper valence damaged, chrome peeling, no back seat, driver seat tearing, needs new battery, minor exterior damage.>, As is, where is	266,753 km	\$1,000	1GCHK49K79E137154
\$2,731.12	2-608	Truck 2008 Chevrolet 2500 HD extended cab, 4X4, 8' box 6.2L V8, gas auto air, tilt, cruise, power windows/locks, AM/FM aluminum headache rack, GVW 4,173 kg, tire size 245/75R16, hitch receiver, two sets of keys, white, TOW ONLY, NO SGI Inspection. It is unknown if any repairs or safety concerns exist (if any). Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs if required. , 204,702 km, , KNOWN PROBLEMS: Engine light on, camshaft problem, has not been used in 2 years, headlights foggy, dent in passenger side rear fender, has been repainted - rust showing through, fender flares covering rust, stone chips throughout, hood paint peeling, tires poor, needs battery, minor exterior damage > As is where is	204,702 km	\$500	1GCHK29K78E208291
PRINCE ALBERT, Environment, 201 - 1061 Central Ave					
Contact Emelyn Feliciano 306-953-3233, emelyn.feliciano2@gov.sk.ca or Tammy Allan, tammy.allan@gov.sk.ca					
\$10.00	2-528	Bookshelf, wood Dark brown, 5 shelves, 37"w x 12"d x 71"h. Good		\$2	
\$5.00	2-529	Briefcase, vinyl exterior, metal hardware Black. Fair		\$1	
\$77.77	2-530	Chair, Lot of 3 cloth Black and faded purple, adjustable, 5 casters, ergonomic, swivel, tilts. Fair		\$2	
\$1.00	2-531	Clipboard, Lot of 2 metal Silver. Fair		\$1	
No Bid	2-532	Cork Board, wood 36"h x 48"w. Fair		\$1	

Bid Price	Item #	Description	Kms	Min Price	Serial Number
\$2.00	2-533	Desk Riser , Lot of 2 wood Dark walnut and gray, 34" w x 31" d x 20.5in h, keyboard tray. Good		\$2	
\$20.00	2-534	File Cabinet, Lot of 2 lateral, wood Off white, 2 drawer, 36"w x 24"d 27"h, no keys. Good		\$2	
\$2.00	2-535	File Cabinet, lateral, wood Off white, pedestal, 3 drawers, 18"w x 24"d x 26"h, no keys. Broken Repairable		\$1	
No Bid	2-536	Label Maker, Pt-touch 2030 Non-operational. Broken Repairable		\$1	UG2817-L32885761
\$11.11	2-537	Laminator, plastic, Swingline GBC Black, non-operational. Poor		\$1	WL1706000145
No Bid	2-538	Laptop Bag, polyester, ThinkPad Heavy duty, black. Fair		\$1	
\$2.00	2-539	Desk, wood Grey, L shape with overhead cabinets, main: 29"w x 42"d x 102"h, return side: 29"w x 38"d x 101"h. hutch: 42"w x 19"d x 72"h. Good		\$2	
No Bid	2-540	Office Partition, wood and cloth Beige, free standing, 60"w x 72" h. Good		\$2	
No Bid	2-541	Planner Case, Lot of 2 leather, Franklin Covey Brown and burgundy. Poor		\$1	
PRINCE ALBERT, Saskatchewan Polytechnic, 1100 15th St E					
Contact Doug Wagar 306-765-1780, wagardo@saskpolytech.ca or pashipping@saskpolytech.ca or Leslie Morin 306-765-1584, pashipping@saskpolytech.ca					
\$753.49	2-524	Dual Sander, General, 100 Operational, voltage 208/2HP/6.8Amp/3PH. Good		\$150	R560
\$201.00	2-526	Scaffold, Metaltech, Bakers 69.75" w x 29.25" d x 44.5" h, plywood deck, safety rails, swing gate, wheels. Good		\$50	
\$191.91	2-527	Scaffold, Metaltech, Bakers 69.75" w x 29.25" d x 44.5" h, plywood deck, safety rails, swing gate, wheels. Good		\$50	
\$125.88	2-525	Scaffold, Metaltech, Bakers 69.75" w x 29.25" d x 44.5" h, plywood deck. Fair		\$50	
\$18.00	2-501	Document Camera, Elmo, TT-02rx Operational, cables included. Good		\$1	525,952
\$17.00	2-502	Document Camera, Elmo, TT-12i Operational, cables included. Good		\$1	1,500,339
\$17.00	2-503	Document Camera, Elmo, TT-12iD Operational, cables included. Good		\$1	1,355,277
\$17.00	2-504	Document Camera, Elmo, TT-12iD Operational, cables included. Good		\$1	1,354,334
\$17.00	2-505	Document Camera, Elmo, TT-12iD Operational, cables included. Good		\$1	1,328,348
\$17.00	2-506	Document Camera, Elmo, TT-12iD Operational, cables included. Good		\$1	1,328,364
\$21.00	2-507	Document Camera, Elmo, TT-12iD Operational, cables included. Good		\$1	1,328,346

Bid Price	Item #	Description	Kms	Min Price	Serial Number
\$17.00	2-508	Document Camera, Elmo, TT-12iD Operational, cables included. Good		\$1	1,328,363
\$17.00	2-509	Document Camera, Elmo, TT-12iD Operational, cables included. Good		\$1	1,328,360
\$17.00	2-510	Document Camera, Elmo, TT-12iD Operational, cables included. Good		\$1	1,355,278
\$17.00	2-511	Document Camera, Elmo, TT-12iD Operational, cables included. Good		\$1	1,328,344
\$17.00	2-512	Document Camera, Elmo, TT-12iD Operational, cables included. Good		\$1	1,327,002
\$17.00	2-513	Document Camera, Elmo, TT-12iD Operational, cables included. Good		\$1	1,328,365
\$17.00	2-514	Document Camera, Elmo, TT-12iD Operational, cables included. Good		\$1	1,335,754
\$17.00	2-515	Document Camera, Elmo, TT-12iD Operational, cables included. Good		\$1	1,355,276
\$21.00	2-516	Document Camera, Elmo, TT-12iD Operational, cables included. Good		\$1	1,335,765
\$17.00	2-517	Document Camera, Elmo, TT-12id Operational, cables included. Good		\$1	1,335,745
\$17.00	2-518	Document Camera, Elmo, TT-12iD Operational, cables included. Good		\$1	132,345
\$17.00	2-519	Document Camera, Elmo, TT-12iD Operational, cables included. Good		\$1	1,355,279
\$17.00	2-520	Document Camera, Elmo, TT-12iD Operational, cables included. Good		\$1	1,244,379
\$30.25	2-521	Projector, NEC, VT660K VGA, operational. Good		\$1	3800459NB
\$125.64	2-522	Speakers, Octasound, SP520A/SP540A Operational. Good		\$1	54007691/92 54007842/43
\$155.55	2-523	Speakers, Peavey, SP-5G Operational. Good		\$1	09125405/09096974

Bid Price	Item #	Description	Kms	Min Price	Serial Number
REGINA, Saskatchewan Liquor and Gaming Authority, 12252 Ewing Avenue					
Contact Al Kentz or Todd Leurer, DCMaintenance@slga.com					
\$2,500.00	2-589	Reach Truck Raymond 752-R45TT Electric mast approx. 14 ft high, built-in on/off key operational, batteries are operational but approximately 5 years old, charger included - #215CS32099, Important Notice - Machines are sold "as-is.", no guarantees, warranties, returns, or refunds are provided, the seller assumes no responsibility for the condition, performance, or any issues after purchase. Removal Responsibility - the buyer is solely responsible for the complete removal and pickup of the machine from the property within seven (7) days following auction closure, the seller will not provide assistance with removal, laydown, or any related tasks, any damage to the premises or lot during removal will be the buyer's responsibility, the buyer assumes full responsibility for all aspects of removal, including any associated tasks., red/black, , Key H - 17687, DdMan - 10465, Known Recent Repairs: Serviced twice annually., , As is, where is	Key H - 17687, DdMan - 10465	\$2,000	752-15-AD48998
\$3,200.00	2-590	Reach Truck Raymond 752-R45TT Electric mast approx. 14 ft high, built-in on/off key operational, batteries are operational but approximately 5 years old, charger included - #215CS32104, Important Notice - Machines are sold "as-is.", no guarantees, warranties, returns, or refunds are provided, the seller assumes no responsibility for the condition, performance, or any issues after purchase. Removal Responsibility - the buyer is solely responsible for the complete removal and pickup of the machine from the property within seven (7) days following auction closure, the seller will not provide assistance with removal, laydown, or any related tasks, any damage to the premises or lot during removal will be the buyer's responsibility, the buyer assumes full responsibility for all aspects of removal, including any associated tasks., red/black, , Key H - 19337, DdMan - 10070, Known Recent Repairs: Serviced twice annually., , As is, where is	Key H - 19337, DdMan - 10070	\$2,000	752-15-AD48995
\$2,900.00	2-591	Reach Truck Raymond 752-R45TT Electric mast approx. 14 ft high, built-in on/off key operational, batteries are operational but approximately 5 years old, charger included - #216CS4639, Important Notice - Machines are sold "as-is.", no guarantees, warranties, returns, or refunds are provided, the seller assumes no responsibility for the condition, performance, or any issues after purchase. Removal Responsibility - the buyer is solely responsible for the complete removal and pickup of the machine from the property within seven (7) days following auction closure, the seller will not provide assistance with removal, laydown, or any related tasks, any damage to the premises or lot during removal will be the buyer's responsibility, the buyer assumes full responsibility for all aspects of removal, including any associated tasks., red/black, , Key H - 18436, DdMan - 11777, Known Recent Repairs: Serviced twice annually., , As is, where is	Key H - 18436, DdMan - 11777	\$2,000	752-15-AD49001

Bid Price	Item #	Description	Kms	Min Price	Serial Number
\$2,900.00	2-592	Reach Truck Raymond 752-R45TT Electric mast approx. 14 ft high, two keys operational, batteries are operational but approximately 5 years old, charger included - #215CS32102, Important Notice - Machines are sold "as-is.", no guarantees, warranties, returns, or refunds are provided, the seller assumes no responsibility for the condition, performance, or any issues after purchase. Removal Responsibility - the buyer is solely responsible for the complete removal and pickup of the machine from the property within seven (7) days following auction closure, the seller will not provide assistance with removal, laydown, or any related tasks, any damage to the premises or lot during removal will be the buyer's responsibility, the buyer assumes full responsibility for all aspects of removal, including any associated tasks., red/black, , Key H - 18409, DdMan - 10856, Known Recent Repairs: Serviced twice annually., , As is, where is	Key H - 18409, DdMan - 10856	\$2,000	752-15-AD49004
\$2,900.00	2-593	Reach Truck Raymond 752-R45TT Electric mast approx. 14 ft high, built-in on/off key operational, batteries are operational but approximately 5 years old, charger included - #215CS32101, Important Notice - Machines are sold "as-is.", no guarantees, warranties, returns, or refunds are provided, the seller assumes no responsibility for the condition, performance, or any issues after purchase. Removal Responsibility - the buyer is solely responsible for the complete removal and pickup of the machine from the property within seven (7) days following auction closure, the seller will not provide assistance with removal, laydown, or any related tasks, any damage to the premises or lot during removal will be the buyer's responsibility, the buyer assumes full responsibility for all aspects of removal, including any associated tasks., red/black, , Key H - 16600, DdMan - 10403, Known Recent Repairs: Serviced twice annually., , As is, where is	Key H - 16600, DdMan - 10403	\$2,000	752-16-AD55553
REGINA, Saskatchewan Liquor and Gaming Authority, 12252 Ewing Avenue					
Contact Todd Leurer 306-510-4368, dcmaintenance@slga.com or tleurer@slga.com					
No Bid	* 1-526	Cradles, Lot of 4 wood, metal Approx. 14'l x 3.5'w x 3.5'h. Good		\$200	
REGINA, Saskatchewan Liquor and Gaming Authority, 1702 Park Street					
Shola Babarinde 306-787-5864, sbabarinde@slga.com or Meet Patel, mpatel4@slga.com					
No Bid	2-596	Chairs, Lot of 2 fabric Brown and grey. Fair		\$10	
\$15.00	2-597	Chairs, Lot of 2 fabric Brown. Good		\$10	
No Bid	2-598	Chairs, Lot of 2 fabric Navy and blue, 5 castor, adjustable, seat/arms/height, operational. Fair		\$10	

Bid Price	Item #	Description	Kms	Min Price	Serial Number
\$25.00	2-599	Chairs, Lot of 2 fabric Navy blue, 5 castor, adjustable seat/arms/height, operational. Good		\$10	
\$15.00	2-600	Chairs, Lot of 2 fabric Sky blue and wine. Good		\$10	
\$20.00	2-601	Chairs, Lot of 2 fabric Wine. Good		\$10	
\$3.01	2-602	Coat Racks, Lot of 2 metal Grey. Good		\$2	
\$2.63	2-603	Coat Racks, Lot of 2 metal Black. Fair		\$1	
No Bid	2-604	Table, wood Brown, 26" w x 26" d x 16" h. Good		\$10	
No Bid	2-605	Table, wood and metal Biege, 60" w x 30" d x 29.5" h. Fair		\$10	
SASKATOON, Community Safety, 910 - 60th St E					
Contact Terry Schreiner 306-200-2749, terry.schreiner3@gov.sk.ca or Maintenance Shop 306-956-8844					
\$320.00	2-609	Boiling Pot, Cleveland Operational, approx 40 gal, natural gas, stainless Fair		\$1	
\$320.00	2-610	Boiling Pot, Cleveland, KGL-60 Operational, 60 gal, natural gas, stainless Fair		\$1	110,423,056,786
\$168.58	2-611	Cooler, Glass door, 31" w x 30" d x 79" h, non-operational, shelves are rusted. Broken Repairable		\$1	
\$260.00	2-612	Deep Fryer, Quest, MV 40/130 Operational, 16.5" w x 31" d x 42.5" h, natural gas, 130 KBTU, stainless. Fair		\$1	18,239
\$250.00	2-613	Deep Fryer, Quest, MV 40/130 Operational, 16.5" w x 31" d x 42.5" h, natural gas, 130 KBTU, stainless. Fair		\$1	18,393
\$33.00	2-552	Dryer, Amana YNED4655EW1 Operational when last used, dirty, dents, scratches, paint missing. Poor		\$1	MD2414377
No Bid	2-553	Dryer, Amana YNED4655EW1 Operational when last used, dirty, dents, scratches, parts missing. Poor		\$1	M92927380
\$33.00	2-554	Dryer, Amana YNED4655EW1 Operational when last used, dirty, dents, scratches. Fair		\$1	MD2413904
\$10.00	2-555	Dryer, Huebsch HDEMNRGS173CW01 Operational when last used, dirty, dents, scratches, paint. Poor		\$1	2,012,065,119
*MT	2-556	Dryer, Huebsch SDEMNRGS173CW01 Operational when last used, dirty, dents, scratches, paint. Fair		\$1	2,012,065,121
\$10.00	2-557	Dryer, Huebsch ZDE3SRGS173CW01 Operational when last used, dirty, dents, scratches, parts missing. Poor		\$1	1,509,051,644
\$10.00	2-558	Dryer, Huebsch ZDE3SRGSW173CW01 Operational when last used, dirty, dents, scratches. Poor		\$1	1,910,030,811

Bid Price	Item #	Description	Kms	Min Price	Serial Number
\$10.00	2-559	Dryer, Huebsch ZDESRGS175CW01 Operational when last used, dirty, dents, scratches. Poor		\$1	2,010,061,489
\$33.00	2-560	Dryer, Maytag YMED4500MW0 Operational when last used, dirty, dents, scratches, parts missing. Poor		\$1	MC0301813
\$50.99	2-561	Dryer, Maytag YMED4500MW034F Operational when last used, dirty, dents, scratches. Poor		\$1	MC0301804
*MT	2-562	Dryer, Speed Queen SDEMNRGS173CW01 Operational when last used, dirty, dents, scratches, paint missing. Fair		\$1	1,803,064,252
\$55.55	2-563	Food Trolley, stainless steel 2 sides, wheels, outside dimensions excluding wheels 35" w x 25" d x 49" h, heated section cord cut - unknown if operational, dented Fair		\$1	
\$55.55	2-564	Food Trolley, stainless steel Operational when last used, 2 sides, wheels, out side dimensions excluding wheels 33" w x 25" d x 42" h. Fair		\$1	
\$55.55	2-565	Food Trolley, stainless steel Operational when last used, 2 sides, wheels, out side dimensions excluding wheels 33" w x 25" d x 42" h. Fair		\$1	
\$55.55	2-566	Food Trolley, stainless steel Operational when last used, 2 sides, wheels, out side dimensions excluding wheels 33" w x 25" d x 42" h. Fair		\$1	
\$20.00	2-567	Food Trolley, stainless steel Operational when last used, 2 sides, wheels, out side dimensions excluding wheels 33" w x 25" d x 42" h. Fair		\$1	
\$20.00	2-568	Food Trolley, stainless steel Operational when last used, 2 sides, wheels, out side dimensions excluding wheels 33" w x 25" d x 42" h. Fair		\$1	
\$7.00	2-569	Food Trolley, stainless steel Operational when last used, 2 sides, wheels, out side dimensions excluding wheels 33" w x 25" d x 42" h. Fair		\$1	
\$12.00	2-570	Food Trolley, stainless steel Operational when last used, 2 sides, wheels, out side dimensions excluding wheels 33" w x 25" d x 42" h. Fair		\$1	
\$12.00	2-571	Food Trolley, stainless steel Operational when last used, 2 sides, wheels, out side dimensions excluding wheels 33" w x 25" d x 42" h. Fair		\$1	
\$12.00	2-572	Food Trolley, stainless steel Operational when last used, 2 sides, wheels, out side dimensions excluding wheels 33" w x 25" d x 42" h. Fair		\$1	
\$12.00	2-573	Food Trolley, stainless steel Operational when last used, 2 sides, wheels, out side dimensions excluding wheels 33" w x 25" d x 42" h. Fair		\$1	
\$44.44	2-574	Food Trolley, stainless steel Operational when last used, 2 sides, wheels, out side dimensions excluding wheels 33" w x 25" d x 42" h. Fair		\$1	
\$44.44	2-575	Food Trolley, stainless steel Operational when last used, 2 sides, wheels, out side dimensions excluding wheels 33" w x 25" d x 42" h. Fair		\$1	
No Bid	2-614	Meat Slicer, Bizerba, M-22 non-operational Broken Repairable		\$1	12,104,831
\$58.88	2-615	Oven, Manitowoc, MCO-GD-10S Operational, natural gas, 2089/240v 1 phase, stainless, 38" w x 48" d x 32" h. Fair		\$1	1,611,100,102,764

Bid Price	Item #	Description	Kms	Min Price	Serial Number
\$58.88	2-616	Oven, Manitowoc, MCO-GD-10S Operational, natural gas, 2089/240v 1 phase, stainless, 38" w x 48" d x 32" h. Fair		\$1	1,011,100,102,769
\$58.88	2-617	Oven, Manitowoc, MCO-GD-10S Operational, natural gas, 2089/240v 1 phase, stainless, 38" w x 48" d x 32" h. Fair		\$1	1,611,100,102,768
\$58.88	2-618	Oven, Manitowoc, MCO-GD-10S Operational, natural gas, 2089/240v 1 phase, stainless, 38" w x 48" d x 32" h. Broken Repairable		\$1	1,611,100,102,767
\$58.88	2-619	Oven, Manitowoc, MCO-GD-10S Operational, natural gas, 2089/240v 1 phase, stainless, 38" w x 48" d x 32" h. Fair		\$1	161,100,102,766
\$58.88	2-620	Oven, Manitowoc, MCO-GD-10S Operational, natural gas, 2089/240v 1 phase, stainless, 38" w x 48" d x 32" h. Fair		\$1	1,611,100,102,765
\$450.88	2-621	Steamer, Cleveland, 22CET6.1 Operational, 22" w x 31" d x 22" h, stainless, 208V, 3 phase, 29.8 amp. Fair		\$1	161,223,050,023
\$450.88	2-622	Steamer, Cleveland, 22CET6.1 Operational, 22" w x 31" d x 22" h, stainless, 208V, 3 phase, 29.8 amp. Fair		\$1	170,123,050,701
\$17.00	2-623	Stove, Garland, G36-6R Operational, natural gas, 35" w x 35" d x 57" h, stainless Fair		\$1	1,607,100,100,010
No Bid	2-576	Washer, Amana 4516FW4 Operational when last used, dirty, dents, scratches, corroded/rust Poor		\$1	
No Bid	2-577	Washer, Amana 4516FW4 Operational when last used, dirty, dents, scratches, corroded/rust. Poor		\$1	
No Bid	2-578	Washer, Amana 4516FW4 Operational when last used, dirty, dents, scratches, corroded/rust. Poor		\$1	
\$33.00	2-579	Washer, Amana 4516FW4 Operational when last used, dirty, dents, scratches. Fair		\$1	
\$33.00	2-580	Washer, Amana 4605EW0 Operational when last used, dirty, dents, scratches. Fair		\$1	C60629456
\$50.99	2-581	Washer, Maytag MVW4505MW1 Non-operational, needs repair, dirty, dents, scratches. Broken Repairable		\$1	CD1209793
\$50.99	2-582	Washer, Maytag MVW4505MW1 Non-operational, needs repair, dirty, dents, scratches. Broken Repairable		\$1	CD1403698
\$40.00	2-583	Washer, Whirlpool WTW4855HW3 Operational when last used, dirty, dents, scratches, corroded/rust Poor		\$1	
\$40.00	2-584	Washer, Whirlpool WTW4855HW3 Operational when last used, dirty, dents, scratches, corroded/rust. Poor		\$1	CD3300135
\$40.00	2-585	Washer, Whirlpool WTW4855HW3 Operational when last used, dirty, dents, scratches. Fair		\$1	CD440490
\$40.00	2-586	Washer, Whirlpool WTW4855HW3 Operational when last used, dirty, dents, scratches. Fair		\$1	

Bid Price	Item #	Description	Kms	Min Price	Serial Number
*MT	2-587	Washer, Whirlpool WTW4855HW3 Operational when last used, dirty, dents, scratches. Good		\$1	CD2300820
SASKATOON, SaskBuilds and Procurement, Hangar 17 Wayne Hicks Lane					
Contact Eric Braaten 306-491-8565, eric.braaten2@gov.sk.ca or Tim Sawatzky 306-385-2164, tim.sawatzky@gov.sk.ca					
\$9.00	2-624	Mobile Lifting Aid, AMT solutions, A150001 Goes down but does not go up, folds up and comes apart into 3 pieces for easy transport. Broken Repairable		\$1	1
\$50.00	2-625	Videoscope, Karl Storz, V05021AEM Unit powers on but has limited functionality, three boxes are included, two boxes were used for shipping and are empty, one box contains the videoscope and all attachments. Broken Repairable		\$1	114,814
SASKATOON, Saskatchewan Research Council, Bay 2D, 820 51st Street E					
Contact: Roger Dauvin 306-385-4035, roger.dauvin@src.sk.ca					
\$1,804.00	2-594	Stacker, 2022 U-Line H-5440 Semi-Electric Straddle Stacker FA009441 Semi-Electric 137" lift, manual push/pull Operational, holds charge well, 2 keys yellow 4.1 hours As is, where is	4.1 hours	\$1	25,211,100,708
SASKATOON, Saskatchewan Research Council, 143 - 111 Research Dr					
Contact: Roger Dauvin 306-385-4035, roger.dauvin@src.sk.ca					
\$100.00	2-626	Dishwasher, Labconco, FlaskScrubber 4420320 Operational. Poor		\$1	80,253,083
No Bid	2-627	Disintegration Apparatus, Agilent, 100 Operational, PN - G7962-64002. Fair		\$1,500	MY21081201
No Bid	2-628	Elemental Micro Analyzer, VELP Scientific, EMA 502 Operational, CHNSO, PN - F30800100. Fair		\$10,000	662,338
SASKATOON, Western Canada Lottery Corporation, 1914 1st Ave N					
Contact Curtis Adair 306-933-5425 or 306-850-0165, adairc@sk-wclc.com					
\$3,210.99	2-542	Van 2014 Dodge Grand Caravan SE 2WD 3.6L V6, gas 6 speed auto air, tilt, cruise, power windows/locks/seats cargo barrier, remote start, aftermarket stereo - Pioneer Mixtrax, GVW 2,745 kg, wheel base 3078 mm, tire size 225/65/16, two key fobs, white, TOW ONLY, NO SGI Inspection. It is unknown if any repairs or safety concerns exist (if any). Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs if required. , 251,226 km, , KNOWN PROBLEMS: Rust on tailgate, minor exterior damage.>, As is, where is	251,226 km	\$1	2C4RDGBG1ER416053

Bid Price	Item #	Description	Kms	Min Price	Serial Number
\$6,666.66	2-588	Van 2021 Dodge Promaster City SLT 2WD 2.4L inline 4, gas 9 speed, auto air, tilt, cruise, AM/FM, power windows/locks remote start, two sets of keys, white, TOW ONLY, NO SGI Inspection. It is unknown if any repairs or safety concerns exist (if any). Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs if required. , 253,920 km, , KNOWN PROBLEMS: Left and right front needs inner and outer tie-rod, left and right front ball joints are worn, left and right front disc pads, left and right front rotors are rusted and grooved, front brake calipers, rear brake drums rusted, power steering line leaking, coolant leak, minor exterior damage.>, As is, where is	253,920 km	\$1	ZFBHRFDBXM6V58029
SOUTHEND, Community Safety, 15 College Dr					
Contact Casey Howey 306-758-6254 or 306-961-9763, casey.howey@gov.sk.ca					
\$428.00 *	1-501	Towing Toboggan, oak 10 feet long with steel hitch in addition to overall length, comes with canvas bag, back stand-up bar, side boards, full bottom white puck board and additional puck board runners. Good		\$350	
\$428.00 *	1-502	Towing Toboggan, oak 9 feet long with steel hitch in addition to overall length, comes with canvas bag, side boards for protection, back stand bar, puck board material on bottom for protection. Good		\$350	