

As a reminder there is **NO ONSITE VIEWING, ONLINE-ONLY VIEWINGS** of sale items.

Thank you for your cooperation.

Every effort has been made to accurately describe items and their condition; however additional problems may exist, items may not be complete or exactly as described. Bidders are deemed to have reviewed Conditions on bid forms and relied entirely on their own inspection and evaluation prior to bidding. Vehicles and equipment are sold "AS IS, WHERE IS", there is no implied or express warranty.

Visit www.SaskSurplus.ca for pictures and link to download Bid Form.

- Items identified with * have been on a previous sale and will be listed first on www.SaskSurplus.ca web site.
- SaskBuilds and Procurement, SaskSurplus, reserves right to have unadvertised minimum selling prices on items.

It is the Bidder's responsibility to review the terms and conditions of sale on the Offer to Purchase, Bid Form.

Bid Forms are available from www.SaskSurplus.ca or from the SaskSurplus Sales Lot, 500 McLeod Street, Regina, SK.

Bid Forms can be submitted in the following ways:

- by deposit in the bid box at the SaskSurplus Sales Lot,
- by fax to (306)787-2092; by phone (306)787-2062 or (306)787-2238,
- by email to sasksurplus@gov.sk.ca, or
- by mail, addressed to: Ministry of SaskBuilds and Procurement, SaskSurplus, 500 McLeod Street, Regina, SK S4N 4Y1.

(If mailing your bid, please allow sufficient time for bid to be received.)

- Bids received after close date and time cannot be accepted.

MT = (Ministry Transfer) This means that the item has been claimed by another ministry and automatically transferred.

WD = (Withdrawn) This can happen if the item was requested to be removed by the seller,
or if bid prices did not meet the seller's minimum selling price. In this case, the item may be carried forward to a future sale.

Item #	Description	Kms	Minimum Selling Price	Serial Number	
REGINA, SaskBuilds and Procurement, SaskSurplus Sales Lot, 500 McLeod Street - Vehicles					
ON-LINE VIEWING ONLY. NO ON-SITE VIEWING. Contact SaskSurplus 306-787-2062 or 306-798-3306.					
*WD	6-001	Car 2009 CHEVROLET Impala LS FWD, 4 Door 3.5L V6 Gas Auto Dual zone A/C, tilt, cruise, AM/FM/CD player, power locks/windows/mirrors/driver seat/trunk release, keyless entry (1 key, 1 fob) , Black, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , Recent Repairs:, PROBLEMS: Transmission cooler line sweating, both outer tie rods loose, rear links, rear pads/rotors, front pad/rotor, left front caliper, right rear caliper pins, wheel alignment, A/C not working, hood hail damage/scratches, both bumpers chips/scratches, both left fenders hail damage/scratches, RF fender hail damage, all doors rust inside bottom, trunk lid rust/scratches/hail damage, roof rust/hail damage, trunk switch, head lamp foggy, left rear tail light assembly, wiper blades, battery poor, minor exterior damage.>, As is, Where is	192,551 Kms	2G1WB57K691326291	
6,600.00	6-002	SUV 2002 CHEVROLET Suburban 2500 LS 4x4, 5 passenger 6.0L V8 Gas Auto power locks and windows, a/c, tilt, cruise, AM/FM, rear HVAC cargo barrier behind rear seat (plywood floor cargo area), front towhooks, mud flaps, hitch, trailer wiring, electrical trailer brake, roof rack, White, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , Recent Repairs:, PROBLEMS: both rear inner fenders broken, rear bumper dented/bent, right rocker panel rusted, holes drilled in front hump, windshield cracked, exhaust manifolds bolts broken, no rear seat, 4 sealed holes in roof, spare tire may be incompatible, spare tire hoist missing, jack missing, battery poor, minor exterior damage.>, As is, Where is	162,960 Kms	\$700	3GNGK26U02G284816
*MT	6-003	SUV 2003 JEEP Liberty 4WD, 5 passenger 3.7L V6 Gas Auto A/C, tilt, cruise, AM/FM/CD player, power locks/mirrors/windows, keyless entry (2 keys, 1 fob) front tow hooks, grille inserts, hood deflector, hitch, trailer wiring, roof rails, spare tire cover , Silver, Passed SGI Inspection., Recent Repairs:, PROBLEMS: Hood dent/scratches, RF fender scratches, all doors rust along bottom (inside), obsolete phone mounted in vehicle, surface rust under car, battery poor, minor exterior damage.>, As is, Where is	93,954 Kms	\$500	1J4GL48KX3W668791
6,289.89	6-004	Truck 2007 CHEVROLET Silverado 2500 HD 4WD, crew cab, has back seat, 6'6" box 6.0L V8 Gas Auto A/C, tilt, cruise, AM/FM/CD player, power mirrors/locks/windows, keyless entry (1 key, 1 fob) driving lights, front tow hooks, side steps, hitch, trailer wiring, White, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , Recent Repairs:, PROBLEMS: Power steering leak, oil leaks, right lower ball joint has play, hood paint peeling/chips, hole in front bumper, rear bumper bent/dent, both rear fenders road rash, rust/dents, rocker panel rust, all doors rust along bottom/dents, right tail light assembly, left fog out, tailgate rust/corners bent, drivers door handle, holes drilled in front of box, rear bumper pushed against both 1/4 panels, hole in top of B pillars inside, drivers seat tear/worn, back of both front seats has holes, missing jump seat, roof rust spots/scratches/3 sealed holes, battery poor, minor exterior damage.>, As is, Where is	289,898 Kms	\$530	1GCHK23K27F547283

Item #	Description	Kms	Minimum Selling Price	Serial Number
5,577.00 6-005	Truck 2012 DODGE Ram 2500 4WD, crew cab, has back seat, 6'5" box 5.7L V8 Gas Auto A/C, tilt, cruise, AM/FM/CD player, power heated mirrors/windows/locks grille inserts, front tow hooks, mud flaps, hitch, trailer wiring, White, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , Recent Repairs:, PROBLEMS: Exhaust manifold leaks, steering shock, tie rod to pit, alignment out, front tires, battery hold down, hood dents, front bumper rust spots, all fenders rust/dents, both left doors road rash/rust along bottom, both right doors dents/rust spots, roof rust spots/dents/6 sealed holes, windshield stone bruise, right front head lamp, right plate light, driver seat & back seat badly worn, RR cab corner dent, missing jump seat, hole in RF hump, rocker panels rusted, battery poor, minor exterior damage.>, As is, Where is	271,638 Kms	\$1,155	3C6TD5CT2CG189309
2,924.00 6-006	Van 2012 CHEVROLET Express AWD, Cargo Van 5.3L V8 Gas Auto A/C, tilt, cruise, AM/FM/CD player, power locks & front windows, rear aux heat, 2 keys map box, cargo barrier, wood floor, shelving, beacon, hitch, trailer wiring, electric trailer brake, White, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , Recent Repairs:, PROBLEMS: Engine blown, no motor, rear differential leaking, rear pads/rotors, upper valve train, bent push rod, tires poor, windshield cracked, rust underneath rear, hood chips/dents, both bumpers stone chipped ,LR fender trim broken/ road rash, tailgate paint cracked, LF seat worn/cracked, roof small rust spots, spare tire loose in back, battery poor, no first aid kit or fire extinguisher, brokem valve spring in box in cab, minor exterior damage.>, As is, Where is	192,446 Kms	\$970	1GCSHAF46C1130316
7,277.00 6-007	Van 2009 CHEVROLET Express 1500 AWD, Cargo Van, 135 inch wheelbase 5.3L V8 Gas Auto A/C, tilt, cruise, AM/FM radio, power locks hitch, trailer wiring, map box, computer stand, plywood floor, shelving, electric trailer brake, strobe light (not working), rear heat, White, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , Recent Repairs:, PROBLEMS: Exhaust leak before the muffler, rear pads and rotors, alignment, key tumbler, hood paint peeling, front bumper rust, rear bumper dented, chips, rear fenders paint peeling, roof small rust spots, drip rail rust, left corner marker, plate light, 2 sealed holes in roof, windshield chips, no first aid kit, no fire extinguisher, battery poor, parking lot dents and scratches.>, As is, Where is	171,971 Kms	\$1,010	1GCFH154091153389
5,121.00 6-008	Van 2009 CHEVROLET Express 1500 AWD, Cargo Van, 135" wheel base 5.3L V8 Gas Auto A/C, tilt, cruise, AM/FM radio, power locks, 2 keys hitch, trailer wiring, electric trailer brake, map box, cargo barrier, plywood floor, computer stand, White, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , Recent Repairs:, PROBLEMS: TPMS light on, e-brake not holding, rear drive shaft rear u joint loose, rear pads/rotors grooved, high mount out, windshield cracked, driver's inside door handle broken, sliding door damaged, hood chips, dents, bumpers pitted, dented, holes drilled, LF fender/LF door/tailgate paint peeling, RR fender large dent, rust, rocker panels rusted, RR door rusted, driver's seat worn, driver's armrest broken, rear dome light out, holes drilled in bumpers, 4 sealed holes in roof, roof small rust spots, spare tire loose/may be incompatible, no first aid kit, no fire extinguisher, RF mud flap missing, battery poor, minor exterior damage.>, As is, Where is	223,621 Kms	\$960	1GCFH154091153568

Item #	Description	Kms	Minimum Selling Price	Serial Number
8,492.00 6-009	Van 2012 CHEVROLET Express 1500 AWD, Cargo Van 5.3L V8 Gas Auto A/C, tilt, cruise, AM/FM/CD player, power locks/windows, rear aux heat, keyless entry (3 keys/2 fobs) 2 metal boxes removed - not attached to vehicle, map box, cargo barrier, shelving, wood floor, hitch, trailer wiring, electric trailer brake, White, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , Recent Repairs:, PROBLEMS: flange on exhaust midpipe leaking/noisy, both front axle seals leaking, rear rotors/pads rusted/worn, front bumper/tailgate/right rocker panel rusted, rear bumper bent/dented TPMS light on, tailgate/left rocker panel paint peeling, driver's seat ripped/worn, no plate light, LR mud flap missing, 1 sealed hole in roof, battery poor, minor exterior damage.>, As is, Where is	196,957 Kms	\$1,037	1GCSHAF44C1134560
3,699.00 6-010	Van 2008 DODGE Caravan SXT FWD, 7 passenger, 2nd and 3rd row Stow & Go 3.3L V6 Gas Auto A/C, cruise, tilt, AM/FM/CD player, power windows/locks/mirrors, brake pedal adjustment, remote keyless entry (2 fobs) roof rack, Silver, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , Recent Repairs: Recall W09 repaired, PROBLEMS: Left front axle seal leaks, both outer tie rods, left inner tie rod, rear shocks, front & rear rotors, missing row of seats, passenger front tire, tires 2/32 needs new tires, wipers, hood scratches/paint bubbling, both bumpers chipped/scratched, RF and RR fenders rust spots, roof scratches, tailgate small dents, windshield chips, LF seat ripped, cushion soft, RR seat trim loose, battery poor, parking lot dents and scratches.>, As is, Where is	192,529 Kms	\$500	2D8HN44H38R785970
5,137.00 6-011	Van 2009 DODGE Grand Caravan FWD, Cargo Van 3.3L V6 Gas Auto A/C, tilt, cruise, AM/FM/CD player, power front windows/mirrors/locks computer stand, map box, cargo barrier, steel floors, shelving, hitch, roof rack with beacon, handle mounted to tailgate, White, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , Recent Repairs: Recall W09 repaired, PROBLEMS: Engine oil low on fluid, power steering return hose leaking, TPMS light, front brake pads worn out, front washers inoperable, front washer hose broken, hood paint peeling, both bumpers cracked/scratched, RF fender dented, RF door paint chipping at top, windshield small chips, RR door rust, driver seat worn/holes, right visor worn, 2 sealed holes in roof, battery poor, parking lot dents and scratches, minor exterior damage.>, As is, Where is	75,437 Kms	\$1,376	2D4HN11E09R683408
4,907.00 6-012	Van 2008 DODGE Grand Caravan FWD, Cargo Van 3.3L V6 Gas Auto A/C, tilt, cruise, AM/FM/CD player, power front windows, power locks map box, cargo barrier, steel floor, roof rack with beacon-condition unknown, shelving, hitch, handle mounted to roof at rear, box of 10 blue parts bins for shelving,>, White, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , Recent Repairs: Recall W09 repaired, instruments, gauges, PROBLEMS: Undercarriage damage, crossover pipe, hood paint bubbling/peeling/hail damage, LF bumper cracked, both bumpers chipped, RF fender rusted, LF door missing molding, roof rusted/hail damage/3 holes sealed, tailgate inside panel missing trim, windshield chipped, cracked top right corner, driver rubber floor mat worn, tires soon, battery poor, parking lot dents and scratches, minor exterior damage.>, As is, Where is	115,392 Kms	\$1,250	1D4HN11H08B143886

Item #	Description	Kms	Minimum Selling Price	Serial Number
5,300.00 6-013	Van 2008 DODGE Grand Caravan FWD, Cargo Van 3.3L V6 Gas Auto A/C, tilt, cruise, AM/FM/CD player, power front windows/mirrors/locks map box, cargo barrier, shelving, steel floor, roof rack with beacon step mounted to rear bumper, handle mounted to tailgate, hitch, White, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , Recent Repairs: Recall W09 repaired, PROBLEMS: Check engine, battery dead needs replacing, windshield cracked, hood hail damage, front bumper cracked, rear bumper scratches, LR fender small dent, tailgate large dent, RR wheel cover broken, high mount brake light, 2 sealed holes in roof, minor exterior damage.>, As is, Where is	71,411 Kms	\$1,350	1D4HN11H88B17215
5,751.00 6-014	Van 2009 DODGE Grand Caravan FWD, Cargo Van 3.3L V6 Gas Auto A/C, tilt, cruise, AM/FM/CD player, power front windows/mirrors/power locks map box, cargo barrier, steel floor, shelving, with 4 blue bins, roof rack, with beacon- unknown condition, rear step mounted to hitch,, White, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , Recent Repairs: Recall W09 repaired, PROBLEMS: Transmission leak, rear shocks, rear rotors, brakes noisy, hood paint bubbling, front bumper cracked, hole in front bumper skirt, RR door dented, roof rust spots/3 holes sealed, tailgate dented/rust spot, windshield chips, LR tail light lens broken, 2 holes in front floor board, battery poor, parking lot dents and scratches.>, As is, Where is	64,731 Kms	\$1,351	2D4HN11E99R617651
2,599.00 6-015	Van 2009 DODGE Grand Caravan SE FWD, 7 passenger Stow-n-Go (rear seat only) 3.3L V6 Gas Auto A/C, tilt, cruise, AM/FM/CD player, power mirrors/locks/front windows, rear HVAC, keyless entry (1 fob) , Red, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , Recent Repairs:, PROBLEMS: Transmission cooler lines, coolant crossover rusted, rear pads/rotors, alignment out, tires poor/separating, hood scratches/dents/chips, rear bumper cracked/scratches, both left fenders rusted/scratches/chips, all doors dents/scratches, tailgate glass scratched, front wipers, rear wiper blade, wheel wrench missing, battery poor, no first aid kit or fire extinguisher, minor exterior damage.>, As is, Where is	220,118 Kms	\$526	2D8HN44EX9R641517
5,177.00 6-016	Van 2007 DODGE Grand Caravan, 7 passenger Stow-n-Go (2nd row & 3rd row seats) FWD 3.3L V6 Gas Auto Dual zone A/C, tilt, cruise, AM/FM/CD player, rear HVAC, power front windows/side vent/windows/mirrors/locks, keyless entry , 2 key fobs, Cargo barrier, beacon (condition unknown), jack, wheel wrench (cover broken), White, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , Recent Repairs:, PROBLEMS: power steering rack leaking, front & rear wipers, rear wiper spray, battery hold down, exhaust hanger, hood rust spot, front bumper scratches, LF door rust along inside bottom, roof rust spots, battery poor, rust underneath, tires cracked, minor exterior damage, no first aid kit, no fire extinguisher >, As is, Where is	45,158 Kms	\$660	1D4GP24E77B213671

Item #	Description	Kms	Minimum Selling Price	Serial Number
4,176.75 6-017	Van 2008 DODGE Grand Caravan CV FWD, Cargo Van 3.3L V6 Gas Auto A/C, tilt, cruise, AM/FM/CD player, power locks/front windows/mirrors computer stand, map box, cargo barrier, shelving, metal floor in rear, roof rack with beacon- condition unknown, White, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , Recent Repairs: Recall W09 repaired, indicator lamps, PROBLEMS: Check engine light (P0300) random misfire, rough idle, plugs & wires, all tires worn & separating, right tail light assembly, windshield cracked, beacon light not working, hood paint bubbling, both bumpers scrapes/chips, LF and LR fenders rust/chips/dents, RF fender rust, both left doors dents/bent at bottom, RR door paint worn at top, roof small rust spots/dent/3 sealed holes,tailgate chips, scratches, holes in top molding, battery poor, parking lot dents and scratches,minor	105,345 Kms	\$1,400	1D4HN11H18B172720
2,089.89 6-018	Van 2007 FORD E350 RWD 5.4L V8 Gas Auto A/C, tilt, cruise, AM/FM radio, power front windows & locks, rear HVAC, 4 keys hitch with receiver & pin, trailer wiring, White, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , Recent Repairs:, PROBLEMS: Large oil leak, power steering leak, inner tie rod, right upper ball joint, rear rotors, missing seat belts, 2 back seats broken, rocker panels rust, both bumpers rust, all fenders rust/road rash, both front doors rust along bottom, all seats soiled, back rests on bench seats are bent, 1st bench seat has a hole, roof rust at top of windshield & drip rails, no fire extinguisher/first aid kit, battery poor, minor exterior damage.>, As is, Where is	207,540 Kms	\$562	1FBSS31L97DB24983
7,053.00 6-019	Van 2004 GMC Savana 3500 RWD, Cargo Van, with man lift 6.0L V8 Gas Auto A/C, tilt, cruise, AM/FM, electric trailer brake, trailer wiring heavy duty rear bumper, pintle hook, ladder, Warwick ladder/televift with beacon (good condition), generator compartment, map box, cargo barrier, plywood floor, shelving, boxes for batteries, computer stand, propane extended bumper, White, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , Recent Repairs:, PROBLEMS: engine oil cooler lines leaking, LR tire steel cords, front wheel alignment out, backup alarm disconnected, pintle hitch seized, front bumper badly rusted, RR fender/right rocker panel/passenger's door rusted, hood dented, driver's door/tailgate paint peeling, front beacon light not working, front mud flaps poor, spare tire missing, wheel wrench missing, driver's seat worn with frame visible, knob for dashlight dimmer missing, washer nozzles broken, 2 sealed holes in roof, battery poor, minor exterior damage>, As is, Where is	118,053 Kms	\$4,225	1GTHG35U641220514
7,024.00 6-020	Van 2006 GMC Savana 3500 RWD 6.0L V8 Gas Auto A/C, tilt, cruise, AM/FM radio, power locks, no auxilary heater Telelift aerial man lift (max capacity 300 lbs - condition unknown),semi annual inspection records in vehicle, mud flaps, compressor compartment, map box, computer stand, beacon, shelving, wooden floor, HD rear bumper, pintel hook, trailer wiring, rear trailer brake, ladder mounted at rear, White, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , Recent Repairs:, PROBLEMS: Engine oil cooler lines leaking oil, rear transmission seal leaking, steering box leaking oil, rear tires cracking, center brake light not working, drivers seat badly worn/frame visible, left side mirror broken, hood dents/scratches/chips, front bumper chips/scratches, both rear fenders rust, right rocker panel rust/dent, LR door rust, both right doors paint peeling, RR sliding door	125,024 Kms	\$3,950	1GTHG35U961240100

Item #	Description	Kms	Minimum Selling Price	Serial Number
*MT 6-021	Van 2008 DODGE Grand Caravan FWD 3.3L V6 Gas Auto A/C, tilt, cruise, AM/FM/CD player, power front windows & mirrors map box, cargo barrier, roof rack with beacon, rear roof handle, hitch, steel floor, shelving, White, Passed SGI Inspection., Recent Repairs: Recall W09 repaired, PROBLEMS: Rear rotors, cross over tube, front tires poor, rear bumper crack/chips, LF fender scratches, RF fender missing lower molding/rust, RR door scratched, tailgate window scratched, LF seat worn, 2 sealed holes in roof, battery poor, missing front mud flaps, minor exterior damage.>, As is, Where is	94,539 Kms	\$1,550	1D4HN11H28B139922
5,300.00 6-022	Van 2009 DODGE Grand Caravan FWD 3.3L V6 Gas Auto A/C, tilt, cruise, AM/FM/CD player, power front windows/mirrors/locks map box, computer stand, cargo barrier, shelving, steel floor, step attached to hitch, handle attached to tailgate, roof rack with beacon, White, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , Recent Repairs: Recall W09 repaired, PROBLEMS: Front & rear rotors, alignment, rear tires poor, front tire soon 3rd brake light out, driver seat ripped/foam showing, hood scratches/dents, both bumpers chips, scratches, LR & RR fenders rusting, RR door paint chipped at top/rusting/dents, 2 holes in roof, tailgate glass scratched, windshield chips, front bumper cover cracked, battery PO562 low, parking lot dents and scratches.>, As is, Where is	82,086 Kms	\$1,350	2D4HN11E39R617631
4,024.00 6-023	Van 2009 DODGE Grand Caravan CV FWD 3.3L V6 Gas Auto A/C, tilt, cruise, AM/FM/CD player, power mirrors/front windows/locks computer stand, map box, ladder rack with beacon, hitch, cargo barrier, steel floor, shelving, handle mounted on top of tailgate, White, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , Recent Repairs: Recall W09 repaired, PROBLEMS: All rotors noisy/pulsation, oil change needed, heater speed switch, windshield cracked, hood paint poor/bubbling, front bumper cracked/hole, rear bumper scratched, tailgate rust spots, washer fluid low, 3 sealed holes in roof, battery poor, RF seat stained, parking lot dents and scratches.>, As is, Where is	124,194 Kms	\$1,450	2D4HN11E19R683403
REGINA, SaskBuilds and Procurement, SaskSurplus Sales Lot, 500 McLeod Street - Miscellaneous Items and Equipment.				
ON-LINE VIEWING ONLY. NO ON-SITE VIEWING. Contact SaskSurplus 306-787-2062 or 306-798-3306.				
10.01 6-101	24 Hour Control Paragon model 4005-005, max load 40 amp , , , , , New - Unused		\$1	TD-1749-00
30.99 6-102	Air Cylinders Lot of 3 Bimba, Speedair Stainless steel, threaded one end, 8 inches long, with pin at one end, 1 1/2 " diameter , , , , , New		\$1	SR-175-DP
40.00 6-103	Artificial Plants Lot of 10 Plastic, with pots various sizes and colours, 33 inches to 72 inches , , , , , Fair		\$1	
40.00 6-104	Artificial Plants Lot of 11 Plastic, with pots various sizes and colours, 9 inches to 72 inches , , , , , Fair		\$1	
9.05 6-105	Battery Back Up Belkin 750VA, unsure if operational , , , , , Fair		\$1	
41.00 6-106	Battery Charger Motomaster, Model 011-1586-4 Start, battery/alt, tester, 2/20/55 amp, 150 amp engine start, with timer , , , , , Poor		\$20	
70.00 6-107	Battery Charger Schumacher SF4022 charger, tester, starter, 2/10/40/100/200 amp, with timer , , , , , Poor		\$20	

Item #	Description	Kms	Minimum Selling Price	Serial Number
40.00 6-108	Battery Charger with Cart Solar 560, metal with pneumatic wheels charger, tester, starter, 60/40/6 amp, with timer , , , , , Poor		\$20	
No Bid 6-109	Bearings Lot of 2 Torrington, Ingersoll-Rand 1- 1/2 inch ball bearing , 1/2 inch deep ; 1- 1/2 inch x 2 1/4 inch deep, ball bearing , , , , , New - Unused		\$1	
8.00 6-110	Bolts, Nuts, Washers Lot of 21 Miscellaneous 1/4 to 3 1/2 inch, pan, philips, robertson, flatheads, some full boxes, some partial, all in new condtion , , , , , Good		\$1	
7.03 6-111	Brass weights Lot of 2 2 brass weights in wooden box with leather handle 9" WX 4"DX 4 3/4 " H, varnished , , , , , Good		\$1	
1.27 6-112	Breaker lock Lot of 2 Cutler-Hammer SMCU 150D , , , , , New in Box		\$1	1261CUG07
No Bid 6-113	Bulbs Lot of 17 Sylvania E17 medium, ballast S55 , , , , , New - Unused		\$1	
3.00 6-114	Bulbs Lot of 28 Sylvania, Philips, Litemor 9- 67510 s68, 4 ET 2315, 9- 25 Watt Philips, blue, 2-100 Watt Rough Service, Philips, 2- Sylvania 100 watt, Rough Service, 2- Litemor 100 Watt, Long life , , , , , Good		\$1	
No Bid 6-115	Bulbs Lot of 8 Sylvania, Philips, Lumalux 2- ED 37 mercury bulb, 2-ET 23.5, 1-ED 28, 1-Lumalux 568 Sylvania, 2-C E 26, 125 Watt Philips , , , , , New - Unused		\$1	
No Bid 6-116	Bulbs Lot of 26 Sylvania, Sunlux, Philips, Westinghouse Ceramalux, Panasonic, Haskelite 4- ET1 8 Sylvania, 1- LU250 Sunlux, 1-Lumalux S62 , Sylvania, 1-Ceramalux, 150Watt 50 Volt, Philips, 6- LU150 55 Volt, Sylvania, 2- Ceramalux C150 S55 Westinghouse, 1- 20 Watt reflector flood LED, Philips, 1- LED 60 watt Sylvania, 2- 100 watt, incandescent 1- A18 LED Blue, 1- 25 watt philips, blue, 2- 120 volt TCP Blue, 1-EPA 13 E 500L Panasonic, 1- A23 Haskelite, 150W 230 Volt, Philips, 1- philips 50Watt 230 Volt , , , , , New - Unused		\$1	
No Bid 6-117	Bulbs Lot of 68 Westinghouse 11- L56 electrical interlock, 2 NO Pole 3 L56 Electrical interlock, universal pole, 13-Type OT light lens red, 8- Type OT Light lens Red, 8- OT3 light lens, green, 7- OT4 light lens, amber, 4- OTITG pilot light with transformer, 13- push to test light, 240 volt AC OTPG, 1- push button accessories, OT2PG , , , , , New - Unused		\$1	
12.75 6-118	Canvas Painting Flower Painting 29"l x 53"w with frame. Painted by S. Hilton , , , , , Fair		\$1	
5.00 6-119	Canvas Painting Water/Wave Painting 30"l x 42"w, with frame. Painted by Anderson , , , , , Good		\$1	
10.75 6-120	Cart Metal 46WX82LX41H, 2 fixed 2 Swivel casters, with hitch blue , , , , , Fair		\$1	
7.25 6-121	Cart Stainless steel 24WX38LX37H, 3 shelves, 2 swivel casters, 2 fixed, , , , , Fair		\$1	
42.69 6-122	Cart Stainless steel 30 1/2 WX 41 1/2 LX 36H, 2 shelves, 2 swivel casters, 2 fixed casters, , , , , Fair		\$1	
14.95 6-123	Cart Stainless steel 32WX45LX41H, 2 shelves, 2 swivel casters, 2 fixed, hitch and ball, , , , , Fair		\$1	
No Bid 6-124	Cart Wood 22" w x 50"l x 30"h, 2 swivel casters, 2 fixed, pink , , , , , Fair		\$1	
No Bid 4-197	Cart Wooden 20.5"W x 40"L x 37"H, all swivel casters, white , , , , , Fair		\$1	
No Bid 6-125	Cart Wooden 22 1/2 WX 41LX 40H, platform, 2 swivel casters, 2 fixed, brown, , , , , Fair		\$1	
2.25 6-126	Cart Wooden 22 1/2 WX 52LX 37H, platform, 2 swivel casters, 2 fixed, brown , , , , , Fair		\$1	

Item #	Description	Kms	Minimum Selling Price	Serial Number
No Bid 6-127	Cart Wooden 23WX48LX50H, 2 shelves, 2 swivel casters, 2 fixed, brown , , , , , Fair		\$1	
6.37 6-128	Cart Wooden 23WX50 1/2 LX 40H, platform, 2 swivel casters, 2 fixed, blue, , , , , Fair		\$1	
No Bid 6-129	Cart Wooden 24WX48LX50H, platform, 2 swivel casters, 2 fixed, 2 shelves, 1 drawer, brown , , , , , Fair		\$1	
No Bid 6-130	Cart Wooden 25WX48LX50H, platform, 2 shelves, 2 swivel casters, 2 fixed, brown , , , , , Fair		\$1	
No Bid 6-131	Cart Wooden 25WX54LX54H, platform, 2 shelves, 2 swivel casters, 2 fixed, brown , , , , , Fair		\$1	
5.25 6-132	Cart Wooden 32WXX60Lx30 1/2 H, 6 wheels, 4 swivel, brown , , , , , Fair		\$1	
No Bid 4-199	Cart Wooden 36"L x 24"W x 52"H, 2 shelves, swivel casters, brown , , , , , Good		\$1	
No Bid 5-125	Cart Wood 22"w x 48"l x 37"h, 2 caster wheels, 2 fixed wheels, metal handle, worn, scuffed , , , , , Fair		\$1	
10.00 4-201	CD Player JVC model XL-FZ158BK 5-disc CD changer, unsure if operational , , , , , Poor		\$1	
No Bid 4-202	CD/Cassette Player Sharp unsure if operational , , , , , Poor		\$1	
No Bid 6-133	Chair Ergo 5 casters, no arms, grey , , , , , Poor		\$1	
No Bid 6-134	Chair metal, stacking chrome, brown , , , , , Good		\$1	
5.00 6-135	Chair Steno 4 casters, black , , , , , Fair		\$1	
No Bid 4-149	Chairs Lot of 3 Metal and Fabric , , , , , Fair		\$1	
26.00 6-136	Circuit Breakers Lot of 5 Square D, Cutler-Hammer Square D 15 Amp, 3 pole, 240 volt AC; Square D 20 Amp, 2 poles, 120-240 Volt; Square D 15 Amp, 1 pole, 120-240 volt; Cutler -Hammer, 30 Amp, 1 pole, 120 volt; Square D 15 Amp, 1 pole, 120 -240 volt , , , , , New - Unused		\$1	
11.00 6-137	Closed circuit cameras and recorders Lot of 7 Panasonic and Sanyo 2 cameras CR234, 1 camera BF134, 1 camera 1-BP114, 1 camera 1BL 204, 3 power supplies, some cords, 1 Panasonic digital Disk recorder, 1 Sanyo Real time video cassette recorder, condition of all are unknown , , , , , as is where is		\$1	Cameras 01W07688, ACR08736, ACR 08900, 47W09292, 24B00744. Panasonic recorder AAA03580, Sanyo recorder
22.00 6-138	Come along puller 1 Metal, with loop 16'Wx 6 1/2" D X 1 1/4 " H, with opening jaws for wire pulling , , , , , Good		\$1	
1.01 6-139	Come along puller 1 Metal, with loop 39" long on cable, with hook, loop for wire pulling , , , , , Good		\$1	
20.00 6-140	Conduit Bender 1/2 EMT Benfield bender 39 inch shaft , , , , , Good		\$1	
5.01 6-141	Conduit Bender Lakin- Hickley, 1/2 inch 50 inch shaft , , , , , Good		\$1	
5.01 6-142	Conduit Bender Metal, 1/2 inch 46 inch shaft , , , , , Good		\$1	
5.01 6-143	Conduit Bender Metal, 1 1/8 inch 45 inch shaft , , , , , Good		\$1	
5.01 6-144	Conduit Bender Metal, 1/2 inch 49 inch shaft , , , , , Good		\$1	
5.01 6-145	Conduit Bender Metal, 2 inch 46 inch shaft , , , , , Good		\$1	

	Item #	Description	Kms	Minimum Selling Price	Serial Number
	10.00 6-146	Conduit Bender Wiremold, Cut 600B 36 inch shaft , , , , , Good		\$1	
	No Bid 6-147	Core and Coil HID Replacement Advance ballast, capacitor, fittings in box , , , , , New - Unused		\$1	
*MT	6-148	Desk Arborite Top, Light Brown 112"W x 84"D x 29.5"H, Hutch piece is 108"W x 14.5"D x 44.5"H. Includes 1 Pedestal with key, , , , , Fair		\$1	
	52.50 6-149	Desk Arborite Top, Light Brown 112"W x 84"D x 29.5"H, Hutch piece is 108"W x 14.5"D x 44.5"H. Includes 2 Pedestals with key, , , , , Fair		\$1	
	No Bid 6-150	Desk Runoff Pepperdust 30"w x 48"l x 28.5"h, left hand, finish worn , , , , , Fair		\$1	
	No Bid 6-151	Desk Runoff Pepperdust 42"w x 29"d x 28"h, right hand return only, broken feet , , , , , Broken Repairable		\$1	
	No Bid 6-152	Desk Runoff Pepperdust 42"w x 30.5"d x 29"h, left hand, finish worn , , , , , Fair		\$1	
	6.27 6-153	Desk Runoff Pepperdust 48"w x 30"d x 29"h, left hand return only , , , , , Fair		\$1	
	No Bid 6-154	Desk Center Pepperdust 40"w x 42"d x 29"h , , , , , Good		\$1	
	No Bid 6-155	Desk Return Pepperdust 42"w x 30"d x 29"h, right hand , , , , , Poor		\$1	
	No Bid 6-156	Desk Return Pepperdust 48"w x 30"d x 29"h, left hand , , , , , Fair		\$1	
	5.99 6-157	Digital Recorder Kodak DO1100, with remote and carrying bag , , , , , Poor		\$1	34W01000039
	5.00 6-158	Drafting instruments Partial set In case, grey , , , , , Good		\$1	
	258.00 6-159	Drive X4 AC TB Woods AC drive , , , , , New - Unused		\$1	
	No Bid 6-160	Electrical and Plumbing Fittings Lot of 2 boxes Various, Plastic Box 1--1-1 3/4" threaded coupling,,1-2 "45-degree elbow,,6- 1 1/2 "tees,10 -2"X 2" X1 1/2 "tees,1-1" 90-degree elbow,1-1 1/2 "45-degree elbow,1-2 "90-degree elbow,1-1 1/2 "coupling,1-2 1/2 "X 1 1/2 "tees,1-3 1/2 "X 2 1/4 "tee,1-2" threaded coupling		\$1	Continue Box 2 1- 4" coupling,2- 2 3/4" treaded one end coupling,1- 2" coupling,1-2 "union, 1- 1 1/2" treaded union,2- 2 "floor fixtures,
	5.00 6-161	Electrical Panel Box Stelpro empty, 12 1/2 "L X12 1/2 "Wx 4 1/4 "D, grey , , , , , New - Unused		\$1	
	No Bid 6-162	Fan Blade Unknown brand aluminum fins, 4 blade, 20 inches across, centre hole 1/2 inch, brass centre bearing, steel blade supports , , , , , New - Unused		\$1	
	14.95 6-163	Fittings Lot of 24 Plastic 18-2 inch coupling, 5- 1/2 inch, 1- 2 1/2 inch , , , , , New - Unused		\$1	
	21.56 6-164	Fittings Lot of 46 Plastic 20- 2 inch 90 degree elbows; 26- 2 inch tees , , , , , New - Unused		\$1	
	5.99 6-165	Floor Signs Lot of 6 Plastic 3 yellow, 1 pink, wet floor , , , , , Good		\$1	
	2.78 6-166	Framed Picture Photo of the Prairies heavily faded frame photograph of a farmer field and hills, likely Saskatchewan. 24.5"w x 20.5"l , , , , , Poor		\$1	
*WD	6-167	Hot stick. Hi-Line Tools, 75000 volts, tested 1951, 54 inch wood shaft , , , , , Poor		\$1	
	No Bid 6-168	Hutch Pepperdust 42"w x 17"d x 42"h, no doors, 1 shelf , , , , , Fair		\$1	
	No Bid 6-169	Hutch Pepperdust 48"w x 18"d x 42.25"h, 2 doors, 1 shelf, finish worn , , , , , Fair		\$1	

	Item #	Description	Kms	Minimum Selling Price	Serial Number
No Bid	6-170	Hutch Pepperdust 60"w x 18"d X 42"h, 4 doors, 2 shelves , , , , , Fair		\$1	
No Bid	6-171	Hutch Pepperdust 72"w x 18"d x 42"h, 4 doors, 2 shelves, unit is broken , , , , , Broken Repairable		\$1	
No Bid	6-172	Hutch Pepperdust 42"w x 16"d x 42"h, 1 shelf, no doors , , , , , Fair		\$1	
No Bid	6-173	Hutch Pepperdust 60"w x 18"d x 42"h, light attached- condition unknown, 4 doors, 2 shelves, broken , , , , , Broken Repairable		\$1	
No Bid	4-223	Ironing Board metal , , , , , Fair		\$1	
3.00	5-133	Lamp Model 004250 black, no bulb, working condition unknown , , , , , Poor		\$1	
No Bid	4-224	Lamp Unknown Brand, metal Unknown if operational , , , , , Poor		\$1	
2.25	4-225	Laptop and Document Bags Lot of 3 Various Brands document bag is 26" W x 18" H x 6.5" D. Mudd bag is 16.5" W x 12" H x 3" D. Samsonite bag is 20.5" W x 14" H x 7" D , , , , , Poor		\$1	Poor Condition
No Bid	6-174	Magnetic ballasts Lot of 2 Sylvania, Luminux For 50 watt, high pressure sodium bulbs,.120 volt , , , , , New in Box		\$1	
No Bid	6-175	Manual Motor Controller Pass and Seymour, Legrand 3-30 HP motor rating, all poles breaking, 3 P, 3PH , , , , , Good		\$1	Cut 7863-R
1.75	6-176	Metal cleaner Lot of 5 EZ-Off , tubes 5 1/4 oz., 4 new in box , , , , , Excellent		\$1	
6.01	6-177	Microamperes Test Kit Simpson model 29, unsure if operational , , , , , Fair		\$1	3242
No Bid	6-178	Microwave Oven Danby Model DMW657W, unknown condition, does light up , , , , , Fair		\$1	
No Bid	4-156	Muffin Trays Lot of 4 Stainless steel 12" x 9" , , , , , Fair		\$1	
5.27	6-179	Nails Lot of 6 finishing, 2 inch to 2 1/2 inch, assorted, some full boxes, some partial, all in new condtion , , , , , Good		\$1	
4.50	6-180	Newspaper Printout Metal 23"l x 34"w, Newspaper printed on piece of metal from the Moose Jaw Times/herald from February 15, 1986 , , , , , Good		\$1	
1.50	6-181	Office supplies Lot of 5 File holders, 2 computer cable locks, 2 Harmon Kardon compact speakers , , , , , Fair		\$1	
21.21	6-182	Optical Air Mouse Gyration 2.4 GHZ, new in box , , , , , New - Unused		\$1	
10.00	6-183	Partial Coil of Twisted Wire Steel 1/4 inch dia. Approx 100 feet, rusted , , , , , New - Unused		\$1	
11.10	6-184	Picture Canadian National Railways, picture of Boys Summer Camp Framed black and white photograph from the Boys Camp on the Maganatawanriver, highlands of Ontario. w 34.5" x l 24.5" , , , , , Fair		\$1	
2.00	6-185	Picture frames Lot of 9 Plastic, all with glass 7- 9 1/2 x 12 inches, 2- 11 1/2 X 14 1/2 inches , , , , , Good		\$1	
1.26	4-228	Pitchers Lot of 6 stainless steel 5WX8H, with top and bottom holes, 4 rubber tubes , broken , , , , , Poor		\$1	
10.07	6-186	Portable Lock Box Heavy gauge metal 14"w x 14"l x 8.75"h, 12-3/4"d, 2 doors, 2 compartments, 2 locks with keys. Beige. , , , , , Good		\$5	

Item #	Description	Kms	Minimum Selling Price	Serial Number
No Bid 6-187	Pressure switch Lot of 2 Square D Class 9016, Type GVG-1, Form F, 3361-169, On 3, Off 8 , , , , , New		\$1	
No Bid 4-230	Projector Bell & Howell Model 2592B 16mm, unsure if operational , , , , , Poor		\$1	TG-45082
10.00 6-188	Push Button Kit For A/200 Series Motor Control Lot of 2 Westinghouse motor controllers and control panel , , , , , New - Unused		\$1	
No Bid 6-189	Push button sign indicators Lot of 137 Metal, Westinghouse 1 3/4 " W, 1 /2 " open centre for Westinghouse panel , , , , , Good		\$1	
No Bid 6-190	Razor Outlet Lot of 3 E+H LTD 110 volt, 60 cycles, single razor outlet, for inside use, 2 1/4 inch deep box, , , , , New - Unused		\$1	
5.00 6-191	Sectional Terminal Blocks Buchanan extra heavy duty contact sections, 6 sections , , , , , New - Unused		\$1	
21.27 6-192	Shelving Unit Wood 72.5"l x 24"w x 68.5"h, on casters , , , , , Poor		\$1	
21.27 6-193	Shelving Unit Wood 72.5"l x 24"w x 68.5"h, on casters, wheels of casters do not roll well , , , , , Poor		\$1	
11.99 6-194	Smoke alarms Lot of 3 BRK Electronics 9 Volt, dual ionization , , , , , New - Unused,		\$1	
No Bid 4-235	Speakers Lot of 2 Unknown brand, Vintage Unknown if operational , , , , , Poor		\$1	
No Bid 4-242	Suitcases Lot of 3 Unknown Brands, vinyl Brown suitcase measures 24.5" W x 18" H x 5" D. Brown suitcases measure 18" W x 15.5" H x 4" D. Black bag measures 12" W x 16.5" H x 3" D , , , , , Poor		\$1	
28.80 6-195	Table Metal 84"l x 33"w x 30"h, folding legs, laminate top, worn edges, top worn, grey , , , , , Fair		\$1	
No Bid 6-196	Table Metal 25"w x 39"l x 26"h, pedestal legs, laminate top, worn edges, chipped, white , , , , , Poor		\$1	
1.75 6-197	Table Metal 27"w x 60"l x 29"h, chrome legs, wooden top, brown , , , , , Poor		\$1	
No Bid 6-198	Table Metal 27"w x 54"l x 30"h, arborite top, brown , , , , , Poor		\$1	
6.27 6-199	Table Metal 30"w x 48"l x 29"h, 1 shelf, laminate top, grey , , , , , Fair		\$1	
35.99 6-200	Table Metal 30"w x 48"l x 29"h, arborite top, brown , , , , , Good		\$1	
40.99 6-201	Table Metal 30"w x 60"l x 29"h, laminate top, grey , , , , , Good		\$1	
20.99 6-202	Table Metal 30"w x 60"l x 29"h, laminate top, grey , , , , , Good		\$1	
25.99 6-203	Table Metal 30"w x 60"l x 29"h, laminate top, grey , , , , , Good		\$1	
No Bid 6-204	Table Metal 30"w x 60"l x 30"h, laminate top, grey , , , , , Good		\$1	
No Bid 6-205	Table Metal 30"w x 60"l x 29"h, laminate top, grey , , , , , Good		\$1	
1.75 6-206	Table Metal 30"w x 96"l x 30"h, folding legs, plywood top, brown , , , , , Poor		\$1	
No Bid 6-207	Table Metal 31"w x 61"l x 30"h, pedestal base, chrome, arborite top, brown , , , , , Poor		\$1	
No Bid 6-208	Table Metal 31"w x 61"l x 30"h, pedestal legs, chrome, brown , , , , , Poor		\$1	

Item #	Description	Kms	Minimum Selling Price	Serial Number
No Bid 6-209	Table Metal 31"w x 61"l x 30"h, pedestal legs, chrome, white , , , , Fair		\$1	
No Bid 6-210	Table Metal 33"w x 96"l x 31"h, folding legs, scuffed, laminate top, grey , , , , Poor		\$1	
No Bid 6-211	Table Metal 36"w x 47"l x 29"h, chrome legs, arborite top, brown , , , , Poor		\$1	
No Bid 6-212	Table Metal 36"w x 47"l x 30"h, rounded corners, white , , , , Poor		\$1	
No Bid 6-213	Table Metal 36"w x 48"l x 29"h, arborite top, green , , , , Fair		\$1	
No Bid 6-214	Table Metal 36"w x 48"l x 29"h, arborite top, grey , , , , Poor		\$1	
No Bid 6-215	Table Metal 36"w x 48"l x 29"h, chrome legs, arborite top, brown , , , , Poor		\$1	
No Bid 6-216	Table Metal 36"w x 48"l x 29"h, top edges rounded similar to split table, no board insert, green , , , , Poor		\$1	
No Bid 6-217	Table Metal 36"w x 48"l x 30"h, arborite top, brown , , , , Poor		\$1	
No Bid 6-218	Table Metal 36"w x 48"l x 30"h, chrome legs, arborite top, brown , , , , Poor		\$1	
No Bid 6-219	Table Metal 37"w x 73"l x 32"h, laminate top, white , , , , Poor		\$1	
No Bid 6-220	Table Metal 48"w X32"dx 30"h, laminate top, brown , , , , Poor		\$1	
No Bid 6-221	Table Metal 60"w X 30" D X 30"h, laminate top, brown , , , , Fair		\$1	
No Bid 6-222	Table Metal 60"w X30"d X 30"h, laminate top, 1 drawer, brown , , , , Poor		\$1	
1.75 6-223	Table Metal 60"w X30"d x29h, wood top, brown , , , , Fair		\$1	
No Bid 6-224	Table Metal 67"w X34"d X 30"h, pedestal, laminate top, white , , , , Poor		\$1	
No Bid 6-225	Table Metal 72"w X 30"d X 28"h, laminate top, brown , , , , Poor		\$1	
No Bid 6-226	Table Metal Legs and Frame 19.5"w x 54"l x 29.5"h, laminate top, scuffed, brown , , , , Fair		\$1	
No Bid 6-227	Table Metal Legs and Frame 20"w x 56"l x 29"h, laminate top, worn edges, brown , , , , Fair		\$1	
No Bid 6-228	Table Metal Legs and Frame 24"w x 60"l x 28"h, laminate top, scuffed, edge missing, brown , , , , Poor		\$1	
No Bid 6-229	Table Metal Legs and Frame 30"w x 48"l x 29"h, 1 shelf, laminate top, scuffed and chipped, white , , , , Poor		\$1	
No Bid 6-230	Table Metal Legs and Frame 30"w x 48"l x 29"h, laminate top, 1 shelf, scuffed and chipped, white , , , , Poor		\$1	
40.99 6-231	Table Metal Legs and Frame 30"w x 60"l x 29"h, brown , , , , Good		\$1	
No Bid 6-232	Table Metal Legs and Frame 30"w x 60"l x 29"h, laminate top, brown , , , , Good		\$1	
No Bid 6-233	Table Metal Legs and Frame 30"w x 60"l x 29"h, laminate top, brown , , , , Good		\$1	
No Bid 6-234	Table Metal Legs and Frame 30"w x 60"l x 29"h, laminate top, brown , , , , Good		\$1	

Item #	Description	Kms	Minimum Selling Price	Serial Number
No Bid 6-235	Table Metal Legs and Frame 30"w x 60"l x 29"h, laminate top, scratched on frame, brown , , , , , Fair		\$1	
2.50 6-236	Table Metal Legs and Frame 30"w x 60"l x 29"h, with drawer, brown , , , , , Good		\$1	
No Bid 6-237	Table Metal Legs and Frame 36"w x 48"l x 30"h, laminate top, scuffed and chipped at the corners, brown , , , , , Poor		\$1	
No Bid 6-238	Table Metal Legs and Frame 36"w x 60"l x 28"h, laminate top, brown , , , , , Poor		\$1	
5.55 6-239	Table Wood 20"w x 60"l x 30"h, scuffed, worn edges , , , , , Fair		\$1	
No Bid 6-240	Table Wood 30"w x 60"l x 28"h, laminate top, chipped, brown , , , , , Fair		\$1	
5.55 6-241	Table Wood 29"w x 60"l x 29"h, chipped top, carved up, brown , , , , , Poor		\$1	
No Bid 6-242	Table Wood 30"w x 60"l x 29"h, arborite top, brown , , , , , Fair		\$1	
No Bid 6-243	Table Wood 30"w x 60"l x 29"h, arborite top, brown , , , , , Poor		\$1	
No Bid 6-244	Table Wood 30"w x 60"l x 29"h, laminate top, scuffed , , , , , Fair		\$1	
*MT 6-245	Television RCA 42inch, flat screen, with remote, unknown condition , , , , , Fair		\$1	
7.65 6-246	Television Samsung 22 inch, model LN22A450C1D, unknown condition , , , , , Fair		\$1	
10.00 6-247	Thread Holders Lot of 2 Wood pre-drilled holes for mounting, 14 rolls of thread and ribbon included , , , , Fair		\$1	
7.01 6-248	Time Switch Tork model 7200, double pole, single throw, 40 amps per pole , , , , , New - Unused		\$1	6261-21001
10.80 6-249	Tire and Rim 16 inch, 215/65R/16, Goodyear Assurance M+S, Tire poor. Application unknown. Manufacture date: week 37, year 2011, tread depth 3/32 , , , , , Poor		\$10	
No Bid 6-250	Tire and Rim 16 inch, 225/60R/16. Goodyear Ultra Grip Ice. Snow flake. May be compatible with a 2009 Chev Impala. Manufacture date: week 41, year 2011, tread depth 9/32 , , , , , Good		\$30	
No Bid 6-251	Tire and Rim 16 inch, LT 245/75R/17. Goodyear Wrangler Pro Grade, M+S, snow flake, Load range E. rim rusted. May be compatible with a 2010 Ford F250. Manufacture date: 43 week, year 2009, tread depth		\$15	
No Bid 6-252	Tires Set of 4 16 inch, 225/60R/16, Artic Claw Winter TXI. M+S. Snowflake, Manufacture date: week 23, year 2015, tread depth 4/32 , , , , , Poor		\$40	
No Bid 6-253	Tires Set of 4 16 inch, 215/60R/16, Firestone Allseason, Manufacture date: week 11, year 2019, tread depth 6/32 , , , , , Good		\$160	
No Bid 5-138	Tires Set of 4 16 inch, 225/60R/16, Cooper Grand Touring, M+S, Manufacture date - week 48, year 2016, 6/32 tread depth , , , , , Fair		\$120	
81.01 6-254	Tires Set of 4 16 inch, 225/60R/16, Winter Claw M+S, Snowflake, Manufacture date: week 19, year 2013, tread depth 4/32 , , , , , Poor		\$40	
148.80 6-255	Tires Set of 4 16 inch, 225/60R/16. Sumitomo Ice Edge, M+S, Snow flake. Manufacture date: week 20, year 2018, tread depth 8/32 , , , , , Fair		\$120	
No Bid 6-256	Tires Set of 4 16 inch, 225/65R/16. Artic Claw Winter TXI, M+S, Snow flake. Manufacture date: week 22, year 2016, tread depth 4/32 , , , , , Poor		\$40	

Item #	Description	Kms	Minimum Selling Price	Serial Number
265.20 6-257	Tires Set of 4 16 inch. 225/60R/16, Firestone Winterforce 2. M+S. Snowflake, Manufacture date: week 05, year 2019, tread depth 10/32 , , , , , Excellent		\$200	
No Bid 6-258	Tires Set of 4 17 inch, 215/65R/17. Goodyear Assurance. Triple tread, All Season M+S. Manufacture date: week 08, year 2016, tread depth 5/32 , , , , , Fair		\$120	
No Bid 6-259	Tires Set of 4 17 inch, 225/55R/17, Goodyear Assurance All Season M+S. Manufacture date: week 44, year 2019, tread depth 8/32 , , , , , Fair		\$100	
343.00 6-260	Tires Set of 4 18 inch, 275/65R/18, Goodyear Wrangler Fortitude HT, Manufacture date: week 11, year 2020, tread depth 7/32 , , , , , Excellent		\$200	
No Bid 6-261	Tires Set of 4 16 inch, 225/60R/16, Sumitomo HTR Enhance L/X, M+S, Manufacture date: week 07, year 2019 , , , , , Good		\$160	
237.00 6-262	Tires Set of 4 17 inch, 215/60R/17, Sumitomo HTR Enhance L/X, M+S, Manufacture date: week 32, year 2018 , , , , , Good		\$160	
No Bid 6-263	Tool Box Plastic compartments in lid, grey , , , , , Fair		\$1	
3,256.00 6-264	Trailer, Flatdeck 1 1984 Saturn, Tandem Pintle ring hitch (1 3/4"), 6 pin round plug, plywood deck: width 194", length 268", bed: 120" long x 46" wide, total width inside of wheel wells 77 1/2", fenders are 12 1/2 x 68", weight: 12,000 lb, tires: advance st 235/85 R16, 8 stud axle, front tongue jack, has a spare tire (Bridgestone It 245/75 R16) and break away kit, no ramps or beaver tails. , , , , , Good		\$500	25917B325EW010291
1,528.00 6-265	Trailer, Reel 1 1977 Brandt Pintle eye hook up with 1 3/4 inch diameter of the rod ring, RV 6 pin round traiolel wiring connector with centre pin as part of the 6 pin style connection, 14,000lb hydraulic cable dolly, with 3 hydraulic pump jacks, 1 for lifting the tongue, 2 to lift the arms, total length 196 inches, total width bincluding fenders 101 inches wide, 12.00x20 14 ply Michelin tires, 2 rear stabilizer jacks, , , , , , Good		\$500	101977
1,518.00 6-266	Trailer, Reel 1 1977 Brandt Pintle eye hook up, RV 6 pin style connection, 14,000 hydraulic cable dolly, with 3 hydraulic pump jacks, 1 for lifting the tongue, 2 to lift the arms, length 196 inches, 101 inches wide, 1200x20 14 ply, 2 rear stabilizer jacks, tires , , , , , Good		\$500	81977
555.00 6-267	Trailer, Reel 1 1987 Scarrow IND. Mechanical Pintle ring hook up (1 1/2"), 6 pin round plug, 2500 lb cable dolly (has a winch to lift reels), 132" long x 81" wide, 5/16" winch cable, 2 rear stabilizer legs, tires LT 7.00 - 15, has a tongue jack and spare tire , , , , , Good		\$500	870601
No Bid 6-268	Transformer Standard high pressure sodium for 12/277/347 volt lights, lamp ignitor, and capacitor , , , , , New - Unused		\$1	
No Bid 4-245	Trolley Cart wood 2 shelves, 39" W x 23.5" D x 38" H , , , , , Poor		\$1	N/A
No Bid 4-246	Trolley Cart wood 2 shelves, larger wheels, 45" W x 21" D x 35" H , , , , , Poor		\$1	N/A
14.95 6-269	Tub Plastic 27WX39LX31H, hole in bottom, 2 swivel casters, 2 fixed, white , , , , , Fair		\$1	
1.25 6-270	Tub Plastic 27WX39LX31H, hole in bottom, 4 casters, orange , , , , , Poor		\$1	
12.86 6-271	Tub Plastic 33 1/2 WX51LX 36 1/2 H, holes in bottom, white , , , , , Fair		\$1	
12.86 6-272	Tub Plastic 33 1/2 WX51LX 36 1/2 H, holes in bottom, white , , , , , Fair		\$1	

Item #	Description	Kms	Minimum Selling Price	Serial Number
18.00 6-273	Tub Plastic 33 1/2 WX51LX 36 1/2 H, holes in bottom, hitch and ball, white , , , , Fair		\$1	
12.86 6-274	Tub Plastic 33 1/2 WX51LX 36 1/2 H, holes in bottom, hitch and ball, white , , , , Fair		\$1	
12.86 6-275	Tub Plastic 33WX51LX37H holes in bottom, hitch and ball, white , , , , Fair		\$1	
12.86 6-276	Tub Plastic 33WX51LX37H, 2 swivel casters, 2 fixed, holes in bottom, hitch and ball, white , , , , Fair		\$1	
12.86 6-277	Tub Plastic 33WX51LX37H, 2 swivel casters, 2 fixed, holes in bottom, white , , , , Fair		\$1	
12.86 6-278	Tub Plastic 33WX51LX37H, 2 swivel casters, 2 fixed, hitch and ball, white , , , , Poor		\$1	
12.86 6-279	Tub Plastic 33WX51LX37H, 2 swivel casters, 2 fixed, hitch and ball, white , , , , Fair		\$1	
12.86 6-280	Tub Plastic 33WX51LX37H, 2 swivel casters, 2 fixed, hitch and ball, white , , , , Fair		\$1	
12.86 6-281	Tub Plastic 33WX51LX37H, 2 swivel casters, 2 fixed, hitch and ball, white , , , , Fair		\$1	
12.86 6-282	Tub Plastic 33WX51LX37H, 2 swivel casters, 2 fixed, hitch and ball, white , , , , Fair		\$1	
*MT 6-283	Tub Plastic 33WX51LX37H, 2 swivel casters, 2 fixed, holes in bottom, white , , , , Fair		\$1	
12.86 6-284	Tub Plastic 33WX51LX37H, 2 swivel casters, 2 fixed, white holes in bottom , , , , Fair		\$1	
12.86 6-285	Tub Plastic 33WX51LX37H, 2 swivel casters, 2 fixed , white , , , , Fair		\$1	
12.86 6-286	Tub Plastic 33WX51LX37H, holes in bottom 2 swivel casters, 2 fixed, hitch and ball, white , , , , Fair		\$1	
21.00 6-287	Tub Plastic 33WX51LX37H, holes in bottom 2 swivel casters, 2 fixed, hitch and ball, white , , , , Fair		\$1	
12.86 6-288	Tub Plastic 33WX51LX37H, holes in bottom 2 swivel casters, 2 fixed, white , , , , Fair		\$1	
12.86 6-289	Tub Plastic 33WX51LX37H, holes in bottom 2 swivel casters, 2 fixed, white , , , , Fair		\$1	
24.95 6-290	Tub Plastic 34WX58LX32H, holes in bottom, 2 swivel casters 2 fixed, white , , , , Fair		\$1	
21.00 6-291	Tub Plastic 37WX57LX33H, holes in bottom, 2 swivel casters, 2 fixed , , , , Fair		\$1	
12.86 6-292	Tub Plastic 39WX41LX37 1/2 H, 2 swivel casters, 2 fixed, holes in bottom, white , , , , Fair		\$1	
21.01 6-293	Tub Stainless steel 37WX68LX42 1/2 H, 2 swivel casters, 2 fixed, ball and hitch, white , , , , Poor		\$1	
No Bid 6-294	Vacuum switch 1 Square D Class 9016, type GVG-1, Form E, On 3, Off 8, 2 pole , , , , New		\$1	
No Bid 6-295	Vapor Barrier Lot of 6 GMI inside dimensions 16"WX16"LX8"D, clear, with 3 inch edges on all sides , , , , New - Unused		\$1	
16.01 6-296	Voltage Regulator Armaco 110 to 130 volts, unknown condition , , , , Fair		\$1	
50.00 6-297	Voltage Tester Modiewark model S-9A, 1995, Voltage 240 volts, 14.2 to 220 KV, unsure if operational , , , , Fair		\$1	
No Bid 6-298	Water line plugs Lot of 2 Rubber, steel Tapered rubber, 3" top diameter, 2" bottom diameter, 2 1/2 " high, with threaded rod, washers, 3 nuts , , , , Good		\$1	

Item #	Description	Kms	Minimum Selling Price	Serial Number
66.00 6-299	Weigh Scale Kilo Tech Model KPS 150-2 12" w X 12.25" IX 2" h, working when last used, with transformer , , , , , Fair		\$20	KPS12070003
10.00 6-300	Wood Screws Lot of 28 Miscellaneous 1/4 to 3 inch, pan, philips, robertson , flat heads, some full boxes, some partial, all in new condtion , , , , , Good		\$1	
10.00 5-146	Chair Ergonomic 5 caster wheels hydraulics work, worn arms, blue, , , , , Fair		\$1	
1.25 5-147	Chair Ergonomic 5 caster wheels, hydraulics work, worn arms, blue , , , , , Fair		\$1	
No Bid 5-148	Chair Ergonomic, fabric 5 caster wheels, tilt, arm poor condition, grey , , , , , Poor		\$1	
No Bid 5-149	Chair Ergonomic, Fabric 5 caster wheels, hydraulics poor, counter height , brown , , , , , Poor		\$1	
No Bid 5-150	Chair Ergonomic, Fabric 5 caster wheels, hydraulics work, arms in poor condition, blue , , , , , Poor		\$1	
No Bid 5-151	Chair Ergonomic, Fabric 5 caster wheels, hydraulics work, arms in poor condition, blue , , , , , Poor		\$1	
No Bid 5-152	Chair Ergonomic, Fabric 5 caster wheels, hydraulics work, arms in poor condition, blue , , , , , Poor		\$1	
2.75 5-153	Cork Board Metal frame 36"w x48"h, brown , , , , , Fair		\$1	
1.75 5-155	File Cabinet 3 Drawers ,Lateral 36"w x 18"d x 40"h, lock no key, beige, scuffed , , , , , Fair		\$1	
2.25 5-156	File Cabinet 3 Drawers, Lateral 36"w x 18"d x 40"h, lock no key, beige , , , , , Fair		\$1	
REGINA, Saskbuilds and Procurement, 500 McLeod St				
ON-LINE VIEWING ONLY. NO ON-SITE VIEWING.				
42.00 5-116	Cart Metal 18"l x 24"w x 26"h, 4 casters all swivel, lock detached, no key, rubber mat on top, orange , , , , Fair		\$1	
1.26 5-122	Cart Metal with Wood Platform approx. 24.5"w x 61"l x 38"h, 2 fixed wheels, 2 caster wheels, platform chipped/worn at edges , , , , , Poor		\$1	
HUMBOLDT Agriculture, Unit 7 1710 8th Ave, Humboldt				
ON-LINE VIEWING ONLY. Contact Dawn Berger 306-682-6701 dawn.berger@gov.sk.ca				
50.00 6-501	Cabinet Pepperdust 66" high x 35" wide x 19" deep , , , , , Fair		\$1	
10.00 6-502	Desk 2 piece; Pepperdust DESK Piece 1: 72"L x 36" D x 29" H DESK Piece 2: 41"L x 20"D x 29"H right return; 1 set drawers attached , , , , , Fair		\$1	
No Bid 6-503	Desk 3 piece, Pepperdust DESK piece 1: 28.5"L x 42" W x 29" H DESK piece 2: 42" L x 42" W x 29" H DESK piece 3: 30"L x 36" W x 29" H left return with front counter , , , , , Good		\$1	
No Bid 6-504	Desk 3 piece, Pepperdust DESK piece 1: 65" L x 31" W x 29" DESK piece 2: 42" L x 25" W x 29" H COUNTER (on Piece 1): 65" L x 10"W, 31" L x 10"W right return with front counter , , , , , Fair		\$1	
No Bid 6-505	Desk 2 piece; Pepperdust DESK piece 1: 42"L x 20" W x 29" H DESK piece 2: 72.5" L x 36" W x 29" H left return; 2 sets drawers attached , , , , , Good		\$1	

Item #	Description	Kms	Minimum Selling Price	Serial Number
No Bid 6-506	Desk 3 piece; Pepperdust DESK Piece 1: 65"L x 31" W x 29"H DESK Piece 2: 42"L x 25"W x 29"H; COUNTER (on Piece 1): 65" L x 10"W, 31" L x 10"W left return with front counter , , , , , Fair		\$1	
10.00 6-507	Dividers 5 Grey 36.5"W x 2.5"D x 65"H , , , , , Good		\$1	
70.00 6-508	Dividers 11 Grey 49"W x 2.5"D x 65"H , , , , , Good		\$1	
No Bid 6-509	Hutch Pepperdust HUTCH 42"L x 17.5"W x 29"H 2 door , , , , , Good		\$1	
No Bid 6-510	Hutch Pepperdust HUTCH 48" L x 17" D x 42" H NOTE: no doors 2 shelf , , , , , Fair		\$1	
No Bid 6-511	Hutch Pepperdust HUTCH: 41"L x 17.5"D x 41.5"H 2 door , , , , , Good		\$1	
No Bid 6-512	Hutch Pepperdust HUTCH 42" L x 17.5" W x 42" H 2 door, with moveable shelf , , , , , Good		\$1	
No Bid 6-513	Hutch Pepperdust HUTCH 48" L x 17" D x 42" H 2 door , , , , , Good		\$1	
5.00 6-514	Pedestal Pepperdust 30" L x 18" W x 28" H 3 drawer , , , , , Good		\$1	
5.00 6-515	Pedestal Pepperdust 30" L x 18"W x 28"H 3 drawer , , , , , Good		\$1	
5.00 6-516	Pedestal Pepperdust 30"L x 18"W x 28"H 2 drawer , , , , , Good		\$1	
5.00 6-517	Pedestal Pepperdust 30"L x 18"W x 28"H 3 drawer , , , , , Good		\$1	
No Bid 6-518	Table 2 Rectangle 60"L x 30"W x 30"H , , , , , Good		\$1	
No Bid 6-519	Table Square 36" , , , , , Good		\$1	
LUMSDEN, Parks Culture and Sports, Operations, Condie Nature Refuge.				
ON-LINE VIEWING ONLY. Contact Steve Abbott 306-580-7896, email: steve.abbott@gov.sk.ca or Clayton Scheller 306-536-1366				
350.00 6-520	Auger Not sure if it works , , , , , Fair		\$1	
151.00 6-521	Ballast Box Kubota , , , , , Good		\$1	
212.12 6-522	Cement Mixer 3HP, Tecumseh Not sure if it works , , , , , Poor		\$1	1T03HP
353.00 6-523	Fertilizer Spreader FS 150 Not sure if it runs , , , , , Good		\$1	
11.27 6-524	Lawn Mower Yard Machines Not sure if it runs , , , , , Poor		\$1	1A255K31411
21.00 6-525	Motor 3HP, Briggs and Stratton Not sure if it runs , , , , , Poor		\$1	
31.00 6-526	Motor Monarch BSG-8 Not sure if it runs , , , , , Poor		\$1	8,612
25.40 6-527	Portable Tire Changer Not sure if it works , , , , , Poor		\$1	
42.60 6-528	Pressure Washer Karcher Not sure if it runs , , , , , Fair		\$1	
7.58 6-529	Pressure Washer Karcher Not sure if it works, missing parts , , , , , Poor		\$1	145,595
550.00 6-530	Rotary Cutter John Deere 709 Not sure if it works , , , , , Poor		\$1	
550.00 6-531	Rotary Cutter John Deere 709 Not sure if it works , , , , , Poor		\$1	

Item #	Description	Kms	Minimum Selling Price	Serial Number
41.01 6-532	Steel Chain Hooks rusty , , , , , Poor		\$1	
826.00 6-533	Trailer Flat deck needs repairs, specifically the hitch needs a new latch , , , , , Broken Repairable		\$1	2CU1FBA412009660 (VIN)
87.78 6-534	Weed Wackers lot of 3 Honda GX31 none run , , , , , Broken Repairable		\$1	
1,419.00 6-535	Car 2008 Chevrolet Impala 2WD, 4 door 3.5 L V6 Gas Auto A/C, Tilt, Cruise, CD, Power windows, Power Doors, Power Mirrors , Metallica Beige/Bronze, TOW ONLY, No SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , Recent Repairs: none, PROBLEMS: Needs front end work, flat tire, starts well, windows and mirrors work well, Fob works, nothing else known about the vehicle. Tires are poor, 2 are flat, brakes need work, body is fair, has some rust, windshield is good, interior is fair. , As is, Where is	228,000kms	\$250	2G1WB58K281355137
MEADOW LAKE, Environment, 306-6th Street E.				
ON-LINE VIEWING ONLY. Contact Tangy Laird tangy.laird@gov.sk.ca 306-236-7557 or 306-304-0677				
1,665.99 6-536	ATV 2007 YAMAHA 500 KODIAK Single Cylinder, Gas Standard 4x4 , dark green, TOW ONLY, does not start. , None, Last ran in 2016. Does not run now. Not sure what is wrong with it. Exterior body is in good shape., fair	Unknown	\$100	5Y4AJ14W17A310384
MUENSTER, Sask Crop Insurance, 601 Taphorn Street E.				
ON-LINE VIEWING ONLY. Contact Heather Ames 639-638-6281, email: heather.ames@scic.ca				
1,278.78 6-537	ATV 2007 CAN AM Outlander 400 Single Cylinder, Gas Auto 4x4, Single Axel, 400cc engine, , Red, TOW ONLY, does not start. , New tires in 2020, PROBLEMS: Engine seems to have a problem with the cam. Timing chain is stretched and has jumped a cog, now engine is out of time and will not run. Engine will need to be removed and split to change the chain and gears. Motor does not start. , fair	Unreadable	\$1	2BVEKHF187V000729
NORTH BATTLEFORD, Social Services, 300 1146 102 Street				
ON-LINE VIEWING ONLY. Contact Leona Boehm 306-446-7893, email: leona.boehm2@gov.sk.ca or Shannen Barthel at 306-446-7928, email: shannen.barthel@gov.sk.ca				
No Bid 5-509	Sofa Vinyl Dark Brown, tears in some areas and worn out. Approximatley 87" X 17" , , , , , Poor		\$1	
No Bid 5-508	Love Seat Vinyl Dark Brown , tears in some areas and worn out. Approximatley 66" X 17" , , , , , Poor		\$1	
No Bid 5-507	Chair Vinyl Dark Brown, tears below cushion Approximatley 45" X 17" , , , , , Poor		\$1	
PRINCE ALBERT, Highways, Operations, 8th floor, 800 Central Ave.				
ON-LINE VIEWING ONLY. Contact Tara Nelson 306-953-3523, email: tara.nelson2@gov.sk.ca or Stella Werminsky 306-953-2583, email: stella.werminsky3@gov.sk.ca				
15.01 6-538	GPS Etrex Garmin small hand held device, working condition unknown , , , , , Fair		\$1	
27.50 6-539	Satellite Personal Tracker Spot with arm band, working condition unknown , , , , , Fair		\$1	

Item #	Description	Kms	Minimum Selling Price	Serial Number
REGINA, Highways, 1610 PARK STREET				
ON-LINE VIEWING ONLY. Contact Ed Hildebrand, 306-694-3881 ed.hildebrand@gov.sk.ca				
216.21 6-540	Broken Sign Posts Lot of 49 Wood 8' to 14', Fir 4x4 and 4x6, banded in bundle as pictured, mostly 4x6. must have flatdeck trailer for pick up. , , , , , Fair		\$1	
216.21 6-541	Broken Sign Posts Lot of 49 Wood 8' to 14', Fir 4x4 and 4x6, banded in bundle as pictured, mostly 4x6. must have flatdeck trailer for pick up. , , , , , Fair		\$1	
216.21 6-542	Broken Sign Posts Lot of 49 Wood 8' to 14', Fir 4x4 and 4x6, banded in bundle as pictured, mostly 4x6. must have flatdeck trailer for pick up. , , , , , Fair		\$1	
250.00 6-543	Broken Sign Posts Lot of 64 Wood 8' to 14', Fir 4x6, banded in bundle as pictured. must have flatdeck trailer for pick up. , , , , , Fair		\$1	
REGINA, Agriculture, 3085 Albert Street				
ON-LINE VIEWING ONLY. Contact Denise Konieczny at 306-787-5854, denise.konieczny@gov.sk.ca				
8.00 6-544	File Cabinet Lateral, 3 Drawer 39"x36"x18", beige , , , , , Good		\$1	
1.08 6-545	File Cabinet Lateral, 3 Drawer 52"x36"x18", beige, w/key , , , , , Good		\$1	
1.08 6-546	File Cabinet Lateral, 3 Drawer, 2 Shelves 65"x36"x18", beige , , , , , Good		\$1	
1.08 6-547	File Cabinet Lateral, 3 Drawer, 2 Shelves 65"x36"x18", beige , , , , , Good		\$1	
1.25 6-548	File Cabinet Lateral, 3 Drawer, 2 Shelves 65"x36"x18", beige w/key , , , , , Good		\$1	
1.08 6-549	File Cabinet Lateral, 4 Drawer 52"x36"x18", beige , , , , , Good		\$1	
1.08 6-550	File Cabinet Lateral, 4 Drawer 52"x36"x18", beige , , , , , Good		\$1	
No Bid 6-551	Hutch and Pedestals Lot of 3 Metal Wall mounted hutch with hardware (72"x15"x14"), 2 under desk pedestals (28"x15"x22") , , , , , Good		\$1	
SASKATOON, Corrections, Policing and Public Safety, SCC, 910 60th street East, Saskatoon. Loading Dock Stores				
ON-LINE VIEWING ONLY. Contact Bob Kirton 306-956-8835 bob-kirton@gov.sk.ca Danielle.Corriveau@gov.sk.ca.				
5.55 6-552	Bosu Ball with pump Full Size (Grey) , , , , , Fair		\$1	
2.00 6-553	Camcorder batteries Lot of 3 Optex Canpower Rechargeable NP45 For Hitachi Lead Acid VHS, Size J6V GP super alkaline battery, NPF550 Digital video battery Lithium ION , , , , , Fair		\$1	
5.55 6-554	Duffle Bag Heavy Duty , , , , , New - Unused		\$1	
2.00 6-555	First Aid Kits Lot of 2 Safeco first aid items SK#1 9Hx 6 1/2W x 2 1/2D; AFE empty first aid box manufactured April 26/91 7 5/8 W x 4 5/8H x 3"D , , , , , Fair		\$1	

Item #	Description	Kms	Minimum Selling Price	Serial Number
*WD	6-556 Flag Canadian Flag 26"H x 54"W , , , , , New - Unused			
22.22	6-557 Flashlights/bulbs Lot of 30 Various types some need minor repairs and bulbs , , , , , Fair		\$1	
1.00	6-558 Key box safe lockable, no keys, mounting hardware 9 7/8"W x 14"H x 4 3/8"D , , , , , Good		\$1	
No Bid	6-559 Kitchen Equipment kitchen food serving table, 3 well buffet trays rusted, lights need repair , , , , , Broken Repairable		\$1	
20.00	6-560 Light Bulbs Lot of 75 Various sizes and types 40 watts and 100 watts , , , , , New - Unused		\$1	
20.00	6-561 Lighters Lot of 15 Barbeque style , , , , , New - Unused		\$1	
21.00	6-562 Locks Lot of 50 Various sizes and types heavy duty, most have keys with them , , , , , Fair		\$1	
No Bid	6-563 Miscellaneous Supplies Lot of 5 Miscellaneous Shower curtain/liner/paper towel holder		\$1	
No Bid	6-564 Office Organizers Lot of 72 Accurair rails for cabinets 24 per box , , , , , New - Unused		\$1	
No Bid	6-565 Office Organizers Lot of 5 Desk keyboard pull out trays Desk keyboard pull out trays , , , , , New - Unused		\$1	
No Bid	6-566 Office Organizers Lot of 8 Metal, plastic trays book ends, plastic file organizers, plastic and metal trays , , , , , Excellent		\$1	
1.00	6-567 Office Supplies Lot of 17 Miscellaneous card paper, meter rulers, office supplies, magnetic strips approximately 5" wide x 3 ft. , , , , , Fair		\$1	
2.00	6-568 Office Supplies Lot of 3 Sealing machines, desk lamp , , , , , Fair		\$1	
27.03	6-569 Pistol safe Homak Security Model H510036684 10"Wx 5 3/4D x 7 11/16 H , , , , , Good		\$1	
No Bid	6-570 Radio batteries Lot of 11 Motorola 7.2 nickel Cadmium , , , , , Fair		\$1	
46.00	6-571 Security Safes Lot of 2 2-Sentry Safes Some need repair and some are new. Digital w/ keys included 16.8Wx 6.9Hx 11.6D , , , , , Good		\$1	
11.01	6-572 Shoe glue rubber Lot of 9 Shoe glue rubber All sealed and in original packaging , , , , , Good		\$1	
3.00	6-573 Wheels and Casters Lot of 40 Various sizes and types For office chairs , , , , , Fair		\$1	
15.99	6-574 Wii Remotes Lot of 3 Assorted , , , , , Fair		\$1	
SASKATOON, Highways, Operations and Maintenance Division, Unit 18-3603 Millar Ave.				
ON-LINE VIEWING ONLY. Contact Connie Olafson 306-933-7601, email connie.olafson2@gov.sk.ca				
WD	5-521 Film Camera Pentax SF10 Film Camera Comes with two lenses: Magnicon MC28-70 & Magnicon MC70-210, no memory card. , , , , , Fair		\$1	

Item #	Description	Kms	Minimum Selling Price	Serial Number
SASKATOON, Labour Relations and Workplace Safety, OHS, 1222 3rd Ave N.				
ON-LINE VIEWING ONLY. Contact Karen Paulson 306-933-5295, email: karen.paulson@gov.sk.ca or Sandy Falk 306-933-5395, email: sandy.falk@gov.sk.ca				
5.00 6-575	Desk Pepperdust keyboard cutout piece, 36"Wx48"Lx29"H at largest section, 24"W at cutout section , , , , Fair		\$1	
8.00 6-576	Desk Pepperdust regular 36"WX72"L; left runoff 27.5"WX42"LX25.5" , , , , , Fair		\$1	
SASKATOON, Saskatchewan Research Council, 125-15 Innovation Boulevard				
ON-LINE VIEWING ONLY. Contact Roger Dauvin 306-385-4035 roger.dauvin@src.sk.ca				
523.00 6-577	Injection Moulding Machine Screw Plunger Injection Battenfeld 4538-BSKM-30/50 Injection In-line Screw Reciprocat Moulding Machine , , , , , Fair		\$500	
SOUTHEND, Environment, 15 College Drive.				
ON-LINE VIEWING ONLY. NO ON-SITE VIEWING. Contact Nolan Hoggarth 306-758-6624, 3063-688-0966, email: nolan.hoggarth@gov.sk.ca				
No Bid 4-556	Outboard Motor 1966 Johnson 5HP Has not ran in years, engine partially disassembled. Sold as is. , , , , , As is, where is		\$1	C482568
SWIFT CURRENT, Agriculture Pastures, Lands SPP Old Wives Pasture 101-350 Cheadle St W.				
ON-LINE VIEWING ONLY. Contact Trevor Dyck 306-778-8957 trevor.dyck@gov.sk.ca				
1,870.00 6-578	ATV Yamaha Kodiak condition unknown. Last operated in Summer of 2019. May have mice infestation , , , , , Poor		\$1	5Y4AJ15W86A303087
38.90 6-579	ATV Ramps Make Unknown 8 inches X 6 ft. Aluminum , , , , , Good		\$1	
123.45 6-580	Generator Homelight 11 hp - 5500 watts - condition unknown , , , , , Poor		\$1	HA1670077
21.00 6-581	Pipe Fittings Miscellaneous various pipe fitting and water trough floats , , , , , Good		\$1	
21.00 6-582	Solar Pump make unknown condition unknown , , , , , Poor		\$1	
51.01 6-583	Steel Saw Bennett condition unknown , , , , , Poor		\$1	
1,257.00 6-584	Trailer Rainbow 12ft x 8 ft., ball hitch. Tires have air. 1997 model , , , , , Fair		\$1	2R92P1210W2625176
YORKTON, Environment, Compliance & Field Services, Rm 201 - 120 Smith St. E.				
ON-LINE VIEWING ONLY. Contact Sherry 306-786-1463 or email: yorktonfieldofficeenv@gov.sk.ca				
2.00 4-565	Portable Heater Igloo Master Naptha Gas Unknown if operational , , , , , Poor		\$1	
WD 4-562	Camp Stove Coleman 2 Burner Naptha Gas Unknown if operational , , , , , Poor		\$1	
260.00 4-575	3-Phase Unisaw Delta, Cat. No. 36-951 200-230/460 volts, 60Hz ITEM MUST BE PICKED UP NO LATER THAN AUGUST 25TH, , , , , Good		\$250	02J78788, type 2