

COVID-19 Update

To support safe SaskSurplus Sale operations during the COVID-19 pandemic, new measures have been introduced for clients to follow. These include online-only viewings of sale items, a pre-pickup screening checklist, and SaskSurplus Sales - Pick-up Guidelines.

The safety of SaskSurplus clients and employees is our top priority, and we thank you for your cooperation with these new measures. For general Government of Saskatchewan information related to COVID-19, please visit saskatchewan.ca

Every effort has been made to accurately describe items and their condition; however additional problems may exist, items may not be complete or exactly as described. Bidders are deemed to have reviewed the Terms and Conditions on bid forms and relied entirely on their own inspection and evaluation prior to bidding. Vehicles and equipment are sold "AS IS, WHERE IS", there is no implied or express warranty.

Visit www.SaskSurplus.ca for pictures and link to download Bid Form.

- Items identified with * have been on a previous sale and will be listed first on www.SaskSurplus.ca web site.
- Central Services, SaskSurplus reserves right to have unadvertised minimum selling prices on items.

It is the Bidder's responsibility to review the terms and conditions of sale on the Offer to Purchase, Bid Form.

Bid Forms are available from www.SaskSurplus.ca or from the SaskSurplus Sales Lot, 500 McLeod Street, Regina, SK.

Bid Forms can be submitted in the following ways:

- by deposit in the bid box at the SaskSurplus Sales Lot.
- by fax to (306)787-2092; by phone (306)787-2062 or (306)787-2238
- by email to sasksurplus@gov.sk.ca
- or by mail, addressed to: Ministry of Central Services, SaskSurplus, 500 McLeod Street, Regina, SK S4N 4Y1.
(If mailing your bid, please allow sufficient time for bid to be received.)
- Bids received after close date and time cannot be accepted.

MT = (Ministry Transfer) This means that the item has been claimed by another ministry and automatically transferred.

WD = (Withdrawn) This can happen if the item was requested to be removed by the seller,
or if bid prices did not meet the seller's minimum selling price. In this case, the item may be carried forward to a future sale.

Item #	Description	Kms	Serial Number	Ministry / Client	Ministry / Client Ref.#	Disposal Request #
REGINA, Saskbuilds and Procurement, SaskSurplus Sales Lot, 500 McLeod Street - Vehicles						
Due to COVID-19, ON-LINE VIEWING ONLY. NO ON-SITE VIEWING. For information on items contact SaskSurplus (306) 787-2062 or (306) 798-3306						
2,551.87	11-001	Car 2006 CHEVROLET Cobalt FWD 2.2L V4 Gas Auto power locks , Brown, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , replaced battery, PROBLEMS: power locks not working, surface rust on rockers, As is, Where is	144,256 Kms	1G1AJ58F367726144	CVA	117952 TOW ONLY, 86-5 2102-624
1,851.99	11-002	Car 2006 CHEVROLET Cobalt FWD 2.2L L4 Gas Auto air, tilt, cruise, AM/FM/CD player, power locks keyless entry- 2 keys, 2 fobs, Silver, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: left front strut, alignment out, license plate light out, over spray on both rear doors, rear bumper and right rear fender, minor exterior damage., As is, Where is	167,654 Kms	1G1AJ58F267726118	CVA	117978 TOW ONLY, 106-1 2102-645
1,551.99	11-003	Car 2006 CHEVROLET Cobalt LS FWD 2.2L V4 Gas Auto power locks, air, tilt, cruise, AM/FM/CD player, keyless entry, 2 fobs , Blue, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: poor tires, rear brake drums and shoes, no license plate light, windshield chips, hood badly chipped and scratched, trunk badly scratched, hail damage, minor cosmetic damage, As is, Where is	213,243 Kms	1G1AJ55F667860599	CVA	118307 TOW ONLY, 92-5 2102-644

Item #	Description	Kms	Serial Number	Ministry / Client	Ministry / Client Ref.#	Disposal Request #
1,358.00 11-004	Car 2007 CHEVROLET Impala FWD 3.5L V6 Gas Auto air, tilt, cruise, AM/FM/CD player, power locks, windows, mirrors, driver seat, trunk release keyless entry - 3 fobs, Blue, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: power steering rack leaking, driver door pins damaged, hood chips/dents, R bumper scrapes, LF fender scratches, RR fender dent, both L doors road rash, both R door scratches/road rash, roof rust/dents, windshield chips, RF mirror housing broken/loose, trunk lid scratches/dents., As is, Where is	235,828 Kms	2G1WB58K579357156	CVA	314658 TOW ONLY, 101-2	2102-614
1,251.99 11-005	Car 2008 CHEVROLET Impala LS FWD 3.5L V6 Gas Auto Power locks, mirrors, windows, trunk release, air, tilt, cruise, AM/FM, CD player, keyless entry, 2 fobs , Grey, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: Oil Leak, rear links loose, hail dents, lower grille broken, windshield chips, hole in RF seat cushion, front brake pads and rotors, left reverse light out, minor cosmetic damage, As is, Where is	256,098 Kms	2G1WB58K881353425	CVA	315564 TOW ONLY, 93-2	2102-620
1,651.99 11-006	Car 2007 CHRYSLER Sebring FWD 2.7L V6 Gas Auto air, tilt, cruise, AM/FM/CD player, power driver seat, windows, locks, trunk release, heated mirrors keyless entry - 2 keys, Silver, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: pads/rotors, TMPS damage left door, rear shocks, rear tires poor, right plate light out, hood paint bubbling/discoloured, minor cosmetic damage., As is, Where is	210,721 Kms	1C3LC56RX7N634697	CVA	145078 TOW ONLY, 101-6	2102-610
1,851.99 11-007	Car 2007 CHRYSLER Sebring FWD 2.7L V6 Gas Auto power locks, windows, driver seat, trunk release, heated mirrors, air, tilt, cruise, AM/FM/CD player, keyless entry, 2 fobs , White, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , tire pressure warning light, PROBLEMS: all 4 tires worn and starting to cup and crack, windshiled chips, minor cosmetic damage, As is, Where is	256,150 Kms	1C3LC56R47N634744	CVA	150276 TOW ONLY, 87-5	2102-639

Item #	Description	Kms	Serial Number	Ministry / Client	Ministry / Client Ref.#	Disposal Request #
1,049.00 11-008	Car 2007 CHRYSLER Sebring FWD 2.7L V6 Gas Auto air, tilt, cruise, power locks, mirrors, windows, trunk release, driver seat, AM/FM, CD player, keyless entry, 2 keys , White, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: separated frame, cracked windshield, air filter restricted, rust underneath rockers, crack in front bumper, poor tires, minor cosmetic damage, As is, Where is	219,750 Kms	1C3LC56RX7N634747	CVA	150409 TOW ONLY, 89-5	2102-629
1,289.89 11-009	Car 2008 CHRYSLER Sebring FWD 2.7L V6 Gas Auto air, tilt, cruise, AM/FM/CD player, power heated mirrors, power windows, locks & trunk release keyless entry- 2 keys, Beige, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: windshield cracked, driver door binding, headlight assembly moisture, rear bumper rust stain, left front fender scuffs, rust on trunk lid, minor exterior damage., As is, Where is	224,370 Kms	1C3LC56R38N230531	CVA	142992 TOW ONLY, 106-3	2102-649
1,851.99 11-010	Car 2009 CHRYSLER Sebring FWD 2.4L L4 Gas Auto air, tilt, cruise, AM/FM/CD player, power windows, locks, mirrors- heated, trunk release keyless entry- 2 fobs, Silver, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: RF axle boot torn, front pads & rotors, LF strut mounts, hail damage on roof, trunk lid scratches/dull paint, RR fender dent/rust, some rust along the bottom of the doors, minor exterior damage., As is, Where is	217,573 Kms	1C3LC46B29N573409	CVA	156695 TOW ONLY, 104-4	2102-635
3,280.00 11-011	Car 2009 CHRYSLER Sebring FWD 2.4L L4 Gas Auto air, tilt, cruise, AM/FM/CD player, power locks, windows, heated mirrors, trunk release keyless entry- 2 key (fobs), Silver, Passed SGI Inspection., battery, PROBLEMS: car door will not shut completely, front bumper cracked/scraped, faded spots and some rust along the bottom of the doors, headlights fogged, minor exterior damage., As is, Where is	238,144 Kms	1C3LC46B09N573408	CVA	156984 PASSED SGI, 106-2	2102-647

Item #	Description	Kms	Serial Number	Ministry / Client	Ministry / Client Ref.#	Disposal Request #
2,589.89 11-012	SUV 2009 CHEVROLET Tahoe RWD, police special 5.3L V8 Gas Auto power locks, windows, mirrors, front seats, keyless entry, 3 fobs- condition unknown rear vinyl seat, front tow hooks, side steps, White, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: E brake does not hold, right ball joints loose, broken grille, missing jump seat and centre console, holes in head liner, holes in interior trim, holes in dash, 8 sealed holes in roof, rust on LR door, minor cosmetic damage, As is, Where is	288,599 Kms	1GNEC03029R129477	CVA	421016 TOW ONLY, 91-2	2102-648
3,300.00 11-013	SUV 2009 CHEVROLET Tahoe RWD, police special 5.3L V8 Gas Auto power locks, windows, mirrors, front seats, keyless entry, 3 fobs rear vinyl seat, front tow hooks, side steps, White, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: front brake pads, road rash and rust on fenderscracked mirrors, LF seat ripped and worn, minor cosmetic damage, As is, Where is	278,139 Kms	1GNEC03009R129638	CVA	425868 TOW ONLY, 91-1	2102-646
2,401.99 11-014	SUV 2005 DODGE Durango 4WD, 7 passenger 5.7L V8 Gas Auto power locks, windows, L/F seat, heated mirrors, air, tilt, cruise, AM/FM, CD player, keyless entry, 2 fobs, driving lights, grille inserts, front tow hooks, roof rails, hitch, trailer wiring, rear HVAC, Silver, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: Drive belt tensioner, driver seat moulding, fog light assembly, RF axle, surface rust on fenders, tailgate panel broken, minor cosmetic damage, As is, Where is	201,403 Kms	1D4HB48D05F598755	CVA	437665 TOW ONLY, 89-4	2102-630

Item #	Description	Kms	Serial Number	Ministry / Client	Ministry / Client Ref.#	Disposal Request #
1,655.51 11-015	SUV 2009 DODGE Durango SLT 4x4, 7 passenger 4.7L V8 Gas Auto air, tilt, cruise, power locks, windows, driver seat, heated mirrors, rear HVAC roof rails, mud flaps, grille inserts, front tow hooks, driving lights, hitch, trailer wiring, keyless entry- 2 keys, Beige, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: check engine light, right lower ball joint, right outer tie rod, right front strut leaking, front rotors, front alignment out, tail gate rusted, right rear fender rusted, both front wheel bearings noisy, LR fender badly rusted, rocker panel rusted, rust on doors, tailgate and wheels, jack missing, minor cosmetic damage., As is, Where is	191,662 Kms	1D8HB48P29F717999	CVA	434834 TOW ONLY, 103-1	2102-622
2,213.17 11-016	SUV 2009 FORD Escape XLT 4WD 3.0L V6 Gas Auto power locks, windows, driver seat, heated mirrors, air, tilt, cruise, AM/FM/CD player, touch pad keyless entry, 1 fob driving lights, roof racks, hitch, White, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , oil change, PROBLEMS: timing cover leaking, LR shock starting to leak, both front lower control arm bushings tearing, tire light on, rear hatch wont open, windshield chips, holes in dash, holes in interior trim, holes in head liner, minor cosmetic damage, As is, Where is	224,334 Kms	1FMCU93G29KC55714	CVA	442285 TOW ONLY, 87-4	2102-638
*MT 11-017	SUV 2008 JEEP Liberty 4WD 5 passenger 3.7L v6 Gas Auto power mirrors, locks, windows, LF seat, air, tilt, cruise, AM/FM, CD player front tow hooks, hitch, trailer wiring, driving lights, Black, Passed SGI Inspection., , PROBLEMS: rear rotors rusted, license plate light, windshield chips, minor cosmetic damage, As is, Where is	282,243 Kms	1J8GN28K08W269179	CVA	443317 PASSED SGI, 89-3	2102-631

Item #	Description	Kms	Serial Number	Ministry / Client	Ministry / Client Ref.#	Disposal Request #
1,150.99 11-018	SUV 2009 JEEP Patriot (North Edition) 4x4, 5 passenger 2.4L L4 Gas Auto a/c, tilt, cruise, AM/FM/CD plaer, power windows, locks & mirrors grille inserts, hitch, White, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: check engine light, transmission problems- no reverse or forward, right inner tie rod, no alignment, wiper blades, rust on all doors & fenders, minor exterior damage., As is, Where is	154,069 Kms	1J4FF28B59D240235	CVA	442491 TOW ONLY, 107-6	2102-659
3,030.30 11-019	Truck 2008 CHEVROLET Silverado 4x4, extended cab, has a back seat, 8' box 5.3L V8 Gas Auto air, tilt, cruise, CD player, power locks, windows, doors, mirrors grille inserts, front tow hooks, mud flaps, hitch, trailer wiring, eletric trailer brake, Blue, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: driver rear parking brake cable damage, driver front axle outer boot torn, need rear drums replaced, all tires cupped, RF wheel steel damage, drive train fluid dirty, hood badly scratched, bumper pad loose, road rash on fenders and doors, roof badly scratched, 2 holes sealed in roof, wheel wrench loose under back seat, jack missing, minor cosmetic damage., As is, Where is	279,186 Kms	1GCEK19038E202287	CVA	433901 TOW ONLY, 103-3	2102-623
4,189.55 11-020	Truck 2008 CHEVROLET Silverado RWD, extended cab, has a back seat, 8' box, partial cab height metal cage on box 5.3L V8 Gas Auto air, tilt, cruise, AM/FM radio grille inserts, side steps, mud flaps, hitch, trailer wiring, box liner, Grey, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: both lower ball joints, u-joint seized, right front strut, tire badly cupped, rear bumper bent, both rear fenders cracked, road rash on driver door, missing some "Silverado" decal lettering, minor cosmetic damage., As is, Where is	150,281 Kms	1GCEC19038E209575	CVA	451005 TOW ONLY, 104-2	2102-628

Item #	Description	Kms	Serial Number	Ministry / Client	Ministry / Client Ref.#	Disposal Request #
8,888.88 11-021	Truck 2014 CHEVROLET Silverado 4x4, crew cab, has a back seat, 5'10" box 4.3L V6 Gas Auto air, tilt, cruise, AM/FM radio, power windows, locks, mirrors front tow hooks, side steps, hitch, trailer wiring, OEM trailer brakes, Brown, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: oil leaking, front bumper valance loose/half missing, left license plate light out, RR bumper bent, rear doors paint chips/dents, tailgate bent, trim on pillars have slots cut out, centre arm rest ripped, minor cosmetic damage., As is, Where is	249,994 Kms	3GCUKPEH2EG379010	CVA	800256 TOW ONLY, 103-4	2102-625
*MT 11-022	Truck 2011 DODGE Ram 1500 4WD, quad cab, has a back seat, 6'3" box 5.7L V8 Gas Auto Power locks, mirrors, windows, air, tilt, cruise, AM/FM, CD player front tow hooks, side steps, hitch, trailer wiring, extra wheel and tire, grille inserts (may not be compatable with vehicle), Grey, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: Windshield cracked, license plate lamp not working, RF fender rust through, front rotors rusted, park brake cables seized, wheel alignment, minor cosmetic damage, As is, Where is	198,222 Kms	1D7RV1GT4BS632849	CVA	436987 TOW ONLY, 88-2	2102-618
2,250.00 11-023	Truck 2007 DODGE Ram 2500 4x4, quad cab, has a back seat, 6'2" box 5.7L V8 Gas Auto air, tilt, cruise, AM/FM/CD player grille inserts, side steps, mud flaps, front tow hooks, headache rack, hitch, trailer wiring, Silver, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: check engine light on, both upper ball joints, RF wheel bearing, hood shocks, negative battery cable, alignment, windsheild washer not working, tailgate missing, inside of box dented/bent, missing front console, both front box corners cracked, driver seat worn/frame exposed, headlight foggy, rocker panel rust, some rust on doors, hole in roof sealed, spare tire/wheel wrench missing, minor cosmetic damage., As is, Where is	201,637 Kms	3D7KS28D47G813360	CVA	431103 TOW ONLY, 101-3	2102-613

Item #	Description	Kms	Serial Number	Ministry / Client	Ministry / Client Ref.#	Disposal Request #
4,095.00 11-024	Truck 2007 DODGE Ram 2500 4x4, quad cab, has a back seat, 6'3" box 5.7L V8 Gas Auto air, tilt, cruise, AM/FM/CD player grille inserts, front tow hooks, side steps, mud flaps, hitch, trailer wiring, White, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: power steering box leaking & very loose, u-joint at rear differential worn out, park brake not holding, brake, signal & license lights inoperable, oil dark/low, RR tail light broke, hood chips, F bumper rust, R bumper bent, LR fender rust/dents/scratches, RR fender large dent, RF door dent, roof rust, sealed hole in roof, tailgate dented/scratched, windshield chips, parking lot dents & scratches., As is, Where is	150,695 Kms	3D7KS28DX7G817896	CVA	431202 TOW ONLY, 101-1	2102-615
5,093.00 * 10-021	Truck 2014 DODGE RAM 2500 4x4, crew cab, has a back seat, 6.5" box 5.7L V8 gas Auto air, tilt, cruise, AM/FM, PW, PL, PM, keyless entry grill inserts, front tow hooks, side steps, mud flaps, hitch, trailer wiring, OEM trailer brake, Leer box cap, tool tray, roof rack, White, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: Check engine light on, engine misfire, engine manifold leaking, cupped tires, cracked windshield, L/F mirror housing cracked, parking lot dents & scratches, As is, Where is	320,593 Kms	3C6TR5CT2EG207666	CVA	800200 Tow only, 119-1	2010-466
*MT 11-025	Truck 2007 DODGE Ram Pickup 4WD, quad cab, has a back seat, 6'4" box 5.7L V8 Gas Auto air, tilt, cruise, AM/FM, CD player front seat covers, side steps, front tow hooks, mud flaps, hitch, trailer wiring, headache rack with beacon, box liner, Silver, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , Oil change, PROBLEMS: both upper ball joints, rust on LF fender, rust on box, noisy brakes, minor cosmetic damage, As is, Where is	193,130 Kms	3D7KS28D87G813359	CVA	431137 TOW ONLY, 88-1	2102-619

Item #	Description	Kms	Serial Number	Ministry / Client	Ministry / Client Ref.#	Disposal Request #
6,100.00 11-026	Truck 2011 DODGE Ram Pickup 4x4 quad cab, has a back seat, 6'2" box 5.7L V8 Gas Auto power locks, mirrors, windows, air, tilt, cruise, AM/FM, CD player side steps, grille inserts, front tow hooks, hitch, trailer wiring, Black, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: front fenders damaged, alignment, windshield cracked, left side step broken, minor cosmetic damage, As is, Where is	208,794 Kms	1D7RV1GT0BS632847	CVA	437332 TOW ONLY, 86-4	2102-626
5,128.00 11-027	Truck 2011 DODGE Ram Pickup 4x4, quad cab, has a back seat, 6'4" box 5.7L V8 Gas Auto air, tilt, cruise, AM/FM/CD player, power locks, windows, mirrors- heated front tow hooks, side steps, mud flaps, hitch, trailer wiring, OEM trailer brakes, weather tech mats, front seat covers, Black, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: park brake doesn't hold, power steering pump leak, ABS light on, TRAC light on, RR tire flat, passenger door handle damaged, washer nozzle broken, tailgate rust, bumper rust dents/holes, rust on cab corners & passenger door, parking lot dents & scratches., As is, Where is	233,928 Kms	1D7RV1GT1BS524351	CVA	436706 TOW ONLY, 107-4	2102-657
1,155.54 11-028	Truck 2008 FORD F250 4x4, crew cab, has a back seat, 6'7" box 5.4L V8 Gas Auto air, tilt, cruise, AM/FM radio, power locks front grille inserts, front tow hooks, side steps, mud flaps, hitch, trailer wiring, Brown, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: pitman arm and steering shock, front wheel alignment out, no high mount, no reverse lights or license plate light, both R fenders have holes, some rust on R bumper, fenders & doors, weather stripping loose, tailgate rusted, driver seat trim loose, left cab corner rust, inside box dented/paint peeling, missing centre arm rest, hole in head liner, centre cup holder loose, 1 sealed hole in roof, spare tire missing, minor cosmetic damage., As is, Where is	343,607 Kms	1FTSW21598EE44702	CVA	434206 TOW ONLY, 101-5	2102-611

Item #	Description	Kms	Serial Number	Ministry / Client	Ministry / Client Ref.#	Disposal Request #
8,241.00 11-029	Truck 2013 FORD F250 Super Duty 4WD, crew cab, back seat, 6'8" box 6.2L V8 Gas Auto Power locks, mirrors, windows, air, tilt, cruise, AM/FM, CD player, keyless entry, 2 fobs front tow hooks, grille inserts, side steps, mud flaps, trailer tow mirrors, hitch, trailer wiring, OEM trailer brakes, Blue, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: Engine front cover leaking, needs alignment, windshield cracked, license plate bulb burnt out, LF seat worn and ripped, spare tire is loose in box and may not be compatible, minor cosmetic damage, As is, Where is	286,441 Kms	1FT7W2B6XDEA25426	CVA	438611 TOW ONLY, 88-3	2102-617
2,551.99 11-030	Truck 2008 FORD F350 RWD, crew cab, has a back seat, 8' box 6.8L V10 Gas Auto Power locks, mirrors, windows, air, tilt, cruise, AM/FM, CD player grille inserts, front tow hooks, hitch, trailer wiring, headache rack, White, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: Upper ball joints, exhaust manifold leak, alignment, windshield cracked, drivers seat ripped, right headlight, license plate light, As is, Where is	248,384 Kms	1FTWW30Y88EA9935 7	CVA	450197 TOW ONLY, 93-1	2102-621
4,395.95 11-032	Truck 2002 GMC Sierra 4WD, crew cab, back seat, 6'6" box 6.0L V8 Gas Auto Power locks, mirrors, windows, air, tilt, cruise, AM/FM, CD player, keyless entry, 2 fobs hood deflector, front tow hooks, mud flaps, hitch, trailer wiring, Arrow colour matched topper (unknown condition), Grey, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs., , PROBLEMS: check engine light (code: P0300), no brake light, no backup lights, wiper blades, drive belt, rear shocks, rust hole in box, 5 sealed holes in roof, minor cosmetic damage, As is, Where is	290,181 Kms	1GTHK23V22F217024	CVA	434639 TOW ONLY, 88-4	2102-616

Item #	Description	Kms	Serial Number	Ministry / Client	Ministry / Client Ref.#	Disposal Request #
3,636.00 11-033	Truck 2008 GMC Sierra 4x4, extended cab, has a back seat, 6'6" box 5.3L V8 Gas Auto air, tilt, cruise, AM/FM radio, power windows, mirrors & locks front tow hooks, mud flaps, side steps, hitch, trailer wiring, grille inserts, box liner, Black, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: left exhaust manifold bolt broken, right rear wheel cylinder broken, wheel alignment out, windshield cracked, rear quarter panels rusted, hole in tailgate, both box rails rusted/dented, right cab corner rusting, hood bent, rust/chips/dents on fenders, tailgate hole/dents, all seats stained, 1 hole sealed in roof, parking lot dents & scratches., As is, Where is	208,388 Kms	1GTEK19058Z298416	CVA	434313 TOW ONLY, 107-5	2102-658
*MT 11-034	Van 2005 CHEVROLET Express RWD, 8 passenger 5.3L V8 Gas Auto a/c, tilt, cruise, AM/FM radio 60/40 swing out doors on both sides, cargo barrier behind 3rd seat, rear aux heat, Grey, Passed SGI Inspection., , PROBLEMS: some rust on front bumper, missing front emblem, minor exterior damage., As is, Where is	129,785 Kms	1GNFG15T651203109	CVA	422261 PASSED SGI, 109-6	2102-661
3,151.99 11-035	Van 2009 DODGE Grand Caravan FWD 3.3L V6 Gas Auto power windows, mirrors, locks, air, tilt, cruise, AM/FM, CD player, keyless entry, 2 fobs rear HVAC, Brown, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: poor front tires, power lock on LR door not working, air heater off switch, windshield chips, rust on fenders, minor cosmetic damage, As is, Where is	222,482 Kms	2D8HN44E69R685322	CVA	172809 TOW ONLY, 92-3	2102-641

Item #	Description	Kms	Serial Number	Ministry / Client	Ministry / Client Ref.#	Disposal Request #
1,251.99 11-036	Van 2009 DODGE Grand Caravan FWD, Cargo Van 3.3L V6 Gas Auto air, tilt, cruise, AM/FM/CD player, power front windows, mirrors & locks cargo barrier, shelving, rubber floor in cargo area, wire barriers on rear windows, dark tinted rear glass, remote start (not working), White, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: exhaust leak by passenger door, rear left brake stuck on, caliper seizing, (rotors/caliper/pads), interior extremely dirty, drivers seat worn out, drivers floor ripped/large hole, driver door dent/crease, rust on doors/trim missing, left rear fender and tailgate rust, hood paint poor, minor cosmetic damage. , As is, Where is	270,497 Kms	2D4HN11E19R683417	CVA	172932 TOW ONLY, 106-4	2102-650
3,076.99 11-037	Van 2012 DODGE Grand Caravan FWD, 7 passenger Stow-n-Go 3.6L V6 Gas Auto air, tilt, cruise, AM/FM/CD player, power heated mirrors, power windows & locks keyless entry- 1 fob, spare tire cover under vehicle, Red, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , oil change, PROBLEMS: check engine light on, engine oil leak at filter housing, windshield cracked, surface rust on front rotors, hood paint bubbling, rust along bottom of tailgate, rear wiper blade, spare tire loose in back/poor condition, fire extinguisher removed, minor exterior damage., As is, Where is	294,240 Kms	2C4RDGBG2CR268623	CVA	173666 TOW ONLY, 106-5	2102-651
3,766.00 11-038	Van 2005 FORD E350 Econoline Wagon RWD, 15 passenger 5.4L V8 Gas Auto air, tilt, cruise, aftermarket AM/FM/CD player hitch, duraguard on lower areas both sides, rear HVAC, White, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , Oil change, PROBLEMS: ABS light on, rear brake pads and rotors, seat belt, windshield chips, LF seat worn, rust on fenders, RR door missing inside trim piece, minor cosmetic damage, As is, Where is	110966 Kms	1FBSS31L65HB28608	CVA	422303 TOW ONLY, 89-1	2102-633

Item #	Description	Kms	Serial Number	Ministry / Client	Ministry / Client Ref.#	Disposal Request #
2,406.00 11-039	Van 2006 FORD Econoline Wagon RWD, 15 passenger 5.4L V8 Gas Auto air, tilt, cruise, AM/FM radio, rear HVAC trailer hitch wiring, has a wheel wrench and jack (missing jack crank), Grey, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: park brake doesn't hold, drive belt, rear interior pannels broken off, left front hub cap missing, head light assembly, paint poor on fenders, driver door & tailgate, right rear door cracked at bottom, roof rust/scrapes, roof vents and rear dash vent broken, driver seat has holes, 2nd and 3rd row seats-backs are bent, all rear seat belts pulled through seats, parking lot dents & scratches., As is, Where is	173,896 Kms	1FBSS31L16DA87961	CVA	422535 TOW ONLY, 107-2	2102-653
2,543.00 11-040	Van 2007 FORD Econoline Wagon RWD, 15 passenger 5.4L V8 Gas Auto air, tilt, cruise, power locks & windows hitch, trailer wiring, rear HVAC (not working), dark tinted glass, seat covers on all bench seats, White, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: both lower ball joints & right upper ball joint, side door cracked, right front door rusting along bottom, both bumpers rusted, both fenders rust/creases/dents, rocker panel paint peeling, rear heater not working, rear seats not secure, driver & passenger seats worn, roof vents missing, missing speaker covers, missing jack, parking lot dents & scratches., As is, Where is	160,543 Kms	1FBSS31L77DB24982	CVA	424069 TOW ONLY, 107-3	2102-656

Item #	Description	Kms	Serial Number	Ministry / Client	Ministry / Client Ref.#	Disposal Request #
REGINA, Saskbuilds and Procurement, SaskSurplus Sales Lot, 500 McLeod Street - Miscellaneous Items and Equipment.						
Due to COVID-19, ON-LINE VIEWING ONLY. Contact SaskSurplus (306) 787-2062 or (306) 798-3306.						
No Bid * 8-179	Books lot of 7 Annual Criminal Code, 2016, Martin's , , , , , Good			CVA	SS3472	2007-278
5.25 * 8-171	Booster Cables Brand unknown light gauge, 8 feet in lenth , , , , , Good			CVA	SS3698	2006-223
1.00 * X-397	Computer Arm Monitor mounting , , , , , Poor			CS SaskSurp	ss3370	2004-093
1.25 * 10-103	Dishware 1 box of miscellaneous items metal thermal cup lids , , , , , Poor			SaskSurp lus	X-V386	2009-452
1.50 * 10-111	Electrical Shop Parts 1 box of miscellaneous parts adaptor plates, light switches, various electrical components. Other misc items may be included. Refer to picture , , , , , Poor			SaskSurp lus	X-V353	2009-452
1.50 * 10-113	Electrical Shop Parts 1 box of miscellaneous parts computer parts, repair parts. Other misc items may be included. Refer to picture , , , , , Poor			SaskSurp lus	X-V357	2009-452
1.50 * 10-124	Electrical Shop Parts 1 box of miscellaneous parts stove elements. Other misc items may be included. Refer to picture , , , , , Poor			SaskSurp lus	X-V348	2009-452
1.50 * 10-125	Electrical Shop Parts 1 box of miscellaneous parts stove elements. Other misc items may be included. Refer to picture , , , , , Fair			SaskSurp lus	X-V352	2009-452
1.27 * 10-127	Electrical Shop Parts 1 box of miscellaneous parts thermostat, electrical plugins, switches. Other misc items may be included. Refer to picture , , , , , Poor			SaskSurp lus	X-V349	2009-452
1.25 * 10-128	Electrical Shop Parts 1 box of miscellaneous parts thermostat, switches, various wiring. Other misc items may be included. Refer to picture , , , , , Poor			SaskSurp lus	X-V343	2009-452

Item #	Description	Kms	Serial Number	Ministry / Client	Ministry / Client Ref.#	Disposal Request #
1.25 * 10-131	Electrical Shop Parts 1 box of miscellaneous parts various electrical components. Other misc items may be included. Refer to picture , , , , , Poor			SaskSurplus	X-V362	2009-452
1.25 * 10-135	Electrical Shop Parts 1 box of miscellaneous parts wall plugins, wall plates, switches. Other misc items may be included. Refer to picture , , , , , Poor			SaskSurplus	X-V355	2009-452
20.10 * 8-214	Keypad Microphone Motorola model HMN4079D. may be non functional. Is compatible with the Motorola model KTL 2500 , , , , , Good			CVA	SS3479	2007-280
20.10 * 8-215	Keypad Microphone Motorola model HMN4079D. may be non functional. Is compatible with the Motorola model KTL 2500 , , , , , Good			CVA	SS3480	2007-280
1.10 * 10-144	Machine Shop Parts 1 box of miscellaneous parts bearings, cords. Other misc items may be included. Refer to picture , , , , , Poor			SaskSurplus	X-V338	2009-452
1.25 * 10-145	Machine Shop Parts 1 box of miscellaneous parts bearings, lint protectors. Other misc items may be included. Refer to picture , , , , , Fair			SaskSurplus	X-V288	2009-452
5.51 * 10-146	Machine Shop Parts 1 box of miscellaneous parts bearings, spinners, o-rings. Other misc items may be included. Refer to picture , , , , , Fair			SaskSurplus	X-V327	2009-452
1.25 * 10-147	Machine Shop Parts 1 box of miscellaneous parts bearings, springs, various repair items. Other misc items may be included. Refer to picture , , , , , Fair			SaskSurplus	X-V319	2009-452
1.25 * 10-148	Machine Shop Parts 1 box of miscellaneous parts belts, cords. Other misc items may be included. Refer to picture , , , , , Poor			SaskSurplus	X-V336	2009-452
1.49 * 10-149	Machine Shop Parts 1 box of miscellaneous parts belts, hose. Other misc items may be included. Refer to picture , , , , , Poor			SaskSurplus	X-V292	2009-452
1.25 * 10-150	Machine Shop Parts 1 box of miscellaneous parts belts, hoses, gears. Other misc items may be included. Refer to picture , , , , , Poor			SaskSurplus	X-V303	2009-452
1.25 * 10-151	Machine Shop Parts 1 box of miscellaneous parts belts, hoses. Other misc items may be included. Refer to picture , , , , , Fair			SaskSurplus	X-V308	2009-452

Item #	Description	Kms	Serial Number	Ministry / Client	Ministry / Client Ref.#	Disposal Request #
1.25 * 10-152	Machine Shop Parts 1 box of miscellaneous parts belts, plates. Other misc items may be included. Refer to picture , , , , , Fair			SaskSurplus	X-V293	2009-452
1.25 * 10-156	Machine Shop Parts 1 box of miscellaneous parts clamps, pipes, various machine pieces. Other misc items may be included. Refer to picture , , , , , Fair			SaskSurplus	X-V333	2009-452
1.25 * 10-157	Machine Shop Parts 1 box of miscellaneous parts coils, bearings, blades. Other misc items may be included. Refer to picture , , , , , Fair			SaskSurplus	X-V323	2009-452
1.25 * 10-160	Machine Shop Parts 1 box of miscellaneous parts gasket caps, various machine pieces. Other misc items may be included. Refer to picture , , , , , Fair			SaskSurplus	X-V334	2009-452
1.25 * 10-165	Machine Shop Parts 1 box of miscellaneous parts gears, bearings. Other misc items may be included. Refer to picture , , , , , Poor			SaskSurplus	X-V296	2009-452
2.80 * 10-166	Machine Shop Parts 1 box of miscellaneous parts gears, switches. Other misc items may be included. Refer to picture , , , , , Poor			SaskSurplus	X-V286	2009-452
1.25 * 10-168	Machine Shop Parts 1 box of miscellaneous parts hose clamps, gears, bearings. Other misc items may be included. Refer to picture , , , , , Fair			SaskSurplus	X-V315	2009-452
1.25 * 10-172	Machine Shop Parts 1 box of miscellaneous parts o-rings, motor parts. Other misc items may be included. Refer to picture , , , , , Fair			SaskSurplus	X-V302	2009-452
1.25 * 10-173	Machine Shop Parts 1 box of miscellaneous parts pipes, hose. Other misc items may be included. Refer to picture , , , , , Poor			SaskSurplus	X-V337	2009-452
1.25 * 10-174	Machine Shop Parts 1 box of miscellaneous parts pipes, steel wool, squeegee repair. Other misc items may be included. Refer to picture , , , , , Poor			SaskSurplus	X-V311	2009-452
1.25 * 10-176	Machine Shop Parts 1 box of miscellaneous parts pulleys, bearings, brakes. Other misc items may be included. Refer to picture , , , , , Poor			SaskSurplus	X-V330	2009-452
1.25 * 10-178	Machine Shop Parts 1 box of miscellaneous parts pulleys, o-rings, plastic bushings. Other misc items may be included. Refer to picture , , , , , Fair			SaskSurplus	X-V324	2009-452

Item #	Description	Kms	Serial Number	Ministry / Client	Ministry / Client Ref.#	Disposal Request #
1.25 * 10-179	Machine Shop Parts 1 box of miscellaneous parts pulleys, o-rings, various machine pieces. Other misc items may be included. Refer to picture , , , , , Poor			SaskSurplus	X-V335	2009-452
1.25 * 10-181	Machine Shop Parts 1 box of miscellaneous parts rubber pulleys, various machine parts. Other misc items may be included. Refer to picture , , , , , Poor			SaskSurplus	X-V297	2009-452
3.80 * 10-183	Machine Shop Parts 1 box of miscellaneous parts saw blades, gears, bearings. Other misc items may be included. Refer to picture , , , , , Poor			SaskSurplus	X-V322	2009-452
1.25 * 10-184	Machine Shop Parts 1 box of miscellaneous parts springs, bearings. Other misc items may be included. Refer to picture , , , , , Poor			SaskSurplus	X-V318	2009-452
3.65 * 10-185	Machine Shop Parts 1 box of miscellaneous parts squeegees, various machine pieces. Other misc items may be included. Refer to picture , , , , , Fair			SaskSurplus	X-V301	2009-452
1.25 * 10-186	Machine Shop Parts 1 box of miscellaneous parts tubes, pulleys, nuts and bolts. Other misc items may be included. Refer to picture , , , , , Poor			SaskSurplus	X-V295	2009-452
1.25 * 10-188	Machine Shop Parts 1 box of miscellaneous parts various machine pieces, hardware. Other misc items may be included. Refer to picture , , , , , Poor			SaskSurplus	X-V326	2009-452
1.25 * 10-189	Machine Shop Parts 1 box of miscellaneous parts various machine pieces. Other misc items may be included. Refer to picture , , , , , Fair			SaskSurplus	X-V287	2009-452
5.51 * 10-190	Machine Shop Parts 1 box of miscellaneous parts various machine pieces. Other misc items may be included. Refer to picture , , , , , Fair			SaskSurplus	X-V312	2009-452
1.25 * 10-191	Machine Shop Parts 1 box of miscellaneous parts various machine pieces. Other misc items may be included. Refer to picture , , , , , Poor			SaskSurplus	X-V320	2009-452

Item #	Description	Kms	Serial Number	Ministry / Client	Ministry / Client Ref.#	Disposal Request #
2.55 * 10-193	Machine Shop Parts 1 box of miscellaneous parts various machine pieces. Other misc items may be included. Refer to picture , , , , , Poor			SaskSurplus	X-V332	2009-452
1.25 * 10-194	Machine Shop Parts 1 box of miscellaneous parts wheel rim, electrical wiring, bearings. Other misc items may be included. Refer to picture , , , , , Poor			SaskSurplus	X-V299	2009-452
2.40 * 10-195	Machine Shop Parts 1 box of miscellaneous parts wheels, filter. Other misc items may be included. Refer to picture , , , , , Poor			SaskSurplus	X-V294	2009-452
No Bid * 8-216	radio extension speaker Motorola 0025 E mal-2 has mounting bracket. External speaker for 2 way radios. 7.5 watts. Maybe non functional , , , , , Good			CVA	SS3481	2007-280
No Bid * 8-253	Rear Bench Seat may fit a 2008 Dodge 1 ton, quad cab folding, grey in colour , , , , , Fair			CVA	SS3579	2009-413
260.00 * X-102	Side Steps Set of 2 Removed from 2019 Chevy Silverado , , , , , New - Unused			CVA	SS1798	2003-1215
No Bid * 12-120	Tires Set of 4 17 inch, 215/60/R17, Extreme Grip MX Winter Claw Manufacture Date: week 17, year 2013 , , , , , Poor			CVA	ss2294	1911-957
No Bid * 8-108	Tire Sumitomo HTR Enhance L/X M+S 205/60R/16 , , , , , Good			CVA	SS3656	2006-206
124.46 * 8-136	Tires set of 4 Firestone FR710 M+S 255/65R/16 Manufacture Date: week 03, year 2014 , , , , , Fair			CVA	SS3661	2006-208
No Bid * 8-137	Tires set of 2 Winter Claw Extreme Grip MX 195/60R/15 Manufacture Date: week 18, year 2014 , , , , , Poor			CVA	SS3663	2006-208
No Bid * 8-154	Tires set of 4 Winter Claw Extreme Grip MX 225/60R/16 Manufacture Date: week 27, year 2014 , , , , , Poor			CVA	SS3679	2006-220
111.00 * 8-155	Tires set of 4 Winter Claw Extreme Grip MX 225/60R/16 Manufacture Date: week 23, year 2014 , , , , , Poor			CVA	SS3683	2006-220
No Bid * 8-162	Tires set of 4 Winter Claw Extreme Grip M+S 225/55R/17 Manufacture Date: week 26, year 2013 , , , , , Poor			CVA	SS3686	2006-221
No Bid * 8-223	Tires set of 4 Winter Claw Extreme Grip MX, M+S, snowflake 215/65R/16 Manufacture Date: week 12, year 2013 , , , , , Poor			CVA	SS3551	2008-368

Item #	Description	Kms	Serial Number	Ministry / Client	Ministry / Client Ref.#	Disposal Request #
No Bid * 8-239	Tires set of 4 Winter Claw Extreme Grip MX, M+S, snow flake 195/60R/15 Manufacture Date: week 18, year 2014 , , , , , Poor			CVA	SS3564	2009-402
No Bid * 8-289	Tires set of 4 Artic Claw Winter TXI M+S 205/60R/16 Manufacture Date: week 21, year 2012 , , , , , Poor			CVA	SS3652	2006-203
72.22 * X-106	Tires Set of 4 15 inch 215/70/R15 Matrix Tour RS Manufacture Date: week 02, year 2013 , , , , , Poor			CVA	SS1773	2003-1215
76.00 * X-116	Tires Set of 4 16 inch, 205/60/R16, Matrix Tour RS Manufacture Date: week 50, year 2014 , , , , , Poor			CVA	SS1777	2003-1215
85.55 * X-123	Tires Set of 4 17 inch, 215/60/R17, Firestone FR710 M + S Manufacture Date: week 47, year 2013 , , , , , Poor			CVA	SS1786	2003-1215
No Bid * 8-184	Wheel Centre Cap lot of 4 Ford OEM, still in box compatible with Ford Expedition 2003-2014 and Ford 150 2004-2008 models only , , , , , Excellent			CVA	SS3471	2007-278
No Bid * X-258	Chair (side chair) metal & fabric light pink, dirty , , , , , Fair			SS VVC	ss3322	2003-1218
1.75 * 10-199	Office Supplies 1 box of miscellaneous items monitor stands, lights, cd cases, various cables , , , , , Fair			SaskSurp lus	X-V371	2009-452
1.00 * 10-201	Office Supplies 1 box of miscellaneous items various tv parts , , , , , Fair			SaskSurp lus	X-V372	2009-452
13.00 * 8-263	Plotter Hewlett-Packard DesignJet T1100PS, model number-Q6688A, manufacture date May 12th 2008 large plotter on wheels, hard drive has been removed, unsure if operational. , , , , , Fair		MY85C5C08N	CS ITD	448517	2009-453
No Bid * 8-256	Printer Hewlett-Packard Color LaserJet 5550DTN, model number-Q3716A, manufacture date Feb 22nd 2007 large printer on wheels, hard drive removed, unsure if operational. , , , , , Fair		JPSC72P03H	CS ITD	3-425700	2009-453
No Bid * 8-212	Printer Hewlett-Packard Color LaserJet 5550DTN, model number-Q3716A, manufacture date June 26th 2007 medium printer on wheels, no hard drive, unsure if operational , , , , , Fair		JPSC76S090	CVA	J1-436842 SS3223	2007-254

Item #	Description	Kms	Serial Number	Ministry / Client	Ministry / Client Ref.#	Disposal Request #
No Bid * 8-193	Printer Hewlett-Packard Color LaserJet 5550N, Model-Q3714A medium sized printer, hard drive removed, unsure if operational. Manufacture date-Oct 6th 2004 , , , , , Fair		JPDC4B500Y	CS ITD	P7-400311 SS3229	2006-193
No Bid * 8-257	Printer Hewlett-Packard Color LaserJet 8100DN, model number-C4216A, manufacture date Sept 25 1998 large printer, hard drive removed, unsure if operational. , , , , , Fair		USBC006776	CS ITD	429844	2009-453
1.00 * 8-258	Printer Hewlett-Packard Color LaserJet 9050DN, model number-Q3723A, manufacture date May 24 2011 large printer, hard drive removed, unsure if operational. , , , , , Fair		JPRCC5Q04L	CS ITD	420582	2009-453
1.00 * 8-201	Printer Hewlett-Packard LaserJet 9050DN, Model number-Q3723A large sized printer, hard drive removed, unsure if operational. Manufacture date Dec 10th 2007 , , , , , Fair		JPRL7D9056	CS ITD	P9-448323 SS3228	2006-193
1.00 * 8-202	Printer Hewlett-Packard LaserJet 9050DN, Model-Q3723A large sized printer on wheels, hard drive removed, unsure if operational. Manufacture date Dec 10th 2007 , , , , , Fair		JPRL7D905P	CS ITD	P5-448329 SS3222	2006-193
1.00 * 8-203	Printer Hewlett-Packard LaserJet 9050DN, Model-Q3723A large sized printer, hard drive removed, unsure if operational. Manufacture date Dec 2nd 2009 , , , , , Fair		JPRC9D04TX	CS ITD	P10-424602 SS3227	2006-193
1.00 * 8-204	Printer Hewlett-Packard LaserJet 9050DN, Model-Q3723A large sized printer, hard drive removed, unsure if operational. Manufacture date June 27th 2010 , , , , , Fair		JPRCB6W40B	CS ITD	P13-433346 SS3225	2006-193
1.00 * 8-205	Printer Hewlett-Packard LaserJet 9500N, Model-C8547A Large Printer on wheels, hard drive removed, unsure if operational. Manufacture date May 4th 2007 , , , , , Fair		JPNJB06921	CS ITD	P6-440589 SS3224	2006-193
No Bid * 8-206	Printer Hewlett-Packard LaserJet M4345xs MFP, Model-CB427A medium sized printer, hard drive removed, unsure if operational. , , , , , Fair		CNDC99P13K	CS ITD	P4-466539 SS3221	2006-193
1.25 * X-622	Printer Cartridge HP Laser Jet 05A , , , , , New - Unused			HI	Pic #7	1911-950

Item #	Description	Kms	Serial Number	Ministry / Client	Ministry / Client Ref.#	Disposal Request #
1.25 * X-623	Printer Cartridge HP Laser Jet 27X , , , , , New - Unused			HI	Pic #3	1911-950
1.50 * X-625	Printer Cartridge Lot of 4 HP Laser Jet 501A & 503A , , , , , New - Unused			HI	Pic #1	1911-950
1.50 * X-626	Printer Cartridge Lot of 2 HP Laser Jet 92A , , , , , New - Unused			HI	Pic #5	1911-950
1.25 * X-627	Printer Cartridge HP Laser Jet Q6470A , , , , , New - Unused			HI	Pic #6	1911-950
REGINA, Saskbuilds and Procurement, SaskSurplus, 1660 Park St						
Due to COVID-19, ON-LINE VIEWING ONLY. Contact Neil Hamel at 306-787-2795 or at neil.hamel@gov.sk.ca						
28.75 * 10-563	Heated Food Transport Cart Blickman Health Industries, Foodveyer Model AHS8861 operability unknown, 208-230 V, 1500 W, 29" w, 76.5" d from ball hitch to coupler, 46" h , , , , , Poor			36,426 SaskSurplus	X-V498 X-V498	2011-509
31.80 * 10-564	Heated Food Transport Cart Blickman Health Industries, Foodveyer Model ALS6271 operability unknown, 110-120 V, 1250 W, 29.5" w, 72" d from ball hitch to coupler, 42.5" h , , , , , Poor		54344-3	SaskSurplus	X-V495 X-V495	2011-509
29.06 * 10-567	Heated Food Transport Cart Brute Kitchen Equipment Co. Inc., Model VFCH58 operability unknown, 208 V, 3000 W, 14.4 amps, 60 Hz, 28" w, 79" d from ball hitch to coupler, 42" h , , , , , Poor			712,019 SaskSurplus	X-V499 X-V499	2011-509
32.22 * 10-568	Heated Food Transport Cart Brute Kitchen Equipment Co. Inc., Model VFCH58 operability unknown, 208 V, 3000 W, 14.4 amps, 60 Hz, 28" w, 79" d from ball hitch to coupler, 42" h , , , , , Poor			712,019 SaskSurplus	X-V500 X-V500	2011-509
1.25 * 10-616	Refrigerator General Electric, Model VL10 EBRW2911 operability unknown, white, 115 V, 2.4 amps, 60 Hz, 24" w, 29.5" d, 56.5" h , , , , , Poor		FT3 05506	SaskSurplus	X-V506 X-V506	2011-509
1.25 * 10-617	Refrigerator McClary-Easy, Model M10-76-1 operability unknown, white, 115 V, 2.9 amps, 24" w, 30.5" d, 56.5" h , , , , , Poor		J 14228-7	SaskSurplus	X-V508 X-V508	2011-509
1.25 * 10-618	Refrigerator Norge, Model NNT156J operability unknown, white, 29" w, 29.5" d, 61" h , , , , , Poor		LQ36764292	SaskSurplus	X-V450 X-V450	2011-509

Item #	Description	Kms	Serial Number	Ministry / Client	Ministry / Client Ref.#	Disposal Request #
27.77 * 10-620	Salon Chairs Lot of 2 Belvedere brand, vinyl and metal adjustable height, includes 2 black half-circle rubber mats , , , , , Fair			SaskSurplus	X-V533 X-V533	2011-509
5.00 * 10-621	Salon Hair Dryer Belvedere Model B900 operability unknown, 120 V, 10 amps, 60 Hz , , , , , Poor			SaskSurplus	X-V532 X-V532	2011-509
3.75 * 10-519	Chairs Lot of 4 Acme Chrome Furniture Ltd. metal and vinyl, 3 grey, 1 red, stackable , , , , , Poor			SaskSurplus	X-V421 X-V421	2011-509
3.25 * 10-520	Chairs Lot of 3 Acme Chrome Furniture Ltd. metal and vinyl, green, stackable , , , , , Poor			SaskSurplus	X-V423 X-V423	2011-509
4.75 * 10-523	Chairs Lot of 5 Global Upholstery Co. Ltd. metal and fabric, beige, stackable , , , , , Poor			SaskSurplus	X-V430 X-V430	2011-509
4.00 * 10-527	Chairs Lot of 5 Global Upholstery Co. Ltd., Jayden Products Ltd. metal and fabric/metal and vinyl, 2 blue, 2 beige striped pattern, 1 salmon, stackable , , , , , Poor			SaskSurplus	X-V432 X-V432	2011-509
3.50 * 10-532	Chairs Lot of 5 Ideal Brass & Plating Co. metal and vinyl, beige , , , , , Poor			SaskSurplus	X-V414 X-V414	2011-509
2.50 * 10-542	Chairs Lot of 4 Prima Chrome Furniture Co. Ltd. metal and vinyl, 2 salmon, 1 blue, 1 teal , , , , , Poor			SaskSurplus	X-V417 X-V417	2011-509
2.00 * 10-546	Chairs Lot of 4 Royal Metal Manufacturing Co. Ltd. metal and vinyl, 3 beige, 1 teal , , , , , Poor			SaskSurplus	X-V415 X-V415	2011-509
4.25 * 10-549	Chairs Lot of 8 Various brands various materials, colours, and sizes , , , , , Poor			SaskSurplus	X-V427 X-V427	2011-509
1.75 * 10-550	Chairs Lot of 4 Various brands various materials, colours, and sizes , , , , , Poor			SaskSurplus	X-V443 X-V443	2011-509
2.00 * 10-551	Chairs Lot of 4 Various brands various materials, colours, and sizes , , , , , Poor			SaskSurplus	X-V447 X-V447	2011-509
1.75 * 10-619	Rolling Reclining Chair Vinyl, metal 26" w, 36" d (adjustable), 44" h (adjustable) , , , , , Poor			SaskSurplus	X-V592 X-V592	2011-509

Item #	Description	Kms	Serial Number	Ministry / Client	Ministry / Client Ref.#	Disposal Request #
No Bid * 10-639	Swinging Chairs Lot of 4 Unknown brand metal and plastic, 3 blue, 1 beige, various sizes , , , , , Poor			SaskSurplus	X-V445 X-V445	2011-509
1.25 * 10-647	Vintage 3-Piece Seating Arrangement Vinyl, metal, wood 75" w, 25" d, 31" h, one connecting piece missing , , , , , Poor			SaskSurplus	X-V538 X-V538	2011-509
BIG RIVER, Environment, Compliance and Field Services, CALL FOR DIRECTIONS						
Due to COVID-19, ON-LINE VIEWING ONLY. Contact Frazer Parsons 306-479-7309 or 1-800-567-4224, Frazer.Parsons@gov.sk.ca						
925.00 11-556	Utility Trailer 2001 8'6" wide x 14' long, 2" hitch, needs welding on ramps, deck rusted, lights not working , , , , , Broken Repairable			9,122,000 ENV	1	2006-216
925.00 11-555	Utility Trailer 1955 tilt deck, 4' wide x 8' long, 2" hitch, deck rotten, tires dry rotted and flat, lights unknown , , , , , Broken Repairable		AT2001	ENV	2	2006-216
MOOSE JAW, Highways, 1 km south of Moose Jaw on Highway #2						
Due to COVID-19, ON-LINE VIEWING ONLY. Contact Al Froehlich at 306-694-3775 or allan.froehlich@gov.sk.ca						
101.00 11-570	Clutch & Flywheel Installer SPX OTC handles 14" and 15 1/2" clutch assemblies , , , , , Fair			HI	3	2101-600
460.00 11-567	One Way Plow metal 12', worn , , , , , Poor			HI	M-2078	2008-359
251.11 11-568	One Way Plow metal 12', worn , , , , , Poor			HI	M-2099	2008-359
11.00 11-571	Step Ladder FeatherLite one step ladder , , , , , Fair			HI	2	2101-600
11.00 11-572	Step Ladder FeatherLite one step ladder , , , , , Fair			HI	1	2101-600
56.00 11-573	wheel Dolly Power Fist jack missing , , , , , Fair			HI	4	2101-600

Item #	Description	Kms	Serial Number	Ministry / Client	Ministry / Client Ref.#	Disposal Request #
NIPAWIN, Environment, Compliance and Field Services, 210 1ST St East						
Due to COVID-19, ON-LINE VIEWING ONLY. Contact John Worsley at 306-862-1790, 306-812-6308 or john.worsley@gov.sk.ca						
*WD	11-565	Deepfreeze 2005 Kenmore Model 970-162021 CWD storage freezers, rust on interior, non-operational , , , , , Poor		WB73133191	ENV 1	2007-265
*WD	11-566	Deepfreeze 2007 Frigidaire Model AFC2525DW2 CWD storage freezers, rust on interior, non-operational , , , , , Poor		WB53327100	ENV 2	2007-265
PRINCE ALBERT, Environment, Compliance and Field Services, CALL FOR DIRECTIONS						
Due to COVID-19, ON-LINE VIEWING ONLY. Contact Casey Howey 306-953-2441 or 306-961-9763 or casey.howey@gov.sk.ca						
185.00	11-559	Boat Motor Johnson Has not run in 10+ years, the rewind rope is completely pulled out and not rewinding back in, tank not included and is a direct drive motor no gear shifter , , , , , Poor		C15114	ENV 1	2006-217
228.00	11-557	Boat Motor Evinrude has not run in years, condition unknown, tank is older metal style, no fuel , , , , , Poor		6202DC 61637	ENV 3	2006-217
400.00	11-558	Boat Motor Evinrude runs well and was last used in 2019, comes with tank and hose pictured. , , , , , Good		C7234645	ENV 2	2006-217
PRINCE ALBERT, Environment, Fish, Wildlife and Lands, 3301 SK-2						
Due to COVID-19, ON-LINE VIEWING ONLY. NO ON-SITE VIEWING. Contact Tom Perry 306-940-6280, or at tom.perry@gov.sk.ca						
2,354.00	11-584	Argo Ontario Drive & Gear (ODG) Argo. 8-wheel drive, comes with wheels and snowtracks. Has not been run in many years, but has been		HTB3756	ENV 3 Prince Albert,	2008-290
1,276.00	11-585	ATV Honda Fourtrax 4x4 Honda Fourtrax 4x4 ATV with electric winch. The ATV has not been run in many years. , , , , , Broken Repairable			ENV 4 Prince Albert,	2008-290
27.76	11-586	Grinder Frantom lapidary saw This tool has not been used in many years. Unsure if in working condition. , , , , , Broken Repairable			ENV 5 Prince Albert,	2008-290

Item #	Description	Kms	Serial Number	Ministry / Client	Ministry / Client Ref.#	Disposal Request #
508.11 11-587	Motorcycle 1970s Suzuki 100 CC. Has not been started in many years. , , , , , Beyond Repair			ENV	2 Prince Albert,	2008-290
3,571.00 11-588	Snowmobile 2009 Ski-doo Skandic Tundra 550F Electric/Pull start, 2-stroke 2-cylinder, reverse, 2-up seat, 154 inch track 16 inch wide track. Snowmobile running in poor condition, shuts off when revving high. , , , , , Poor		2BPSGD9A09V000386	ENV	1 Prince Albert, Nisbet Depot	2008-290
PRINCE ALBERT, Highways, 81 North Industrial Drive						
Due to COVID-19, ON-LINE VIEWING ONLY. Contact Cory Palko at 306-960-5152 or Cory.Palko@gov.sk.ca						
4,306.00 11-569	Office trailer 2009 CJAY Trailers 26' v-nose trailer lockers in the back, 2 benches with storage, cabinets in front. Fire and smoke damaged. , , , , , Beyond Repair		2JAAH702991001390	HI	1	2101-599
PRINCE ALBERT, Saskatchewan Public Safety Association, 530 18th Street East.						
Due to COVID-19, ON-LINE VIEWING ONLY. Contact Paul Roberts (306)960-8318, or paul.roberts@gov.sk.ca						
50.00 * 8-689	Satellite phone Globalstar Qualcomm GSP-1600 phone, AC charger, 12VDC charger, carry case, extra battery, batteries may not hold charge, phones power on but not tested , , , , , Fair		N107C6WGC	SPSA	6	2002-1144
40.00 * 8-690	Satellite phone Globalstar Qualcomm GSP-1600 phone, AC charger, 12VDC charger, carry case, extra battery, batteries may not hold charge, phones power on but not tested , , , , , Fair		N106L3593	SPSA	7	2002-1144
40.00 * 8-691	Satellite phone Globalstar Qualcomm GSP-1600 phone, AC charger, 12VDC charger, carry case, extra battery, batteries may not hold charge, phones power on but not tested , , , , , Fair		N107WTRV7	SPSA	8	2002-1144

Item #	Description	Kms	Serial Number	Ministry / Client	Ministry / Client Ref.#	Disposal Request #
REGINA, Central Services, Property Management, 1660 Park Street.						
Due to COVID-19, ON-LINE VIEWING ONLY. Contact Rhonda Gelowicz 306-552-8049, or at rhonda.gelowicz@gov.sk.ca						
No Bid * 8-712	Coupling Lot of 2 Hymax 6.42-7.68 O.D. NBR Coupling, suitable for all types of pipes-ductile iron, cast iron, steel, copper 11"x11"x12"high sell for \$386.90 USD/ea , , , , New - Unused			CS Prop Man	CS20-08	2010-488
No Bid * 8-716	Shrink Wrap Machine 1998 Wulftec International Model WRT-150 Machine works normally, all functions worked, the top cover button is missing from panel, the rotation motor is likely soon to be replaced as it has carbon dust and grease markings on the back end, motor is quiet and doesn't draw extra amperage- this could mean motor needs service, reflector will need to be fastened properly NOTE: • Specialized equipment - successful bidder will have to dismantle and unbolt the device from the concrete. A lifting kit is required to take the wrappers down. This can be purchased directly through Wulftec. , , , , Fair		9708-1-0703	CS Prop Man	CS20-02	2010-488
No Bid * 8-717	Shrink Wrap Machine 2002 Wulftec International Model WRT-150 All functions work properly, photo eye is weak and needs replacement auto height sensor switch works but needs replacing soon		0200-5525	CS Prop Man	CS20-01	2010-488
No Bid * 8-718	Steam Trap Armstrong bucket steam trap Armstrong inverted bucket steam trap 816 series - up to 20,000 lb/hr / 9072 kG/hr, cast iron, pressures to 250 psig , , , , New - Unused			CS Prop Man	CS20-05	2010-488
REGINA, Energy and Resources, 11th Floor 1945 Hamilton St						
Due to COVID-19, ON-LINE VIEWING ONLY. Contact Tristyn Firth at 306-787-8716 or at tristyn.firth@gov.sk.ca						
*WD	* 10-667 Calculator Sharp calculator, compact CS 1630A, includes paper, 2 color ribbon, unknown if working , , , , Fair			ER	5	2010-484
*WD	* 10-668 CD Rack plastic black, 4 areas to hold multiple cds , , , , Fair			ER	10	2010-484

Item #	Description	Kms	Serial Number	Ministry / Client	Ministry / Client Ref.#	Disposal Request #
*WD * 10-670	Filing Cabinet metal lateral, 4 drawer, beige, includes key. 36" wide, 19" deep, 53 1/2" tall. , , , , Fair			ER	13	2010-484
*WD * 10-671	Legal Hanging Folders black, frame, multiple holders , , , , Fair			ER	8	2010-484
*WD * 10-672	Map Dividers plastic reddish brown, 3 rolls that come in 2 boxes , , , , Fair			ER	12	2010-484
*WD * 10-673	Misc Parts for Shelving/Filing Cabinets Lot of 28 metal Item 1736 - Metal, various sizes, white. Item 1735 - Metal, 3 various sizes, black, white and offwhite. , , , , Fair			ER	1	2010-484
*WD * 10-674	Shelf Dividers metal two varying sizes, 3 boxes each 1/4 full. , , , , Fair			ER	9	2010-484
*WD * 10-675	Side Chair metal grey fabric, black plastic arm rests , , , , Fair			ER	3	2010-484
REGINA, Energy and Resources, 15th Floor 1945 Hamilton St						
Due to COVID-19, ON-LINE VIEWING ONLY. Contact Patrice Naces at 306-787-2830 or at patrice.naces@gov.sk.ca, or Tristyn Firth at 306-787-8716 or at tristyn.fi						
*WD * 10-663	Monitor Arms Lot of 2 metal Black monitor arms; working , , , , Fair			ER	1711 CDP-30848	2010-458
*WD * 10-664	Wireless Headsets Lot of 4 plastic, metal 1. 0000-4753; not working/not compatible			ER	1712 CDP 30849	2010-458
REGINA, Energy and Resources, 201 Dewdney Ave E.						
Due to COVID-19, ON-LINE VIEWING ONLY. Contact Richard Wood 306-787-2621, richard.wood@gov.sk.ca						
No Bid * X-603	Satellite System Raven satellite dish, modern charger, 2 single coaxial cables and 1 satellite finder, small coaxial cable. , , , , Poor			ER	40	2004-079
6.00 * X-604	Satellite System Raven Satellite system is mostly complete but is missing the limb and the bracket that attach the satellite dish to its support. Does not come with a router. , , , , Fair		UEO88-34365-W	ER	39	2004-079

Item #	Description	Kms	Serial Number	Ministry / Client	Ministry / Client Ref.#	Disposal Request #
6.00 * X-605	Satellite System Raven Satellite system is mostly complete. Only missing parts are the limb that attaches from the satellite dish to the bracket support and phone. The router is not included. , , , , , Good		UA076-01109-G	ER	38	2004-079
REGINA, Highways, Operations, 1610 Park St						
Due to COVID-19, ON-LINE VIEWING ONLY. Contact Ed Hildebrand at 306-694-3881, 306-533-3421 or Ed.Hildebrand@gov.sk.ca						
130.50 11-563	Broken Sign Posts Fir 4 x 6 Approx. 56 posts, 8' to 14', banded in bundle as pictured, must have flatdeck trailer for pick up. , , , , , Fair			HI	pic 4-#1,#2	2007-261
130.50 11-564	Broken Sign Posts Fir 4 x 6 Approx. 56 posts, 8' to 14', banded in bundle as pictured, must have flatdeck trailer for pick up. , , , , , Fair			HI	pic 5-#1,#2	2007-261
REGINA, Immigration and Career Training, 1000-2103 11th Ave.						
Due to COVID-19, ON-LINE VIEWING ONLY. NO ON-SITE VIEWING. Contact Tristyn Firth at 306-787-8716, tristyn.firth@gov.sk.ca, or Patrice Naces at 306-787-28						
25.10 11-579	Cabinet pepperdust grey, 106cm W x 40cm D x 92cm H , , , , , Fair			ICT	4 CD30902	2010-486
6.50 11-574	Calculator Lot of 5 plastic 1 broken, 4 unknown if working. , , , , , Poor			ICT	1 CD29936	2010-485
15.05 11-575	Chair Zody black, chair seat does not adjust , , , , , Broken Repairable			ICT	4 CD29986	2010-485
1.25 11-576	Computer Mouse Microsoft black, sculpt ergonomic mouse, wireless (usb) included, scroller does not work , , , , , Broken Repairable			ICT	2 CD29983	2010-485
4.50 11-580	Desk Calculators Lot of 3 Electronic 1. Electronic Desk Calculator, with paper holder, no paper, unknown if working, Sharp 2 color, EL-2615G 2. Electronic desk calculator, with paper holder, no paper, unknown if working, Sharp 12 digit, EL-2630pIII, white. 3. Electronic desk calculator, with paper holder, no paper, unknown if working, Sharp 12 digit, EL-2630P, white. , , , , , Fair			ICT	1 CD30908	2010-486

Item #	Description	Kms	Serial Number	Ministry / Client	Ministry / Client Ref.#	Disposal Request #
5.25 11-581	File Cabinet Lot of 2 pepperdust lateral, 3 drawer, one has broken wheel and no key ring, no keys included. 45cm W x 60cm D x 27cm H , , , , , Fair			ICT	3 CD30903	2010-486
15.25 11-582	Misc Office Items 1 Box electronic pencil sharpener panasonic, black, unknown if working, desk paper tray desk paper tray, black 5 desk pen trays - desk pen trays with different sized compartments, black. 2 upright plastic dividers - 1. 3 slots, black 2. 4 slot, black 13 coat hangers for cubicles - 2 different sizes, all black, diskette file box - 4 dividers, has a lid and comes with a key , , , , , Fair			ICT	5 CD31197	2010-486
1.25 11-577	Monitor Stand Dell Silver and black, unknown if working , , , , , Fair			ICT	5 CD31197	2010-485
1.63 11-578	Phone SaskTel, Northern Telecom beige, no cord for the receiver of the phone, includes cord for the wall outlet. , , , , , Poor			ICT	3 CD29928	2010-485
No Bid 11-583	Phone Headset Lot of 2 1. Microsoft, black, comes with cords, unknown if working. 2. GN Netcom, includes cords, unknown if working. , , , , , Fair			ICT	2 CD30915	2010-486
SHAUNAVON, Environment, 54 3rd Ave East.						
Due to COVID-19, ON-LINE VIEWING ONLY. Contact Calvin Fiala 306-297-7232, calvin.fiala@gov.sk.ca						
6,680.00 11-562	Boat and Trailer 1997 Lund Rebel SSDLX 16 Ft, 1997 custom built trailer, 50HP four stroke yamaha outboard motor, 2 seats , tarp, depth sounder (needs work) , 2 Paddles , , , , , Fair		ZLUM0379F596- boat	ENV	1	2007-251
13,660.00 11-561	Boat, Trailer and Hitch 2000 Crestliner Super Hawk 2000 90 HP mercury outboard, 2000 yacht club bunk trailer, swing away hitch , poor tires, 2 inch ball, 3 seats, mercury controls, tilt (may need some work on it), some scratches and dents on hull. , , , , , Fair		4H100191XW0230987- Trailer NOR-64722G900-Boat OT302735-Motor	ENV	1	2007-250
111.00 11-560	Trailer 1991 Home-built deck is 93" x 149.5" , wooden deck(needs replacement) , tires 205/75/14 (poor condition) one flat , electric brakes not working , 2 inch ball , , , , , Fair		SK400465462	ENV	1	2006-224

Item #	Description	Kms	Serial Number	Ministry / Client	Ministry / Client Ref.#	Disposal Request #
WHITE SPRUCE - ORCADIA, Central Services, Property Management, NE-35-TP26-R5-W2ND.						
Due to COVID-19, ON-LINE VIEWING ONLY. Contact Mark Bigoraj 306-786-5871, mark.bigoraj2@gov.sk.ca						
52.31	11-534	Air Compressor Weg Motores, year unknown , , , , ,	Poor	CS Prop Man	1	2006-199
800.00	11-502	Bearing Puller Set complete set of gear or bearing pullers , , , , , Fair	Operational	CS Prop Man		2006-196
3.00	11-536	Cart plastic has electrical plugs on it , , , , ,	Poor	CS Prop Man	3	2006-199
No Bid	11-537	Cart wooden , , , , ,	Poor	CS Prop Man	4	2006-199
26.00	11-547	Cloth Roll Year Unknown , Model Unknown , , , , ,	New - Unused	CS Prop Man	17	2006-199
51.00	11-553	Ladder Werner Model -7520-2 Operational -20 Foot -Fiberglass , , , , ,	Fair	CS Prop Man	21	2006-199
5.50	11-501	Lawn Edger Black & Decker 2 HP, operational , , , , ,	Fair	CS Prop Man	1,2	2006-195
No Bid	11-522	Mop Pail Chatterson Operational , , , , ,	Poor	CS Prop Man	28	2006-198
10.63	11-525	Plastic Contatiner Rubbermaid on wheels, operational , , , , ,	Poor	CS Prop Man	40	2006-198
No Bid	11-503	Plug dividers 1 & 2 Lot of 24 10 foot lengths Operational , , , , ,	Poor	CS Prop Man	52	2006-197
No Bid	11-526	Projector THE FIVE "o" EIGHTY EIGHT Operational , , , , ,	Poor	CS Prop Man	31	2006-198
50.29	11-527	Pump ITT Bell & Gosset Operational 1/2 hp , 1 ph , , , , ,	Poor	CS Prop Man	34	2006-198
50.29	11-528	Pump ITT Bell & Gosset Operational 1/2 hp , 1 ph , , , , ,	Poor	CS Prop Man	33	2006-198

Item #	Description	Kms	Serial Number	Ministry / Client	Ministry / Client Ref.#	Disposal Request #
50.29	11-529 Pump ITT Bell & Gosset Operational 1/2 hp , 1 ph , , , , , Poor			CS Prop Man	32	2006-198
4.50	11-530 Spinner Game Year Unknown , Model Unknown Operational , , , , , Poor			CS Prop Man	35	2006-198
5.63	11-531 Step Year Unknown , Model Unknown Operational , , , , , Poor			CS Prop Man	37	2006-198
5.63	11-532 Step Year Unknown , Model Unknown Operational , , , , , Poor			CS Prop Man	36	2006-198
68.79	11-554 Step Ladder Featherlite Operational -16 foot- Alminum , , , , , Fair			CS Prop Man	20	2006-199
1.03	11-533 Vacuum Cleaner Electrolux , Model E-2000 Operational , , , , , Poor			CS Prop Man	39	2006-198
No Bid * X-519	Water Cooler Haws, Model: HF8 115 volt Operational , , , , , Fair		20,839	CS Prop Man	5 Water Fountain 1,2	2003-1226
No Bid	11-535 Bench wooden -12' , , , , , Poor			CS Prop Man	2	2006-199
No Bid	11-515 Cart Blane & Brothers Operational , , , , , Poor			CS Prop Man	26	2006-198
7.79	11-538 Chair wooden , , , , , Poor			CS Prop Man	8	2006-199
No Bid	11-539 Chair stool metal, fabric, model Unknown , , , , , Poor			CS Prop Man	16	2006-199
No Bid	11-540 Chairs Set of 4 metal, fabric, stackable , , , , , Poor			CS Prop Man	10	2006-199
No Bid	11-541 Chairs Set of 3 metal, fabric, stackable , , , , , Poor			CS Prop Man	12	2006-199
No Bid	11-542 Chairs Set of 4 metal, plastic, stackable , , , , , Poor			CS Prop Man	11	2006-199
No Bid	11-543 Chairs Set of 8 metal, plastic, stackable , , , , , Poor			CS Prop Man	13	2006-199

	Item #	Description	Kms	Serial Number	Ministry / Client	Ministry / Client Ref.#	Disposal Request #
No Bid	11-544	Chairs Set of 3 metal, plastic, stackable , , , , , Poor			CS Prop Man	14	2006-199
8.00	11-545	Chairs Set of 5 metal, plastic, stackable , , , , , Poor			CS Prop Man	15	2006-199
47.79	11-546	Chairs Set of 6 wooden , , , , , Poor			CS Prop Man	9	2006-199
No Bid	11-516	Coffee Table model Unknown, wooden Operational , , , , , Poor			CS Prop Man	38	2006-198
No Bid	11-548	Computer Chair plastic, fabric Missing arm rest , , , , , Poor			CS Prop Man	7	2006-199
No Bid	11-549	Computer Chair Year Unknown , Model Unknown , , , , , Poor			CS Prop Man	5	2006-199
No Bid	11-550	Computer Chair Year Unknown , Model Unknown , , , , , Poor			CS Prop Man	6	2006-199
No Bid	11-551	Computer Chair Year Unknown , Model Unknown , , , , , Poor			CS Prop Man	18	2006-199
No Bid	11-552	Desk Year Unknown , Model Unknown , , , , , Poor			CS Prop Man	19	2006-199
No Bid	11-517	Lamps Lot of 5 Year Unknown , Model Unknown Operational , , , , , Poor			CS Prop Man	25	2006-198
No Bid	11-518	Lamps Lot of 2 Year Unknown , Model Unknown Operational , , , , , Poor			CS Prop Man	24	2006-198
No Bid	11-519	Lamps Lot of 5 Year Unknown , Model Unknown Operational , , , , , Poor			CS Prop Man	23	2006-198
No Bid	11-520	Lamps Lot of 5 Year Unknown , Model Unknown Operational , , , , , Poor			CS Prop Man	22	2006-198
No Bid	11-521	Lights Lot of 4 Year Unknown , Model Unknown Operational - 4 foot fluorescent lights , , , , , Poor			CS Prop Man	27	2006-198
2.22	11-523	Night Stand Year Unknown , Model Unknown Operational , , , , , Poor			CS Prop Man	29	2006-198

Item #	Description	Kms	Serial Number	Ministry / Client	Ministry / Client Ref.#	Disposal Request #
No Bid 11-524	Organizer Year Unknown , Model Unknown Operational , , , , , Poor			CS Prop Man	30	2006-198
2.63 11-514	Table set 1 60" X 24" Operational , , , , , Poor			CS Prop Man	41	2006-197
8.63 11-513	Table set 10 Lot of 2 72" X 30" Operational , , , , , Poor			CS Prop Man	50	2006-197
2.63 11-504	Table set 11 30" X 60" table top only Operational , , , , , Poor			CS Prop Man	51	2006-197
7.00 11-505	Table set 2 47.5" X 29.2" Operational , , , , , Poor			CS Prop Man	42	2006-197
4.63 11-510	Table set 3 6' X 3' Operational , , , , , Poor			CS Prop Man	43	2006-197
13.63 11-512	Table set 4 60" X 30" with drawers Operational , , , , , Poor			CS Prop Man	44	2006-197
No Bid 11-511	Table set 5 60" X 30" Operational , , , , , Poor			CS Prop Man	45	2006-197
No Bid 11-506	Table set 6 47.5" X 29.2" Operational , , , , , Poor			CS Prop Man	46	2006-197
No Bid 11-508	Table set 7 48" round Operational , , , , , Poor			CS Prop Man	47	2006-197
No Bid 11-507	Table set 8 47.5" X 29.2" Operational , , , , , Poor			CS Prop Man	48	2006-197
No Bid 11-509	Table set 9 48" X 30" Operational , , , , , Poor			CS Prop Man	49	2006-197

Item #	Description	Kms	Serial Number	Ministry / Client	Ministry / Client Ref.#	Disposal Request #
WHITE SPRUCE - ORCADIA, CS Property Management, 12.2 km NW of Yorkton						
Due to COVID-19, ON-LINE VIEWING ONLY. Contact Mark Bigoraj 306-786-5871, mark.bigoraj2@gov.sk.ca						
147.00	11-590			CS Prop Man	1	2009-441
	Guard House , 0870-02 insulated, drywall inside, stucco exterior, 2 x 4 wall construction , , , , , Poor					
YORKTON, Highways, Operations/Fleet Services, 245 York Road East						
Due to COVID-19, ON-LINE VIEWING ONLY. NO ON-SITE VIEWING. For information on items contact: Brian Perih at 306-786-1651 or brian.perih@gov.sk.ca. Or I						
510.00	11-589			HI	1	2008-352
	Snow Plow Frink, model 188-43-79 12', worn , , , , , Poor					