

SALE SUMMARY LIST

PLEASE NOTE: Every effort has been made to accurately describe items and their condition; however, additional problems may exist, items may not be complete or exactly as described. Bidders are deemed to have reviewed the Terms and Conditions on bid forms and relied entirely on their own inspection and evaluation prior to bidding. Vehicles and equipment are sold "AS IS, WHERE IS", there is no implied or express warranty.

Visit www.SaskSurplus.ca for pictures and link to download Bid Form.

- Items identified with * have been on a previous sale and will be listed first on www.SaskSurplus.ca web site.
- SaskBuilds and Procurement, SaskSurplus, reserves right to have unadvertised minimum selling prices on items.

It is the Bidder's responsibility to review the terms and conditions of sale on the Offer to Purchase, Bid Form.

Bid Forms are available from www.SaskSurplus.ca or from the SaskSurplus Sales Lot, 500 McLeod Street, Regina, SK.

Bid Forms can be submitted in the following ways:

- by deposit in the bid box at the SaskSurplus Sales Lot,
- by fax to 306-787-2092; by phone 306-787-2062 or 306-787-2238,
- by email to sasksurplus@gov.sk.ca, or
- by mail, addressed to: Ministry of SaskBuilds and Procurement, SaskSurplus, 500 McLeod Street, Regina, SK S4N 4Y1.

(If mailing your bid, please allow sufficient time for bid to be received.)

- Bids received after close date and time cannot be accepted.

MT = (Ministry Transfer) This means that the item has been claimed by another ministry and automatically transferred to the ministry.
WD = (Withdrawn) This can happen if the item was requested to be removed by the seller.
No Bid = Items that did not receive any bids are normally carried forward to the next sale or may be withdrawn.

Item #	Description	Kms	Min Price	Serial Number
REGINA, SaskBuilds and Procurement, SaskSurplus Sales Lot, 500 McLeod Street - Vehicles				
Contact SaskSurplus 306-787-2062 or 306-798-3306.				
1,711.00 6-001	Car 2013 CHEVROLET, Impala LS, FWD, 3.6L, V6, gas, auto, A/C, tilt, cruise, AM/FM/CD player, power mirrors/locks/windows/driver seat, truck release, keyless entry- 2 fobs -2 keys , white, TOW ONLY, FAILED SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. **Please note: the SGI Inspection currently provided is only valid for 30 days after the date of the inspection.** 276,847 km , , PROBLEMS: Transmission shift hard (bangs), suspension & attachments front links poor, check engine light with fault codes P0877-00 - transmissions fluid pressure 4, P0989-00 - transmission fluid pressure 5, P069E-00 - fuel pump control module, missing plastic engine cover, front left carpet worn holes, bumper front chips, left front fender dent, roof dent, windshield chips, poor battery, minor exterior damage.>, As is, Where is	276,847 km	\$1,082	2G1WA5E37D1187215
4,175.00 6-002	Car 2009 CHRYSLER, Sebring LX , FWD, 2.4L, inline 4, gas, auto, A/C, tilt, cruise, AM/FM/CD player, power heated mirrors/locks/windows, trunk release, keyless entry 2- key fobs , silver, TOW ONLY, FAILED SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. **Please note: the SGI Inspection currently provided is only valid for 30 days after the date of the inspection.** 226,442 km , , PROBLEMS: Front and rear pads/rotors need to be repaired, gas cap door does not close tight, tire pressure monitor system (TPMS) light while driving, driver sun visor poor, hood paint bubbling/hail dents/scratches, both bumpers chips/scratches, left front fender scratches, left front door rust at bottom, right side doors rusted at bottom/chips, roof hail damage, trunk lid hail/rust, windshield chips, poor battery, minor exterior damage.>, As is, Where is	226,442 km	\$980	1C3LC46BX9N557183
4,089.89 6-004	Car 2011 DODGE, Avenger SXT, FWD, 2.4L, inline 4, gas, auto, A/C, tilt, cruise, AM/FM/CD player, power mirrors/windows/locks, trunk release, 2 key fobs , silver, TOW ONLY, FAILED SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. **Please note: the SGI Inspection currently provided is only valid for 30 days after the date of the inspection.** 245,220 km , , PROBLEMS: Shock absorbers & strut assemblies need to be repaired, both front struts leaking, both rear struts sweating, suspension/axles right front axle seal poo, front wheel alignment needed, both rocker arms have surface rust, gas door doesn't close tight, left head light fogged, right front door dent, hood paint bubbling/hail/scratches, both bumpers scratch/chips, left front door rust at bottom, right side doors rust at bottom of doors, roof hail dents, trunk lid rust bottom edge hail dents, windshield cracked, poor battery, minor exterior damage.>, As is, Where is	245,220 km	\$1,369	1B3BD4FB8BN514053

Item #	Description	Kms	Min Price	Serial Number
4,273.57 6-005	Car 2011 DODGE, Avenger SXT, FWD, 2.4L, inline 4, gas, auto, A/C, tilt, cruise, AM/FM/CD player, power mirrors, power locks/windows, trunk release, keyless entry -2 key fobs , silver, TOW ONLY, FAILED SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. **Please note: the SGI Inspection currently provided is only valid for 30 days after the date of the inspection.** 235,349 km, Recent Repairs: Instrument lamps, PROBLEMS: Hood dents/ paint bubbling/ scratches, both bumpers chips/scratches, left front fender scratches, right rear fender crease, left rear door rust at bottom, right rear door badly rusted, roof hail, trunk lid hail dents/ rusting at bottom, windshield chips, windshield blades need replacement, head lamp foggy, poor battery, minor exterior damage.> , As is, Where is	235,349 km	\$1,445	1B3BD4FB3BN528166
2,575.00 6-007	SUV 2008 JEEP, Liberty, Sport, 4WD, 2.7L, V6, gas, auto, A/C, tilt, cruise, AM/FM/CD player, driving lights, power mirrors, windows, locks, keyless entry-2 key fobs Hitch, trailer wiring , white, TOW ONLY, FAILED SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. **Please note: the SGI Inspection currently provided is only valid for 30 days after the date of the inspection.** 272,415 km, , PROBLEMS: Right lower ball joint, inner tie rod, front, rear U joints need replacement, driver belts, rear rotors, left front axels and transmission case need attention, four wheel alignment, check engine codes (PO452 EVAP pressure switch, PO456 EVAP leak, PO300 misfire), all pads and rotors need replacement, tire pressure monitor system (TPMS) on, hood prop not secured, rear right door gasket ripped, antenna on roof rusted at base, molding loose on left front door, hood chips, both bumpers' chips/scratches, right front fender scratched, both dog legs rusted, left front door rusted, rear left door rusted at bottom, both right doors rusted at bottom, roof rusted, tailgate rusted, windshield chips, both front seats missing trim, wiper blades need replacement, poor battery, minor exterior damage.>, As is, Where is	272,415 km	\$728	1J8GN28K38W251775

Item #	Description	Kms	Min Price	Serial Number
7,575.00 6-009	Truck 2012 DODGE, Ram 1500 , 4WD, Crew Cab, 5.7L, V8, gas, auto, A/C, tilt, cruise, AM/FM/CD player, power mirrors/locks/windows, keyless entry -2 key fobs -2 keys Has back seat, 5'8" box, front tow hooks, grille inserts, side steps, mud flaps, hitch, trailer wiring, electric brake control, roof rack brackets no cross bar, black Leer topper rear corners chipped, sliding windows in good condition., black, TOW ONLY, FAILED SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. **Please note: the SGI Inspection currently provided is only valid for 30 days after the date of the inspection.** 244,369 km , PROBLEMS: Both outer CV boots torn, front wheel alignment out of spec, exhaust manifolds leaking, rear rotors slight surface rust, right low beam not working, left plate light not working, paint worn our rear near topper, both rear fenders road rash/scratches, center console incomplete, hood dents/scratches, front bumper rusted, rear bumper scratches, left rear door scratches, right front door dent, roof small rust spots, hole in roof 2 sealed, tailgate chips/scratches/dents, windshield small chips, poor battery, minor exterior damage.>, As is, Where is	244,369 km	\$4,245	1C6RD7KT1CS224678
6,177.00 6-010	Truck 2013 DODGE, Ram 1500 SLT, 4WD, Quad Cab, 6'4" box, 4.8L, V8, gas, auto, AM/FM, AC, tilt, cruise power heated mirrors, power locks/windows/left front seat, keyless entry 2 key fobs, 2 keys Front tow hooks, sidestep, mud flaps, hitch, trailer wiring, original equipment manufacturer(OEM) electric brakes, has back seat, white, TOW ONLY, FAILED SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. **Please note: the SGI Inspection currently provided is only valid for 30 days after the date of the inspection.** 272,527 km , PROBLEMS: Steering linkage inner tie rod end, transmission out put seal leaking, left and right axle shaft, both lower ball joints, bellows on rack torn, missing wheel wrench and jack, air filter dusty, poor tires, back up lamp, right cab corner dented/rusted, right and left front door glass scratched. Left rear taillight cracked, hood paint bubbling, front bumper rust/scrapes, rear bumper rusted/dents, left front fender rusted, left rear fender rusted/dents, fender right front and rear rusted, left side doors dents/road rash, right rear door road rash, roof scratched, tailgate rust/dents, windshield large stone bruises, poor battery, minor exterior damage.>, As is, Where is	272,527 km	\$2,898	1C6RR7GP4DS558864

Item #	Description	Kms	Min Price	Serial Number
6,075.00 6-011	Truck 2014 DODGE, Ram 2500, RWD, crew cab, 6'7" box, 5.7L, V8, gas, auto, A/C, tilt, cruise, AM/FM, power heated mirrors, locks, windows, keyless entry – 2 key fobs, 1 key Grille inserts, mud flaps, side steps, hitch, trailer wiring, original equipment manufacture (OEM) trailer brake, has a back seat, white, TOW ONLY, FAILED SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. **Please note: the SGI Inspection currently provided is only valid for 30 days after the date of the inspection.** 322,901 km, , PROBLEMS: Both exhaust manifolds leaking, all four tires need replacement, box damaged on left side, tailgate does not open, front bumper rust spots, left front fender dent/rust, left rear fender cracked/dents, right front fender rust, right rear fender cracked/dents, left rear door dent, windshield chips, 4 holes in front hump mat, 2 of the holes are through the floor pan, poor battery, minor exterior damage.>, As is, Where is	322,901 km	\$4,605	3C6TR4CT8EG192973
4,075.00 6-013	Truck 2007 FORD, F150, Supercab, RWD, Extended cab, 6'6" box, 4.6L, V8, gas, auto, A/C, tilt, cruise, AM/FM, 2 keys Loose headache rack in box - may not be compatible with vehicle, hitch, trailer wiring., grey, TOW ONLY, FAILED SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. **Please note: the SGI Inspection currently provided is only valid for 30 days after the date of the inspection.** 258,022 km, , PROBLEMS: Rack and pinion steering leaking, all four tires are leaking and need an alignment, front seat stained/ripped, hood dents, front bumper dented, rear bumper rusts/dents, left front fender chips/paint chips, left rear fender rust, right front fender road rash, right rear fender rust, left front door dents/chips/weather stripping, roof scratches/stains from magnets, tailgate dents/scratches/bent, inside of box dented/scratched, windshield chips, poor battery, minor exterior damage.>, As is, Where is	258,022 km	\$1,172	1FTRX12W87FB24034
3,875.00 6-014	Van 2008 CHEVROLET, Uplander, FWD, 3.9L, V6, gas, auto, A/C, tilt, cruise, AM/FM/CD player, power mirrors/locks/front windows, keyless entry- 3 fobs- 2 keys 7 passenger, 2nd row captains chairs, 3rd row split bench, brown, TOW ONLY, FAILED SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. **Please note: the SGI Inspection currently provided is only valid for 30 days after the date of the inspection.** 236,018 km, , PROBLEMS: Rad support bent, front and rear alignment needed, noises and vibrations clunk in rear end, lock switches condition unknown, hood chips/dent/scratches, rear bumper scratches/cracks, left front and rear fender road rash/chips/scratches, dog leg rear scratches/road rash, both rocker panel rust inside at back doors, right both rear doors chips/dents/rust at bottom, roof small rust spots, tailgate rust/glass scratched, left front seat worn/soft, missing wheel covers, poor battery, minor exterior damage.>, As is, Where is	236,018 km	\$1,476	1GNDU23W68D162812

Item #	Description	Kms	Min Price	Serial Number
6,510.00 6-015	Van 2006 GMC, Savana 3500, Cargo, RWD, 6.0L, V8, gas, auto, A/C, tilt, cruise, AM/FM, rear heat, power locks, 1 key Cargo barrier, map box, computer stand, plywood floor, shelving, generator compartment, HD rear bumper, pintle hook, electric trailer brake, Warrick ladder at rear, condition unknown, frame supports inside van for ladder., white, TOW ONLY, FAILED SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. **Please note: the SGI Inspection currently provided is only valid for 30 days after the date of the inspection.** 98,951 km, , PROBLEMS: Front and rear brakes rotors rusted, check engine light on with fault codes, P0030/P0050/P0053/P0059, A/C not working, left front signal light not working, grille faded/missing badge, hood dents/chips/scratches, front bumper rusted/dented, left front fenders broken/paint poor rear rusted, right fenders front and rear paint poor/ rusted/dented, rocker panel both sides rusted, left front door paint poor, right sides doors paint poor, roof scratched/dented, hole in roof sealed, tailgate paint poor, inside handle loose, windshield cracked, spare tire in cargo area, left front seat worn, cushion is poor, wheel wrench missing, jack missing, no first aid or fire extinguisher, poor battery, minor exterior damage.>, As is, Where is	98,951 km	\$4,210	1GTHG35U861239441
REGINA, SaskBuilds and Procurement, SaskSurplus Sales Lot, 500 McLeod Street - Miscellaneous Items and Equipment.				
Contact SaskSurplus 306-787-2062 or 306-798-3306.				
No Bid * 3-101	Cargo Cover, OEM Chrysler cargo cover, roll out. grey vinyl May be compatible with a 2006 Dodge Magnum. Good		\$40	192,088
No Bid * 1-104	Floor Mats - Front, GM Original Equipment Manufacturer (OEM), rubber, light grey in colour May be compatible with Chevrolet Astro. Excellent		\$1	
4.00 * 1-105	Floor Mats - Front, GM Original Equipment Manufacturer (OEM), rubber, light grey in colour May be compatible with Chevrolet Astro. Excellent		\$1	
61.02 6-110	Chest, Titan Stainless, Aluminum Front facing lock handle, 30.25"w x 17.75"d x 19.75"h, has some mount holes, no lock or keys. Good		\$10	
60.00 6-111	Chest, Titan Stainless, Aluminum Front facing lock handle, 30.25"w x 17.75"d x 19.75"h, has some mount holes, no lock or keys. Good		\$10	
60.00 6-112	Chest, Titan Stainless, Aluminum Front facing lock handle, 30.25"w x 17.75"d x 19.75"h, has some mount holes, no lock or keys. Good		\$10	
60.00 6-113	Chest, Titan Stainless, Aluminum Front facing lock handle, 30.25"w x 17.75"d x 19.75"h, has some mount holes, no lock or keys. Good		\$10	
60.00 6-114	Chest, Titan Stainless, Aluminum Front facing lock handle, 30.25"w x 17.75"d x 19.75"h, has some mount holes, no lock or keys. Good		\$10	
211.00 6-115	Fork Extensions, Set of 2Arnold Welding made, not Engineered 6.5"w x 84"d, inside to inside on back side. Good		\$25	

Item #	Description	Kms	Min Price	Serial Number
211.00 6-116	Fork Extensions, Set of 2 Arnold Welding made, not Engineered 6.5"w x 84"d, inside to inside on back side. Good		\$25	
441.01 6-117	Generator, Honda 2500 WATT, 2011 Has been sitting for awhile, unknown if operational. *No Meter. Comes with manuals. Good		\$150	EZCN 1089019
553.00 6-118	Generator, Honda 3000 WATT, 2011 100 hrs, has been sitting for awhile, unknown if operational. Comes with manuals. Good		\$150	EZGL 1039336
553.00 6-119	Generator, Honda 3000 WATT, 2011 138 hrs, has been sitting for awhile, unknown if operational. Good		\$150	EZGL 1039333
517.00 6-120	Generator, Honda 3000 WATT, 2011 65 hrs, has been sitting for awhile, unknown if operational. Good		\$150	EZGL 1031207
517.00 6-121	Generator, Honda 3000 WATT, 2011 78 hrs, has been sitting for awhile, unknown if operational. Good		\$150	EZGL 1039522
500.00 6-122	Generator, Honda 3000 WATT, 2011 81.5 hrs, has been sitting for awhile, unknown if operational. Comes with manuals. Good		\$150	EZGL 1039514
No Bid * 4-125	GPS, GPS Tattle brand, remote monitoring device Online portal or Tattle Systems "Go mobile app" required. GPS may not be functional. Fair		\$10	
6.00 * 3-106	Inside Tailgate Cover, Ford Original Equipment Manufacturer (OEM). Moulded black plastic May be compatible with a 2003 Ford Ranger. Good		\$5	Part # F77J-940726-AD.
7.00 * 3-105	Inside Tailgate Cover, Ford Original Equipment Manufacturer (OEM). Moulded black plastic including top of tailgate May be compatible with a 2003 Ford Ranger. Good		\$5	Part # F77J-940726-AD.
6.00 * 3-104	Inside Tailgate Cover, Ford Original Equipment Manufacturer (OEM). Moulded black plastic including top of tailgate. May be compatible with a 2003 Ford Ranger. Good		\$5	Part # F77J-940726-AD.
No Bid * 6-103	Ladder rack, 64"w x 90"h Metal adjustable ladder rack with beacon. Mounting brackets included. White in color, unknown manufacturer. Good		\$150	
No Bid * 1-106	License Plate Bracket - Front, Chrysler Original Equipment Manufacturer (OEM), NO mounting kit May be compatible with 2002-2006 Sebring. Excellent		\$1	
No Bid * 1-107	License Plate Bracket - Front, Chrysler Original Equipment Manufacturer (OEM), NO mounting kit May be compatible with 2002-2006 Sebring. Excellent		\$1	
No Bid * 1-127	License Plate Bracket - Front, GM Original Equipment Manufacturer (OEM) Compatible with 2006-2016 Impala, includes mounting kit. Excellent		\$1	
No Bid * 1-128	License Plate Bracket - Front, GM Original Equipment Manufacturer (OEM) Compatible with 2006-2016 Impala, includes mounting kit. Excellent		\$1	
No Bid * 1-130	License Plate Bracket - Front, GM Original Equipment Manufacturer (OEM) Compatible with 2006-2016 Impala, includes mounting kit. Excellent		\$1	

Item #	Description	Kms	Min Price	Serial Number
No Bid * 1-131	License Plate Bracket - Front, GM Original Equipment Manufacturer (OEM) Compatible with 2006-2016 Impala, includes mounting kit. Excellent		\$1	
No Bid * 1-113	License Plate Bracket - Front, GM Original Equipment Manufacturer (OEM), includes mounting kit May be compatible with 2003-2007 Chevrolet Silverado 1500. Excellent		\$1	
No Bid * 1-114	License Plate Bracket - Front, GM Original Equipment Manufacturer (OEM), includes mounting kit May be compatible with 2003-2007 Chevrolet Silverado 1500. Excellent		\$1	
No Bid * 1-115	License Plate Bracket - Front, GM Original Equipment Manufacturer (OEM), includes mounting kit May be compatible with 2003-2007 Chevrolet Silverado 1500. Excellent		\$1	
No Bid * 1-116	License Plate Bracket - Front, GM Original Equipment Manufacturer (OEM), includes mounting kit May be compatible with 2003-2007 Chevrolet Silverado 1500. Excellent		\$1	
No Bid * 1-117	License Plate Bracket - Front, GM Original Equipment Manufacturer (OEM), includes mounting kit May be compatible with 2003-2007 Chevrolet Silverado 1500. Excellent		\$1	
No Bid * 1-110	License Plate Bracket - Front, Jeep Original Equipment Manufacturer (OEM), includes mounting kit. May be compatible with 2005-2007 Liberty. Excellent		\$1	
No Bid * 1-111	License Plate Bracket - Front, Jeep Original Equipment Manufacturer (OEM), includes mounting kit. May be compatible with 2005-2007 Liberty. Excellent		\$1	
No Bid * 1-112	License Plate Bracket - Front, Jeep Original Equipment Manufacturer (OEM), includes mounting kit. May be compatible with 2005-2007 Liberty. Excellent		\$1	
No Bid * 6-123	Manhole Gate Holder, Titan Stainless, aluminum 39"w x 46.5"d x 7.5"h, door hinge broken. Good		\$15	
No Bid * 3-135	Pillar Trim, Ford Original Equipment Manufacturer (OEM) Grey plastic, for left side inside pillar. Compatible with many Ford F250 and F350 trucks. Fair		\$10	
3.02 * 4-107	Safety Triangles, Lot of 2Auto Trend 18 inches each side. Good		\$1	
111.01 6-102	Shelves, 4 shelf unit, 2 shelf unit First metal shelf. 39 1/2"w x 14 1/2"d x 36 1/2"h, wood backing. Second metal shelf. 48"w x 18 1/2"d x 37"hm wood backing is warped. Good		\$100	
3.02 * 1-132	Shield for Inner Fender, 1 SetChrysler Original Equipment Manufacturer (OEM) 1 right and 1 left, rear only, may be compatible with a 2008 Chrysler 1500, 2500 or 3500. Excellent		\$1	
201.00 * 5-101	Tailgate, Original Equipment Manufacturer (OEM), Chevrolet Minor dents and scratches. May be compatible with 2002 and newer 1500, 2500, 3500 trucks, yellow. Good		\$200	A04010.
201.00 * 5-102	Tailgate, Original Equipment Manufacturer (OEM), GMC Sierra Missing one support cable. Minor dents or scratches. May be compatible with 2002 and newer 1500, 2500, 3500 trucks, yellow. Good		\$200	A02006.

Item #	Description	Kms	Min Price	Serial Number
No Bid * 11-125	Tires, Set of 3225/65R/16 Firestone FR710. M+S, manufacture date: week 47, year 2016. Good		\$120	
No Bid * 2-102	Tires, Set of 316 inch, 215/65R/16, Sumitomo HTR Enhance L/X manufacture date: week 27, year 2018. Good		\$120	
No Bid * 2-128	Tire, 16 inch, 225/65R/16, Sailun IceBlazer, Snowflake manufacture date. Week 16, year 2021. Good		\$40	
No Bid * 2-130	Tires, Set of 216 inch, 205/60R/16, Matrix Tour RD Multi-mile. manufacture date: week 44, year 2011. Fair		\$50	
No Bid * 3-107	Tires, Set of 4Dunlop Grantrek SJB. Snowflake. 215/65R/16, Manufacture date. Week 13, year 2009. Fair		\$120	
48.02 * 3-111	Tires, Set of 4Firestone FR710. M+S 225/65R/16, Manufacture date. Week 01, year 2016 Poor		\$40	
225.00 6-104	Tires, Set of 4 Firestone Winter Force 2. Snow flake. Mud and Snow. 225/55R/17 Manufacture date. Week 11. Year 2018. Good		\$160	
205.10 6-106	Tires, Set of 4 Firestone Winter Force 2. Snow flake. Mud and Snow. 225/60R/17 Manufacture date. Week 06, year 2020. Good		\$160	
120.00 6-107	Tires, Set of 4 Nordman WR SUV. Snow flake. Mud and Snow. 215/70R/16 Manufacture date. Week 30. Year 2016. Fair		\$120	
No Bid * 6-108	Tires, Set of 4 Sumitomo Ice Edge. Snow flake. Mud and snow. 215/65R/16 Manufacture date. Week 22. Year 2018. Fair		\$120	
188.88 6-109	Tires, Set of 4 Sumitomo Ice Edge. Snow flake. Mud and snow. 225/60R/16 Manufacture date. Week 15. Year 2019. Good		\$160	
155.55 6-124	Tires and Rims, Set of 2460 Case Trencher 5 Studded Rims 26 x 12R 12 NHS. Good		\$20	
61.02 6-128	Tires, Set of 4Artic Claw Winter TXI. M+S 225/65R/16, manufacture date. Week 23, year 23016. Poor		\$40	
No Bid * 6-129	Tires, Set of 4Sumitomo Enhance HTR LX. M+S. 215/65R/17, manufacture date. Week 26, year 2017. Fair		\$120	
171.00 6-130	Tires, Set of 4Sumitomo Ice Edge. Snow flake, M+S. 215/60R/16, manufacture date. Week14, year 2019. Good		\$160	
179.19 6-131	Tires, Set of 4Sumitomo Ice Edge. Snow flake, M+S. 215/60R/17, manufacture date. Week 26, year 2018. Good		\$160	
No Bid * 6-132	Tires, Set of 4Sumitomo Ice Edge. Snow flake, M+S. 215/65R/16, manufacture date. Week 21, year 2018 Good		\$160	
No Bid * 6-133	Tires, Set of 3Sumitomo Ice Edge. Snow flake, M+S. 225/75R/17, manufacture date. Week 18, year 2018. Good		\$160	

Item #	Description	Kms	Min Price	Serial Number
1,490.00 6-101	Trailer, 1986TransportHomebuilt 10 ft X 6 ft wide enclosed trailer, total length 14 1/2 ft, has a 4 ft tongue with jack, 5 - 7.00 x 15 10 ply tires, has spare tire mount on tongue, pintle eye		\$500	TB001
No Bid * 6-125	Winter Front / Bug Screen, For a 2000 2002 Dodge Ram Van, Via WF 923-3 Snaps may be missing. Good		\$5	
No Bid * 6-126	Winter Front / Bug Screen, For a 2007 2008 Dodge Durango, Via WF 929-57 Snaps may be missing. Good		\$5	
No Bid * 6-127	Winter Front / Bug Screen, For a 2007 2008 Dodge Durango, Via WF 929-57 Snaps may be missing. Good		\$5	
5.02 * 11-142	Arm chairs, Lot of 2 grey, cloth, on wheels Fair		\$1	
3.02 * 5-108	Chair, Swivel, Cloth Blue, 5 caster. Poor		\$1	
No Bid * 11-143	Chair, task. grey cloth, no arms. Fair		\$1	
3.02 * 11-145	Chair, task. lever controls partially working. Poor		\$1	
No Bid * 5-112	File Cabinet, Metal 14"l x 27"w x 28"h. Fair		\$1	
11.00 * 5-114	File Cabinet, Metal, Vertical Locks with key. 18"l x 28"w x 51.5"h. Fair		\$1	
11.00 * 11-160	File cabinet, no keys, lock destroyed, scuffed and scratched 4 drawer, vertical, metal. Fair		\$1	
No Bid * 5-117	File Cabinet , Metal, Vertical 17"l x 30"w x 29.5"h. Fair		\$1	
11.00 * 5-118	File Cabinet , Metal, Vertical Lock with no keys, 18"l x 28"w x 51"h. Fair		\$1	
No Bid * 5-120	Table, Metal, Wood 36"l x 24.5"w x 27"h. Fair		\$1	

Item #	Description	Kms	Min Price	Serial Number
FORT CARLTON PROVINCIAL PARK, Parks				
Contact Shani Bear 306-492-5676, shani.bear@gov.sk.ca				
21.00 6-501	Bunk Trailer, Atco Dormitory style trailer with 7 exterior doors, includes furnace. Not used for several years as a trailer, used as storage, all utilities disconnected, furniture is removed and decking pulled away. Trailer is on a towable frame, buyer will need to purchase tires for towing or haul away on a flat deck trailer. Sold as is, decking not included. Poor		\$1	15,415,667
22.00 6-502	House Trailer, 1981Atco Staff quarters, 2 bedrooms. All utilities disconnected and items removed. All decking and outside structures disconnected from house trailer, dock ready to move out on a towable frame. It will be the responsibility of the buyer to determine wheels to tow away and transport. Poor		\$1	152,816,664
HUDSON BAY, Corrections, Policing and Public Safety, 501 Prince Street				
Contact Randy Carlson (306)-865-4400, Randy.Carlson@gov.sk.ca or Shelley Kraft-Schnell (306) 865-4400, shelley.kraftschnell@gov.sk.ca				
805.00 * 5-545	Boat, Lund 12 ft aluminum (has small holes in bottom but repairable). Broken Repairable		\$1	2LU038670181
No Bid * 5-549	Chest Waders, Acton One size 10 and one size 11 chest waders. Unknown if they leak. Fair		\$1	
71.91 * 5-550	Game Caller, Johnny Stewart, MS-512 Cassette tape comes with loud speaker, carry case, vehicle charger and 5 cassette tapes. Fair		\$1	80,569
74.01 * 5-551	Game Caller, Johnny Stewart, MS-512 Cassette tape comes with loud speaker, carry case, vehicle charger and 5 cassette tapes. Fair		\$1	
76.01 * 5-552	Game Caller, Johnny Stewart, MS-513 Cassette tape comes with loud speaker, carry case, vehicle charger and 5 cassette tapes. Fair		\$1	87,572
No Bid * 5-557	Spotlight, Coleman Unknown if operational. Poor		\$1	
LARONGE, Saskatchewan Public Safety Agency, Hangar #2, LaRonge Airport				
Contact Brent Toth 306-425-4637 brent.toth@gov.sk.ca or Meghan Houk 306-425-4596, meghan.houk@gov.sk.ca				
4,400.00 6-530	Aircraft Cylinders, Lot of 2210 470 Unknown if operational. Poor		\$1	
1,500.00 6-531	Aircraft Cylinders, Lot of 75R2800 Unknown if operational. Poor		\$1	
50.00 6-532	Aircraft Jack, Metal Unknown if operational. Broken Repairable		\$1	
50.00 6-533	Aircraft Jack, Metal Unknown if operational. Broken Repairable		\$1	
50.00 6-534	Aircraft Jacks, Lot of 2Metal Unknown if operational. Broken Repairable		\$1	
1.00 6-535	Blue Storage Cabinet, Metal 28"l x 56"h x 60"w Fair		\$1	
2,500.00 6-536	Conversion Parts, Approx 215 parts, 500 plus piecesMiscellaneous Parts from Canadair CL-		\$1	
1,500.00 6-538	Engine Cowls and Parts , Approx 215 parts, 30 piecesAircraft, Canadair CL-215 Conversion,		\$1	
100.00 6-539	Engine Diagnostic System, For Vehicle Unknown if operational. Broken Repairable		\$1	

Item #	Description	Kms	Min Price	Serial Number
1,500.00 6-540	Engine Mount Tubs, Lot of 2 Aircraft, Canadair CL-215, Metal Unknown if operational. Poor		\$1	
150.00 6-542	Engine Mounts, Lot of 3 Aircraft, I-O 470 Needs Repair Broken Repairable		\$1	
500.00 6-541	Engine Mounts, Lot of 5 Aircraft, CL215, R2800 Unknown if operational. Broken Repairable		\$1	
2,500.00 6-543	Engine Parts, Approx 300 Pieces Aircraft, Miscellaneous Parts from Canadair CL-215 aircraft		\$1	
5,757.00 6-544	Engines, Lot of 5 Aircraft, CL215, R-2800 Unknown if operational. Broken Repairable		\$1	
600.00 6-545	Exhaust Pipes, Aircraft, 215, Metal Non-operational Poor		\$1	
1.00 6-546	Fire Extinguisher, Tanks and Stand, Non-operational Poor		\$1	
300.00 6-547	Foam Tanks, Lot of 2 Aircraft, CL215, Stainless Non-operational Poor		\$1	
300.00 6-548	Foam Unit, Aircraft, Amerex, Metal Unknown if operational. Broken Repairable		\$1	
300.00 6-549	Foam Unit, Aircraft, Amerex, Metal Unknown if operational. Broken Repairable		\$1	
300.00 6-550	Foam Unit, Aircraft, Amerex, Metal Unknown if operational. Broken Repairable		\$1	
300.00 6-551	Ground Power Units, Lot of 3 Aircraft Unknown if operational. Broken Repairable		\$1	
50.00 6-552	Hand Jack, M104 Hydraulic, unknown if operational. Broken Repairable		\$1	
389.80 6-553	Motor Generator Set, Metal Cord broken, unknown if operational. Broken Repairable		\$1	
126.99 6-554	Nose Casing, Aircraft, R-2800 Used in Pratt & Whitney R-2800 engine Poor		\$1	
100.00 6-555	Oil Coolers, Lot of 3 Aircraft, Aluminum Needs Repair Broken Repairable		\$1	
100.00 6-556	Oil Tank, Aircraft, CL215, Stainless steel Unknown if operational. Poor		\$1	
*WD 6-557	Power System, Generac Unknown if operational. Poor		\$1	
455.00 6-558	Pressure Washer, Unknown if operational. Broken Repairable		\$1	
2,500.00 6-559	Propeller, Aircraft, CL215P, Metal Unknown if operational. Broken Repairable		\$1	
*WD 6-560	Propeller Dome, Aircraft, 215 Unknown if operational. Fair		\$1	
600.00 6-561	Propeller Hub, Aircraft, CL215, Metal Unknown if operational. Poor		\$1	
9,000.00 6-537	Propellers, Lot of 4 Dowty Removed from a Twin Commander Aircraft, Garrett TPE331 engine, unknown if operational. Broken Repairable		\$1	
*WD 6-562	Pump and Tank, Unknown if operational. Broken Repairable		\$1	
245.75 6-563	Tracker Propeller Blades, Aircraft, Metal Unknown if operational. Poor		\$1	
*WD 6-564	Utility Heater, Herman Nelson, Portable Unknown if operational. Broken Repairable		\$1	
50.00 6-565	Water Pump, Yamaha YP30T 4", gas powered. Broken Repairable		\$1	

Item #	Description	Kms	Min Price	Serial Number	
MEADOW LAKE, Highways, Meadow Lake Airport, Meadow Lake, SK S0M 2M0.					
Contact Mark Eisenkirch 306-526-9103, mark.eisenkirch@gov.sk.ca					
21,105.00	6-595	Tractor, 1998New HollandTV140, Broom4WD7.5L inline 6, diesel hydrostaticA/C, tilt3 speed, single tires, tire size 480/85 R34, 10 ply, bi directionalyellow7,938 hrs.PROBLEMS: Battery, body exterior paint, windshield and windshield wipers, lights, mirrors and horn all in poor condition, tires are wore out, hood and cab are rusty and paint peeling. Unit runs and drives well, broom comes with unit, engine, transmission and hydraulics all work well. Minor exterior damage.> As is, Where is	7,938 hrs.	\$3,000	D203898
MEADOW LAKE, SaskBuilds and Procurement, 101 Railway Pl					
Contact Jim Wassing (306)-240-5407, jim.wassing@gov.sk.ca or Mathew Chuckrey (306)-304-5556, mathew.chuckrey@gov.sk.ca					
No Bid *	5-523	A/C Unit, Ducane Model AC10B3C-A Unknown if operational. Poor		\$1	3,406,410,219
MOOSE JAW, Highways & Infrastructure, Fleet Services, 1 km south of Moose Jaw on Highway #2.					
Contact Al Froehlich 306-694-3775, allan.froehlich@gov.sk.ca or Tara Watson 306-694-3773, tara.watson@gov.sk.ca					
5,155.00	6-594	Tractor, 1990FordBroom, 77102WD4.4L inline 4, diesel manualA/C, GVW 10,800 lbs.8 speed, single tires, tire size front 11L-16, rear 460/85R34, single axleyellow 3,761 hrs.PROBLEMS: Leak at hydraulic return filter, hydraulic motor on broom leaking, tail, signal and interior lights not working, instrument panel glitches in and out, sprockets and chain worn on broom, hard to shift, block heaters not working, brakes and battery poor, rear wiper not working, body paint rusty. Minor exterior damage.> As is, Where is	3,761 hrs.	\$500	BC26710
KENOSEE LAKE, Parks Culture and Sport, Moose Mountain Provincial Park					
Contact Leigh Potter 306-577-7810, leigh.potter@gov.sk.ca					
277.00	6-593	Truck, 2005FordF1504WD Supercab5.4L V8 gas Triton, autosingle tire, tire size 265/70R/17whiteTOW ONLY, NO SGI Inspection. It is unknown if any repairs or safety concerns exist (if any). Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs if required. 298,379 kmPROBLEMS: motor, transmission, brakes, exhaust unknown, tires and paint are poor, A/C doesn't work, windshield glass cracked, front right seat worn, tow only vehicle, hasn't ran in a year, dead battery, minor exterior damage.> As is, Where is	298,379 km	\$50	1FTPX14555NB71469
NORTH BATTLEFORD, Highways 502 114th Street.					
Contact Mark Eisenkirch 306-526-9103, mark.eisenkirch@gov.sk.ca					
5,002.00	6-529	Trailer, 1981Trailking 16 ton, tilt deck, GVW 32,000 lbs.tires dual, tire size 8.25x15, 14 plyyellowRecent Repairs: All deck boards were replace 1 year agoPROBLEMS: Unit failed SGI inspection,deck frame wrotten, minor exterior damage.> As is, Where is		\$500	TK1981-61

Item #	Description	Kms	Min Price	Serial Number
OUTLOOK, Agriculture, Crops and Irrigation, 410 Saskatchewan Ave W.				
Contact Heather Duczek-Reynolds 306-867-5529, heather.duczek-reynolds@gov.sk.ca or Jason Drury 306-867-5518, jason.drury@gov.sk.ca				
No Bid * 6-566	Auto Processor, 35mm With manual, unknown if operational. Fair		\$1	
3.55 6-505	Bookcase, wood, 4 shelves 36"l x 12"w * 73"h. Fair		\$1	
3.55 6-504	Bookcase, wooden 38"l x 12"w x 94"h, 5 shelves. Fair		\$1	
10.00 6-567	Camera Flash, Nikon Autofocus Speedlight SB-22 With carrying case and manual. Fair		\$1	
3.02 6-506	Chair, office, blue, cloth Upholstered, with castors. Fair		\$1	
No Bid * 6-507	Chair, occasional Green cloth with wood frame. Fair		\$1	
100.00 6-508	Desk, reception Great condition. Three sided receptionist "U" shaped desk. Includes one rolling under counter cabinet (3 drawer) and one fixed (2 drawer) under counter cabinet. Scalloped seating area. Will accommodate a stand up desk table top structure. Height of surround, 40"h to top of reception top. Desk Structure, 10.5' (longest side) x 91" x 66", desk width is 24 inches. Good		\$1	
No Bid * 6-509	Desk/Table, 3 drawer, 50"l x 30"w x 30"h. Fair		\$1	
No Bid * 6-510	Desk/Table, With one drawer, 50"l x 30"w x 30"h. Fair		\$1	
No Bid * 6-511	Drafting Table, Tech Master, metal Adjustable, with foot rail. 60"l x 40"w x 54"h. Fair		\$1	
No Bid * 6-568	Easel, dual purpose With carrying bag, * top cross piece fits loosely. Poor		\$1	
No Bid * 6-512	File Cabinet, Lot of 4lateral Beige, three drawer, 36"l x 18"w x 40"h. Fair		\$1	
No Bid * 6-513	File Cabinet, lateral, 3 drawer, beige 36"l x 18"w x 41"h, lock and key. Fair		\$1	
No Bid * 6-514	File Cabinet, lateral, 4 drawer, beige 36"l x 18"w x 64"h, lock and key. Fair		\$1	
No Bid * 6-515	File Cabinet, metal, lateral Three drawer, beige. *Top drawer slides open (does not stay shut). 36"l x 18"w x 39"h. Fair		\$1	
No Bid * 6-516	File Cabinet, vertical, 4 drawer, beige 28"w x 18"l x 51"h, lock and key. Fair		\$1	
23.00 6-517	Lectern, Sound-Craft Systems, Inc. With self contained speaker and microphone plug in. *All		\$1	
No Bid * 6-518	Map Storage Unit, metal Chest style, 34"l x 29"w x 43"h. Fair		\$1	
No Bid * 6-570	Overhead Projector, Elmo, HP L290 Deluxe Unknown if operational. Fair		\$1	
No Bid * 6-569	Overhead Projector, 3M With carrying case, unknown if operational. Fair		\$1	
No Bid * 6-572	Projection Screen, Draper, portable With stand and case, 5' x 5'. Fair		\$1	
No Bid * 6-573	Projection Screen, Portable With stand, brown casing, 5' x 5'. Fair		\$1	
5.00 6-571	Projection Screen, Dalite, portable With stand, green, 63"w x 57"h. Fair		\$1	

Item #	Description	Kms	Min Price	Serial Number
20.00 6-575	Reel to Reel Projector, Bell & Howell, 16 mm, Filmosound, Autoload, model 1592 With carrying case and manual, unknown if operational. Good		\$1	
No Bid * 6-577	Slide Projector, Lot of 2Kodak Ektagraphic, III A With carrying case, lens, spare bulb, cords and manual, unknown if operational. Fair		\$1	
No Bid * 6-576	Slide Projector, Lot of 2Kodak Ektagraphic AF-2 With carrying case, lens, spare bulb, cords and slide deck, unknown if operational. Fair		\$1	
*WD 6-519	Storage Cabinet, arborite 42"l x 14"w x 36"h. Fair		\$1	
No Bid * 6-520	Storage Unit, 24"l x 12"w x 30"h, used for 3.5*5 floppy discs. Fair		\$1	
No Bid * 6-521	Table, wood With storage on wheels, 30"l x 22"w x 27"h. Fair		\$1	
No Bid * 6-522	Table/Desk, arborite topped, wooden With pencil drawer, 50"l x 30"w x 31"h. Fair		\$1	
3.02 6-579	Tripod, Manfrotto Professional Tripod, model - 183 With carrying strap. Good		\$1	
PRINCE ALBERT, Highways, Northern Operations, 81 North Industrial Dr.				
Contact Cory Palko 306-960-5152, cory.palko@gov.sk.ca.				
27,777.78 6-599	Motor Grader, 2004Volvo G720BRWD7.1L inline 6, diesel, D7D GBE2 PowershiftA/C, AM/FM radio, locking differential8 speed, single tires, tire size 17.5R25yellow12,342 hrs.PROBLEMS: Hydraulic pump leaks oil, tires and battery are poor, will need batteries to start unit, minor exterior damage.> As is, Where is	12,342 hrs.	\$12,500	35,934
*MT 6-598	Motor Grader, 2004Volvo G720B4WD7.1L inline 6, diesel PowershiftA/C, scarified, locking differential, unit comes with various parts. 8 speed forward and reverse, single tires 11,407 hrs.PROBLEMS: May need batteries to start, tires and battery are poor, minor exterior damage.> As is, Where is	11,407 hrs.	\$12,500	35,950
58,356.00 6-605	Motor Grader, 2010John Deere770G4WD9L, inline 6, gas PowershiftA/C, locking differentialgear 8 forward, 8 reverse, tandem rear axle, single tires, tire size 17.5R25yellow12,252 hrs.PROBLEMS: Tires are poor, may need batteries to start, minor exterior damage.> -**Front mount scarified does not sell with unit. As is, Where is	12,252 hrs.	\$45,000	DW770GX626069
128.00 6-628	Arrow board, Vermac ST4825 Unit has been sitting unused Poor		\$1	
129.00 6-629	Arrow board, Vermac ST4825 Unit has been sitting unused Poor		\$1	
130.00 6-630	Arrow board, Wanco WTSP75-LSAC Unit has been sitting unused Poor		\$1	
751.50 6-613	Auto Crane, Truck mounted Unit has a lot of rust and needs multiple hoses changed. Fair		\$1	3,203
51.00 6-620	Cement Bucket, Crane Attachment For moving cement, unknown condition. Poor		\$1	
1,556.00 6-608	Fenders, Set of 8Fits John Deere motor grader, 870G New takeoffs. Good		\$1	
80.99 6-624	Fuel tank, Diesel, metal Portable, square, with electric fuel pump, red. Poor		\$1	

Item #	Description	Kms	Min Price	Serial Number
122.22 6-625	Fuel tank, Regal diesel, metal Portable, max capacity 388L, red, not certified. Fair		\$1	
111.11 6-626	Fuel tank, Regal diesel, metal Portable, max capacity 388L, red, not certified. Fair		\$1	
155.55 6-627	Fuel tank, Regal diesel, metal Portable, max capacity 388L, red, not certified. Fair		\$1	
156.00 6-609	Headlight Mounts, Set of 7 Fits John Deere motor grader, 870G New takeoffs. Good		\$1	
234.56 6-614	Mig Welder, Miller Millermatic 200 Has been sitting unused and needs servicing. Fair		\$1	
128.00 6-615	Mobile Air Cleaner, Enviroflex Smoke eater, has been sitting unused and needs servicing. Fair		\$1	
965.65 6-621	Mobile Crane, Hiab 965 Used, missing control levers on one side. Poor		\$1	
577.77 6-601	Oil Distributer, 1975 International 17002 WDIHC 392, 6.4L V8, gas auto Heat, 2 speed axle, GVW 24,000 lbs. 4 speed, single axle, dual rear tires, tire size 10 x 20, 12 ply. GVW 24,000 lbs. yellow 75,675 km PROBLEMS: Rear engine needs a new clutch, spray bar is missing parts, tires and battery are poor, will need new batteries to start unit, minor exterior damage.> As is, Where is	75,675 km	\$1	D0522ECA20236
2,600.00 6-600	Packer, 1974 Ford Bros SP3000 Rubber Wheel, RWD 3.1L inline 4, gas manual 4 speed, 9 tires, tire size 7.5 R 15, 6 ply yellow 9,069 hrs. PROBLEMS: Needs external fuel tank to run, battery poor, may need a battery to start unit, minor exterior damage.> As is, Where is	9,069 hrs.	\$2,500	8,435
526.00 6-623	Plow, Frinkone way, metal 11', manual blade adjustment Fair		\$1	19,374
5,777.77 6-606	Plow Truck, 1997 Volvo WG64 RWD 12.8L, VED12 inline 6, diesel RTLO-12610B, standard A/C, Cruise, locking differential 10 speed, tandem axle, dual tires, size 11R22.5. Wheel base 197", GVW 39,500 lbs. yellow 103,139 km PROBLEMS: Motor, brakes, battery, body, frame and paint, windshield, windshield wipers and horn are all in poor condition, brakes sticking, may need batteries to start, minor exterior damage.> As is, Where is	103,139 km	\$5,000	4V5JCBGE2VR85150
510.50 6-617	Propane Tank, metal, white 500 lb max capacity, not certified. Fair		\$1	
5,001.00 6-597	Steel Wheel Packer, 1982 Bros 735DDPRWD 3.48L inline 4, diesel hydrostatic 3 speed, single tire yellow 2,675 hrs. PROBLEMS: Transmission, tires, battery, body exterior and paint all in poor condition. Drive motor and drum vibrator leak oil, has various oil leaks, transmission is hard shifting, body has a lot of corrosion. Will need battery to start, minor exterior damage.> As is, Where is	2,675 hrs.	\$5,000	1,142
625.00 6-631	Traffic Lights, RC Flagman 2000 Solar remote, non functional controller, batteries damaged, flat tires, one unit missing lights. Not used in 10 years Poor		\$1	RCF0027 & RCF0028
201.00 6-604	Trailer, 1980 Utility Steamer Single axle Unit has been sitting unused, unknown condition yellow PROBLEMS: Overall condition poor. As is, Where is		\$1	SK400849150

Item #	Description	Kms	Min Price	Serial Number
1,901.00 6-607	Trailer, 1990ArmcoTilt deck GVW 40,000 lbs.tire size 255 70R 22.5, 14 plyyellowPROBLEMS: Frame is bent, tires are poor, minor exterior damage.> As is, Where is		\$500	P6KZ000134
327.00 6-603	Trailer, 1989HomebuiltUtility Single axle, flat bed, steelyellowPROBLEMS: Driver side wheel and rim missing. As is, Where is		\$1	SK400363627
1,901.00 6-602	Trailer, 2004TrailtechTD220 20 ton, pintle hitch, tandem axleyellow19,036 kmTires, battery, body and paint all in poor condition. Substantial frame damage, will need SGI inspection to pass, minor exterior damage.> As is, Where is	19,036 km	\$1	2CU4CAVN342016532
127.77 6-632	Truck Box, Steel Conveyor box with floor missing, has liquid tanks, holes rusted through. Poor		\$1	
127.77 6-633	Truck Box, Steel Conveyor box, has holes rusted through and no chain. Poor		\$1	
*WD * 6-634	Truck Box, Steel Conveyor box, has holes rusted through and no chain. Poor		\$1	
127.77 6-635	Truck Box, Steel Conveyor box, has holes rusted through and no chain. Poor		\$1	
177.77 6-610	Truck Fenders, Lot of 8Stainless Steel 25"w x 96"l, used on tandem axle gravel trucks, unused. Fair		\$1	
2.01 6-618	Winch, Truck mount type, metal Rusted, may be missing parts. Poor		\$1	
2.01 6-619	Winch, Truck mount type, metal Rusted, may be missing parts. Poor		\$1	
PRINCE ALBERT, Saskatchewan Public Safety Agency, 2120 Central Avenue North				
Contact Brent Zbaraschuk 306-953-2428, brent.zbaraschuk@gov.sk.ca or Tyla Wills 306-953-3400, Tyla.wills@gov.sk.ca				
No Bid * 3-533	Tires, Set of 4Michelin 215/75R17.5 Manufacture date: week 39, year 2011. Poor		\$1	
No Bid * 3-534	Tires, Set of 2Multi Trac G/S 23 x 10.5 -12 NHS For a quad. Poor		\$10	
REGINA, Highways, Operations and Maintanance, 221 N Winnipeg St.				
Contact Ethan Reoch 306-519-3560 ethan.reoch@gov.sk.ca or Braden Huel 306-531-4705 Braden.Huel@gov.sk.ca				
1.00 * 4-505	Car Seats , 2005 Dodge seats x2 seat row for dodge vehicle. Seats have never been used. Good		\$1	
No Bid * 4-506	Car Seats , Blue, three seat row with seat buckles. Unknown make. Fair		\$1	
No Bid * 4-507	Car Seats , Grey, three seat row with seat buckles. Unknown make. Fair		\$1	
No Bid * 4-508	Ducted Fume Hood, Includes vent, 30" x 65" x 47". Broken Repairable		\$1	
REGINA, Labour Relations and Workplace Safety, Corporate Services, 1870 Albert St.				
Contact Waneta Hardy 306-798-0312, waneta.hardy@gov.sk.ca, or Derek Wagner 306-787-1879, derek.wagner@gov.sk.ca				
5.00 6-586	Lab Equipment, 1 box Nalgene Tubing Four aquarium pumps (modified to suck in instead of blowing out), hand air pump, flow meter, and four filter cassette holders for sampling. Fair		\$1	
No Bid * 6-580	Binders, 4 boxes Mostly black and white, varying sizes, used. Fair		\$1	
No Bid * 6-581	Headset, Agptek Headset only, no base so unable to determine if operational. Poor		\$1	

Item #	Description	Kms	Min Price	Serial Number
2.00 6-582	Headset, Mpow No base. Poor		\$1	
No Bid * 6-583	Headsets, Lot of 4Jabra No bases. Poor		\$1	
No Bid * 6-584	Headsets, Lot of 3Jabra With bases, unsure if operational. Poor		\$1	
No Bid * 6-585	Headsets, Lot of 5Plantronics With bases, unsure if operational. Poor		\$1	
No Bid * 6-587	Painting, Picture of a tree, 10"w x 20"h. Fair		\$1	
No Bid * 6-588	Projector, Kodak Ektagraphic III Unsure if operational Poor		\$1	A-631031
No Bid * 6-589	Step File, Lot of 3 Black coating. Good		\$1	
SASKATOON, Saskpolytech, 1130 Idylwyld Drive N.				
Contact Chris Perry 306-659-4043, perrychr@saskpolytech.ca				
321.51 6-590	Vinyl Plank Flooring, Lot of 12Model WD5471, 319 sq.ft 4 mm luxury vinyl plank, 6"w x 36" l, 22.79 sq.ft/box New - Unused		\$199	
SMEATON, Parks, Culture and Sports, Narrow Hills Provincial Park, Box 130				
Contact Tanya White (306) 426-2622, tanya.white@gov.sk.ca or Laurie Shymanski (306) 426-2624, laurie.shymanski@gov.sk.ca				
No Bid * 4-553	Book, On The Living Edge Handbook to Waterfront Living, soft cover. Good		\$10	
No Bid * 4-554	Book, Small Fishing Vessel Safety Manual, soft cover. Good		\$5	
TISDALE, Highways & Transportation, Northern Tisdale, 1103-12th Ave.				
Contact David Derr, 306-878-8823 or 306-921-7202, david.derr@gov.sk.ca or Brent Douglas 306-961-0525, brent.douglas@gov.sk.ca				
5.00 * 3-502	Bunk Car, 1967Atco 10' x 30', trailer cannot move under its own weight, it is not floating on a base/frame that will need deconstructing, all utilities have been disconnected. Other information: loading required for removal - it is the responsibility of the buyer to measure height of unit, if necessary, for transportation route. As is, where is. 48 hours notice is required for pick up. Poor		\$1	
21.90 6-503	Pressure Washer, ClarkePortable Hot water, gas powered. Non operational. Poor		\$1	
TISDALE, SaskBuilds and Procurement, 1105-99 St Brocklebank Pl.				
Contact Cosette Koziel, 306-878-8800 cosette.koziel@gov.sk.ca				
No Bid * 6-523	Dumpster, metal, plastic top Floor has rust, rest of bin is good condition. Size is 6' wide x 5.5' deep x 5' tall at front and sloping to 4' tall at back. Fair		\$500	
YORKTON, Highways, Fleet Services, 245 York Road East.				
Contact Brian Perih 306-786-1651 or Ed Patzwald 306-786-1687 email: brian.perih@gov.sk.ca or ed.patzwald@gov.sk.ca.				
No Bid * 6-622	Pneumatic Torque Wrench Accessories, 2005Sioux, Model TM50AO-1075 Includes regulator, case and reaction arm ring. Torque wrench itself is not included. Fair		\$25	

Item #	Description	Kms	Min Price	Serial Number
128.00 6-527	Posts, wooden, mostly fir 4 inches x 6 inches x 14 feet approximately, old broken sign posts, approximate weight of lift is 6500 lbs. ** Must bring deck over trailer for assistance with loading, if deck over trailer cannot be provided loading is responsibility of buyer. Ministry staff will not load any trailer deemed unsafe to load. Trailers with fenders will not be loaded by Ministry staff. Please note lifts are now smaller to make handling safer. 55-65 posts per lift. Fair		\$1	
136.00 6-528	Posts, wooden, mostly fir 4 inches x 6 inches x 14 feet approximately, old broken sign posts, approximate weight of lift is 6500 lbs. **Must bring deck over trailer for assistance with loading, if deck over trailer cannot be provided loading is responsibility of buyer. Ministry staff will not load any trailer deemed unsafe to load. Trailers with fenders will not be loaded by Ministry staff. Please note lifts are now smaller to make handling safer. 55-65 posts per lift. Fair		\$1	
501.00 * 5-541	Trailer, 1978GICTilt deck 16 ton, dual tires, tire size: 8.25 x R15, 14 ply. GVW 32 000. Tires are fair. Brakes, body, paint and lights all in poor condition, yellow, 7333 hrs.yellow7333 hrsPROBLEMS: Spring hangers broken, excess corrosion between springs, fishplates on hitch have excess corrosion and material loss, several cross members and deck supports rusted through decking would need to be removed for repair, landing gear in poor shape and handle is falling apart, couple of wheel hubs leaking, toolbox rusted through, wires hanging down in several areas, lamps are cracked, Brakes, body, paint and lights all in poor condition, tires are fair. As is, Where is	7333 hrs	\$1	G61278